

# Mercedes Sprinter - Vito Viano MB100 Vario





**FREECARS (CHINA) COMPANY LIMITED**

**GUANGZHOU SUN ASIA IMPORT AND EXPORT CO.,LTD**

RM801-803,Goctic Centre,No.450,Huanshi East Road,Yuexiu District Guangzhou City

Tel: +86-20-84201892 Fax: +86-20-84201893 Mob: +86-13002023915

Email: freecars@163.com sales@freecars.com.cn

Website: www.freecarsautoparts.com

## Mercedes Sprinter Vito Viano MB100 Vario

| ITEM NO.   | OEM                                                                                | PHOTOS                                                                              | DESCRIPIFION              | MODEL                                                        | REMARK                                         |
|------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------|--------------------------------------------------------------|------------------------------------------------|
| FCS-BS-001 | 611 010 01 14<br>646 010 06 68<br>611 010 00 14<br>611 010 02 14                   |    | Crankshaft Oil Seal Cover | SPRINTER 208<br>312<br>412<br>313<br>413 CDI                 | OM 601<br>OM 602<br>OM 611<br>OM 612<br>OM 646 |
| FCS-BS-002 | 612 010 23 20<br>051 171 56 AA<br>050 800 025 AA<br>665 010 13 20<br>665 010 16 20 |    | Cylinder Head             |                                                              |                                                |
| FCS-BS-003 | 611 010 44 20<br>611 010 23 20<br>611 010 54 20<br>611 010 66 20<br>611 010 67 20  |    | Cylinder Head             | SPRINTER 208<br>311<br>313<br>413 CDI                        | OM 611                                         |
| FCS-BS-004 | 651 016 02 20                                                                      |    | Cylinder Head Gasket      | SPRINTER 311<br>313<br>315<br>318<br>515                     | OM 651                                         |
| FCS-BS-005 | 602 016 39 20                                                                      |   | Cylinder Head Gasket      |                                                              |                                                |
| FCS-BS-006 | 661 016 31 20                                                                      |  | Cylinder Head Gasket      |                                                              |                                                |
| FCS-BS-007 | 601 141 11 80                                                                      |  | Intake Manifold Gasket V4 | SPRINTER 208<br>207<br>208<br>209<br>308                     | OM 601                                         |
| FCS-BS-008 | 602 141 08 80                                                                      |  | Intake Manifold Gasket V5 | SPRINTER 212<br>210<br>310<br>410<br>312                     | OM 602                                         |
| FCS-BS-009 | 611 098 03 80                                                                      |  | Gasket, Intake Manifold   | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI            | OM 611<br>OM 646                               |
| FCS-BS-010 | 613 142 04 80<br>611 142 03 80<br>612 142 01 80                                    |  | Gasket, Intake Manifold   | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI            | OM 611<br>OM 612<br>OM 613<br>OM 628<br>OM 629 |
| FCS-BS-011 | 646 098 02 80                                                                      |  | Gasket, Intake Manifold   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI | OM 646                                         |
| FCS-BS-012 | 651 091 00 60                                                                      |  | Gasket, Intake Manifold   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI | OM 651                                         |


|            |                                |                                                                                     |                                                         |                                            |                                                |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------|--------------------------------------------|------------------------------------------------|
| FCS-BS-013 | 651 142 05 80                  |    | Gasket,intake Manifold                                  | SPRINTER 218 CDI<br>318 CDI<br>518 CDI     | OM 651                                         |
| FCS-BS-014 | 646 010 07 62                  |    | Valve,engine Block Breather                             | SPRINTER 311<br>313<br>315<br>515          | OM 611<br>OM 612<br>OM 646<br>OM 647           |
| FCS-BS-015 | 646 010 08 62<br>646 010 15 62 |    | Valve,engine Block Breather                             | SPRINTER 311<br>313<br>315<br>515          | OM 646                                         |
| FCS-BS-016 | 646 010 15 62                  |    | Valve,engine Block Breather                             | SPRINTER 311<br>313<br>315<br>515          | OM 646                                         |
| FCS-BS-017 | 611 016 01 34                  |    | Valve,engine Block Breather                             | SPRINTER 311<br>313<br>316<br>413<br>416   | OM 611<br>OM 612<br>OM 646                     |
| FCS-BS-018 | 611 016 03 34                  |    | Valve,engine Block Breather                             | SPRINTER 311<br>313<br>316<br>413<br>416   | OM 611<br>OM 612<br>OM 613<br>OM 646<br>OM 648 |
| FCS-BS-019 | 642 090 02 70                  |   | Intake Throttle Motor                                   |                                            |                                                |
| FCS-BS-020 | 642 098 30 07<br>642 098 12 07 |  | Charge Air Pipe - (2010 - up)                           |                                            |                                                |
| FCS-BS-021 | 642 090 69 37                  |  | Intake Manifold, Left (2010 - up)                       |                                            |                                                |
| FCS-BS-022 | 642 090 06 37                  |  | Intake Manifold, Right<br>(with Servomotor)-(2010 - up) |                                            |                                                |
| FCS-BS-023 | 642 141 05 80                  |  | Intake Manifold Gasket                                  | SPRINTER 209 CDI<br>315<br>515 CDI<br>VITO | OM 642                                         |
| FCS-BS-024 | 642 090 29 37                  |  | Intake Manifold Left-(2007 - 09)                        |                                            |                                                |
| FCS-BS-025 | 642 090 38 37                  |  | Intake Manifold, Right<br>(with Servomotor)-(2007 - 09) |                                            |                                                |
| FCS-BS-026 | 611 016 06 20                  |  | Cylinder Head Gasket                                    |                                            |                                                |




|            |               |                                                                                     |                                                  |                                                      |                                                          |
|------------|---------------|-------------------------------------------------------------------------------------|--------------------------------------------------|------------------------------------------------------|----------------------------------------------------------|
| FCS-BS-027 | 000 016 00 30 |     | Bypass Heater                                    | SPRINTER 311<br>315<br>515<br>518                    | OM 646<br>OM 651                                         |
| FCS-BS-028 | 611 016 06 30 |    | Bypass Heater                                    | SPRINTER 311<br>313<br>316<br>413<br>416             | OM 611<br>OM 612<br>OM 613                               |
| FCS-BS-029 | 642 016 03 30 |    | Bypass Heater                                    | SPRINTER 311<br>315<br>515<br>518                    | OM 651                                                   |
| FCS-BS-030 | 651 016 00 30 |    | Bypass Heater                                    | SPRINTER 311<br>315<br>515<br>518                    | OM 642                                                   |
| FCS-BS-031 | 111 018 03 02 |    | Oil Filter Cap                                   |                                                      |                                                          |
| FCS-BS-032 | 602 030 17 03 |    | Seal Ring To Crankshaft<br>Sealing Rear Follower | SPRINTER 212<br>312<br>412                           | OM 602<br>W 901<br>W 902<br>W 903<br>W 904               |
| FCS-BS-033 | 611 030 02 03 |   | Seal Ring To Crankshaft<br>Sealing Rear Follower | SPRINTER 211<br>213 311 313<br>411 413CDI            | OM 611 OM 611A<br>OM 611LA<br>W 901 W 902<br>W 903 W 904 |
| FCS-BS-034 | 651 030 07 03 |  | Crakshaft Pulley                                 | SPRINTER 515<br>518                                  | OM 651                                                   |
| FCS-BS-035 | 651 030 31 05 |  | Flywheel                                         | SPRINTER 515<br>518                                  | OM 651                                                   |
| FCS-BS-036 | 602 030 23 05 |  | Ring Gear To Flywheel                            | SPRINTER 212<br>312<br>412                           | OM 602<br>W 901<br>W 902<br>W 903<br>W 904               |
| FCS-BS-037 | 601 050 07 11 |  | Engine Timing Chain                              | SPRINTER 208<br>210<br>308<br>312<br>412.VITO108.110 | OM 601<br>OM 602<br>W 901<br>W 902<br>W 903 W 904        |
| FCS-BS-038 | 640 050 01 11 |  | Chain Adjuster                                   | SPRINTER 208<br>213,313,315,413,515,<br>518CDI,616   | OM 611<br>OM 612<br>OM 646<br>OM 647                     |
| FCS-BS-039 | 642 050 03 11 |  | Chain Adjuster                                   | SPRINTER 515<br>518                                  | OM 642                                                   |
| FCS-BS-040 | 111 050 14 16 |  | Sliding Rail                                     | SPRINTER 214<br>314<br>VITO 113<br>114<br>230        | M 111                                                    |





|            |               |                                                                                     |                            |                                                                      |                                                                             |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|----------------------------------------------------------------------|-----------------------------------------------------------------------------|
| FCS-BS-041 | 111 052 10 16 |     | Sliding Rail               | SPRINTER 214<br>314<br>VITO 113<br>114<br>230                        | M 111                                                                       |
| FCS-BS-042 | 112 052 00 16 |    | Sliding Rail               |                                                                      | M 112                                                                       |
| FCS-BS-043 | 112 052 01 16 |    | Sliding Rail               |                                                                      | M 112                                                                       |
| FCS-BS-044 | 112 052 02 16 |    | Sliding Rail               |                                                                      | M 112                                                                       |
| FCS-BS-045 | 601 050 05 16 |    | Sliding Rail               | SPRINTER 208<br>308<br>312<br>412                                    | OM 601<br>OM 602                                                            |
| FCS-BS-046 | 601 050 08 16 |    | Sliding Rail Clamping Rail | SPRINTER 208<br>210,308,312,412,VITO108,<br>110                      | OM 601;OM 602;OM<br>603;OM 604;OM 605;<br>W 638;W 901;W 902;<br>W 903       |
| FCS-BS-047 | 601 052 03 16 |   | Sliding Rail               | SPRINTER 208<br>308<br>312<br>412                                    | OM 601<br>OM 602                                                            |
| FCS-BS-048 | 611 052 00 16 |  | Sliding Rail               | SPRINTER 209<br>211,215,309,311,315,511,<br>515 CDI                  | OM 611;OM 612;<br>OM 613;OM 646;W 639;<br>W 901;W 902;W 903;<br>W 904;W 906 |
| FCS-BS-049 | 611 052 03 16 |  | Engine Timing Chain        | SPRINTER 211<br>213<br>311<br>313<br>411;413 CDI                     | OM 611;OM 612;<br>OM 646;W 901;W 902;<br>W 903;W 904;W 906;<br>W 639        |
| FCS-BS-050 | 611 052 04 16 |  | Sliding Rail               | SPRINTER 208<br>213;216;308;313;316;412;<br>413;416;616 CDI          | OM 611;OM 612;<br>OM 613;OM 646;<br>W 639,W 901,W 902,<br>W 903,W 904;W 906 |
| FCS-BS-051 | 642 050 09 16 |  | Rep.kit.sliding Rail       | SPRINTER 311<br>315<br>511<br>515 CDI                                | OM 642                                                                      |
| FCS-BS-052 | 651 050 00 16 |  | Guides,timing Chain        | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI | OM 651                                                                      |
| FCS-BS-053 | 651 052 00 16 |  | Sliding Rail               | SPRINTER 311<br>315<br>511<br>515 CDI                                | OM 651                                                                      |
| FCS-BS-054 | 651 052 01 00 |  | Sliding Rail               | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI | OM 651                                                                      |

|            |                                |                                                                                     |                         |                                                                                                            |                                                                                |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------|------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|
| FCS-BS-055 | 003 997 74 94                  |     | Oil Pump Chain          | SPRINTER 208;<br>213 CDI;312;313 CDI;412;<br>413 CDI;515 CDI;<br>518 CDI;VITO 108;<br>112 CDI;114; 120 CDI | OM 601;OM 602;OM<br>603;OM 611;<br>OM 646; W 639;<br>W 901;W 904;W<br>638;W639 |
| FCS-BS-056 | 601 050 08 25                  |    | Valve Tappet            | SPRINTER 208<br>310;410;210;308;312;408                                                                    | OM 601.900;<br>OM 601.911;<br>OM 601.940;<br>OM 601.941<br>W 601;W 602;        |
| FCS-BS-057 | 611 050 02 25<br>611 050 00 25 |    | Sliding Rail            | SPRINTER 208<br>308<br>313<br>413<br>616CDI                                                                | OM 611;OM 612;<br>OM 646;OM 647;<br>W 639;W 901;W 902;<br>W 903;W 904;W 905    |
| FCS-BS-058 | 000 993 63 76                  |    | Timing Chain            |                                                                                                            |                                                                                |
| FCS-BS-059 | 602 075 07 29                  |    | Sprocket Injection Pump | SPRINTER 212<br>312<br>412                                                                                 | OM 601<br>OM 602.980<br>OM 602.982<br>OM 602.986                               |
| FCS-BS-060 | 602 075 08 29                  |    | Sprocket Injection Pump | SPRINTER 212<br>312<br>412                                                                                 | OM 602.980<br>OM 602.982<br>OM 602.986                                         |
| FCS-BS-061 | 602 070 47 32                  |   | Hose, fuel Overflow     | SPRINTER 212<br>312<br>412                                                                                 | OM 602                                                                         |
| FCS-BS-062 | 611 070 00 32                  |  | Line                    | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                                          | OM 611                                                                         |
| FCS-BS-063 | 611 070 84 32-1                |  | Line, Lea Line Kit      | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                                          | OM 611<br>OM 646                                                               |
| FCS-BS-064 | 611 070 19 32                  |  | Fuel Line               |                                                                                                            | OM 611<br>OM 612                                                               |
| FCS-BS-065 | 611 070 20 32                  |  | Fuel Line               |                                                                                                            | OM 611                                                                         |
| FCS-BS-066 | 611 070 29 32                  |  | Fuel Line               |                                                                                                            | OM 611                                                                         |
| FCS-BS-067 | 611 070 68 32                  |  | Fuel Line               |                                                                                                            | OM 611<br>OM 612                                                               |
| FCS-BS-068 | 611 070 76 32                  |  | Fuel Line               |                                                                                                            | OM 611                                                                         |

|            |                                |                                                                                     |                    |                                                                      |                                                      |
|------------|--------------------------------|-------------------------------------------------------------------------------------|--------------------|----------------------------------------------------------------------|------------------------------------------------------|
| FCS-BS-069 | 612 070 00 32                  |     | Line               | SPRINTER 216 CDI<br>316 CDI<br>416 CDI                               | OM 612                                               |
| FCS-BS-070 | 612 070 39 32-1                |    | Line,Lea Line Kit  | SPRINTER 216 CDI<br>316 CDI<br>416 CDI                               | OM 612<br>OM 647                                     |
| FCS-BS-071 | 612 070 30 32<br>612 070 38 32 |    | Hose,Fuel Overflow | SPRINTER 216 CDI<br>316 CDI<br>416 CDI                               | OM 612                                               |
| FCS-BS-072 | 642 070 56 32                  |    | Hose,Fuel Overflow | SPRINTER 515<br>518                                                  | OM 642                                               |
| FCS-BS-073 | 646 070 09 32                  |    | Hose,Fuel Overflow | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 646                                               |
| FCS-BS-074 | 646 070 11 32                  |    | Hose,Fuel Overflow | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                    | OM 611<br>OM 646                                     |
| FCS-BS-075 | 646 070 15 32                  |   | Hose,Fuel Overflow | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 646                                               |
| FCS-BS-076 | 651 070 01 32                  |  | Line               | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI         | OM 651<br>W 639<br>W 906                             |
| FCS-BS-077 | 651 070 24 32                  |  | Hose,Fuel Overflow | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 651                                               |
| FCS-BS-078 | 601 070 37 33S                 |  | Cylinder Line      | SPRINTER 208<br>308<br>408                                           | OM 601.942<br>OM 601.943<br>OM 601.946<br>OM 601.947 |
| FCS-BS-079 | 601 070 37 33                  |  | Cylinder Line      | SPRINTER 208<br>308<br>408                                           | OM 601                                               |
| FCS-BS-080 | 601 070 38 33                  |  | Cylinder Line      | SPRINTER 208<br>308<br>408                                           | OM 601                                               |
| FCS-BS-081 | 601 070 39 33                  |  | Cylinder Line      | SPRINTER 208<br>308<br>408                                           | OM 601                                               |
| FCS-BS-082 | 601 070 40 33                  |  | Cylinder Line      | SPRINTER 208<br>308<br>408                                           | OM 601                                               |






|            |                                |                                                                                     |                                     |                                                                      |                                                      |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------|------------------------------------------------------|
| FCS-BS-083 | 601 070 45 33                  |     | High Pressure Pipe Injection System |                                                                      | OM 601                                               |
| FCS-BS-084 | 602 070 32 33                  |    | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602.980<br>OM 602.981<br>OM 602.982<br>OM 602.986 |
| FCS-BS-085 | 602 070 37 33                  |    | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602                                               |
| FCS-BS-086 | 602 070 38 33                  |    | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602                                               |
| FCS-BS-087 | 602 070 39 33                  |    | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602                                               |
| FCS-BS-088 | 602 070 40 33                  |    | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602                                               |
| FCS-BS-089 | 602 070 41 33                  |   | Cylinder Line                       | SPRINTER 208<br>308<br>312<br>412                                    | OM 602                                               |
| FCS-BS-090 | 611 070 00 33<br>611 070 02 33 |  | Cylinder Line                       | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CD                     | OM 611<br>OM 612                                     |
| FCS-BS-091 | 611 070 10 33                  |  | High Pressure Pipe Injection System |                                                                      | OM 646<br>OM 647                                     |
| FCS-BS-092 | 611 070 11 33                  |  | High Pressure Pipe Injection System | SPRINTER 208<br>308<br>312<br>412                                    | OM 646<br>OM 647                                     |
| FCS-BS-093 | 611 070 14 33                  |  | High Pressure Pipe Injection System | SPRINTER 208<br>308<br>312<br>412                                    | OM 611<br>OM 612                                     |
| FCS-BS-094 | 646 070 02 33                  |  | High Pressure Pipe Injection System | SPRINTER 208<br>308<br>312<br>412                                    | OM 611<br>OM 612                                     |
| FCS-BS-095 | 646 070 03 33                  |  | High Pressure Pipe Injection System |                                                                      | OM 646                                               |
| FCS-BS-096 | 651 070 24 33                  |  | Fuel Pipe Line                      | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 651<br>W 639<br>W 906                             |

|            |               |                                                                                     |                                                       |                                                                      |                                                               |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------------------------------------------|----------------------------------------------------------------------|---------------------------------------------------------------|
| FCS-BS-097 | 651 070 25 33 |     | High Pressure Pipe Injection System                   |                                                                      | OM 651                                                        |
| FCS-BS-098 | 651 070 30 33 |    | High Pressure Pipe Injection System                   |                                                                      | OM 651                                                        |
| FCS-BS-099 | 000 010 16 51 |    | Injector With Cable                                   | SPRINTER 312<br>412                                                  | OM 602<br>W 901<br>W 902<br>W 903<br>W 904                    |
| FCS-BS-100 | 611 070 16 87 |    | Injector                                              | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                    | OM 611 DE LA<br>OM 612 DE LA<br>W 901<br>W 902<br>W 903;W 904 |
| FCS-BS-101 | 611 016 07 38 |    | Injector Holder                                       | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI<br>315;518         | OM 611<br>OM 612<br>OM 613<br>OM 628<br>OM 646                |
| FCS-BS-102 | 612 070 03 87 |    | Fuel Injector                                         |                                                                      | OM611<br>OM612                                                |
| FCS-BS-103 | 647 070 01 87 |   | Fuel Injector                                         |                                                                      | OM647                                                         |
| FCS-BS-104 | 611 017 00 60 |  | Seal, Fuel Injector                                   |                                                                      |                                                               |
| FCS-BS-105 | 642 070 15 87 |  | Fuel Injector OM642<br>(2007 - 2009)                  |                                                                      | OM642                                                         |
| FCS-BS-106 | 642 070 12 87 |  | Fuel Injector Bluetec Diesel<br>(2010-up)             |                                                                      |                                                               |
| FCS-BS-107 | 651 070 49 87 |  | Fuel Injector                                         |                                                                      |                                                               |
| FCS-BS-108 | 642 070 11 01 |  | Diesel Injection Pump<br>- VIN Specific (2010 - up) - |                                                                      |                                                               |
| FCS-BS-109 | 642 070 03 01 |  | Diesel Injection Pump<br>- VIN Specific -             |                                                                      |                                                               |
| FCS-BS-110 | 611 078 01 49 |  | Pressure Control Valve<br>Common Rail System          | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 611<br>OM 612<br>OM 613<br>OM 628<br>OM 668                |

|            |                                                                              |                                                                                     |                                              |                                                                      |                                                                              |
|------------|------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------------|------------------------------------------------------------------------------|
| FCS-BS-111 | 611 07 80 549                                                                |     | Pressure Control Valve<br>Common Rail System | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 611<br>OM 612<br>OM 628                                                   |
| FCS-BS-112 | 642 078 01 49                                                                |    | Pressure Control Valve<br>Common Rail System | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI | OM 642                                                                       |
| FCS-BS-113 | 642 078 02 49                                                                |    | Pressure Control Valve<br>Common Rail System | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI | OM 642                                                                       |
| FCS-BS-114 | 646 074 00 84                                                                |    | Pressure Control Valve<br>Common Rail System | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                    | OM 646<br>OM 647<br>OM 648                                                   |
| FCS-BS-115 | 000 078 09 56                                                                |    | Breather Valve                               | SPRINTER 212<br>312;412;208 CDI<br>213 CDI;313 CDI;413 CDI           | OM 602<br>OM 603<br>OM 604<br>OM 606<br>OM 611                               |
| FCS-BS-116 | 601 090 14 52                                                                |    | Fuel Filter                                  | SPRINTER 207<br>210<br>307<br>308<br>312;412                         | OM 601<br>OM 602.911<br>OM 602.961<br>OM 603.912                             |
| FCS-BS-117 | 601 092 01 05                                                                |   | Fuel Filter                                  | SPRINTER 208 D<br>308 D<br>408 D                                     | OM 601<br>OM 605<br>OM 606                                                   |
| FCS-BS-118 | 611 092 01 01                                                                |  | Fuel Filter                                  | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                    | OM 612.983<br>OM 611.980<br>OM 611.981<br>OM 668;W 901;<br>W 902;W 903;W 904 |
| FCS-BS-119 | 646 092 05 01                                                                |  | Fuel Filter                                  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                    | OM 642<br>OM 646<br>W 639<br>W 906                                           |
| FCS-BS-120 | 646 092 07 01<br>642 092 01 01<br>642 092 05 01<br>5170896AB<br>6460900252HE |  | Fuel Filter                                  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI | OM 646<br>OM 647<br>W 639<br>W 906                                           |
| FCS-BS-121 | 651 090 15 52                                                                |  | Fuel Filter                                  | SPRINTER 515<br>518                                                  | OM 651                                                                       |
| FCS-BS-122 | 612 092 00 01                                                                |  | Fuel Filter                                  |                                                                      |                                                                              |
| FCS-BS-123 | 642 090 63 52                                                                |  | Fuel Filter Sprinter 2007+                   |                                                                      |                                                                              |
| FCS-BS-124 | 642 092 03 01                                                                |  | Fuel Filter - (2010 - 2011)                  |                                                                      |                                                                              |

|            |                                                                                   |                                                                                     |                                                                            |                                                                      |                                                                      |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------|----------------------------------------------------------------------|----------------------------------------------------------------------|
| FCS-BS-125 | 642 090 48 52                                                                     |     | Fuel Filter - (2012 - 2014)                                                |                                                                      |                                                                      |
| FCS-BS-126 | 651 090 29 52                                                                     |    | Fuel Filter - (2014 & up) w/ 4 cyl only, NO water separator (check w vin#) |                                                                      |                                                                      |
| FCS-BS-127 | 651 090 31 52                                                                     |    | Fuel Filter - (2014 & up) w/ 4 cyl only, NO water separator (check w vin#) |                                                                      |                                                                      |
| FCS-BS-128 | 601 090 03 52                                                                     |    | Fuel Filter                                                                |                                                                      |                                                                      |
| FCS-BS-129 | 601 092 01 01<br>60209420101                                                      |    | Fuel Filter                                                                |                                                                      |                                                                      |
| FCS-BS-130 | 611 090 08 52<br>611 092 02 01<br>045 690 59 30<br>098 645 05 06<br>611 092 06 01 |    | Fuel Filter                                                                |                                                                      | OM612.983<br>OM611.980<br>OM611.981<br>OM611.987<br>OM668;W901;W902; |
| FCS-BS-131 | 611 090 03 50<br>611 090 02 50<br>050 802 55 AA<br>611 090 01 50                  |   | Fuel Pump                                                                  | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 611<br>OM 612                                                     |
| FCS-BS-132 | 651 200 10 56                                                                     |  | Fuel Filter Housing Bracket                                                |                                                                      |                                                                      |
| FCS-BS-133 | 000 090 50 01<br>000 090 78 01<br>000 090 37 51                                   |  | Air Filter Box                                                             |                                                                      |                                                                      |
| FCS-BS-134 | 906 430 01 03                                                                     |  | Air reservoir Expansion Tank                                               |                                                                      |                                                                      |
| FCS-BS-135 | 001 230 71 11                                                                     |  | A/C Compressor                                                             |                                                                      |                                                                      |
| FCS-BS-136 | 001 230 32 11                                                                     |  | A/C Compressor                                                             |                                                                      |                                                                      |
| FCS-BS-137 | 001 230 86 11                                                                     |  | A/C Compressor                                                             |                                                                      |                                                                      |
| FCS-BS-138 | 7SBU16C<br>447100-6820<br>A0002307011<br>0002342911<br>A0002306811                |  | A/C Compressor                                                             | MERCEDES-BENZ<br>SPRINTER 2-t Box<br>(901, 902) 210 D                |                                                                      |

|            |                                                 |                                                                                     |                    |                                                                               |                                  |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|--------------------|-------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-139 | 646 074 04 84                                   |     | Flow Control Valve |                                                                               |                                  |
| FCS-BS-140 | 651 090 01 48                                   |    | Air Flow Meter     |                                                                               |                                  |
| FCS-BS-141 | 612 070 01 01                                   |    | High Pressure Pump |                                                                               |                                  |
| FCS-BS-142 | 648 070 02 01                                   |    | High Pressure Pump |                                                                               |                                  |
| FCS-BS-143 | 000 094 18 48                                   |    | Air Mass Sensor    |                                                                               |                                  |
| FCS-BS-144 | 000 094 22 48                                   |    | Air Filter Box     |                                                                               |                                  |
| FCS-BS-145 | 000 094 34 48                                   |   | Air Mass Sensor    |                                                                               |                                  |
| FCS-BS-146 | 000 094 32 48                                   |  | Air Mass Sensor    |                                                                               |                                  |
| FCS-BS-147 | 003 094 75 04                                   |  | Air Filter         |                                                                               |                                  |
| FCS-BS-148 | 000 090 16 51                                   |  | Air Filter         | VITO<br>VIANO<br>108<br>111<br>113;115 CDI                                    | W 639                            |
| FCS-BS-149 | 000 090 26 51<br>000 090 37 51<br>000 090 50 01 |  | Air Filter         | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI          | W 906                            |
| FCS-BS-150 | 000 090 38 51                                   |  | Air Filter         | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI          | W 906                            |
| FCS-BS-151 | 638 090 01 51                                   |  | Air Filter         | VITO 108<br>110                                                               | W 638                            |
| FCS-BS-152 | 003 094 83 04                                   |  | Air Filter         | SPRINTER 208<br>210;212;312<br>412;208 CDI;313 CDI<br>316 CDI;413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |



|            |                                                                                   |                                                                                     |               |                                                                                |                                                                          |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------|--------------------------------------------------------------------------------|--------------------------------------------------------------------------|
| FCS-BS-153 | 004 094 26 04                                                                     |     | Air Filter    | SPRINTER 208<br>210;212;312<br>412;208 CDI;313 CDI<br>316 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904                                         |
| FCS-BS-154 | 611 094 00 48                                                                     |    | Air Filter    | SPRINTER 208<br>213 CDI<br>312<br>313 CDI<br>412;413 CDI                       |                                                                          |
| FCS-BS-155 | 646 090 16 70                                                                     |    | Throttle Body | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI           | OM 646                                                                   |
| FCS-BS-156 | 651 090 63 80                                                                     |    | Turbocharger  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI           | OM 651                                                                   |
| FCS-BS-157 | 611 096 08 99<br>611 096 16 99                                                    |    | Turbocharger  | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                              | OM 611<br>W 901<br>W 902<br>W 903<br>W 904                               |
| FCS-BS-158 | 601 096 02 99                                                                     |    | Turbocharger  | VITO 108<br>110                                                                | OM 601<br>W 638                                                          |
| FCS-BS-159 | 602 096 08 99                                                                     |   | Turbocharger  | SPRINTER 210<br>212<br>310<br>312<br>410;412                                   | OM 602<br>W 901<br>W 902<br>W 903<br>W 904                               |
| FCS-BS-160 | 602 096 09 99                                                                     |  | Turbocharger  | SPRINTER 310<br>312<br>412                                                     | OM 602                                                                   |
| FCS-BS-161 | 612 096 03 99                                                                     |  | Turbocharger  | SPRINTER 216<br>316<br>416 CDI                                                 | OM 612                                                                   |
| FCS-BS-162 | 0051516601                                                                        |  | Starter       | SPRT 208 CDI<br>211 CDI<br>213 CDI ( 01.95 -05.06 )<br>SPRT 208 CDI<br>211 CDI |                                                                          |
| FCS-BS-163 | 0001109250<br>0001218006<br>0001218021<br>0001218108<br>0001218150                |  | Starter       | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                              | OM 611<br>W 901<br>W 902<br>W 903<br>W 904                               |
| FCS-BS-164 | 005 151 13 01<br>000 110 90 14<br>000 110 90 36<br>004 151 89 01<br>004 151 92 01 |  | Starter       | SPRINTER 212<br>312<br>412<br>VITO<br>VARIO                                    | OM602.980<br>OM 602.981<br>OM 602.982<br>OM 602.984<br>W 901;W 902;W 903 |
| FCS-BS-165 | 651 906 00 26<br>006 151 45 01                                                    |  | Starter       | SPRINTER 209<br>315<br>515 CDI                                                 | OM 651                                                                   |
| FCS-BS-166 | 005 151 29 01<br>000 122 30 05<br>005151290180                                    |  | Starter       |                                                                                |                                                                          |

|            |                                                                    |                                                                                     |                                      |                                                                      |                                                     |
|------------|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------|----------------------------------------------------------------------|-----------------------------------------------------|
| FCS-BS-167 | 006 151 75 01<br>000 111 50 76<br>000 111 50 77<br>098 602 22 40   |     | Starter - (2007-2009) -              |                                                                      |                                                     |
| FCS-BS-168 | 0001115006<br>0001115076<br>0001115100<br>0001115108<br>0986018170 |    | Starter - (2010-up) -                |                                                                      |                                                     |
| FCS-BS-169 | 000 152 73 10                                                      |    | Solenoid Switch,starter              |                                                                      | OM 601<br>OM 602<br>OM 615                          |
| FCS-BS-170 | 001 152 65 10                                                      |    | Solenoid Switch,starter              |                                                                      | M 111<br>M 272<br>OM 611<br>OM 612<br>OM 642;OM646  |
| FCS-BS-171 | 000 153 95 13                                                      |    | Solenoid Switch,starter              |                                                                      | OM 642<br>OM 646<br>OM 647<br>OM 648<br>W 639;W 906 |
| FCS-BS-172 | 004 153 52 28                                                      |    | Oil Lever Sensor                     | SPRINTER 311<br>313<br>316<br>413<br>416                             | OM 611<br>OM 612<br>OM 611.950<br>OM 611.980        |
| FCS-BS-173 | 124 542 00 17                                                      |   | Sensor,Engine Oil Level              | SPRINTER<br>PKW<br>VITO                                              | M 102<br>M 103<br>M 104<br>OM 601<br>OM 602;OM 603  |
| FCS-BS-174 | 000 905 03 01<br>006 153 30 28                                     |  | Sensor,Engine Oil Level              | SPRINTER<br>PKW<br>VITO                                              | M 111<br>M 271<br>OM 611<br>OM 612<br>OM 646;OM647  |
| FCS-BS-175 | 000 905 04 01                                                      |  | Sensor,Engine Oil Level              | SPRINTER 209<br>315<br>319 CDI<br>515 CDI;519 CDI<br>VITO;VIANO      | OM 628<br>OM 629<br>OM 642<br>OM 646<br>OM 647      |
| FCS-BS-176 | 140 830 00 72                                                      |  | A/C Pressure Sensor                  |                                                                      |                                                     |
| FCS-BS-177 | 011 542 96 17                                                      |  | Outside Temp Sensor<br>(2001-2006) - |                                                                      |                                                     |
| FCS-BS-178 | 005 153 13 28                                                      |  | Cam Sensor                           |                                                                      |                                                     |
| FCS-BS-179 | 001 153 11 32                                                      |  | Oil Level Sensor - (2007 - up) -     |                                                                      |                                                     |
| FCS-BS-180 | 004 153 75 28                                                      |  | Sensor,Fuel Pressure                 | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 611<br>OM 612                                    |

|            |                                |                                                                                     |                                     |                                                                      |                                                       |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------|-------------------------------------------------------|
| FCS-BS-181 | 005 153 58 28                  |     | Sensor,Fuel Pressure                | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 611<br>OM 612<br>OM 628                            |
| FCS-BS-182 | 006 153 65 28                  |    | Sensor,Fuel Pressure                | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>413 CDI;416 CDI | OM 629<br>OM 693<br>OM 640<br>OM 642<br>OM 646;OM 660 |
| FCS-BS-183 | 000 545 05 27<br>000 545 04 27 |    | Boost Pressure Control Valve        | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI<br>416 CDI;616 CDI | OM 611<br>OM 612                                      |
| FCS-BS-184 | 000 153 55 28                  |    | Boost Pressure Control Valve        | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI<br>416 CDI;616 CDI | M 271<br>M 272<br>OM 642<br>OM 646<br>OM 651          |
| FCS-BS-185 | 006 153 66 28                  |    | Pressure Converter<br>Turbocharger  | SPRINTER 509 CDI<br>515 CDI<br>518 CDI<br>VITO 639                   | M 271;M 272<br>OM 640<br>OM 642<br>OM 646<br>OM 651   |
| FCS-BS-186 | 007 153 31 28                  |    | Pressure Converter<br>Turbocharger  |                                                                      | OM 651                                                |
| FCS-BS-187 | 642 150 04 94                  |   | EGR Servo Motor Intake<br>Manifold  |                                                                      |                                                       |
| FCS-BS-188 | 642 142 23 80                  |  | EGR Valve Gasket<br>- (2007 - up) - |                                                                      |                                                       |
| FCS-BS-189 | 642 140 14 60                  |  | EGR Valve                           |                                                                      |                                                       |
| FCS-BS-190 | 002 540 14 97                  |  | Vacuum Control Valve,Egr            | SPRINTER 208 CDI<br>214 CDI<br>313 CDI<br>413 CDI<br>416 CDI;616 CDI | M 104;M 111<br>M 112;M 113<br>OM 602<br>OM 628        |
| FCS-BS-191 | 002 140 26 60                  |  | Valve,Egr Exhaust Control           | SPRINTER 212<br>312<br>412<br>VITO<br>VARIO                          | OM 601<br>OM 602                                      |
| FCS-BS-192 | 611 090 02 54                  |  | Valve,Egr Exhaust Control           | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                    | OM 611                                                |
| FCS-BS-193 | 611 090 03 54                  |  | Valve,Egr Exhaust Control           | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                    | OM 611                                                |
| FCS-BS-194 | 612 098 04 17                  |  | Valve,Egr Exhaust Control           | SPRINTER 216 CDI<br>316 CDI<br>416 CDI                               | OM 612                                                |

|            |                                                                  |                                                                                     |                                                     |                                                                      |                                                |
|------------|------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------|----------------------------------------------------------------------|------------------------------------------------|
| FCS-BS-195 | 642 140 17 60<br>680 515 14 AA                                   |     | Valve,Egr Exhaust Control                           | SPRINTER 218 CDI<br>318 CDI<br>518 CDI                               | OM 642<br>W 906<br>W 639                       |
| FCS-BS-196 | 646 140 08 60                                                    |    | Valve,Egr Exhaust Control                           | VITO 109 CDI<br>111 CDI<br>115 CDI                                   | OM 646<br>OM 647<br>OM 648<br>W 639            |
| FCS-BS-197 | 646 140 09 60                                                    |    | Valve,Egr Exhaust Control                           | VITO<br>109 CDI<br>111 CDI<br>115 CDI                                | OM 646<br>W 639                                |
| FCS-BS-198 | 647 142 00 19                                                    |    | Valve,Egr Exhaust Control                           | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 646<br>OM 647<br>W 906                      |
| FCS-BS-199 | 007 153 84 28                                                    |    | EGR Cooler Temp. Sensor                             |                                                                      |                                                |
| FCS-BS-200 | 007 153 75 28<br>005 153 79 28<br>007 153 84 28<br>000 905 43 05 |    | Lambda Sensor,Front                                 |                                                                      | OM 611<br>OM 642<br>OM 646<br>W 639<br>W 906   |
| FCS-BS-201 | 000 905 33 00<br>000 905 14 05                                   |   | Exhaust Temp Sensor for<br>Turbo<br>- VIN Specific  |                                                                      |                                                |
| FCS-BS-202 | 005 153 80 28<br>007 153 85 28                                   |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 646<br>OM 648                               |
| FCS-BS-203 | 007 153 62 28<br>000 905 01 32                                   |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 611<br>OM 642<br>OM 646<br>OM 660           |
| FCS-BS-204 | 008 153 22 28                                                    |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 651                                         |
| FCS-BS-205 | 008 153 36 28                                                    |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 642                                         |
| FCS-BS-206 | 000 905 87 00<br>007 153 95 28                                   |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 611<br>OM 640<br>OM 642<br>OM 646<br>OM 651 |
| FCS-BS-207 | 001 905 12 00                                                    |  | Sensor<br>Exhaust Gas Temperature                   | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI:515 CDI | OM 651                                         |
| FCS-BS-208 | 642 905 01 00                                                    |  | Exhaust Pressure Sensor<br>vacuum<br>- VIN Specific |                                                                      |                                                |



|            |                                                                           |                                                                                     |                          |                                                                              |                                                                       |
|------------|---------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------|------------------------------------------------------------------------------|-----------------------------------------------------------------------|
| FCS-BS-209 | 642 905 02 00                                                             |     | Sensor,Exhaust Pressure  |                                                                              |                                                                       |
| FCS-BS-210 | 006 153 95 28                                                             |    | Sensor,Exhaust Pressure  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI         | OM 611<br>OM 642<br>OM 646                                            |
| FCS-BS-211 | 007 153 43 28<br>007 153 98 28                                            |    | Sensor,Exhaust Pressure  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI         | OM 611<br>OM 612<br>OM 629<br>OM 639<br>OM 640                        |
| FCS-BS-212 | 642 905 02 00                                                             |    | Sensor,Exhaust Pressure  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI         | OM 640<br>OM 642<br>OM 651                                            |
| FCS-BS-213 | 651 905 02 00                                                             |    | Sensor,Exhaust Pressure  | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI;515 CDI         | OM 651                                                                |
| FCS-BS-214 | 003 153 28 28                                                             |    | Sensor,Crankshaft Pulse  | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI;318 CDI<br>518 CDI;519 CDI | M 111<br>M 112<br>OM 611<br>OM 612                                    |
| FCS-BS-215 | 003 153 72 28                                                             |   | Sensor,Crankshaft Pulse  | SPRINTER 212<br>312<br>412<br>VITO<br>VARIO                                  | OM 602                                                                |
| FCS-BS-216 | 642 905 00 00                                                             |  | Sensor,Crankshaft Pulse  | SPRINTER 209<br>315<br>319 CDI<br>515 CDI;519 CDI<br>VITO;VIANO              | M 156;M 159;M 271<br>M 272;M 273;OM 629                               |
| FCS-BS-217 | 004 153 00 28                                                             |  | Sensor,camshaft Position | SPRINTER 214<br>314<br>414<br>VITO 113<br>114;230                            | M 111                                                                 |
| FCS-BS-218 | 5080346AA<br>5175762AA<br>003 153 97 28<br>005 153 13 28<br>004 153 69 28 |  | Sensor,Camshaft Position | SPRINTER 209<br>315<br>515 CDI<br>VITO<br>VIANO                              | M 112                                                                 |
| FCS-BS-219 | 003 159 97 28                                                             |  | Sensor,Camshaft Position | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI;318 CDI<br>518 CDI;519 CDI | OM 611<br>OM 612<br>OM 646                                            |
| FCS-BS-220 | 651 905 01 00                                                             |  | Sensor,Camshaft Position | SPRINTER 209<br>315<br>515 CDI<br>VITO<br>VIANO                              | OM 651                                                                |
| FCS-BS-221 | 000 154 17 05                                                             |  | Alternator Regulator     |                                                                              | OM 314;OM 353<br>OM 354;OM 364<br>W 667<br>W 668;W 669<br>W 670;W 673 |
| FCS-BS-222 | 002 154 40 06                                                             |  | Alternator Regulator     |                                                                              | OM 354<br>OM 314<br>W 309;W 310<br>W 313;W 668;W 670                  |




|            |               |                                                                                     |                      |                                         |                                                                |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------|-----------------------------------------|----------------------------------------------------------------|
| FCS-BS-223 | 002 154 41 06 |     | Alternator Regulator | SPRINTER 310<br>312<br>412              | M 102;M 115<br>OM 615;OM 616<br>OM 617;W 601;W 602             |
| FCS-BS-224 | 002 154 85 06 |    | Alternator Regulator |                                         | OM 601;OM 602<br>OM 611;OM 612<br>W 601;W 602<br>W 901;W 902   |
| FCS-BS-225 | 003 154 42 06 |    | Alternator Regulator | 24V                                     | OM 611<br>OM 646<br>W 639<br>W 906                             |
| FCS-BS-226 | 003 154 28 06 |    | Alternator Regulator |                                         |                                                                |
| FCS-BS-227 | 003 154 64 06 |    | Alternator Regulator |                                         | OM 642<br>W 639<br>W 906                                       |
| FCS-BS-228 | 003 154 82 06 |    | Alternator Regulator |                                         | OM 611<br>OM 612<br>OM 647<br>W 906                            |
| FCS-BS-229 | 003 154 83 06 |   | Alternator Regulator |                                         | OM 611<br>OM 612<br>OM 647<br>W 639<br>W 906                   |
| FCS-BS-230 | 003 154 90 06 |  | Alternator Regulator |                                         | OM 611<br>OM 612;OM 647<br>W 901;W 902<br>W 903;W 904<br>W 905 |
| FCS-BS-231 | 003 154 92 06 |  | Alternator Regulator |                                         | OM 640<br>OM 651<br>W 639<br>W 906                             |
| FCS-BS-232 | 003 154 96 06 |  | Alternator Regulator |                                         | OM 611<br>OM 612<br>OM 647<br>W 906                            |
| FCS-BS-233 | 004 154 08 06 |  | Alternator Regulator | SPRINTER<br>PKW<br>VITO                 | OM 642<br>W 639<br>W 906                                       |
| FCS-BS-234 | 004 154 16 06 |  | Alternator Regulator | SPRINTER<br>PKW<br>VITO                 | OM 642<br>W 906                                                |
| FCS-BS-235 | 014 154 27 02 |  | Generator            | SPRINTER 209<br>315<br>515 CDI<br>VIANO | OM 646                                                         |
| FCS-BS-236 | 646 154 08 02 |  | Alternator           |                                         | VALEO, 12V, 220AMP                                             |

|            |                                                                                   |                                                                                     |                             |                                                   |                            |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------|----------------------------|
| FCS-BS-237 | 013 154 11 02                                                                     |     | Alternator                  |                                                   |                            |
| FCS-BS-238 | 012 154 46 02                                                                     |    | Alternator                  |                                                   |                            |
| FCS-BS-239 | 012 154 24 02<br>A013154150280<br>010 154 59 02<br>010 154 96 02<br>011 154 09 02 |    | Alternator                  |                                                   |                            |
| FCS-BS-240 | 013 054 17 02                                                                     |    | Alternator                  |                                                   |                            |
| FCS-BS-241 | 642 154 08 02                                                                     |    | Alternator - 220 amp -      |                                                   |                            |
| FCS-BS-242 | 642 154 04 02                                                                     |    | Alternator - 180 amp -      |                                                   |                            |
| FCS-BS-243 | 604 150 01 60                                                                     |   | Freewheel Clutch,Alternator | VITO 108<br>110                                   | OM 611<br>OM 612<br>W 638  |
| FCS-BS-244 | 611 155 00 15                                                                     |  | Pulley To Alternator        | VITO 108<br>110<br>112 CDI                        | OM 611                     |
| FCS-BS-245 | 611 155 02 15                                                                     |  | Pulley To Alternator        | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI | OM 611                     |
| FCS-BS-246 | 611 155 05 15<br>611 155 07 15                                                    |  | Pulley,Alternator           | SPRINTER<br>VITO                                  |                            |
| FCS-BS-247 | 611 155 07 15                                                                     |  | Freewheel Clutch,Alternator | SPRINTER 209<br>315<br>515 CDI<br>VITO<br>VIANO   | OM 611<br>OM 612<br>OM 647 |
| FCS-BS-248 | 642 150 06 60                                                                     |  | Freewheel Clutch,alternator | SPRINTER 209<br>315<br>515 CDI<br>VITO<br>VIANO   | OM 642                     |
| FCS-BS-249 | 646 150 02 60                                                                     |  | Pulley,alternator           | VANEO                                             |                            |
| FCS-BS-250 | 646 155 01 15                                                                     |  | Pulley,Alternator           | VITO<br>VIANO                                     |                            |

|            |                                |                                                                                     |                                                                     |                                                      |                                                                        |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------|------------------------------------------------------|------------------------------------------------------------------------|
| FCS-BS-251 | 000 158 75 03                  |     | Coil, Ignition                                                      | SPRINTER 214<br>314;414<br>VITO 113<br>114;230       | M 111                                                                  |
| FCS-BS-252 | 000 158 78 03                  |    | Coil, Ignition                                                      | VIANO 639<br>VITO                                    | M 112                                                                  |
| FCS-BS-253 | 001 159 49 01<br>001 159 48 01 |    | Glow Plug                                                           | SPRINTER<br>VITO                                     | OM 611;OM 612<br>OM 646;OM 647<br>W 638;W 901<br>W 902;W 903<br>W 904  |
| FCS-BS-254 | 001 159 50 01                  |    | Glow Plugs (2007 - 2009) -                                          |                                                      |                                                                        |
| FCS-BS-255 | 001 159 66 01                  |    | Glow Plugs - (2010 - 2012) -<br>(w/ 7 volt plugs, check by<br>vin#) |                                                      |                                                                        |
| FCS-BS-256 | 642 153 19 79                  |    | Glow Plug Module - (2007 -<br>2014)                                 |                                                      |                                                                        |
| FCS-BS-257 | 203 540 02 53                  |   | Plug Housing                                                        | PKW<br>VAN                                           | W 639<br>W 903-906                                                     |
| FCS-BS-258 | 601 180 00 65                  |  | Oil Cooler                                                          | SPRINTER 208<br>210;312;412<br>VITO 108<br>110       | OM 601;OM 602<br>OM 603;OM 611<br>OM 646<br>W 901;W 904<br>W 638;W 639 |
| FCS-BS-259 | 611 188 03 01<br>646 188 03 01 |  | Oil Cooler                                                          | SPRINTER 208<br>213 CDI<br>313 CDI<br>413 CDI        | OM 611;OM 612<br>OM 646<br>W 901;W 902<br>W 903;W 904                  |
| FCS-BS-260 | 651 180 20 01                  |  | Oil Pump                                                            | SPRINTER 311<br>313<br>315<br>515<br>518             | OM 651                                                                 |
| FCS-BS-261 | 651 180 06 10<br>651 180 08 10 |  | Oil Cooler, Engine Oil                                              | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI | OM 651                                                                 |
| FCS-BS-262 | 642 180 01 65                  |  | Oil Cooler                                                          |                                                      |                                                                        |
| FCS-BS-263 | 642 200 04 20                  |  | Engine Cooling Fan Clutch<br>Bearing Bracket                        |                                                      |                                                                        |
| FCS-BS-264 | 642 180 01 65                  |  | Engine Oil Cooler                                                   |                                                      |                                                                        |

|            |                                                 |                                                                                     |                                            |                                                       |                                                                      |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------|-------------------------------------------------------|----------------------------------------------------------------------|
| FCS-BS-265 | 642 188 01 80                                   |     | Engine Oil Cooler Seals -<br>*2pervehicle* |                                                       |                                                                      |
| FCS-BS-266 | 611 184 02 80                                   |    | Seal,Oil Cooler                            | SPRINTER 208<br>213 CDI<br>313 CDI<br>413 CDI         | OM 611<br>OM 612<br>OM 613<br>OM 646<br>OM 647                       |
| FCS-BS-267 | 651 184 04 80                                   |    | Seal,Oil Cooler                            | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI  | OM 651                                                               |
| FCS-BS-268 | 651 184 05 80                                   |    | Seal,Oil Cooler                            | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI  | OM 651                                                               |
| FCS-BS-269 | 651 184 07 80                                   |    | Seal,Oil Cooler                            | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI  | OM 651                                                               |
| FCS-BS-270 | 651 184 08 80                                   |    | Seal,Oil Cooler                            | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI  | OM 651                                                               |
| FCS-BS-271 | 651 184 09 80                                   |   | Seal,Oil Cooler                            | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI  | OM 651                                                               |
| FCS-BS-272 | 015 997 48 82                                   |  | Hose,Transmission Oil Cooler               |                                                       | OM 651                                                               |
| FCS-BS-273 | 019 997 83 82                                   |  | Hose,Transmission Oil Cooler               |                                                       | W 901<br>W 902<br>W 903<br>W 904<br>W 905                            |
| FCS-BS-274 | 601 180 01 09                                   |  | Oil Filter                                 | MB210<br>310<br>410                                   | OM 602.911<br>OM 602.940<br>OM 602.942<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-275 | 606 180 00 09                                   |  | Oil Filter                                 | SPRINTER 208<br>210;312<br>412<br>VITO 108<br>110     | OM 602.980<br>OM 602.981<br>OM 602.986<br>OM 602.989<br>W 901;W 902  |
| FCS-BS-276 | 611 180 00 09                                   |  | Oil Filter                                 | SPRINTER 208<br>213 CDI<br>312;313 CDI<br>412;413 CDI | OM 646;OM 647<br>OM 611;OM 612<br>W 901;W 902<br>W 903;W 904         |
| FCS-BS-277 | 613 180 00 09                                   |  | Oil Filter                                 |                                                       | OM 612<br>OM 613<br>OM 648                                           |
| FCS-BS-278 | 651 180 01 09<br>651 180 00 09<br>651 180 03 09 |  | Oil Filter                                 | SPRINTER 209<br>315<br>515 CDI<br>VITO<br>VIANO       | W 639<br>W 906                                                       |

|            |               |                                                                                     |                           |                                                      |                                                                                |
|------------|---------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------------|--------------------------------------------------------------------------------|
| FCS-BS-279 | 019 997 04 45 |     | Seal,Oil Filter Housing   | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI | OM 651                                                                         |
| FCS-BS-280 | 019 997 05 45 |    | Seal,Oil Filter Housing   | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI | OM 651                                                                         |
| FCS-BS-281 | 601 180 00 09 |    | Oil Filter                |                                                      |                                                                                |
| FCS-BS-282 | 642 180 00 09 |    | Oil Filter                |                                                      |                                                                                |
| FCS-BS-283 | 661 180 33 09 |    | Oil Filter                |                                                      |                                                                                |
| FCS-BS-284 | 611 180 00 20 |    | Oil Pipe,Charger          |                                                      | OM 611                                                                         |
| FCS-BS-285 | 611 180 01 20 |   | Oil Pipe,Charger          |                                                      | OM 611                                                                         |
| FCS-BS-286 | 611 180 06 20 |  | Oil Pipe,Charger          |                                                      | OM 611                                                                         |
| FCS-BS-287 | 611 180 07 20 |  | Oil Pipe,Charger          |                                                      | OM 611                                                                         |
| FCS-BS-288 | 646 180 01 20 |  | Oil Pipe,Charger          |                                                      | OM 646                                                                         |
| FCS-BS-289 | 646 180 06 20 |  | Oil Pipe,Charger          | SPRINTER 310<br>312<br>412                           | OM 646                                                                         |
| FCS-BS-290 | 603 181 01 12 |  | Gear,Oil Pump             | SPRINTER 212<br>312<br>412<br>VITO 108<br>110        |                                                                                |
| FCS-BS-291 | 111 180 00 71 |  | Rail,Oil Pump Drive Chain |                                                      | M 111<br>OM 611<br>OM612<br>OM646<br>OM647                                     |
| FCS-BS-292 | 601 181 01 59 |  | Oil Pump Chain,Tightener  | SPRINTER 208<br>210;312<br>412<br>VITO 108<br>110    | OM 601;OM 602;<br>OM 603;OM 604;<br>OM 605;W 901<br>W 902;W 903;W 904<br>W 638 |



|            |                                |                                                                                     |                                       |                                                           |                                                                   |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|-----------------------------------------------------------|-------------------------------------------------------------------|
| FCS-BS-293 | 601 180 14 01                  |     | Oil Pump                              | SPRINTER 208<br>213 CDI<br>313 CDI<br>413 CDI             | OM 611                                                            |
| FCS-BS-294 | 602 180 30 01                  |    | Oil Pump                              | SPRINTER 212<br>312<br>412                                | OM 602                                                            |
| FCS-BS-295 | 611 180 00 01                  |    | Oil Pump                              | SPRINTER 208<br>308<br>408<br>VITO 108<br>110             | OM 611                                                            |
| FCS-BS-296 | 611 180 01 01                  |    | Oil Pump                              | SPRINTER 208<br>308<br>408<br>VITO 108<br>110             | OM 601                                                            |
| FCS-BS-297 | 642 180 21 01                  |    | Oil Pump                              |                                                           | OM 642                                                            |
| FCS-BS-298 | 651 180 26 01                  |    | Oil Pump                              | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI      | OM 651                                                            |
| FCS-BS-299 | 209 553 02 01                  |   | Oil Pump<br>manual Transmission       | SPRINTER 901-904                                          | W 901<br>W 902<br>W 903<br>W 904                                  |
| FCS-BS-300 | 651 180 02 15<br>651 180 03 15 |  | Spring<br>Oil Pressure Valve Oil Pump | SPRINTER 209<br>315<br>319 CDI<br>515 CDI<br>519 CDI      | OM 651                                                            |
| FCS-BS-301 | 000 200 07 01                  |  | Water Pump                            | VITO 638<br>V 280                                         | M 104<br>W 638                                                    |
| FCS-BS-302 | 111 200 41 01 111<br>200 22 01 |  | Water Pump                            | SPRINTER 214<br>314<br>414                                | M 111<br>W 901<br>W 902<br>W 903<br>W 904                         |
| FCS-BS-303 | 272 200 04 01                  |  | Water Pump                            | SPRINTER 224<br>324<br>524<br>(906.613)                   | M 272<br>W 639<br>W 906                                           |
| FCS-BS-304 | 602 200 02 20                  |  | Water Pump                            | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412  | W 901;W 902;<br>W 903;W 904<br>OM 601.943<br>OM 602.980<br>OM 603 |
| FCS-BS-305 | 904 200 00 04                  |  | Water Pump Repair Kit                 | SPRINTER 208<br>212;310<br>312;410<br>412;VITO 108<br>110 | OM 601;OM 602;<br>W 601;W 602;<br>W 611;W 638<br>W 667;W 901      |
| FCS-BS-306 | 611 200 10 01                  |  | Water Pump                            | VITO 108 CDI<br>110 CDI<br>112 CDI                        | OM 611.980<br>W 638                                               |



|            |                                                 |                                                                                     |                           |                                                                                     |                                                                      |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| FCS-BS-307 | 611 200 11 01                                   |     | Water Pump                | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                   | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904                          |
| FCS-BS-308 | 642 180 14 10<br>642 180 00 10                  |    | Oil Filter Housing        |                                                                                     | OM 642                                                               |
| FCS-BS-309 | 642 184 00 80                                   |    | Oil Filter Housing Gasket |                                                                                     |                                                                      |
| FCS-BS-310 | 001 835 13 64                                   |    | Auxiliary Water Pump      |                                                                                     |                                                                      |
| FCS-BS-311 | 646 200 10 01                                   |    | Water Pump                | SPRINTER 209 CDI<br>213 CDI;309 CDI<br>315 CDI;515 CDI<br>VIANO CDI<br>VITO 109 CDI | OM 646<br>W 639<br>W 906                                             |
| FCS-BS-312 | 642 200 07 01                                   |    | Water Pump                |                                                                                     |                                                                      |
| FCS-BS-313 | 647 200 01 01                                   |   | Water Pump                | SPRINTER 216 CDI<br>316 CDI<br>416 CDI                                              | OM 647<br>W 903<br>W 904                                             |
| FCS-BS-314 | 651 200 23 01                                   |  | Water Pump                | SPRINTER 209<br>315<br>515 CDI                                                      | OM 651                                                               |
| FCS-BS-315 | 651 200 33 01<br>651 200 39 01<br>651 200 41 01 |  | Water Pump                | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                   | OM 651                                                               |
| FCS-BS-316 | 000 200 37 22<br>000 200 37 02                  |  | Fan Clutch (Visco)        | SPRINTER 208<br>214;308<br>314;408<br>414                                           | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904                          |
| FCS-BS-317 | 000 200 38 22                                   |  | Fan Clutch (Visco)        | SPRINTER 210<br>212;310<br>312;410<br>412                                           | OM 602.980<br>OM 602.984<br>OM 602.985<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-318 | 000 200 39 22                                   |  | Fan Clutch (Visco)        | SPRINTER 208 CDI<br>213 CDI<br>214 CDI<br>313 CDI<br>413 CDI                        | M 112<br>M 161                                                       |
| FCS-BS-319 | 000 200 51 22 602<br>200 01 22                  |  | Fan Clutch (Visco)        | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                            | OM 601;<br>OM 602.980<br>OM 602.986<br>W 901;W 902<br>W 903;W 904    |
| FCS-BS-320 | 000 200 58 22<br>000 200 49 23<br>051 036 23 AA |  | Fan Clutch (Visco)        | SPRINTER 208<br>213 CDI;312,<br>313 CDI;412<br>413 CDI                              | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904                          |

|            |                                                 |                                                                                     |                             |                                                                    |                                                        |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------|--------------------------------------------------------|
| FCS-BS-321 | 904 200 11 22                                   |     | Fan Clutch                  |                                                                    |                                                        |
| FCS-BS-322 | 000 200 60 23<br>000 200 63 23                  |    | Fan Clutch (Visco)          | 109 CDI<br>111 CDI<br>115 CDI                                      | M 112<br>OM 646<br>W 639                               |
| FCS-BS-323 | 000 200 82 23                                   |    | Fan Clutch (Visco)          | SPRINTER 208 CDI<br>213 CDI<br>214 CDI<br>313 CDI<br>413 CDI       | OM 612                                                 |
| FCS-BS-324 | 000 200 73 23                                   |    | Fan Blade                   | SPRINTER 209 CDI<br>213 CDI;309 CDI<br>315 CDI;515 CDI<br>VITO 639 | OM 642                                                 |
| FCS-BS-325 | 000 200 81 23                                   |    | Fan Blade                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;515 CDI             | OM 646<br>OM 647<br>W 906                              |
| FCS-BS-326 | 000 200 97 23<br>000 200 96 23<br>000 200 90 23 |    | Fan Blade                   | SPRINTER 208 CDI<br>216 CDI<br>316 CDI<br>416 CDI                  | OM 611<br>OM 612                                       |
| FCS-BS-327 | 000 200 99 23                                   |   | Fan Blade                   | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI       | OM 642                                                 |
| FCS-BS-328 | 003 205 02 06                                   |  | Fan Blade                   | SPRINTER 208<br>308                                                | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904            |
| FCS-BS-329 |                                                 |  | Fan Blade                   | MB100                                                              |                                                        |
| FCS-BS-330 | 906 500 04 93<br>680 136 66 AA                  |  | Radiator Fan -(2pervehicle) |                                                                    |                                                        |
| FCS-BS-331 | 000 200 72 23<br>680 124 13 AA                  |  | Fan Blade                   |                                                                    |                                                        |
| FCS-BS-332 | 003 205 03 06                                   |  | Fan Blade                   | SPRINTER 212<br>310<br>312<br>410<br>412                           | OM 602                                                 |
| FCS-BS-333 | 003 205 13 06                                   |  | Fan Blade                   | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412           | OM 602.980<br>OM 602.986<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-334 | 103 200 04 23                                   |  | Fan Blade                   | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                  | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904            |

|            |                                                 |                                                                                     |                                           |                                                                                      |                                                                     |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| FCS-BS-335 | 602 200 06 23                                   |     | Fan Blade                                 |                                                                                      | OM 602                                                              |
| FCS-BS-336 | 642 200 02 15                                   |    | Thermostat<br>- (Unheated) VIN Specific - |                                                                                      |                                                                     |
| FCS-BS-337 | 642 200 08 15                                   |    | Thermostat<br>- (Heated) VIN Specific -   |                                                                                      |                                                                     |
| FCS-BS-338 | 111 200 09 15                                   |    | Thermostat, Coolant                       | SPRINTER 214<br>314<br>414                                                           | M 112                                                               |
| FCS-BS-339 | 611 200 02 15                                   |    | Thermostat                                | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>318 CDI;413 CDI<br>418 CDI;518 CDI<br>519 CDI | OM 611.980<br>OM 611.981<br>OM 611.987<br>OM 612.981<br>W 901;W 902 |
| FCS-BS-340 | 611 200 07 15                                   |    | Thermostat.Housing                        | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>413 CDI;VITO 108<br>110;112                   | OM 611<br>OM 612<br>OM 646<br>OM 647                                |
| FCS-BS-341 | 606 203 05 75<br>004 203 09 75<br>601 200 00 15 |   | Thermostat                                | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                             | OM 601<br>OM 602                                                    |
| FCS-BS-342 | 646 200 12 15                                   |  | Thermostat                                | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                    | OM 612;OM 646<br>W 901;W 902<br>W 903;W 904<br>W 906;W 639          |
| FCS-BS-343 | 651 200 06 15                                   |  | Thermostat                                | SPRINTER 209<br>315<br>515<br>518 CDI                                                | OM 651                                                              |
| FCS-BS-344 | 103 200 05 70                                   |  | Tensioner Pulley,v-ribbed Belt            |                                                                                      | OM 602                                                              |
| FCS-BS-345 | 111 200 00 70                                   |  | Tensioner Pulley,v-ribbed Belt            | SPRINTER 214<br>314;414<br>VITO 112<br>113;114<br>V230                               | M 111                                                               |
| FCS-BS-346 | 112 814 355 94                                  |  | Tension Pulley                            |                                                                                      |                                                                     |
| FCS-BS-347 | 271 206 00 19                                   |  | Deflection/guide Pulley<br>V-ribbed Belt  | SPRINTER 224<br>324<br>524<br>(906.613)<br>VITO 126                                  | M 271                                                               |
| FCS-BS-348 | 271 206 02 19                                   |  | Deflection/guide Pulley<br>V-ribbed Belt  | SPRINTER 224<br>324<br>524<br>(906.613)<br>VITO 126                                  | M 271                                                               |

|            |                                 |                                                                                     |                                          |                                                                                     |                                                              |
|------------|---------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------|
| FCS-BS-349 | 272 202 04 19                   |     | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 224<br>324;524<br>(906.613)<br>VITO 126                                    | M 272                                                        |
| FCS-BS-350 | 601 200 07 70                   |    | Belt Tightener Pulley                    | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                            | OM 601<br>OM 602<br>W 901;W 902<br>W 903;W 904               |
| FCS-BS-351 | 601 200 09 70                   |    | Belt Tightener Pulley                    | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                            | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904                  |
| FCS-BS-352 | 601 200 10 70                   |    | Belt Tightener Pulley                    | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                            | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904                  |
| FCS-BS-353 | 000 202 00 19<br>A611 155 03 15 |    | Belt Tightener Pulley                    | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                   | OM 611;OM 612<br>OM 646;OM 647<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-354 | 000 202 04 19                   |    | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 612<br>OM 647                                             |
| FCS-BS-355 | 604 150 03 60                   |   | Pulley To Alternator                     | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412                            | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904                  |
| FCS-BS-356 | 611 234 02 93                   |  | Belt Tightener Pulley                    | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                   | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904                  |
| FCS-BS-357 | 642 200 06 70                   |  | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 642                                                       |
| FCS-BS-358 | 642 200 10 70                   |  | Belt Tightener, v-ribbed Belt            | SPRINTER 209 CDI<br>213 CDI;309 CDI<br>315 CDI;515 CDI<br>VIANO CDI<br>VITO 109 CDI | OM 642                                                       |
| FCS-BS-359 | 651 200 02 70                   |  | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 651                                                       |
| FCS-BS-360 | 651 200 06 70                   |  | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 651                                                       |
| FCS-BS-361 | 651 200 07 70                   |  | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 651                                                       |
| FCS-BS-362 | 651 200 09 70                   |  | Deflection/guide Pulley<br>V-ribbed Belt | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                        | OM 651                                                       |

|            |                                                                                   |                                                                                     |                                        |                                                                                                     |                                                              |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------|
| FCS-BS-363 | 111 200 07 70                                                                     |     | Belt Tightener,V-ribbed Belt           | SPRINTER 214<br>314;414<br>VITO 112<br>113;114<br>V230                                              | M 111                                                        |
| FCS-BS-364 | 271 200 04 70                                                                     |    | Belt Tightener,V-ribbed Belt           | SPRINTER 224<br>324<br>524<br>(906.613)<br>VITO 126                                                 | M 271                                                        |
| FCS-BS-365 | 272 200 02 70                                                                     |    | Water Pump                             | SPRINTER 224<br>324<br>524<br>(906.613)<br>VITO 126                                                 | M 272                                                        |
| FCS-BS-366 | 601 981 00 27                                                                     |    | Bearing,tensioner Pulley Lever         | MB 207<br>210<br>310<br>410                                                                         | OM 601<br>OM 602<br>OM 603<br>W 901;W 902<br>W 903;W 904     |
| FCS-BS-367 | 6062000073 S1<br>6012001773 S<br>6012001773                                       |    | Tensioner (With Axle)                  | MB207<br>210<br>310<br>410                                                                          | OM 601<br>OM 602<br>OM 603<br>W 901;W 902<br>W 903;W 904     |
| FCS-BS-368 | 611 200 05 70<br>646 200 02 70<br>646 200 03 70<br>611 200 04 70<br>611 200 02 70 |    | Tensioner Pulley Ribbed V Belt         | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>318 CDI;413 CDI<br>518 CDI;519 CDI                           | OM 611<br>OM 612<br>OM 646<br>W 901;W 902<br>W 903;W 904     |
| FCS-BS-369 | 6112000570-1                                                                      |   | Belt Tightener                         | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                                                   | OM 611;OM 612<br>OM 646;OM 647<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-370 | 606 200 00 73                                                                     |  | Lever Tightener Pulley                 | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410                                                | OM 602<br>W 901;W 902<br>W 903;W 904                         |
| FCS-BS-371 | 606 202 01 20                                                                     |  | Pivot Pin To Tensioner Pulley<br>Lever | SPRINTER 208<br>212;310<br>312;410<br>412                                                           | OM 602<br>W 901<br>W 902<br>W 903<br>W 904                   |
| FCS-BS-372 | 642 200 13 70<br>642 200 00 70                                                    |  | Belt Tightener,v-ribbed Belt           | SPRINTER 209 CDI<br>213 CDI;309 CDI<br>315 CDI;515 CDI<br>VIANO CDI;VITO 109 CDI<br>111 CDI;115 CDI | OM 642                                                       |
| FCS-BS-373 | 642 200 15 70<br>642 200 16 70<br>642 200 26 70 642<br>200 07 70                  |  | Belt Tightener,v-ribbed Belt           | SPRINTER 209 CDI<br>218 CDI<br>309 CDI<br>318 CDI<br>518 CDI                                        | OM 642                                                       |
| FCS-BS-374 | 646 200 00 70<br>611 200 06 70                                                    |  | Belt Tightener,v-ribbed Belt           |                                                                                                     | OM 647                                                       |
| FCS-BS-375 | 6462000070-1                                                                      |  | Belt Tightener,v-ribbed Belt           |                                                                                                     | OM 647                                                       |
| FCS-BS-376 | 651 200 04 70<br>651 200 18 70                                                    |  | Belt Tightener,v-ribbed Belt           | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                        | OM 651                                                       |

|            |                                                                                   |                                                                                     |                                     |                                                              |                                                                          |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------------------|--------------------------------------------------------------------------|
| FCS-BS-377 | 651 200 12 70                                                                     |     | Belt Tightener,v-ribbed Belt        | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI | OM 651                                                                   |
| FCS-BS-378 | 111 200 04 14                                                                     |    | Vibration Absorber<br>V-ribbed Belt | SPRINTER 214<br>314<br>414                                   | M 111                                                                    |
| FCS-BS-379 | 272 200 01 14                                                                     |    | Vibration Absorber<br>V-ribbed Belt | SPRINTER 224<br>324<br>524<br>(906.613)<br>VITO 126          | M 272                                                                    |
| FCS-BS-380 | 604 200 02 14<br>603 200 06 14<br>FEBI 08779                                      |    | Vibration Damper To Belt<br>Drive   | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412     | OM 601;OM 602;<br>OM 603;OM 604;<br>OM 605;W 901<br>W 902;W 903<br>W 904 |
| FCS-BS-381 | 606 993 05 10                                                                     |    | Spring To Belt Drive                | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412     | OM 601;OM 602;<br>OM 603;OM 604;<br>OM 605;W 901<br>W 902;W 903<br>W 904 |
| FCS-BS-382 | 000 230 31 65                                                                     |   | Vacuum Pump                         | SPRINTER 208<br>308<br>408<br>VITO 108<br>110                | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904<br>W 638                     |
| FCS-BS-383 |                                                                                   |  | V Ribbed Belt                       |                                                              |                                                                          |
| FCS-BS-384 |                                                                                   |  | V Ribbed Belt                       |                                                              |                                                                          |
| FCS-BS-385 | 001 993 75 96<br>048 915 87 AB<br>048 915 87 AA<br>051 759 61 AA                  |  | Main Belt                           |                                                              | OM 642                                                                   |
| FCS-BS-386 | 001 993 46 96<br>681 610 95 AA<br>680 124 26 AA<br>680 124 27 AA                  |  | Main Belt                           |                                                              | OM642                                                                    |
| FCS-BS-387 | 001 993 39 96<br>680 124 37 AA<br>680 124 38 AA                                   |  | Secondary V- Belt                   |                                                              |                                                                          |
| FCS-BS-388 | 014 997 06 92<br>051 272 58 AA<br>611 997 30 92<br>611 997 22 92<br>078 903 13 7P |  | Serpentine Ribbed Belt              |                                                              | OM647                                                                    |
| FCS-BS-389 | A0149970492<br>A014997492<br>A0129975092<br>0009933696                            |  | Multi-Rib Belt                      |                                                              | OM612                                                                    |



|            |                                                                                   |                                                                                     |                        |                                                                   |                                                                      |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------|----------------------------------------------------------------------|
| FCS-BS-390 | 002 993 28 96<br>651 200 02 70<br>651 200 06 70<br>651 200 04 70<br>651 200 18 70 |     | Serpentine Ribbed Belt |                                                                   | OM651                                                                |
| FCS-BS-391 | 000 230 36 65                                                                     |    | Vacuum Pump            | SPRINTER 212<br>312<br>412<br>VITO<br>VARIO                       | OM 602.980<br>OM 602.982<br>OM 602.989<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-392 | 000 230 43 65                                                                     |    | Vacuum Pump            | SPRINTER 212<br>312<br>412                                        | OM 602.980<br>OM 602.982<br>OM 602.983<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-393 | 611 230 00 65                                                                     |    | Vacuum Pump            | SPRINTER 208<br>211;311<br>313;316<br>413;416 CDI                 | OM 611<br>OM 612<br>OM 613                                           |
| FCS-BS-394 | 611 230 02 65                                                                     |    | Vacuum Pump            | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>413 CDI;416 CDI<br>616 CDI | OM 611;W 901<br>W 902;W 903<br>W 904;W 905                           |
| FCS-BS-395 | 628 230 00 65                                                                     |    | Vacuum Pump            | SPRINTER 315 CDI<br>515 CDI<br>VITO                               | OM 628<br>OM 629<br>OM 646                                           |
| FCS-BS-396 | 646 230 01 65                                                                     |  | Vacuum Pump            | SPRINTER 315 CDI<br>515 CDI<br>VITO                               | OM 646<br>OM 647                                                     |
| FCS-BS-397 | 651 230 01 65                                                                     |  | Vacuum Pump            | SPRINTER 315 CDI<br>515 CDI<br>VITO                               | OM 651                                                               |
| FCS-BS-398 | 651 230 02 65                                                                     |  | Vacuum Pump            | SPRINTER 315 CDI<br>515 CDI<br>VITO                               | OM 651                                                               |
| FCS-BS-399 | 638 241 14 13                                                                     |  | Engine Mounting        | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                  | W 638                                                                |
| FCS-BS-400 | 638 242 03 13                                                                     |  | Engine Mounting        | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                  | W 638                                                                |
| FCS-BS-401 | 639 241 04 13                                                                     |  | Engine Mounting        | VIANO 111<br>VITO<br>113<br>115                                   | W 636<br>W 639                                                       |
| FCS-BS-402 | 639 241 05 13                                                                     |  | Engine Mounting        | VIANO 111<br>VITO<br>113<br>115                                   | W 636<br>W 639                                                       |
| FCS-BS-403 | 901 241 24 13<br>901 241 25 13                                                    |  | Engine Mounting        | SPRINTER 208<br>213 CDI;312<br>313 CDI;412<br>413 CDI             | W 901<br>W 902<br>W 903<br>W 904                                     |

|            |                                                 |                                                                                     |                                 |                                                        |                                                    |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|--------------------------------------------------------|----------------------------------------------------|
| FCS-BS-404 | 906 241 10 13                                   |     | Engine Mounting                 | SPRINTER 309<br>311<br>315<br>318<br>515               | W 906                                              |
| FCS-BS-405 | 906 241 13 13                                   |    | Engine Mounting                 | SPRINTER 209<br>315<br>515<br>518 CDI                  | W 906                                              |
| FCS-BS-406 | 906 241 15 13                                   |    | Engine Mounting                 | SPRINTER 209<br>315<br>515<br>518 CDI                  | W 906                                              |
| FCS-BS-407 | 906 241 16 13<br>906 241 12 13<br>906 241 11 13 |    | Engine Mounting                 | SPRINTER 209<br>315<br>515<br>518 CDI                  | W 906                                              |
| FCS-BS-408 | 212 240 04 18                                   |    | Gearbox Mounting                | PKW                                                    |                                                    |
| FCS-BS-409 | 638 242 00 13                                   |    | Gearbox Mounting                | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI       | W 638                                              |
| FCS-BS-410 | 638 242 01 13                                   |   | Gearbox Mounting                | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI       | W 638                                              |
| FCS-BS-411 | 668 240 02 17                                   |  | Mounting                        |                                                        |                                                    |
| FCS-BS-412 | 668 242 00 13                                   |  | Gearbox Mounting                | 609<br>709<br>711<br>814                               | W 371;W 390<br>W 668;W 669<br>W 670;W 688<br>W 692 |
| FCS-BS-413 | 668 240 02 17                                   |  | Mounting                        |                                                        |                                                    |
| FCS-BS-414 | 638 266 16 85                                   |  | Mounting,Manual<br>Transmission | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI       | W 638                                              |
| FCS-BS-415 | 639 242 00 13                                   |  | Gearbox Mounting                | VITO<br>VIANO                                          | W 639                                              |
| FCS-BS-416 | 639 242 02 13                                   |  | Gearbox Mounting                | VIANO 111<br>VITO<br>113<br>115                        | W 639<br>W 906                                     |
| FCS-BS-417 | 901 242 14 13                                   |  | Transmission Mounting           | SPRINTER 208<br>213 CDI;312,<br>313 CDI;412<br>413 CDI | W 901<br>W 902<br>W 903<br>W 904                   |

|            |                                |                                                                                     |                        |                                                               |                                               |
|------------|--------------------------------|-------------------------------------------------------------------------------------|------------------------|---------------------------------------------------------------|-----------------------------------------------|
| FCS-BS-418 | 906 242 00 13                  |     | Gearbox Mounting       | SPRINTER 209<br>315<br>515<br>518 CDI                         | W 906                                         |
| FCS-BS-419 | 611 030 20 05                  |    | Clutch Kit             | SPRINTER 208<br>311<br>313<br>413CDI                          | OM 611                                        |
| FCS-BS-420 | 019 250 56 01                  |    | Clutch Kit             | SPRINTER 208<br>308<br>408                                    | OM 601<br>W 638;W 901<br>W 902;W 903<br>W 904 |
| FCS-BS-421 | 019 250 59 01                  |    | Clutch Kit             | SPRINTER 212<br>312<br>412                                    | OM 602<br>W 901<br>W 902<br>W 903<br>W 904    |
| FCS-BS-422 | 023 250 02 01                  |    | Clutch Kit             | SPRINTER 209<br>315<br>515<br>518 CDI                         | W 906                                         |
| FCS-BS-423 | 023 250 82 01                  |    | Clutch Kit             | SPRINTER 209<br>315<br>515<br>518 CDI                         | W 906                                         |
| FCS-BS-424 | 025 250 70 01                  |   | Clutch Kit             | SPRINTER 209<br>315<br>515<br>518 CDI                         |                                               |
| FCS-BS-425 | 015 250 12 03                  |  | Clutch Kit             | VITO 108                                                      | W 638                                         |
| FCS-BS-426 | 015 250 16 03<br>015 250 17 03 |  | Clutch Kit             | SPRINTER 208<br>308<br>408                                    | OM 601;W 638<br>W 901;W 902<br>W 903;W 904    |
| FCS-BS-427 | 015 250 19 03                  |  | Clutch Kit             | SPRINTER 210<br>212;310<br>312;410<br>412                     | OM 602<br>W 901<br>W 902<br>W 903<br>W 904    |
| FCS-BS-428 | 000 252 52 05                  |  | Clutch Kit             | SPRINTER 208<br>213 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904   |
| FCS-BS-429 | 001 250 99 15                  |  | Clutch Release Bearing |                                                               |                                               |
| FCS-BS-430 | 000 254 04 20                  |  | Release Bearing        |                                                               |                                               |
| FCS-BS-431 | 001 250 08 15                  |  | Release Bearing        |                                                               |                                               |

|            |                                                           |                                                                                     |                                         |                                                               |                                             |
|------------|-----------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------|---------------------------------------------------------------|---------------------------------------------|
| FCS-BS-432 | 315 124 80 31<br>001 250 25 15                            |     | Release Bearing                         |                                                               |                                             |
| FCS-BS-433 | 000 254 18 08<br>000 254 13 08<br>000 254 14 08<br>CSC027 |    | Release Bearing                         |                                                               |                                             |
| FCS-BS-434 | 000 254 16 08<br>000 254 25 08                            |    | Clutch Release Bearing                  | SPRINTER 208<br>213 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-435 | 000 254 24 08                                             |    | Clutch Release Bearing                  | VIANO 111<br>VITO<br>113<br>115                               | W 639                                       |
| FCS-BS-436 | 000 254 28 08                                             |    | Clutch Release Bearing                  | SPRINTER 208<br>213 CDI<br>313 CDI<br>316 CDI,<br>413 CDI     | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-437 | 001 250 72 15                                             |    | Clutch Release Bearing                  | SPRINTER 208<br>210;212<br>308;310<br>312;408<br>410;412      | OM 601;OM 602<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-438 | 002 250 18 15                                             |   | Clutch Release Bearing                  | VANEO                                                         |                                             |
| FCS-BS-439 | 901 260 13 38                                             |  | Cable,Manual Transmission               | SPRINTER 208<br>213<br>313<br>411<br>413 CDI                  | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-440 | 901 260 15 38                                             |  | Clutch Cable                            | SPRINTER 208<br>213<br>313<br>411<br>413 CDI                  | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-441 | 906 260 14 51                                             |  | Cable,Manual Transmission               | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI  | W 906                                       |
| FCS-BS-442 | 906 260 15 51                                             |  | Cable,Manual Transmission               | SPRINTER 906                                                  | W 906                                       |
| FCS-BS-443 | 000 268 00 91                                             |  | Cable,Manual Transmission               | VITO 638                                                      | W 638                                       |
| FCS-BS-444 | 000 268 01 91                                             |  | Cable,Manual Transmission               | VITO 638                                                      | W 638                                       |
| FCS-BS-445 | 904 260 01 62                                             |  | Deflection Shaft<br>Gearshift Mechanism | SPRINTER 901-905                                              | W 901<br>W 902<br>W 903<br>W 904<br>W 905   |




|            |                                |                                                                                     |                                                |                                                  |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------|--------------------------------------------------|-------------------------------------------|
| FCS-BS-446 | 903 260 01 89                  |     | Selector-/Gear Lever                           | SPRINTER 901-905                                 | W 901<br>W 902<br>W 903<br>W 904<br>W 905 |
| FCS-BS-447 | 639 267 01 17                  |    | Vacuum Pump                                    | SPRINTER 906<br>VITO 639<br>VITO 639             | W 636<br>W 639<br>W 906                   |
| FCS-BS-448 | 639 267 03 17                  |    | Selector-/Gear Lever                           | SPRINTER 906<br>VITO 639<br>VITO 639             | W 636<br>W 639<br>W 906                   |
| FCS-BS-449 | 000 268 10 96<br>000 268 41 97 |    | Cap, Gear Lever Knob                           | SPRINTER 906                                     | W 900<br>W 906                            |
| FCS-BS-450 | 000 268 40 97                  |    | Gear Lever Gaiter                              | SPRINTER 901-905                                 | W 901<br>W 902<br>W 903<br>W 904<br>W 905 |
| FCS-BS-451 |                                |    | Gear Cover                                     | MB100                                            |                                           |
| FCS-BS-452 | 000 992 05 10                  |   | Bush, Gear Lever                               | PKW                                              | W 309<br>W 601<br>W 602<br>W 611          |
| FCS-BS-453 | 140 270 08 61                  |  | Control Unit<br>Automatic Transmission         | PKW                                              | W 639<br>W 903-906                        |
| FCS-BS-454 | 1402700861-1                   |  | Control Unit Set                               | PKW                                              | W 639<br>W 903-906                        |
| FCS-BS-455 | 140 270 06 83                  |  | Oil Dipstick                                   |                                                  | W 309<br>W 601<br>W 602<br>W 611<br>W 667 |
| FCS-BS-456 | 140 271 00 80                  |  | Seal<br>Automatic Transmission Oil<br>Pan      |                                                  | W 639<br>W 901-906                        |
| FCS-BS-457 | 1262770295-1                   |  | Hydraulic Filter Set<br>Automatic Transmission | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI | W 601<br>W 602<br>W 611<br>W 667          |
| FCS-BS-458 | 140 277 00 95                  |  | Hydraulic Filter<br>Automatic Transmission     |                                                  | W 639<br>W 901-906                        |
| FCS-BS-459 | 000 290 32 12                  |  | Clutch Master Cylinder                         |                                                  | W 901<br>W 902<br>W 903<br>W 904          |

|            |                                                       |                                                                                     |                                 |                                                                   |                                           |
|------------|-------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|-------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-460 | 639 290 00 12<br>639 290 01 12                        |     | Clutch Master Cylinder          | VITO<br>VIANO                                                     | W 639                                     |
| FCS-BS-461 | 002 295 21 07                                         |    | Clutch Master Cylinder          | SPRINTER 208<br>210;312<br>412;VITO 108<br>110                    | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-462 | 906 290 02 12<br>906 290 01 12                        |    | Clutch Master Cylinder          | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI<br>515 CDI      |                                           |
| FCS-BS-463 | A6382900316<br>6382920082<br>9012902016<br>9012901916 |    | Clutch Pedal                    | SPRINTER 208<br>312<br>412<br>313<br>413 CDI                      | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-464 | 638 300 01 04<br>901 300 03 04                        |    | Accelerator Pedal               | SPRINTER 901-904<br>VITO 638                                      | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-465 | 638 292 00 82<br>319 292 00 82                        |    | Pedal Lining, Brake Pedal       | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 638<br>W 901-905                        |
| FCS-BS-466 | 201 292 00 82                                         |  | Pedal Lining, Brake Pedal       | PKW                                                               | W 638<br>W 639<br>W 906                   |
| FCS-BS-467 | 123 291 00 82                                         |  | Pedal Lining, Brake Pedal       | SPRINTER 208<br>209;311<br>313;315<br>515 CDI<br>VIANO            | W 639<br>W 906                            |
| FCS-BS-468 | 201 291 02 82                                         |  | Clutch Pedal Rubber             |                                                                   |                                           |
| FCS-BS-469 | 124 427 03 82                                         |  | Foot Pedal Parking Brake Rubber |                                                                   |                                           |
| FCS-BS-470 | 906 686 06 07                                         |  | Rubber Pad                      |                                                                   |                                           |
| FCS-BS-471 |                                                       |  | Oil Cover                       |                                                                   |                                           |
| FCS-BS-472 | 906 885 02 63 RH<br>906 885 01 63 LH                  |  | Bumper Rear Bracket             |                                                                   |                                           |
| FCS-BS-473 |                                                       |  | Grille                          |                                                                   |                                           |



|            |                                                                                                                                      |                                                                                     |                                     |                                                                                    |                         |
|------------|--------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|------------------------------------------------------------------------------------|-------------------------|
| FCS-BS-474 | 901 300 04 04                                                                                                                        |     | Sensor,Accelerator Position         | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI;413 CDI<br>416 CDI           | W 638<br>W 901-905      |
| FCS-BS-475 | 011 542 86 17                                                                                                                        |    | Sensor,Accelerator Position         | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI;413 CDI<br>416 CDI           | W 901-904               |
| FCS-BS-476 | 251 320 26 04                                                                                                                        |    | Compressor<br>Compressed Air System | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI(01.06-.....)     | W 906                   |
| FCS-BS-477 | 638 320 09 13                                                                                                                        |    | Shock Absorber,Front                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-478 | 639 320 18 13                                                                                                                        |    | Shock Absorber,Front                | VITO<br>VIANO                                                                      | W 639                   |
| FCS-BS-479 | 639 320 36 13                                                                                                                        |    | Shock Absorber,Front                | VITO<br>VIANO                                                                      | W 639                   |
| FCS-BS-480 | 639 320 66 13                                                                                                                        |   | Shock Absorber,Front                | VITO<br>VIANO                                                                      | W 639                   |
| FCS-BS-481 | 901 320 15 30<br>SACHS 115906<br>2D0413029<br>2D0413029B<br>6903207130                                                               |  | Shock Absorber,Front                | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903 |
| FCS-BS-482 | 904 320 15 30<br>904 320 19 30                                                                                                       |  | Shock Absorber,Front                | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                   |
| FCS-BS-483 | 906 320 63 30<br>906 320 62 30<br>906 320 66 30<br>906 320 67 30<br>906 320 55 30                                                    |  | Shock Absorber,Front                | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                   |
| FCS-BS-484 | 906 320 75 30 906<br>320 74 30<br>906 320 73 30<br>906 320 72 30<br>906 320 71 30<br>906 320 70 30 906<br>320 64 30 906 320<br>57 30 |  | Shock Absorber,Front                | SPRINTER 509<br>515<br>518 CDI                                                     | W 906                   |
| FCS-BS-485 | 906 320 76 30                                                                                                                        |  | Shock Absorber,Front                | SPRINTER 509 CDI<br>511 CDI<br>515 CDI<br>518 CDI                                  | W 906                   |
| FCS-BS-486 | 638 326 07 00                                                                                                                        |  | Shock Absorber,Rear                 | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                   | W 638                   |

|            |                                                                                   |                                                                                     |                                                       |                                                                                    |                                  |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-487 | 638 326 11 00<br>638 326 12 00 901<br>223 0058                                    |     | Shock Absorber,Rear                                   | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                   |                                  |
| FCS-BS-488 | 639 326 03 00<br>639 326 21 00                                                    |    | Shock Absorber,Rear                                   | VITO<br>VIANO                                                                      | W 639                            |
| FCS-BS-489 | 639 326 09 00<br>639 326 24 00                                                    |    | Shock Absorber,Rear                                   | VITO<br>VIANO                                                                      | W 639                            |
| FCS-BS-490 | 901 320 06 31<br>901 320 02 31<br>901 320 04 31                                   |    | Shock Absorber,Rear                                   | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903          |
| FCS-BS-491 | 904 320 02 31                                                                     |    | Shock Absorber,Rear                                   | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-492 | 906 320 08 31                                                                     |    | Rear Shocks -<br>(2500, fits 2007-14)                 | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI;(01.06-.....)    | W 906                            |
| FCS-BS-493 | 906 326 13 00<br>906 326 00 00<br>906 326 06 00<br>906 326 08 00<br>906 326 14 00 |   | Rear Shocks -<br>(3500, fits 2007-14) check by<br>VIN | SPRINTER 509 CDI<br>511 CDI<br>515 CDI<br>(01.09-.....)                            | W 906                            |
| FCS-BS-494 | 901 320 06 01                                                                     |  | Spring Front                                          | SPRINTER 208<br>(01.95-05.06)<br>(02.95-05.06)                                     | W 901<br>W 902                   |
| FCS-BS-495 | 903 320 00 01                                                                     |  | Spring Front 2 Leaf                                   | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-496 | 903 320 05 01<br>904 320 04 01                                                    |  | Leaf Spring                                           | SPRINTER 208<br>311<br>312<br>313<br>413                                           | W 901<br>W 903                   |
| FCS-BS-497 | 903 320 06 06                                                                     |  | Spring Pack                                           | SPRINTER 308<br>310;312;314<br>308 CDI;311 CDI<br>313 CDI;316 CDI<br>(02.95-05.06) |                                  |
| FCS-BS-498 | 903 320 16 06                                                                     |  | Spring Rear Leaf No:1                                 | SPRINTER 310<br>312;314<br>308 CDI;311 CDI<br>313 CDI;316 CDI<br>(02.95-05.06)     | W 901<br>W 902<br>W 903          |
| FCS-BS-499 | 903 320 17 06                                                                     |  | Spring Pack                                           | SPRINTER 308<br>310;312;314<br>308 CDI<br>311 CDI<br>313                           |                                  |
| FCS-BS-500 | 90432401                                                                          |  | Spring Rear Leaf No:1                                 | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |

|            |                                                                  |                                                                                     |                               |                                                                                    |                                  |
|------------|------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-501 | 90432402                                                         |     | Spring Rear Leaf No:2         | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-502 | 904 320 04 01                                                    |    | Spring Front 2 Leaf           | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-503 | 904 320 06 01 904<br>321 03 03                                   |    | Spring,Plastic(3.5T-Old Type) | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-504 | 904 320 06 06                                                    |    | Spring Pack                   | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-505 | 9043200706-1                                                     |    | Spring Rear Leaf No:1         | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-506 | 9043200706-2                                                     |    | Spring Rear Leaf No:2         | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-507 | 904 320 16 06                                                    |   | Spring Front 3 Leaf           | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-508 | 906 321 11 03<br>906 321 16 03<br>906 321 12 03                  |  | Leaf Spring(5.0T-New Type)    | SPRINTER 309<br>311<br>315<br>318                                                  | W 906                            |
| FCS-BS-509 | 906 320 24 06                                                    |  | Leaf Spring                   | SPRINTER 309<br>311<br>315<br>318                                                  | W 906                            |
| FCS-BS-510 | 906 320 25 06                                                    |  | Leaf Spring                   | SPRINTER 309<br>311<br>315<br>318                                                  | W 906                            |
| FCS-BS-511 | 906 320 18 06                                                    |  | Spring Rear Leaf No:1         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-512 | 906 321 14 03<br>906 321 15 03<br>906 321 10 03<br>906 321 09 03 |  | Leaf Spring(3.5T-New Type)    | SPRINTER 209 CDI<br>315 CDI<br>518 CDI<br>519 CDI                                  |                                  |
| FCS-BS-513 | 906 321 16 03                                                    |  | Leaf Spring                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-514 | 901 322 00 19                                                    |  | Rubber Bearing Front Spring   | SPRINTER 310<br>312;314<br>308 CDI;311 CDI<br>313 CDI;316 CDI<br>(02.95-05.06)     | W 901<br>W 902<br>W 903<br>W 904 |

|            |                                |                                                                                     |                                |                                                                                |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|--------------------------------|--------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-515 | 901 322 04 19                  |     | Rubber Bearing Front Spring    | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI;<br>313 CDI;413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-516 | 901 322 12 19                  |    | Rubber Bearing Front Spring    | SPRINTER 310<br>312;314<br>308 CDI;311 CDI<br>313 CDI;316 CDI<br>(02.95-05.06) | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-517 | 901 322 01 31                  |    | Plate, Left                    | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI<br>313 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-518 | 901 322 02 31                  |    | Plate, Left                    | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI<br>313 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-519 | 901 322 21 19                  |    | Spring Cushion                 | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI<br>313 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-520 | 901 322 22 19                  |    | Spring Cushion                 | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI<br>313 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-521 | 901 322 19 19<br>901 322 26 19 |   | Spring Cushion                 | SPRINTER 208<br>212;308;310<br>312 CDI;412;311 CDI<br>313 CDI;413 CDI;416 CDI  | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-522 | 601 321 03 50                  |  | Bushing To Torsion Bar         | SPRINTER 208<br>212;213 CDI;312<br>313 CDI;316 CDI<br>413 CDI;416 CDI          | W 901<br>W 902<br>W 903<br>W 904<br>W 906 |
| FCS-BS-523 | 000 321 02 50                  |  | Rubber Bushing To Front Spring | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI                  | W 904                                     |
| FCS-BS-524 | 901 324 00 50                  |  | Bushing, Leaf Spring           | SPRINTER 208<br>212;308;310<br>312;412;311 CDI<br>313 CDI;413 CDI;416 CDI      | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-525 | 901 324 01 50                  |  | Rubber Bushing To Front Spring | SPRINTER 208<br>212;308<br>310;312<br>311 CDI;313 CDI                          | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-526 | 901 324 02 50                  |  | Rubber Bushing To Rear Spring  | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                          | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-527 | 905 324 00 50                  |  | Bush, Leaf Spring              | SPRINTER 515                                                                   | W 905                                     |
| FCS-BS-528 | 901 322 06 19                  |  | Spring Seat                    | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                   | W 901                                     |

|            |               |                                                                                     |                               |                                                                                    |                                             |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------------------|------------------------------------------------------------------------------------|---------------------------------------------|
| FCS-BS-529 | 901 322 25 19 |     | Front Spring Seat             | SPRINTER 208<br>308<br>408                                                         | OM 601<br>W 901<br>W 902                    |
| FCS-BS-530 | 901 322 24 19 |    | Spring Cushion                | SPRINTER 208<br>312<br>313<br>412<br>413 CD                                        |                                             |
| FCS-BS-531 | 906 322 03 19 |    | Spring Seat                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                  | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-532 | 906 322 06 19 |    | Spring Seat                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                  | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-533 | 906 322 09 19 |    | Bushing, Leaf Spring          | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 900<br>W 906                              |
| FCS-BS-534 | 906 322 10 19 |    | Bushing, Leaf Spring          | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 900<br>W 906                              |
| FCS-BS-535 | 906 325 01 44 |   | Buffer, Spring Leaf           | SPRINTER 208<br>311;313<br>315;318<br>518                                          | W 900<br>W 906                              |
| FCS-BS-536 | 906 325 14 44 |  | Buffer, Spring Leaf           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 900<br>W 906                              |
| FCS-BS-537 | 905 325 01 44 |  | Buffer, Spring                | SPRINTER 515                                                                       | W 905                                       |
| FCS-BS-538 | 901 325 01 44 |  | Rubber Spring Rear            | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-539 | 901 325 07 44 |  | Rubber Buffer To Rear Spring  | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-540 | 901 325 08 44 |  | Rubber Buffer, Suspension     | SPRINTER 208<br>311;313<br>315;318<br>518                                          | W 901-903<br>W 906                          |
| FCS-BS-541 | 901 325 00 84 |  | Rubber Buffer To Front Spring | SPRINTER 208<br>212;308;310;312<br>412;311 CDI;313 CDI<br>413 CDI;416 CDI          | W 901<br>W 902<br>W 903<br>W 904            |
| FCS-BS-542 | 901 325 08 47 |  | Spring Clamp                  | SPRINTER 312<br>412<br>313<br>413 CDI                                              |                                             |

|            |                                                                                   |                                                                                     |                                                                                                |                                                                                    |                                           |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-543 | 901 325 11 47                                                                     |     | Clamp To Rear Spring                                                                           | SPRINTER 208<br>212;308;310<br>312;412;311 CDI<br>313 CDI;413 CDI;416 CDI          | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-544 | 904 323 00 85                                                                     |    | Stabilizer Bushing                                                                             |                                                                                    |                                           |
| FCS-BS-545 | 901 323 01 85                                                                     |    | Rubber Mounting To<br>Front Torsion Bar                                                        | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903<br>W 690          |
| FCS-BS-546 | 901 323 02 85                                                                     |    | Rubber Mounting To<br>Connecting Rod                                                           | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904<br>W 690 |
| FCS-BS-547 | 904 323 00 85                                                                     |    | Rubber Mounting To<br>Front Torsion Bar                                                        | SPRINTER 408<br>412<br>411 CDI<br>413 CDI<br>416 CDI                               | W 904                                     |
| FCS-BS-548 | 638 323 02 85<br>639 323 02 85                                                    |    | Rubber Mounting To<br>Front Torsion Bar                                                        | VIANO 108<br>110;108 CDI;110 CDI<br>112 CDI;VITO 108<br>111                        | W 638<br>W 639<br>W 906                   |
| FCS-BS-549 | 639 323 12 85                                                                     |   | Stabilizer Mounting                                                                            | VITO<br>VIANO                                                                      | W 639                                     |
| FCS-BS-550 | 906 323 35 85<br>906 323 14 85<br>2E0 411 04 1C<br>2E0 411 04 1E                  |  | Front Sway Bar Bushings - VIN<br>Specific<br>(16MM sway bar) - updated,<br>needs 906 323 00 40 | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | OM 642<br>OM 646<br>W 906                 |
| FCS-BS-551 | 906 323 36 85<br>906 323 16 85<br>906 323 37 85<br>2E0 407 47 3E<br>2E0 411 04 1F |  | Front Sway Bar Bushings - VIN<br>Specific<br>(for Heavy Duty 20MM sway<br>bar) -               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | OM 642<br>OM 646<br>W 906                 |
| FCS-BS-552 | 906 323 36 85                                                                     |  | Stabilizer Mounting                                                                            | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                                     |
| FCS-BS-553 | 000 323 78 85                                                                     |  | Rubber Buffer To Shock<br>Absorber                                                             | SPRINTER 208<br>212;213 CDI;312<br>313 CDI;316 CDI<br>413 CDI;416 CDI              | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-554 | 638 323 04 20                                                                     |  | Friction Bearing<br>suspension Strut Support<br>Mointing                                       | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                   | W 638                                     |
| FCS-BS-555 | 638 981 01 20                                                                     |  | Friction Bearing<br>suspension Strut Support<br>Mointing                                       | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                   | W 638                                     |
| FCS-BS-556 | 639 323 05 20                                                                     |  | Rubber Buffer To Shock<br>Absorber                                                             | VIANO 108<br>VITO 111<br>115                                                       | W 639                                     |



|            |               |                                                                                     |                                                          |                                                                                    |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-557 | 639 981 03 25 |     | Friction Bearing<br>suspension Strut Support<br>Mointing | VIANO 108<br>VITO 111<br>115                                                       | W 639                            |
| FCS-BS-558 | 901 323 00 85 |    | Rubber Buffer To Shock<br>Absorber                       | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-559 | 901 323 11 85 |    | Rubber Buffer To Shock<br>Absorber                       | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-560 | 906 323 05 20 |    | Rubber Buffer To Shock<br>Absorber                       | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-561 | 901 323 01 98 |    | Rubber Buffer To Shock<br>Absorber                       | SPRINTER 208<br>311<br>312<br>313<br>413                                           | W 901-905                        |
| FCS-BS-562 | 906 323 02 92 |    | Boot For Shock Absorber                                  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-563 | 667 326 00 27 |   | Balance Bar Clamp                                        |                                                                                    |                                  |
| FCS-BS-564 | 667 326 14 40 |  | Rear Torsion Bar Clamp                                   |                                                                                    |                                  |
| FCS-BS-565 | 901 323 02 88 |  | Clamp To Torsion Bar                                     | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-566 | 906 323 00 40 |  | Bracket,Stabilizer Mounting                              | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>511 CDI<br>515 CDI                       | W 906                            |
| FCS-BS-567 | 901 326 00 81 |  | Rubber Mounting To Rear<br>Torsion Bar                   | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903<br>W 690 |
| FCS-BS-568 | 901 326 01 81 |  | Stabilizer Mounting                                      | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI                              | W 901<br>W 902<br>W 903          |
| FCS-BS-569 | 904 326 08 81 |  | Rubber Mounting To<br>Rear Torsion Bar                   | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI                      | W 904                            |
| FCS-BS-570 | 904 326 09 81 |  | Rubber Mounting To<br>Rear Torsion Bar                   | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI                      | W 904                            |

|            |                                |                                                                                     |                                     |                                                                                    |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-571 | 904 326 10 81                  |     | Rubber Mounting To Rear Torsion Bar | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI                      | W 904                            |
| FCS-BS-572 | 638 326 02 81                  |    | Rubber Mounting To Rear Torsion Bar | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-573 | 906 326 02 81                  |    | Rubber Mounting To Rear Torsion Bar | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-574 | 639 326 10 81                  |    | Stabilizer Mounting                 | VIANO 108<br>VITO 111<br>115                                                       | W 639                            |
| FCS-BS-575 | 906 326 04 81                  |    | Rubber Mounting To Rear Torsion Bar | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-576 | 906 326 07 81                  |    | Rubber Mounting To Rear Torsion Bar | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-577 | 906 326 09 81                  |   | Stabilizer Mounting                 | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-578 | 601 326 02 40                  |  | Clamp To Rear Torsion Bar           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 901<br>902<br>903<br>904       |
| FCS-BS-579 | 904 326 08 40<br>904 326 13 40 |  | Clamp To Rear Torsion Bar           | SPRINTER 412<br>408 CDI<br>411 CDI<br>413 CDI<br>416 CDI                           | W 901<br>W 690                   |
| FCS-BS-580 | 901 995 01 10                  |  | Front Spring Seat                   | SPRINTER 208<br>212;308<br>310;312<br>311 CDI<br>313 CDI                           | W 901<br>W 902<br>W 903<br>W 690 |
| FCS-BS-581 | 906 326 19 40                  |  | Bracket, Stabilizer Mounting        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-582 | 000 995 34 02                  |  | Clamp To Rear Torsion Bar           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-583 | 123 320 09 89                  |  | Rod/Strut, Stabiliser               | SPRINTER 208<br>PKW<br>311;312<br>313;413                                          | W 901<br>W 906                   |
| FCS-BS-584 | 901 320 02 89                  |  | Rod To Front Torsion Bar, Left      | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |

|            |                                |                                                                                     |                                 |                                                                              |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------|------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-585 | 901 320 03 89                  |     | Bushing, Leaf Spring            | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-586 | 90132002-0389                  |    | Rod To Front Torsion Bar, L&R   | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-587 | 906 325 14 44                  |    | Rod To Rear Torsion Bar         | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-588 | 901 320 05 89                  |    | Rod/Strut, Stabiliser           | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                 |                                  |
| FCS-BS-589 | 638 323 02 68                  |    | Rod To Front Torsion Bar, left  | VITO 108<br>110                                                              | W 638                            |
| FCS-BS-590 | 638 323 03 68                  |    | Rod To Front Torsion Bar, right | VITO 108<br>110                                                              | W 638                            |
| FCS-BS-591 | 638 323 04 68                  |   | Rod To Front Torsion Bar, left  | VITO 108 CDI<br>110 CDI<br>112 CDI                                           | W 638                            |
| FCS-BS-592 | 638 323 05 68                  |  | Rod To Front Torsion Bar, Right | VITO 108 CDI<br>110 CDI<br>112 CDI                                           | W 638                            |
| FCS-BS-593 | 638 326 00 16                  |  | Rod/Strut, Stabiliser           | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                             | W 638                            |
| FCS-BS-594 | 638 326 01 16                  |  | Rod/Strut, Stabiliser           | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                             | W 638                            |
| FCS-BS-595 | 639 320 02 89<br>639 320 04 89 |  | Rod/Strut, Stabiliser           | VIANO 108<br>VITO 111<br>115                                                 | W 639                            |
| FCS-BS-596 | 639 320 03 89<br>639 320 05 89 |  | Rod/Strut, Stabiliser           | VIANO 108<br>VITO 111<br>115                                                 | W 639                            |
| FCS-BS-597 | 905 320 04 89                  |  | Rod/Strut, Stabiliser           | SPRINTER 616                                                                 | W 903<br>W 905                   |
| FCS-BS-598 | 905 320 05 89                  |  | Rod/Strut, Stabiliser           | SPRINTER 616                                                                 | W 903<br>W 905                   |

|            |                                |                                                                                     |                                 |                                                                                    |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-599 | 906 320 17 89                  |     | Rod To Front Torsion Bar, left  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-600 | 906 320 18 89                  |    | Rod To Front Torsion Bar, right | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-601 | 906 320 13 89<br>906 320 14 89 |    | Rod/Strut, Stabiliser           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-602 | 901 333 02 14                  |    | Control Arm Bushing             | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-603 | 638 333 00 14                  |    | Control Arm Bushing             | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-604 | 638 352 02 50                  |    | Control Arm Bushing, Rear       | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-605 | 638 352 04 50                  |   | Control Arm Bushing             | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-606 | 638 333 08 14                  |  | Control Arm Bushing             | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-607 | 639 333 02 14                  |  |                                 |                                                                                    |                                  |
| FCS-BS-608 | 639 353 00 50                  |  | Control Arm Bushing             | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639                            |
| FCS-BS-609 | 906 324 00 50                  |  | Bush, Leaf Spring               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 900<br>W 906                   |
| FCS-BS-610 | 979 320 01 73                  |  | Bushing                         |                                                                                    |                                  |
| FCS-BS-611 | 906 333 00 14                  |  | Control Arm Bushing             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-612 | 906 333 01 14                  |  | Control Arm Bushing             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |

|            |                                |                                                                                     |                                                             |                                                                                         |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-613 | 906 352 04 50                  |     | Control Arm Bushing                                         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....)      | W 906                            |
| FCS-BS-614 | 906 353 00 43                  |    | Control Arm Bushing                                         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....)      | W 906                            |
| FCS-BS-615 | 901 330 10 25                  |    | Front Wheel Bearing<br>2500/3500 (2001-2006) -              |                                                                                         |                                  |
| FCS-BS-616 | 902 350 00 68                  |    | Wheel Bearing Repair Kit Rear                               |                                                                                         |                                  |
| FCS-BS-617 | 901 330 10 25                  |    | Wheel Bearing Repair Kit<br>Front                           |                                                                                         |                                  |
| FCS-BS-618 | 011 981 91 05                  |    | Bearing                                                     |                                                                                         |                                  |
| FCS-BS-619 | 019 980 69 02<br>005 981 24 05 |   | Bearing,Differential Shaft                                  | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                            | W 901<br>W 903<br>W 904          |
| FCS-BS-620 | 007 981 53 05                  |  | Bearing,Differential Shaft                                  | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                            | W 901<br>W 903<br>W 904          |
| FCS-BS-621 | 011 981 89 05                  |  | Wheel Bearing Kit,Rear                                      | SPRINTER 208<br>311<br>312<br>313                                                       | W 901<br>W 902<br>W 903          |
| FCS-BS-622 | 604 330 00 25                  |  | Wheel Bearing Kit,Front                                     | SPRINTER 208<br>212;214;208 CDI<br>211 CDI;213 CDI<br>216 CDI;308;310<br>312;314;308CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-623 | 015 981 55 05                  |  | Wheel Bearing Kit,Rear                                      | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI            | W 901-905                        |
| FCS-BS-624 | 611 330 08 25                  |  | Wheel Bearing Kit,Front                                     | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI            | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-625 | 638 981 00 27                  |  | Wheel Bearing Kit,Rear                                      | VITO 108<br>110<br>108 CDI<br>110 CDI,<br>112 CDI                                       | W 638                            |
| FCS-BS-626 | 906 330 50 20 906<br>330 40 20 |  | Front Right Hub Assy<br>(2500 only, complete w/<br>Spindle) |                                                                                         |                                  |

|            |                                                            |                                                                                     |                                                             |                                                                                    |           |
|------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------|------------------------------------------------------------------------------------|-----------|
| FCS-BS-627 | 906 330 49 20                                              |     | Front Left Hub Assy<br>(2500 only, complete w/<br>Spindle)  |                                                                                    |           |
| FCS-BS-628 | 906 330 43 20                                              |    | Front Right Hub Assy<br>(3500 only, complete w/<br>Spindle) |                                                                                    |           |
| FCS-BS-629 | 906 330 42 20                                              |    | Front Left Hub Assy<br>(3500 only, complete w/<br>Spindle)  |                                                                                    |           |
| FCS-BS-630 | 6393300632-1<br>6393300732-1<br>6393301232-1               |    | Wheel Bearing                                               | VIANO 108<br>VITO 110<br>111<br>115                                                | W 639     |
| FCS-BS-631 | 906 330 50 20                                              |    | Wheel Bearing                                               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906     |
| FCS-BS-632 | 906 350 00 68                                              |    | Wheel Bearing Kit,Rear                                      | SPRINTER 208<br>212;213 CDI;412<br>408 CDI;411 CDI<br>416 CDI<br>(01.95-05.06)     | W 901-905 |
| FCS-BS-633 | 906 350 39 10<br>2E0501171G<br>906 350 40 10<br>2E0501172F |   | Wheel Hub Bearing                                           | SPRINTER 209<br>211;309;311<br>315;318                                             | W 906     |
| FCS-BS-634 | 906 350 37 10<br>2E0501171E<br>906 350 38 10<br>2E0501172D |  | Wheel Hub Bearing                                           | SPRINTER 315<br>318<br>515                                                         | W 906     |
| FCS-BS-635 | 000 330 02 36                                              |  | Drive Shaft,Outer                                           | VITO 108 D<br>110 D<br>112 D                                                       | W 638     |
| FCS-BS-636 | 000 330 02 36-1                                            |  | Drive Shaft,Inner                                           | VITO 108 D<br>110 D<br>112 D                                                       | W 638     |
| FCS-BS-637 | 000 330 00 36                                              |  | Drive Shaft,Outer                                           | VITO 108 CDI<br>110 CDI<br>112 CDI                                                 | W 638     |
| FCS-BS-638 | 000 330 18 85                                              |  | Drive Shaft,Outer With Abs                                  | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638     |
| FCS-BS-639 | 638 334 17 34                                              |  | Drive Shaft,Complete                                        | VITO 108 D<br>110 D<br>113                                                         | W 638     |
| FCS-BS-640 | 638 334 23 34                                              |  | Drive Shaft,Complete                                        | VITO 108 D<br>110 D<br>113                                                         | W 638     |




|            |                                |                                                                                     |                           |                                                                                    |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-641 | 000 330 19 85                  |     | Front Axle Boot,Outer     | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-642 | 000 330 17 85<br>000 330 20 85 |    | Front Axle Boot,Inner     | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-643 | 000 337 00 85                  |    | Front Axle Boot,Outer     | VITO 108 D<br>110 D<br>113                                                         | W 638                            |
| FCS-BS-644 | 000 337 01 85                  |    | Front Axle Boot,Inner     | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-645 | 667 356 00 73                  |    | Drive Shaft,Lock          | SPRINTER 210<br>212;214;310<br>312;314<br>410;412                                  | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-646 | 000 350 36 23                  |    | Rep.Kit.Differential Gear | SPRINTER 312<br>412                                                                | W 901<br>W 902                   |
| FCS-BS-647 | 611 350 01 26                  |   | Rep.Kit.Differential Gear | SPRINTER 212<br>308<br>312                                                         | W 901,W 902,W 903                |
| FCS-BS-648 | 602 350 29 39                  |  | Ring Gear & Pinion-9/37   | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-649 | 904 350 00 39                  |  | Ring Gear & Pinion-8/35   | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-650 | 903 353 00 10<br>903 353 00 12 |  | Ring Gear & Pinion-7/34   | SPRINTER 208<br>212<br>308<br>312                                                  | W 901<br>W 902<br>W 903          |
| FCS-BS-651 | 638 330 00 27                  |  | Steering Link Ball Joint  | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                   | W 638                            |
| FCS-BS-652 | 639 333 02 27                  |  | Steering Link Ball Joint  | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639                            |
| FCS-BS-653 | 901 333 11 27                  |  | Steering Link Ball Joint  | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-654 | 906 330 40 07<br>906 338 02 27 |  | Track Control Arm         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |

|            |                                                                                   |                                                                                     |                          |                                                                                    |                                  |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-655 | 906 333 02 27                                                                     |     | Steering Link Ball Joint | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-656 | A 901 330 24 07<br>901 330 18 07<br>901 330 16 07                                 |    | Track Control Arm        | MERCEDES-BENZ<br>SPRINTER 2-t Box<br>(901, 902)<br>208 CDI                         |                                  |
| FCS-BS-657 | A 901 330 25 07<br>901 330 19 07<br>901 330 17 07                                 |    | Track Control Arm        | MERCEDES-BENZ<br>SPRINTER 2-t Box<br>(901, 902)<br>208 CDI                         |                                  |
| FCS-BS-658 | 901 460 01 48<br>901 460 00 48<br>901 460 02 48<br>901 460 03 48<br>2D 042 28 11  |    | Steering Tie Rod End     | SPRINTER 208<br>212;308<br>310;312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-659 | 901 460 02 05                                                                     |    | Steering Drag Link       | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-660 | 638 460 00 48                                                                     |    | Steering Tie Rod End     | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-661 | 638 460 02 05<br>638 460 00 55                                                    |   | Steering Drag Link       | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-662 | 639 460 00 48                                                                     |  | Steering Tie Rod End     | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639                            |
| FCS-BS-663 | 639 460 03 48                                                                     |  | Steering Tie Rod End     | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639                            |
| FCS-BS-664 | 639 460 02 55                                                                     |  | Tie Rod                  | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639                            |
| FCS-BS-665 | 906 460 00 48<br>906 460 03 48<br>2E0498104<br>2E0498104A<br>2E0713501            |  | Steering Tie Rod End     | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-666 | 906 460 00 55                                                                     |  | Tie Rod                  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-667 | 901 460 01 55<br>901 460 02 55<br>901 460 04 55                                   |  | Rack End                 |                                                                                    |                                  |
| FCS-BS-668 | 901 460 41 00<br>901 460 29 00<br>901 460 43 00<br>901 460 45 00<br>901 460 08 00 |  | Steering Box Assembly    | SPRINTER 208<br>212;216 CDI<br>312;316 CDI<br>408;411 CDI                          | W 901<br>W 902<br>W 903<br>W 904 |





|            |                                                                                   |                                                                                     |                                                     |                                                                                    |                                                                      |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| FCS-BS-669 | 9014604100-1                                                                      |     | Rep.Kit.Steering Box                                | SPRINTER 208<br>212;216 CDI<br>312;316 CDI<br>408;411 CDI                          | W 901<br>W 902<br>W 903<br>W 904                                     |
| FCS-BS-670 | 638 460 29 00<br>638 460 06 00<br>638 460 21 00                                   |    | Steering Box Assembly                               | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                                                                |
| FCS-BS-671 | 6384602900-1                                                                      |    | Rep.Kit.Steering Box                                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                                                                |
| FCS-BS-672 | 906 460 04 00<br>906 460 08 00<br>906 460 02 00<br>906 460 13 00<br>906 460 06 00 |    | Steering Box Assembly                               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                                                                |
| FCS-BS-673 | 901 460 55 00                                                                     |    | Steering Boot                                       | SPRINTER 208<br>308;311<br>312;313<br>412<br>413 CDI                               | W 901<br>W 902<br>W 903                                              |
| FCS-BS-674 | 901 462 03 96                                                                     |    | Steering Box Boot                                   | VITO 108<br>110<br>113 CDI                                                         | W 638                                                                |
| FCS-BS-675 | 639 460 01 96                                                                     |   | Steering Box Boot                                   | VITO<br>VIANO<br>108<br>111<br>113                                                 | W 639                                                                |
| FCS-BS-676 | 906 460 00 96                                                                     |  | Steering Box Boot                                   | SPRINTER 209 CDI<br>213 CDI<br>309 CDI<br>315 CDI                                  | W 906                                                                |
| FCS-BS-677 | 002 466 75 01<br>002 466 76 01<br>0024667601-88                                   |  | Hydraulic Pump                                      | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI<br>416 CDI                       | OM 611.981<br>OM 611.987<br>OM 612.981<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-678 | 003 466 07 01                                                                     |  | Hydraulic Pump                                      | SPRINTER 208<br>212;214<br>312;314<br>410;412                                      | OM 601.942<br>OM 601.943<br>OM 602.980<br>W 901<br>W 902             |
| FCS-BS-679 | 003 466 72 01<br>003 466 71 01                                                    |  | Hydraulic Pump                                      | VITO;VIANO<br>108<br>111<br>113<br>115 CDI                                         | W 639<br>W 906                                                       |
| FCS-BS-680 | 000 460 28 83                                                                     |  | Power Steering Reservoir                            |                                                                                    |                                                                      |
| FCS-BS-681 | 003 466 93 01<br>680 122 36 AA                                                    |  | Power Steering without<br>bracket 120mm belt 7 slot |                                                                                    |                                                                      |
| FCS-BS-682 | 906 401 00 25                                                                     |  | Wheel Cover                                         |                                                                                    |                                                                      |



|            |                                                 |                                                                                     |               |                                                                              |                         |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|---------------|------------------------------------------------------------------------------|-------------------------|
| FCS-BS-683 | 2E0 601 151<br>906 401 00 25                    |     | Wheel Cover   |                                                                              |                         |
| FCS-BS-684 | 906 400 01 25                                   |    | Wheel Cover   |                                                                              |                         |
| FCS-BS-685 | 639 400 00 25                                   |    | Wheel Cover   |                                                                              |                         |
| FCS-BS-686 | 2D0 601 149                                     |    | Wheel Cover   |                                                                              |                         |
| FCS-BS-687 | 639 401 08 25                                   |    | Wheel Cover   | VITO<br>VIANO                                                                |                         |
| FCS-BS-688 | 639 401 36 02                                   |    | Wheel Cover   | VITO<br>VIANO                                                                |                         |
| FCS-BS-689 |                                                 |   | Wheel Hub     | VITO<br>VIANO                                                                |                         |
| FCS-BS-690 |                                                 |  | Wheel Hub     | VITO<br>VIANO                                                                |                         |
| FCS-BS-691 | 601 401 03 25                                   |  | Wheel Hub Cap | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903 |
| FCS-BS-692 | 667 400 01 25<br>667 400 03 25<br>668 400 01 25 |  | Wheel Hub Cap | SPRINTER 412<br>413<br>609                                                   | W 668<br>W 669          |
| FCS-BS-693 | 668 400 02 25                                   |  | Wheel Hub Cap | 609<br>709<br>711<br>811<br>VARIO                                            | W 668<br>W 669          |
| FCS-BS-694 | 903 401 08 02                                   |  | Disc Wheel    | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903 |
| FCS-BS-695 | 638 401 02 71                                   |  | Wheel Stud    |                                                                              | W 638                   |
| FCS-BS-696 |                                                 |  | Wheel Cover   |                                                                              | MB 100                  |

|              |                                                                                   |                                                                                     |                                                  |                                                                                    |                                  |
|--------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-697   |                                                                                   |     | Wheel Cover                                      |                                                                                    | MB 100                           |
| FCS-BS-698   | 000 990 24 07                                                                     |    | Wheel Stud                                       |                                                                                    | W 906                            |
| FCS-BS-699   | 000 990 49 07                                                                     |    | Wheel Stud                                       | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 639                            |
| FCS-BS-700   | 639 410 04 81                                                                     |    | Intermediate Bearing                             | VITO 109 CDI<br>111<br>115 CDI<br>VIANO                                            | W 639                            |
| FCS-BS-701   | 639 410 06 81                                                                     |    | Intermediate Bearing                             | VITO 109 CDI<br>111<br>115 CDI<br>VIANO                                            | W 639                            |
| FCS-BS-702   | 901 411 03 12<br>901 411 04 12<br>903 410 00 10<br>901 411 03 10                  |    | Intermediate Bearing                             | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-703-1 | 906 410 03 81<br>906 410 10 81<br>906 410 12 81<br>906 410 15 81<br>906 410 17 81 |   | Intermediate Bearing                             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-704-1 | 601 411 01 97<br>901 411 00 97                                                    |  | Shaft Boot                                       | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-705-1 | 906 350 37 10<br>906 350 38 10                                                    |  | Rear Axle Shaft Without<br>Wheel Hub<br>Bearing  |                                                                                    |                                  |
| FCS-BS-706-1 | 906 350 40 10<br>906 350 39 10                                                    |  | Rear Axle Shaft Without<br>Wheel Hub<br>Bearing  |                                                                                    |                                  |
| FCS-BS-707   | 906 350 37 10<br>906 350 38 10                                                    |  | Rear Axle Shaft With Wheel<br>Hub<br>Bearing Set |                                                                                    |                                  |
| FCS-BS-708   | 906 350 40 10<br>906 350 39 10                                                    |  | Rear Axle Shaft With Wheel<br>Hub<br>Bearing Set |                                                                                    |                                  |
| FCS-BS-709   | U122                                                                              |  | Universal Joint                                  |                                                                                    |                                  |
| FCS-BS-710   | ST-1540                                                                           |  | Universal Joint                                  |                                                                                    |                                  |

|            |                        |                                                                                     |                             |                                                                                    |                                  |
|------------|------------------------|-------------------------------------------------------------------------------------|-----------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-711 | SIZE : 27x75           |     | Universal Joint             | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-712 | 24*88<br>906 410 44 06 |    | Universal Joint             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-713 | 27*88<br>906 410 19 06 |    | Universal Joint             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-714 | 27*92                  |    | Universal Joint             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-715 | 901 460 19 09 S        |    | Universal Joint             | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 906                            |
| FCS-BS-716 | 000 420 02 50          |    | Rep.Kit.Brake Caliper       | SPRINTER 311<br>315<br>318<br>515<br>518                                           | W 906                            |
| FCS-BS-717 | 001 420 23 83          |   | Rep.kit.brake Caliper,Front | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI<br>313 CDI                       | W 906                            |
| FCS-BS-718 | 001 420 24 83          |  | Rep.Kit.Brake Caliper       | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                            |
| FCS-BS-719 | 001 420 25 83          |  | Rep.Kit.Brake Caliper,Rear  | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI<br>313 CDI                       | W 901<br>W 902<br>W 903          |
| FCS-BS-720 | 639 420 00 83-1        |  | Rep.Kit.Brake Caliper       | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                            |
| FCS-BS-721 | 639 420 02 83-1        |  | Rep.Kit.Brake Caliper,Rear  | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                            |
| FCS-BS-722 | 639 420 11 83-1        |  | Rep.Kit.Brake Caliper       | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                            |
| FCS-BS-723 | 000 421 08 50          |  | Rep.Kit.Brake Caliper       | SPRINTER 311<br>315<br>318<br>515<br>518                                           | W 906                            |
| FCS-BS-724 | 000 423 05 63          |  | Rep.Kit.Brake Caliper,Rear  | SPRINTER 309 CDI<br>311 CDI<br>315 CDI<br>318 CDI                                  |                                  |



|            |               |                                                                                     |                           |                                                              |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|---------------------------|--------------------------------------------------------------|----------------------------------|
| FCS-BS-725 | 000 423 06 63 |     | Rep.Kit.Brake Caliper     | SPRINTER 515 CDI<br>518 CDI                                  |                                  |
| FCS-BS-726 | 901 300 17 30 |    | Wire Cable                | SPRINTER 208<br>308<br>408                                   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-727 | 901 300 30 30 |    | Wire Cable                | SPRINTER 212<br>312<br>412                                   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-728 | 638 427 03 38 |    | Park Brake Cable          | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI             | W 638                            |
| FCS-BS-729 | 638 420 07 85 |    | Park Brake Cable          | VITO 108 CDI<br>110 CDI<br>112 CDI                           | W 638                            |
| FCS-BS-730 | 639 427 04 38 |    | Park Brake Cable,Rear-L   | VITO 109<br>111<br>115 CDI                                   | W 639                            |
| FCS-BS-731 | 639 427 05 38 |   | Park Brake Cable,Rear-R   | VITO 109<br>111<br>115 CDI                                   | W 639                            |
| FCS-BS-732 | 639 420 17 85 |  | Park Brake Cable,Front    | VITO<br>VIANO<br>108<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-733 | 639 420 29 85 |  | Park Brake Cable,Front    | VITO<br>VIANO<br>108<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-734 | 639 420 32 85 |  | Park Brake Cable,Front    | VITO<br>VIANO<br>108<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-735 | 639 420 34 85 |  | Park Brake Cable,front    | VITO<br>VIANO<br>108<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-736 | 667 420 46 85 |  | Park Brake Cable-L        | SPRINTER 313 CDI<br>208<br>212<br>308<br>412                 | W 901-W 904<br>W 667             |
| FCS-BS-737 | 667 420 47 85 |  | Park Brake Cable-R        | SPRINTER 208<br>212<br>308<br>412                            | W 901-W 904<br>W 667             |
| FCS-BS-738 | 901 420 18 85 |  | Park Brake Cable,Rear-L&R | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI<br>313 CDI | W 901<br>W 902<br>W 903<br>W 904 |

|            |               |                                                                                     |                         |                                                                                |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-739 | 901 420 20 85 |     | Park Brake Cable,Front  | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI   | W 904                            |
| FCS-BS-740 | 901 420 21 85 |    | Park Brake Cable,Front  | SPRINTER 616 CDI<br>313 CDI<br>412;208<br>212;308                              | W 904                            |
| FCS-BS-741 | 901 420 22 85 |    | Park Brake Cable,Front  | SPRINTER 616 CDI<br>313 CDI<br>412;208<br>212;309                              | W 904                            |
| FCS-BS-742 | 901 420 27 85 |    | Park Brake Cable        | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                   | W 901-W 904                      |
| FCS-BS-743 | 901 420 28 85 |    | Park Brake Cable,Rear   | SPRINTER 616 CDI<br>313 CDI<br>412;208<br>212;309                              | W 667<br>W 901-W 905             |
| FCS-BS-744 | 904 420 01 85 |    | Park Brake Cable,Rear-L | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06) | W 904                            |
| FCS-BS-745 | 904 420 02 85 |   | Park Brake Cable,Front  | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06) | W 904                            |
| FCS-BS-746 | 904 420 03 85 |  | Park Brake Cable,Front  | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-747 | 904 420 04 85 |  | Park Brake Cable        | SPRINTER 412<br>413 CDI                                                        |                                  |
| FCS-BS-748 | 904 420 05 85 |  | Park Brake Cable-L      | SPRINTER 208<br>212<br>308<br>412<br>313 CDI;616 CDI                           | W 904                            |
| FCS-BS-749 | 904 420 06 85 |  | Park Brake Cable-R      | SPRINTER 208<br>212<br>308<br>412<br>313 CDI;616 CDI                           | W 904                            |
| FCS-BS-750 | 904 420 07 85 |  | Park Brake Cable-L      | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                   | W 667<br>W 901-W 905             |
| FCS-BS-751 | 906 420 23 85 |  | Brake Cable             |                                                                                |                                  |
| FCS-BS-752 | 904 420 08 85 |  | Park Brake Cable-R      | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                   | W 667<br>W 901-W 905             |


|            |               |                                                                                     |                           |                                                                                    |                         |
|------------|---------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------|-------------------------|
| FCS-BS-753 | 906 420 1985  |     | Park Brake Cable,Rear     | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                                  | W 900<br>W 906          |
| FCS-BS-754 | 906 420 20 85 |    | Park Brake Cable,Rear-L&R | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 900<br>W 906          |
| FCS-BS-755 | 906 420 24 85 |    | Park Brake Cable,Front    | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                                  | W 900<br>W 906          |
| FCS-BS-756 | 906 420 30 85 |    | Park Brake Cable,Rear-L   | SPRINTER 509 CDI<br>515 CDI                                                        | W 906                   |
| FCS-BS-757 | 906 420 31 85 |    | Park Brake Cable,Rear-R   | SPRINTER 509 CDI<br>515 CDI                                                        | W 906                   |
| FCS-BS-758 | 906 420 51 85 |    | Park Brake Cable,Front    | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                                  | W 900<br>W 906          |
| FCS-BS-759 | 003 420 00 20 |   | Brake Pad Set,Rear        | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-760 | 003 420 02 20 |  | Brake Pad Set,Rear        | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-761 | 003 420 46 20 |  | Brake Pad Set             |                                                                                    | W 905                   |
| FCS-BS-762 | 000 421 41 10 |  | Brake Pad Set,Front       | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-763 | 000 421 61 10 |  | Brake Pad Set,Front       | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                   |
| FCS-BS-764 | 000 421 62 10 |  | Brake Pad Set,Rear        | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                   |
| FCS-BS-765 | 000 420 97 20 |  | Brake Pad Set,Rear        | SPRINTER 212<br>310<br>312                                                         | W 901<br>W 902<br>W 903 |
| FCS-BS-766 | 001 421 09 10 |  | Brake Pad Set,Front       | VITO 109<br>111<br>115 CDI                                                         | W 639                   |

|            |                                                                                   |                                                                                     |                            |                                                                                          |                                  |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-767 | 001 421 10 10                                                                     |     | Brake Pad Set,Front        | VITO 109<br>111<br>115 CDI                                                               | W 639                            |
| FCS-BS-768 | 002 420 39 20<br>002 420 99 20<br>004 420 55 20                                   |    | Brake Pad Set,Front        | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI<br>313 CDI                             | W 901<br>W 902<br>W 903          |
| FCS-BS-769 | 002 420 41 20<br>004 420 24 20<br>003 420 17 20<br>004 420 15 20<br>902 421 01 10 |    | Brake Pad Set,Front & Rear | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)           | W 904                            |
| FCS-BS-770 | 002 420 60 20<br>002 420 40 20<br>004 420 18 20<br>004 420 27 20                  |    | Brake Pad Set,Rear         | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)           | W 903                            |
| FCS-BS-771 | 004 420 56 20<br>002 420 56 20<br>003 420 64 20<br>002 420 69 20<br>002 420 38 20 |    | Brake Pad Set,Rear         | SPRINTER 208<br>210;212;214<br>208 CDI<br>211 CDI<br>213 CDI                             | W 901<br>W 902                   |
| FCS-BS-772 | 004 420 69 20                                                                     |    | Brake Pad Set,Rear         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....)       | W 906                            |
| FCS-BS-773 | 004 420 83 20<br>005 420 52 20                                                    |   | Brake Pad Set,Front        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....)       | W 906                            |
| FCS-BS-774 | 004 420 82 20                                                                     |  | Brake Pad Set,Front        | SPRINTER 318 CDI<br>319 CDI<br>519 CDI                                                   | W 906                            |
| FCS-BS-775 | 004 420 81 20                                                                     |  | Brake Pad Set,Rear         | SPRINTER 318 CDI<br>319 CDI<br>519 CDI                                                   | W 906                            |
| FCS-BS-776 | 000 421 59 91                                                                     |  | Spring To Brake Linig      | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-777 | 639 540 15 17<br>639 540 14 17<br>2E0906206G                                      |  | Brake Warning Sensor       |                                                                                          | W 639<br>W 906                   |
| FCS-BS-778 | 901 540 01 17 901<br>540 00 17 901<br>540 02 17                                   |  | Brake Linig Wear Indicator | SPRINTER 208<br>210;212;214<br>208 CDI;310;312<br>314;412;408 CDI<br>411 CDI;413 CDI;416 | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-779 | 906 540 13 17<br>2E0906206B                                                       |  | Brake Warning Sensor       |                                                                                          | W 906                            |
| FCS-BS-780 | 906 540 14 17<br>906 540 15 17<br>2E0906206C                                      |  | Brake Linig Wear Indicator | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                        | W 906                            |


|            |                                                                                     |  |                                            |                                                                                |                         |
|------------|-------------------------------------------------------------------------------------|--|--------------------------------------------|--------------------------------------------------------------------------------|-------------------------|
| FCS-BS-781 | 003 420 70 20                                                                       |  | Hand Brake Shoe Set                        | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                               | W 638                   |
| FCS-BS-782 | 639 420 02 20                                                                       |  | Hand Brake Shoe Set                        | VIANO 108<br>VITO 111<br>115                                                   | W 639                   |
| FCS-BS-783 | 002 420 58 20                                                                       |  | Hand Brake Shoe Set                        | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI<br>313 CDI                   | W 901<br>W 902<br>W 903 |
| FCS-BS-784 | 002 420 59 20                                                                       |  | Hand Brake Shoe Set                        | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06) | W 904                   |
| FCS-BS-785 | 906 420 02 20                                                                       |  | Hand Brake Shoe Set                        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI              | W 906                   |
| FCS-BS-786 | 906 420 03 20                                                                       |  | Hand Brake Shoe Set                        | SPRINTER 209 CDI<br>213 CDI<br>215 CDI<br>315 CDI                              | W 906                   |
| FCS-BS-787 | 906 420 04 20                                                                       |  | Hand Brake Shoe Set                        | SPRINTER 209 CDI<br>211 CDI<br>311 CDI<br>511 CDI<br>515 CDI                   | W 906                   |
| FCS-BS-788 | 906 420 02 38                                                                       |  | Hand Brake Lever                           | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI<br>511 CDI                   | W 900<br>W 906          |
| FCS-BS-789 | 906 420 03 38                                                                       |  | Hand Brake Lever                           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI              | W 900<br>W 906          |
| FCS-BS-790 | 001 420 69 83                                                                       |  | Brake Caliper, Left                        | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                   | W 901-W905              |
| FCS-BS-791 | 001 420 70 83                                                                       |  | Brake Caliper, Right                       | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                   | W 901-W905              |
| FCS-BS-792 | MercedesBenz :<br>0034208783<br>A0034208783<br>0044205783<br>A0044205783            |  | Sprinter 3500 L/F Caliper<br>(2007- up) -  | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318 CDI;515 CDI<br>518 CDI              | W 906                   |
| FCS-BS-793 | 003 420 88 83<br>004 420 58 83                                                      |  | Sprinter 3500 R/F Caliper<br>(2007- up) -  | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318 CDI;515 CDI<br>518 CDI              | W 906                   |
| FCS-BS-794 | 0986134019090<br>A004 420 55 83<br>004 420 55 83<br>A003 420 85 83<br>003 420 85 83 |  | Sprinter 2500 L/F Caliper<br>(2007 - up) - |                                                                                |                         |

|            |                                                                                     |                                                                                     |                                            |                                                                                    |                                  |
|------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-795 | 0986135019090<br>A004 420 56 83<br>004 420 56 83<br>A003 420 86 83<br>003 420 86 83 |     | Sprinter 2500 R/F Caliper<br>(2007 - up) - |                                                                                    |                                  |
| FCS-BS-796 | 003 420 71 83                                                                       |    | Sprinter 2500 L/R Caliper<br>(2007- up) -  |                                                                                    |                                  |
| FCS-BS-797 | 003 420 72 83                                                                       |    | Sprinter 2500 R/R Caliper<br>(2007- up) -  |                                                                                    |                                  |
| FCS-BS-798 | 003 420 73 83                                                                       |    | Sprinter 3500 L/R Caliper<br>(2007- up) -  |                                                                                    |                                  |
| FCS-BS-799 | 003 420 74 83                                                                       |    | Sprinter 3500 R/R Caliper<br>(2007- up) -  |                                                                                    |                                  |
| FCS-BS-800 | 638 421 01 12                                                                       |    | Brake Disc,Front                           | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-801 | 639 421 00 12                                                                       |   | Brake Disc,Front                           | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                            |
| FCS-BS-802 | 902 421 06 12                                                                       |  | Brake Disc,Front                           | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-803 | 905 421 00 12                                                                       |  | Brake Disc,Front,Ventilated                | SPRINTER 616                                                                       | W 904<br>W 905                   |
| FCS-BS-804 | 906 421 00 12                                                                       |  | Brake Disc,Front                           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-805 | 638 423 01 12                                                                       |  | Brake Disc,Rear                            | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-806 | 639 423 01 12                                                                       |  | Brake Disc,Rear                            | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                            |
| FCS-BS-807 | 901 423 06 12                                                                       |  | Brake Disc,Front                           | SPRINTER 208<br>210;212;214<br>208 CDI<br>211 CDI<br>213 CDI                       | W 901<br>W 902                   |
| FCS-BS-808 | 902 423 03 12                                                                       |  | Brake Disc,Rear                            | SPRINTER 310<br>312<br>311 CDI<br>313 CDI<br>316 CDI                               | W 901<br>W 902<br>W 903          |




|            |                                |                                                                                     |                                                            |                                                                                    |                                      |
|------------|--------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------|
| FCS-BS-809 | 904 423 03 12                  |     | Brake Disc,Rear                                            | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                                |
| FCS-BS-810 | 906 423 00 12                  |    | Brake Disc,Rear                                            | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                                |
| FCS-BS-811 | 906 423 01 12                  |    | Brake Disc,Rear                                            | SPRINTER 318 CDI<br>319 CDI<br>519 CDI                                             | W 906                                |
| FCS-BS-812 | 903 421 00 12<br>903 421 01 12 |    | Front Brake Rotor - 285mm<br>for<br>2500 with 16" wheels - |                                                                                    |                                      |
| FCS-BS-813 | 461 423 01 20                  |    | Brake Disc Splash Panel                                    | SPRINTER 208 CDI<br>213 CDI;216 CDI<br>313 CDI;316 CDI                             | W 901- W 903                         |
| FCS-BS-814 | 461 423 02 20                  |    | Brake Disc Splash Panel                                    | SPRINTER 208 CDI<br>213 CDI;216 CDI<br>313 CDI;316 CDI                             | W 901- W 903                         |
| FCS-BS-815 | 904 423 10 51                  |   | Cover Plate<br>dust Cover Wheel Bearing                    | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                       | W 904                                |
| FCS-BS-816 | 904 423 11 51                  |  | Cover Plate<br>dust Cover Wheel Bearing                    | SPRINTER 208<br>312<br>313<br>412<br>413 CDI                                       | W 904                                |
| FCS-BS-817 | 638 428 10 35                  |  | Brake Line                                                 | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                                |
| FCS-BS-818 | 638 428 22 35                  |  | Brake Pad Set,Front                                        | VITO 108 CDI<br>110 CDI<br>112 CDI                                                 | W 638                                |
| FCS-BS-819 | 639 428 08 35                  |  | Brake Hose,Front                                           | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                                |
| FCS-BS-820 | 639 428 09 35                  |  | Brake Hose,Front                                           | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                                |
| FCS-BS-821 | 639 428 10 35                  |  | Brake Hose,Front                                           | VITO<br>VIANO<br>108<br>111<br>115 CDI                                             | W 639                                |
| FCS-BS-822 | 667 428 01 35                  |  | Brake Hose,Rear                                            | SPRINTER 312<br>412<br>MB 609 D<br>711 D<br>814 D                                  | W 611<br>W 667<br>W 670<br>W 901-904 |

|            |                                                             |                                                                                     |                       |                                                                              |                                  |
|------------|-------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-823 | 9014280235<br>9014280435<br>9014280635<br>9014280335 745919 |     | Brake Hose            | SPRINTER 208<br>210;212;214<br>310;312;314<br>308 CDI;411 CDI<br>413 CDI;416 | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-824 | 901 428 05 35<br>901 428 08 35                              |    | Brake Line            | SPRINTER 208<br>308<br>312                                                   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-825 | 904 428 04 35                                               |    | Brake Hose,Rear       | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                 | W 904<br>W 905                   |
| FCS-BS-826 | 904 428 05 35                                               |    | Brake Hose,Rear       | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                 | W 903<br>W 904<br>W 906          |
| FCS-BS-827 | 906 428 03 35                                               |    | Brake Hose,Rear       | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                            | W 900<br>W 906                   |
| FCS-BS-828 | 906 428 05 35                                               |    | Brake Hose,Rear       | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                            | W 903<br>W 904<br>W 906          |
| FCS-BS-829 | 906 428 06 35                                               |   | Brake Hose,Front      | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                            | W 906                            |
| FCS-BS-830 | 906 428 08 35                                               |  | Brake Hose,Front      | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI                            | W 906                            |
| FCS-BS-831 | 003 431 02 12                                               |  | Brake Power Regulator | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                 | W 901-W 905                      |
| FCS-BS-832 | 003 431 12 12                                               |  | Brake Power Regulator | SPRINTER 208<br>212<br>308<br>412<br>313 CDI                                 | W 903                            |
| FCS-BS-833 | 000 431 47 01                                               |  | Brake Master Cylinder |                                                                              |                                  |
| FCS-BS-834 | 000 431 58 01                                               |  | Brake Master Cylinder | VITO 108<br>110 CDI<br>112 CDI<br>114 CDI                                    | W 638                            |
| FCS-BS-835 | 000 431 63 01                                               |  | Brake Master Cylinder | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>316 CDI                 | W 901-W 904                      |
| FCS-BS-836 | 000 431 65 01                                               |  | Brake Master Cylinder | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |


|              |                                                                                                                      |                                                                                     |                                      |                                                              |                           |
|--------------|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------|--------------------------------------------------------------|---------------------------|
| FCS-BS-837   | 000 431 70 01                                                                                                        |     | Brake Master Cylinder                | SPRINTER 408<br>411 CDI<br>416 CDI                           | OM 611<br>OM 612<br>W 904 |
| FCS-BS-838   | 000 431 71 01                                                                                                        |    | Brake Master Cylinder                | SPRINTER 208 CDI<br>213 CDI<br>216 CDI<br>313 CDI<br>316 CDI | W 901<br>W 902<br>W 903   |
| FCS-BS-839   | 000 431 73 01                                                                                                        |    | Brake Master Cylinder                | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI            | W 906                     |
| FCS-BS-840   | 000 431 75 01                                                                                                        |    | Brake Master Cylinder                | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI            | W 906                     |
| FCS-BS-841   | 000 431 76 01                                                                                                        |    | Brake Master Cylinder                | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI            | W 906                     |
| FCS-BS-842   | 000 431 77 01                                                                                                        |    | Brake Master Cylinder                | SPRINTER 209 CDI<br>215 CDI<br>309 CDI<br>315 CDI            | W 906                     |
| FCS-BS-843   | 906 470 30 94                                                                                                        |   | Fuel Pump Assy                       | SPRINTER 511<br>CDI,515<br>CDI,518<br>(01.06-.....)          | W 906                     |
| FCS-BS-844   | 906 470 18 94<br>Bosh 0580203006                                                                                     |  | Fuel Pump Assy                       |                                                              |                           |
| FCS-BS-845   | 901 470 00 94                                                                                                        |  | Fuel Pump Assy                       |                                                              |                           |
| FCS-BS-846   | 901 470 01 94                                                                                                        |  | Fuel Pump Assy                       |                                                              |                           |
| FCS-BS-847   | 906 470 37 94                                                                                                        |  | Fuel Pump Assy                       |                                                              |                           |
| FCS-BS-848   | A9064902081<br>A9064902381<br>A9064904581<br>A9064905481<br>A9064905581<br>A9064907081<br>A9064907281<br>A9064907981 |  | SPRINTER 3.0 CDI                     |                                                              |                           |
| FCS-BS-849-1 | 9064900592<br>9064900992<br>9064901192                                                                               |  | SPRINTER 2.1L 2.2L 3.0L<br>2006-2015 |                                                              |                           |

|              |                                           |                                                                                     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
|--------------|-------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| FCS-BS-849-2 | 9064901592<br>68011959AA                  |     | DODGE SPRINTER 2500/3500<br>FREIGHTLINER SPRINTER<br>2500/3500 MERCEDES<br>SPRINTER 2500/3500                                                                                                                                                                                                                                                                                                                                                                                                      |  |  |
| FCS-BS-849-3 | 9064906381                                |    | Mercedes Benz Sprinter 210/<br>213/ 216<br>310/ 313 (906) 2.2 CDI 2006-<br>2015 2006-2015                                                                                                                                                                                                                                                                                                                                                                                                          |  |  |
| FCS-BS-849-4 | 6394906181 /<br>A6394906181               |    | Mercedes Viano 3.0 CDI<br>03/2006-<br>Mercedes Vito 3.0 CDI<br>03/2006-                                                                                                                                                                                                                                                                                                                                                                                                                            |  |  |
| FCS-BS-849-5 | A9064902914                               |    | Mercedes Sprinter DPF 2.2CDI<br>DIESEL 2013-2017                                                                                                                                                                                                                                                                                                                                                                                                                                                   |  |  |
| FCS-BS-849-6 | A9064906281                               |    | Mercedes Benz Sprinter 210 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 213 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 216 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 310 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 313 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 316 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 316 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 416 2.1 CDi OM651 07/2009 -<br>Mercedes Benz Sprinter 510 2.1 CDi OM651 07/2009 - |  |  |
| FCS-BS-849-7 | A9064900100<br>A9064900183                |  | Mercedes Benz Sprinter 210 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 213 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 216 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 310 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 313 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 316 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 316 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 416 2.1 CDi OM651 07/2009<br>Mercedes Benz Sprinter 510 2.1 CDi OM651 07/2009                   |  |  |
| FCS-BS-849-8 | A9064901481<br>A9064901581<br>A9064901981 |  | Mercedes Sprinter 210 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 213 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 216 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 310 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 313 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 316 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 416 2.1CDi OM651 3/2009-<br>Mercedes Sprinter 510 2.1CDi OM651 3/2009-                                                                                                                       |  |  |
| FCS-BS-849-9 | A6394901092                               |  | Mercedesa Vito WDB639601 2007-<br>Mercedesa Vito WDB639603 2007-<br>Mercedesa Vito WDB639605 2007-<br>Mercedesa Vito WDB639701 2007-<br>Mercedesa Vito WDB639703 2007-<br>Mercedesa Vito WDB639705 2007-<br>Mercedesa Vito WDB639711 2007-<br>Mercedesa Vito WDB639713 2007-<br>Mercedesa Viano WDB639811 2007-<br>Mercedesa Viano WDB639813 2007-<br>Mercedesa Viano WDB639815 2007-                                                                                                              |  |  |

|               |                                                                                     |                                                                                     |                                                                                                                                                                                                                                                                                                                                                                                                             |                                                                          |                                  |
|---------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|----------------------------------|
| FCS-BS-849-10 | A6394900292<br>A6394900892<br>A6394901392                                           |    | Mercedes Vito 2.1 WDB639601 2007<br>Mercedes Vito 2.1 WDB639603 2007<br>Mercedes Vito 2.1 WDB639605 2007<br>Mercedes Vito 2.1 WDB639701 2007<br>Mercedes Vito 2.1 WDB639703 2007<br>Mercedes Vito 2.1 WDB639705 2007<br>Mercedes Vito 2.1 WDB639711 2007<br>Mercedes Vito 2.1 WDB639713 2007<br>Mercedes Viano 2.1 WDB639811 2007<br>Mercedes Viano 2.1 WDB639813 2007<br>Mercedes Viano 2.1 WDB639815 2007 |                                                                          |                                  |
| FCS-BS-850    | 642 140 08 09                                                                       |    | Exhaust Manifold, Right                                                                                                                                                                                                                                                                                                                                                                                     |                                                                          |                                  |
| FCS-BS-851    | 642 140 09 09                                                                       |    | Exhaust Manifold, Left                                                                                                                                                                                                                                                                                                                                                                                      |                                                                          |                                  |
| FCS-BS-852    | 901 490 30 19                                                                       |    | Exhaust Pipe With Muffler                                                                                                                                                                                                                                                                                                                                                                                   | SPRINTER                                                                 | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-853    | 6904907619<br>9014903319<br>9014903919<br>A6904907619<br>A9014903319<br>A9014903919 |    | Exhaust Pipe                                                                                                                                                                                                                                                                                                                                                                                                | SPRINTER                                                                 | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-854    | 901 490 40 21                                                                       |  | Exhaust Pipe                                                                                                                                                                                                                                                                                                                                                                                                | SPRINTER                                                                 | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-855    | 901 492 00 44                                                                       |  | Suspension Ring To Exhaust                                                                                                                                                                                                                                                                                                                                                                                  | SPRINTER 208<br>212;213 CDI<br>312;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-856    | 002 470 68 94                                                                       |  | AdBlue Delivery Pump -<br>(2010 - up)                                                                                                                                                                                                                                                                                                                                                                       |                                                                          |                                  |
| FCS-BS-857    | 906 501 05 03                                                                       |  | Expansion Tank                                                                                                                                                                                                                                                                                                                                                                                              | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI             | W 906                            |
| FCS-BS-857-1  | A9065010015                                                                         |  | Tank Cap                                                                                                                                                                                                                                                                                                                                                                                                    |                                                                          |                                  |
| FCS-BS-857-2  | 2205450024                                                                          |  | Sensor                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                          |                                  |
| FCS-BS-858    | 668 503 630                                                                         |  | Water Tank                                                                                                                                                                                                                                                                                                                                                                                                  | MB 100                                                                   |                                  |


|            |                                                                                              |                                                                                     |                                     |                                                                                                                      |                                  |
|------------|----------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-859 | 220 540 00 45                                                                                |     | Expansion Tank Level Control Switch | PKW                                                                                                                  | W 636<br>W 639<br>W 900<br>W 906 |
| FCS-BS-860 | 638 869 00 08                                                                                |    | Kettle Cap                          |                                                                                                                      |                                  |
| FCS-BS-861 | 638 500 22 01                                                                                |    | Radiator                            | VITO 108<br>110<br>112<br>113 CDI                                                                                    | W 638                            |
| FCS-BS-862 | 638 835 01 70                                                                                |    | Condenser, Air Conditioning         | VITO 108<br>110<br>112<br>113 CDI                                                                                    | W 638                            |
| FCS-BS-863 | 638 501 29 01                                                                                |    | Intercooler                         | VITO 108<br>110<br>112<br>113 CDI                                                                                    | W 638                            |
| FCS-BS-864 | 639 501 02 01                                                                                |    | Intercooler                         | VITO 109<br>111<br>115 CDI                                                                                           | W 639                            |
| FCS-BS-865 | 639 501 04 01                                                                                |   | Radiator                            | VITO 109<br>111<br>115 CDI                                                                                           | W 639                            |
| FCS-BS-866 | 639 835 00 70                                                                                |  | Condenser, Air Conditioning         | VITO 109<br>111<br>115 CDI                                                                                           | W 639                            |
| FCS-BS-867 | 901 500 31 00<br>901 500 33 00<br>901 500 24 00                                              |  | Radiator (MT)                       | SPRINTER 208<br>210;212;214<br>308;310;312<br>314;408;410<br>412                                                     | W 901<br>W 902<br>W 903          |
| FCS-BS-868 | 901 500 34 00                                                                                |  | Radiator (AT)                       | SPRINTER 208 CDI<br>211 CDI<br>313 CDI<br>413 CDI<br>416 CDI                                                         | W 901- W 904                     |
| FCS-BS-869 | 901 500 35 00                                                                                |  | Radiator                            | SPRINTER 208 CDI<br>211 CDI;213 CDI;216 CDI<br>308 CDI;311 CDI;313 CDI<br>316 CDI;408 CDI;411 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-870 | 901 500 05 54                                                                                |  | Condenser, Air Conditioning         | SPRINTER 208<br>212;216 CDI<br>312;316 CDI<br>408;411 CDI                                                            | W 901-905                        |
| FCS-BS-871 | 901 501 07 01<br>901 501 10 01<br>510 411 9AA<br>511 999 7AA<br>96842<br>BTKI<br>IC4401-1303 |  | Intercooler                         | SPRINTER 210<br>212;208 CDI<br>213 CDI;216 CDI<br>412;413 CDI<br>416 CDI                                             | W 901<br>W 902<br>W 903<br>W 904 |




|            |                                          |                                                                                     |                 |                                                                       |                                                  |
|------------|------------------------------------------|-------------------------------------------------------------------------------------|-----------------|-----------------------------------------------------------------------|--------------------------------------------------|
| FCS-BS-872 | 901 500 18 00                            |     | Radiator        | SPRINTER 208<br>308                                                   | OM 601<br>W 901<br>W 902                         |
| FCS-BS-873 | 906 500 01 02                            |    | Radiator        | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318 ,515;518 CDI               | W 906                                            |
| FCS-BS-874 | 906 500 02 02                            |    | Radiator        | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 906                                            |
| FCS-BS-875 | 906 500 03 02                            |    | Radiator        | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 906                                            |
| FCS-BS-876 | 906 500 04 02<br>906 500 14 02<br>67157A |    | Radiator        | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 906                                            |
| FCS-BS-877 | 906 500 12 02                            |    | Radiator        | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 906                                            |
| FCS-BS-878 | 906 501 01 01                            |   | Intercooler     | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 906                                            |
| FCS-BS-879 | 906 501 02 01                            |  | Intercooler     | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI          | W 639                                            |
| FCS-BS-880 | 124 500 04 06                            |  | Radiator Cap    | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI<br>416 CDI          | W 124<br>W 638<br>W 901-905                      |
| FCS-BS-881 | 611 203 04 82                            |  | Radiator Hose   | SPRINTER 208 CDI<br>213 CDI<br>214 CDI<br>313 CDI<br>413 CDI,VITO 639 | OM 611;OM 612<br>OM 646;OM 647<br>W 901<br>W 905 |
| FCS-BS-882 | 611 203 05 82                            |  | Brake Hose,Rear | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>413 CDI                     | OM 611<br>OM 612<br>OM 647<br>W 901<br>W 905     |
| FCS-BS-883 | 638 501 12 82                            |  | Radiator Hose   | VITO 108<br>110<br>112<br>113 CDI                                     | W 638                                            |
| FCS-BS-884 | 638 501 14 82                            |  | Radiator Hose   | VITO 108<br>110<br>112<br>113 CDI                                     | W 638                                            |
| FCS-BS-885 | 638 501 15 82                            |  | Radiator Hose   | VITO 108<br>110<br>112<br>113 CDI                                     | W 638                                            |

|            |               |                                                                                     |                                |                                                                   |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------------------------|----------------------------------|
| FCS-BS-886 | 638 501 19 82 |     | Radiator Hose                  | VITO 108<br>110<br>112<br>113 CDI                                 | W 638                            |
| FCS-BS-887 | 646 203 02 82 |    | Radiator Hose                  | SPRINTER 311<br>315<br>318<br>515<br>518                          | W 906                            |
| FCS-BS-888 | 901 501 11 82 |    | Radiator Hose                  | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-889 | 901 501 15 82 |    | Radiator Hose                  | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-890 | 906 428 08 35 |    | Radiator Hose                  | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-891 | 906 500 00 54 |    | Condenser                      |                                                                   |                                  |
| FCS-BS-892 | 003 835 61 01 |   | Heater Exchanger               |                                                                   |                                  |
| FCS-BS-893 | 901 501 25 82 |  | Radiator Hose                  | SPRINTER 208 CDI<br>211 CDI<br>313 CDI<br>413 CDI<br>416 CDI      | W 901-W 905                      |
| FCS-BS-894 | 901 501 26 82 |  | Radiator Hose                  | SPRINTER 208 CDI<br>211 CDI<br>313 CDI<br>413 CDI<br>416 CDI      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-895 | 901 501 27 82 |  | Radiator Hose                  | SPRINTER 210 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906                            |
| FCS-BS-896 | 901 501 30 82 |  | Hose From Turbo To Intercooler | SPRINTER 308 CDI<br>408 CDI<br>311 CDI<br>416 CDI                 | W 903<br>W 904                   |
| FCS-BS-897 | 901 501 31 82 |  | Hose From Turbo To Intercooler | SPRINTER 308 CDI<br>408 CDI<br>311 CDI<br>416 CDI                 | W 904                            |
| FCS-BS-898 | 901 832 29 23 |  | Radiator Hose                  | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI      | OM 611<br>W 901-904              |
| FCS-BS-899 | 906 501 01 82 |  | Radiator Hose                  | SPRINTER 209<br>215;309<br>315;511<br>515                         | OM 642<br>OM 646<br>W 906        |

|            |               |                                                                                     |                      |                                                                   |                           |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------|-------------------------------------------------------------------|---------------------------|
| FCS-BS-900 | 906 501 04 82 |     | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |
| FCS-BS-901 | 906 501 05 82 |    | Radiator Hose,Top    | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |
| FCS-BS-902 | 906 501 06 82 |    | Radiator Hose        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI |                           |
| FCS-BS-903 | 906 501 07 82 |    | Radiator Hose,Tank   | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>OM 646<br>W 906 |
| FCS-BS-904 | 906 501 08 82 |    | Radiator Hose,Tank   | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 611<br>OM 646<br>W 906 |
| FCS-BS-905 | 906 501 14 82 |    | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 651<br>W 906           |
| FCS-BS-906 | 906 501 20 82 |   | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 651<br>W 906           |
| FCS-BS-907 | 906 501 21 82 |  | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 651<br>W 906           |
| FCS-BS-908 | 906 501 23 82 |  | Radiator Hose,Tank   | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |
| FCS-BS-909 | 906 501 24 82 |  | Radiator Hose        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI |                           |
| FCS-BS-910 | 906 501 29 82 |  | Radiator Hose,Top    | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 651<br>W 906           |
| FCS-BS-911 | 906 501 32 82 |  | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |
| FCS-BS-912 | 906 501 33 82 |  | Radiator Hose,Bottom | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |
| FCS-BS-913 | 906 501 35 82 |  | Radiator Hose,Top    | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906           |

|            |                                |                                                                                     |                                |                                                                    |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|--------------------------------|--------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-914 | 906 501 36 82                  |     | Radiator Hose, Bottom          | SPRINTER 209 CDI<br>218 CDI; 309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906                           |
| FCS-BS-915 | 906 501 37 82                  |    | Radiator Hose, Bottom          | SPRINTER 209 CDI<br>218 CDI; 309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906                           |
| FCS-BS-916 | 906 501 38 82                  |    | Radiator Hose, Tank            | SPRINTER 209 CDI<br>218 CDI; 309 CDI<br>318<br>515<br>518 CDI      | OM 642<br>W 906                           |
| FCS-BS-917 | 906 501 44 82                  |    | Radiator Hose, Tank            | SPRINTER 209 CDI<br>218 CDI; 309 CDI<br>318<br>515<br>518 CDI      | OM 651<br>W 906                           |
| FCS-BS-918 | 638 528 10 82                  |    | Hose From Turbo To Intercooler | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                   | W 638                                     |
| FCS-BS-919 | 638 528 19 82                  |    | Hose To Intercooler            | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                   | W 638                                     |
| FCS-BS-920 | 638 528 26 82                  |   | Hose From Turbo To Intercooler | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                   | W 638                                     |
| FCS-BS-921 | 638 528 28 82                  |  | Turbocharger Intake Hose       | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                   | W 638                                     |
| FCS-BS-922 | 638 528 29 82                  |  | Hose From Turbo To Intercooler | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                   | W 638                                     |
| FCS-BS-923 | 639 528 30 82                  |  | Hose From Turbo To Intercooler | VITO<br>VIANO<br>108<br>111<br>115 CDI                             |                                           |
| FCS-BS-924 | 646 098 00 83                  |  | Hose From Turbo To Intercooler | SPRINTER 209 CDI<br>315 CDI; 511 CDI<br>VITO 108<br>111<br>115 CDI | OM 646<br>W 906                           |
| FCS-BS-925 | 901 528 18 82                  |  | Hose From Turbo To Intercooler | SPRINTER 312<br>412<br>413 CDI                                     | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-926 | 901 528 22 82                  |  | Hose On Intake, Manifold       | SPRINTER 312<br>316<br>412<br>413 CDI                              | W 901<br>W 902<br>W 903<br>W 904<br>W 905 |
| FCS-BS-927 | 901 528 39 82<br>901 528 47 82 |  | Turbocharger Intake Hose       | SPRINTER 208 CDI<br>313 CDI<br>413 CDI<br>416 CDI                  | W 901-904                                 |

|            |                                                                                   |                                                                                     |                                |                                                                   |                                  |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------------------------|----------------------------------|
| FCS-BS-928 | 901 528 43 82                                                                     |     | Hose From Turbo To Intercooler | SPRINTER 312<br>316<br>412<br>413 CDI                             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-929 | 901 528 47 82<br>901 528 47 82-1                                                  |    | Hose To Intercooler            | SPRINTER 308<br>311<br>313<br>413<br>414 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-930 | 901 528 53 82<br>051 201 47 AA                                                    |    | Air Intake Hose                | SPRINTER 208 CDI<br>313 CDI<br>413 CDI<br>416 CDI                 | W 901-904                        |
| FCS-BS-931 | 906 528 01 82<br>906 528 22 82<br>906 528 11 82<br>906 528 02 82<br>906 528 25 82 |    | Hose To Intercooler With Clamp | SPRINTER 210 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906                            |
| FCS-BS-932 | 906 528 01 82<br>906 528 22 82<br>906 528 11 82<br>906 528 02 82<br>906 528 25 82 |    | Hose To Intercooler With Clamp | SPRINTER 210 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906                            |
| FCS-BS-933 | 906 528 32 82                                                                     |    | Hose To Intercooler            | SPRINTER 210 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906                            |
| FCS-BS-934 | 906 528 33 82                                                                     |   | Hose To Intercooler            | SPRINTER 210 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906                            |
| FCS-BS-935 | 906 528 37 82                                                                     |  | Intercooler Hose               |                                                                   |                                  |
| FCS-BS-936 | 906 528 26 82                                                                     |  | Right Intercooler Hose         |                                                                   |                                  |
| FCS-BS-937 | 906 528 37 82                                                                     |  | Intercooler Hose               |                                                                   |                                  |
| FCS-BS-938 | 901 503 01 01                                                                     |  | Protective Grille              |                                                                   |                                  |
| FCS-BS-939 | 000 500 71 93<br>000 500 70 93                                                    |  | Blower,Air Conditioner         | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI      | W 901-905                        |
| FCS-BS-940 | 906 906 02 00                                                                     |  | Blower,Air Conditioner         | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI      | W 906                            |
| FCS-BS-941 | 220 830 00 83                                                                     |  | Dryer ,Air Conditioning        | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413,CDI<br>616 CDI      | W 901-904                        |

|            |                                   |                                                                                     |                                       |                                                                                                      |                                  |
|------------|-----------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|------------------------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-942 | 123 504 02 46                     |     | Support, Cooling Fan                  | SPRINTER 208 CDI<br>211 CDI<br>313 CDI<br>413 CDI<br>416 CDI                                         | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-943 | 901 505 06 55                     |    | Radiator Fan Shroud                   | SPRINTER 212<br>312<br>412                                                                           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-944 | 901 505 16 55                     |    | Radiator Fan Shroud                   | SPRINTER 208<br>210;212;214;<br>208 CDI;211 CDI;213 CDI;<br>216 CDI;308;310<br>308 CDI311 CDI313 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-945 | 906 505 08 55                     |    | Radiator Fan Shroud                   | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI                                         | W 906                            |
| FCS-BS-946 | 906 505 09 55                     |    | Fan Cover                             |                                                                                                      |                                  |
| FCS-BS-947 |                                   |    | Fan Collection Cover                  |                                                                                                      |                                  |
| FCS-BS-948 | 901 505 09 88                     |   | Radiator Backplate                    |                                                                                                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-949 | 901 505 10 88<br>901 505 11 88 LH |  | Radiator Backplate                    |                                                                                                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-950 | 901 505 12 88<br>901 505 13 88 RH |  | Radiator Backplate                    |                                                                                                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-951 | 901 505 14 88                     |  | Radiator Backplate                    |                                                                                                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-952 | 906 528 37 82<br>906 528 15 82    |  | Water Pipe                            |                                                                                                      |                                  |
| FCS-BS-953 | 000 905 06 00                     |  | Coolant Temp. Sensor<br>(for gauge) - |                                                                                                      |                                  |
| FCS-BS-954 | 001 540 30 45                     |  | Temperature Switch                    | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                                     | W 638                            |
| FCS-BS-955 | 000 542 51 18                     |  | Temperature Gauge Switch              | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>318 CDI;413 CDI<br>518 CDI;519 CDI                            | OM 611<br>OM 612<br>OM 647       |



|            |                                                                                                                                           |                                                                                     |                                     |                                                                                  |                                                              |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------------------|--------------------------------------------------------------|
| FCS-BS-956 | 005 542 10 17                                                                                                                             |     | Sender Unit,<br>Coolant Temperature |                                                                                  | OM 601;OM 602<br>OM 603;W 112<br>W 601;W 661                 |
| FCS-BS-957 | 000 542 62 18<br>005 153 23 28<br>005 153 63 28                                                                                           |    | Coolant Temperature Sensor          | SPRINTER 212<br>312;412;313<br>316;413;416                                       | OM 602;OM 611<br>OM 642;OM 111<br>W 901;W 902<br>W 903;W 904 |
| FCS-BS-958 | 004 545 26 14                                                                                                                             |    | Oil Pressure Switch                 | SPRINTER 208<br>212;308<br>312;408<br>412                                        | OM 601.942<br>OM 601.943<br>OM 602.986                       |
| FCS-BS-959 | 008 542 56 17                                                                                                                             |    | Water Temperature Sensor            |                                                                                  |                                                              |
| FCS-BS-960 | 002 542 25 17                                                                                                                             |    | Coolant Temperature Sensor          |                                                                                  |                                                              |
| FCS-BS-961 | 011 542 51 17                                                                                                                             |    | Coolant Temperature Sensor          |                                                                                  |                                                              |
| FCS-BS-962 | 000 545 69 09                                                                                                                             |   | Stop Light Sensor                   |                                                                                  |                                                              |
| FCS-BS-963 | 001 540 49 45<br>000 540 75 45<br>A001 540 49 45                                                                                          |  | Steering Column Switch              | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                                                        |
| FCS-BS-964 | 0015404645<br>A0015404645<br>0015404845<br>A0015404845<br>CBS1261<br>05103745AA<br>5103745AA<br>IS7755<br>SW5290<br>SM417                 |  | Steering Column Switch              | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904                             |
| FCS-BS-965 | 001 540 47 45<br>A001 540 47 45<br>051 035 39 AC<br>051 035 39 AA<br>051 035 39 AB<br>901 540 01 45<br>A901 540 01 45<br>SW5289<br>IS7754 |  | Steering Column Switch              | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904                             |
| FCS-BS-966 | 639 545 01 24                                                                                                                             |  | Steering Column Switch              | VITO<br>VIANO<br>108<br>111<br>115 CDI                                           | W 639                                                        |
| FCS-BS-967 | 906 545 02 10                                                                                                                             |  | Steering Column Switch              | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                                        |

|              |                                              |                                                                                     |                        |                                                                                |                                      |
|--------------|----------------------------------------------|-------------------------------------------------------------------------------------|------------------------|--------------------------------------------------------------------------------|--------------------------------------|
| FCS-BS-968   | 906 545 03 10<br>2E0953513C                  |     | Steering Column Switch | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI              | W 906                                |
| FCS-BS-969   | 000 545 79 09                                |    | Brake Light Switch     | SPRINTER 208<br>210;212;214<br>208 CDI<br>211 CDI<br>213 CDI                   | W 314<br>W 316                       |
| FCS-BS-970   | 001 545 01 09                                |    | Brake Light Switch     | PKW<br>VITO                                                                    | W 638                                |
| FCS-BS-971   | 000 545 98 09                                |    | Brake Light Switch     | SPRINTER 212<br>312<br>412<br>VARIO<br>LT 28-46                                | W 901-904<br>W 667<br>W 669<br>W 670 |
| FCS-BS-972   | 001 545 20 09<br>001 545 38 09               |    | Brake Light Switch     | SPRINTER 208<br>209;311<br>313;315<br>515 CDI                                  | W 638<br>W 639<br>W 901-905          |
| FCS-BS-973   | 001 545 33 09                                |    | Gear Switch            | SPRINTER 208<br>213 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI                  | W901<br>W902<br>W903<br>W904         |
| FCS-BS-974   | 001 545 44 09<br>001 545 67 09               |   | Brake Light Switch     | SPRINTER 208<br>209;311;313;315<br>515 CDI<br>VIANO                            | W 639<br>W 906                       |
| FCS-BS-975   | 001 545 63 09                                |  | Brake Light Switch     | SPRINTER 208<br>209;311;313;315<br>515 CDI<br>VIANO                            | W 639<br>W 906                       |
| FCS-BS-976-1 | 000 540 74 45<br>A000 540 74 45<br>2D0953503 |  | Steering Column Switch | SPRINTER<br>(W901-905)<br>95-07<br>VITO/VIANO<br>(W638)96-03<br>VW LT II 97-06 |                                      |
| FCS-BS-977   | 906 462 01 30                                |  | Steering Lock-         |                                                                                |                                      |
| FCS-BS-978   | 001 545 64 09                                |  | Brake Light Switch     | SPRINTER 208<br>211<br>311<br>313<br>413 CDI                                   | W 901-905                            |
| FCS-BS-979   | 000 545 50 11                                |  | Switch,reverse Light   |                                                                                | W 601<br>W 602<br>W 611              |
| FCS-BS-980   | 000 545 21 14                                |  | Stoplight Switch       | SPRINTER 311<br>313<br>413<br>414<br>416 CDI                                   | W 901<br>W 902<br>W 903<br>W 904     |
| FCS-BS-981   | 004 545 27 14                                |  | Buck Up Gear Switch    | SPRINTER 210<br>212;310;312<br>410;412                                         | W 901<br>W 902<br>W 903<br>W 904     |

|            |                                |                                                                                     |                                                                |                                                           |                                                              |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------------------------------------------------|--------------------------------------------------------------|
| FCS-BS-982 | 001 540 04 17                  |     | Lambda Sensor,Front                                            |                                                           | OM 104;M 111;M 112<br>M 113;W 638;W 901<br>W 902;W 903;W 904 |
| FCS-BS-983 | 000 540 75 17                  |    | Lambda Sensor,Rear                                             |                                                           | OM 104;M 111;M 112<br>M 113;W 638;W 901<br>W 902;W 903;W 904 |
| FCS-BS-984 | 000 540 76 17                  |    | Lambda Sensor,Rear                                             |                                                           | OM 104;M 111;M 112<br>M 113;W 638;W 901<br>W 902;W 903;W 904 |
| FCS-BS-985 | 000 540 92 17                  |    | Lambda Sensor,Front                                            |                                                           | OM 104;M 111;M 112<br>M 113;W 638;W 901<br>W 902;W 903;W 904 |
| FCS-BS-986 | 003 542 70 18                  |    | Lambda Sensor,Front,R                                          |                                                           | OM 272<br>W 636<br>W 639<br>W 900<br>W 906                   |
| FCS-BS-987 | 003 542 71 18                  |    | Lambda Sensor,Front,L                                          |                                                           | OM 272<br>W 636<br>W 639<br>W 900<br>W 906                   |
| FCS-BS-988 | 006 542 49 18                  |   | Lambda Sensor,Front                                            |                                                           | OM 640<br>OM 642<br>OM 651<br>W 639<br>W 906                 |
| FCS-BS-989 | 010 542 57 17                  |  | Sender Unit,<br>Coolant Temperature                            | SPRINTER 212<br>312<br>412                                | W 901<br>W 902<br>W 903<br>W 904                             |
| FCS-BS-990 | 000 542 28 18<br>651 153 00 28 |  | Sender Unit,<br>intake Air Temperature                         | SPRINTER 208<br>312;313;315<br>412;413 CDI<br>515;518 CDI | W 638;W 639<br>W 901;W 902<br>W 903;W 904<br>W 906           |
| FCS-BS-991 | 006 153 20 28                  |  | Sender Unit,<br>Intake Air Temperature                         |                                                           | W 461<br>W 906                                               |
| FCS-BS-992 | 007 542 13 18                  |  | Exterior Temperature Sensor                                    | SPRINTER 209 CDI<br>315 CDI<br>515 CDI<br>VIANO<br>TRUCK  | W 636<br>W 639<br>W 900<br>W 906<br>W 963                    |
| FCS-BS-993 | 906 540 15 17                  |  | Brake Pad Sensors<br>- 2 front/2 rear all models<br>(2007- up) |                                                           |                                                              |
| FCS-BS-994 | 000 905 35 03                  |  | NOX Sensor (front & rear<br>same)<br>- VIN Specific            |                                                           |                                                              |
| FCS-BS-995 | 129 545 02 24                  |  | Sensor,Coolant Level                                           | SPRINTER 208<br>VITO;PKW<br>312;313;412<br>413 CDI        |                                                              |

|             |                                                                                   |                                                                                     |                                  |                                                                                  |                                                 |
|-------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------|
| FCS-BS-996  | 220 545 00 24                                                                     |     | Sensor,Coolant Level             |                                                                                  |                                                 |
| FCS-BS-997  | 004 153 30 28<br>006 153 97 28<br>026 123 01 89<br>005 153 50 28<br>004 153 32 28 |    | Sensor,Boost Pressure            | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI                     | OM 629<br>W 639                                 |
| FCS-BS-998  | 004 153 31 28<br>006 153 14 28<br>004 153 33 28<br>005 153 72 28<br>006 153 98 28 |    | Sensor,Boost Pressure            | SPRINTER 208 CDI<br>213 CDI;308 CDI;313 CDI<br>316 CDI;413 CDI;416 CDI           | M 111;M 112;M 113<br>OM 646;OM 647<br>OM 660    |
| FCS-BS-999  | 006 153 16 28<br>007 153 00 28<br>026 123 04 39                                   |    | Sensor,Boost Pressure            | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI                     | OM 646<br>OM 651<br>W 639                       |
| FCS-BS-1000 | 006 153 99 28<br>006 153 15 28<br>004 153 84 28<br>680 660 40 AA<br>026 123 01 93 |    | Sensor,Boost Pressure            | SPRINTER 209 CDI<br>218 CDI;309 CDI<br>318<br>515<br>518 CDI                     | OM 629;OM 639<br>OM 640;OM 642<br>OM 646;W 639  |
| FCS-BS-1001 | 011 542 07 17                                                                     |    | Sensor,Boost Pressure            | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>313 CDI;316 CDI<br>413 CDI;416 CDI        | OM 601;OM 602<br>OM 603;OM 604<br>OM 605;OM 606 |
| FCS-BS-1002 | 000 545 54 14                                                                     |   | Pressure Switch                  | TRUCK<br>BUS                                                                     | W 310<br>W 313<br>W 684                         |
| FCS-BS-1003 | 001 545 47 14                                                                     |  | Pressure Switch                  | TRUCK<br>BUS                                                                     | W 903<br>W 904                                  |
| FCS-BS-1004 | 003 545 16 14                                                                     |  | Pressure Switch                  | SPRINTER 212<br>312<br>412                                                       | W 670<br>W 901-904                              |
| FCS-BS-1005 | 638 542 02 17                                                                     |  | Wheel Speed Sensor,Front         | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 903<br>W 904                                  |
| FCS-BS-1006 | 901 542 11 17                                                                     |  | Wheel Speed Sensor,Rear          | SPRINTER 208<br>210;212;312<br>412;208 CDI<br>313 CDI;316 CDI<br>413 CDI;416 CDI | W 901-905                                       |
| FCS-BS-1007 | 901 542 17 17                                                                     |  | Wheel Speed Sensor,Front         | SPRINTER 208<br>210;212<br>312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI         | W 901-905                                       |
| FCS-BS-1008 | 906 540 01 17                                                                     |  | Wheel Speed Sensor,Front         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                           |
| FCS-BS-1009 | 906 540 02 17                                                                     |  | Wheel Speed Sensor,Rear<br>Right | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                           |

|             |                                                |                                                                                     |                                          |                                                                                  |                                                  |
|-------------|------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|----------------------------------------------------------------------------------|--------------------------------------------------|
| FCS-BS-1010 | 906 540 03 17                                  |     | Wheel Speed Sensor,Front                 | SPRINTER 209 CDI<br>215 CDI;309 CDI;315 CDI<br>511 CDI;515 CDI                   | W 906                                            |
| FCS-BS-1011 | 906 540 11 17                                  |    | Wheel Speed Sensor,Rear Left             | SPRINTER 209 CDI<br>215 CDI;309 CDI;315 CDI<br>511 CDI;515 CDI                   | W 906                                            |
| FCS-BS-1012 | 906 540 12 17                                  |    | Wheel Speed Sensor,Rear<br>Right         | SPRINTER 209 CDI<br>215 CDI;309 CDI;315 CDI<br>511 CDI;515 CDI                   | W 906                                            |
| FCS-BS-1013 | 906 540 41 17                                  |    | Wheel Speed Sensor,Rear Left             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                            |
| FCS-BS-1014 | 906 540 42 17                                  |    | Wheel Speed Sensor,Rear<br>Right         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                            |
| FCS-BS-1015 | 906 540 43 17                                  |    | Wheel Speed Sensor,Rear Left             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                            |
| FCS-BS-1016 | 906 540 44 17                                  |   | Wheel Speed Sensor,Rear<br>Right         | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                            |
| FCS-BS-1017 | 006 545 10 14                                  |  | Switch<br>clutch Control(engine Control) | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 638<br>W 639<br>W 901-906                      |
| FCS-BS-1018 | 646 153 65 79<br>000 545 35 16                 |  | Relay,Glow Plug System<br>(4Pins)        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | OM 611<br>OM 646<br>W 638<br>W 639<br>W 901-906  |
| FCS-BS-1019 | 000 545 36 16<br>648 900 00 00<br>680 793 72AA |  | Relay,Glow Plug System<br>(6Pins)        | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | OM 611<br>OM 6646<br>W 638<br>W 639<br>W 901-906 |
| FCS-BS-1020 | 651 900 09 00                                  |  | Relay,Glow Plug System                   | SPRINTER 209 CDI<br>313 CDI<br>315 CD<br>515 CDI<br>VIANO                        | OM 651<br>W 639<br>W 900<br>W 906                |
| FCS-BS-1021 | 004 545 29 05                                  |  | Relay,Main Current 12V                   | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 638<br>W 639<br>W 901-906                      |
| FCS-BS-1022 | 002 542 74 19                                  |  | Relay,Main Current                       | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 636<br>W 638<br>W 639<br>W 901-906             |
| FCS-BS-1023 | 002 454 18 32                                  |  | Ignition Switch                          | PKW<br>MB 601<br>602<br>611<br>677                                               | W 601<br>W 602<br>W 611<br>W 667                 |

|             |                                                                      |                                                                                     |                                           |                                                                                  |           |
|-------------|----------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------|----------------------------------------------------------------------------------|-----------|
| FCS-BS-1024 | 000 545 49 06                                                        |     | Relay,Immobilizer                         | PKW<br>VAN                                                                       | W 667     |
| FCS-BS-1025 | 638 720 00 46                                                        |    | Window Winder,L                           | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                 | W 638     |
| FCS-BS-1026 | 638 720 01 46                                                        |    | Window Winder,R                           | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                                 | W 638     |
| FCS-BS-1027 | 639 720 00 46                                                        |    | Window Regulator,L                        | VIANO 108<br>VITO 111<br>115                                                     | W 639     |
| FCS-BS-1028 | 639 720 01 46                                                        |    | Window Regulator,R                        | VIANO 108<br>VITO 111<br>115                                                     | W 639     |
| FCS-BS-1029 | 639 720 04 46                                                        |    | Window Winder,L                           | VIANO 108<br>VITO 111<br>115                                                     | W 639     |
| FCS-BS-1030 | 004 545 27 14                                                        |   | Window Winder,R                           | VIANO 108<br>VITO 111<br>115                                                     | W 639     |
| FCS-BS-1031 | 901 720 20 46/<br>901 720 2 46RH<br>901 720 19 46/<br>901 720 1 46LH |  | Window Regulator Electric<br>(with Motor) |                                                                                  |           |
| FCS-BS-1032 | 901 720 15 46                                                        |  | Window Winder,R                           | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901-905 |
| FCS-BS-1033 | 901 720 14 46                                                        |  | Window Winder,L                           | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901-905 |
| FCS-BS-1034 | 906 720 00 46                                                        |  | Window Winder,L                           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906     |
| FCS-BS-1035 | 906 720 01 46                                                        |  | Window Winder,R                           | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906     |
| FCS-BS-1036 | 901 720 10 16                                                        |  | Door Catch,Left                           | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901-905 |
| FCS-BS-1037 | 901 720 11 16                                                        |  | Door Catch,Right                          | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901-905 |



|             |               |                                                                                     |                        |                                                                                  |                                           |
|-------------|---------------|-------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-1038 | 906 720 03 16 |     | Door Catch             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 900<br>W 906                            |
| FCS-BS-1039 | 901 740 08 37 |    | Door Hinge,L&R         | SPRINTER 208<br>210;212;308<br>312;412;413                                       | W 901-904                                 |
| FCS-BS-1040 | 906 740 00 37 |    | Door Hinge,Top Left    | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1041 | 906 740 01 37 |    | Door Hinge,Top Right   | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1042 | 906 740 02 37 |    | Door Hinge,Lower Left  | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1043 | 007 542 13 18 |    | Door Hinge,Lower Right | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1044 | 906 740 04 37 |   | Door Hinge,Top Left    | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1045 | 906 740 05 37 |  | Door Hinge,Top Right   | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>516 CDI                                | W 906                                     |
| FCS-BS-1046 | 906 740 06 37 |  | Door Hinge,Lower Left  | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1047 | 906 740 07 37 |  | Door Hinge,Lower Right | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1048 | 906 760 04 28 |  | Door Hinge, Top R + L  |                                                                                  |                                           |
| FCS-BS-1049 | 906 760 02 28 |  | Door Catch             | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1050 | 906 760 03 28 |  | Door Catch             | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 906                                     |
| FCS-BS-1051 | 901 720 04 31 |  | Latch To Lock          | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |

|             |                                  |                                                                                     |                                        |                                                                   |       |
|-------------|----------------------------------|-------------------------------------------------------------------------------------|----------------------------------------|-------------------------------------------------------------------|-------|
| FCS-BS-1052 | A 204 880 00 60                  |     | Lock Striker For<br>Mercedes Benz W204 |                                                                   |       |
| FCS-BS-1053 | 906 720 00 04                    |    | Latch To Lock                          | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 906 |
| FCS-BS-1054 | A204 880 00 64                   |    | Lock Striker                           |                                                                   |       |
| FCS-BS-1055 | A212 880 00 64                   |    | Lock Striker                           |                                                                   |       |
| FCS-BS-1056 | A21288800060                     |    | Lock Striker                           |                                                                   |       |
| FCS-BS-1057 | A 000 720 13 35                  |    | Lock Striker - LH                      |                                                                   |       |
| FCS-BS-1058 | A 000 720 12 35<br>688 720 73 35 |   | Lock Striker                           |                                                                   |       |
| FCS-BS-1059 | A204 880 04 60                   |  | Lock Striker                           |                                                                   |       |
| FCS-BS-1060 | A906 740 00 32                   |  | Lock Striker -Back Door                |                                                                   |       |
| FCS-BS-1061 | 906 720 00 04                    |  | Lock Striker -Back Door                |                                                                   |       |
| FCS-BS-1062 |                                  |  | Lock Striker                           |                                                                   |       |
| FCS-BS-1063 |                                  |  | Lock Striker                           |                                                                   |       |
| FCS-BS-1064 | 639 760 05 28                    |  | Rear Door Checker                      |                                                                   |       |
| FCS-BS-1065 | 000 723 05 03                    |  | Lock Striker                           |                                                                   |       |

|             |                                               |                                                                                     |                                   |                                                                                  |                                  |
|-------------|-----------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1066 | 901 720 10 35                                 |     | Side Door Slide Mechanism,Left    | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CD  | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1067 | 901 720 11 35                                 |    | Side Door Slide Mechanism,Right   | SPRINTER 208<br>210;212;214<br>208 CDI;308;310                                   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1068 | 901 730 19 35                                 |    | Right side Sliding Door Door Lock | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1069 | 901 730 10 35                                 |    | Door Lock,Sliding Door Left       | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 638<br>W 901-904               |
| FCS-BS-1070 | 901 730 11 35                                 |    | Door Lock,Sliding Door Right      | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1071 | 901 730 13 35<br>901 730 19 35                |    | Side Door Slide Mechanism,Right   | SPRINTER 208<br>308<br>312<br>412                                                | W 901<br>W 902<br>W 904          |
| FCS-BS-1072 | 906 730 04 35                                 |   | Side Door Slide Mechanism,Left    | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 900<br>W 906                   |
| FCS-BS-1073 | 906 730 13 35                                 |  | Door Lock,sliding Door,top Right  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 900<br>W 906                   |
| FCS-BS-1074 | 051 043 68 AA<br>2D1 827 505<br>901 740 01 35 |  | Engine Cover Lock                 |                                                                                  |                                  |
| FCS-BS-1075 | A 000 720 28 35                               |  | Inside Door Lock - LH             |                                                                                  |                                  |
| FCS-BS-1076 | A000 720 29 35                                |  | Inside Door Lock - RH             |                                                                                  |                                  |
| FCS-BS-1077 | 906 730 35 35                                 |  | Door Lock,sliding Door,top Left   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 900<br>W 906                   |
| FCS-BS-1078 | 906 730 43 35<br>906 730 03 35                |  | Door Lock,Sliding Door Right      | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 900<br>W 906                   |
| FCS-BS-1079 | 906 740 00 35                                 |  | Door Lock,Rear,Top&Bottom         | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                                | W 900<br>W 906                   |

|             |                                    |                                                                                     |                            |                                                                   |                    |
|-------------|------------------------------------|-------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------|--------------------|
| FCS-BS-1080 | 906 740 11 35                      |     | Door Lock,Rear,Top         | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                 | W 900<br>W 906     |
| FCS-BS-1081 | 906 740 12 35                      |    | Door Lock,Rear,Left Bottom | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                 | W 900<br>W 906     |
| FCS-BS-1082 | 906 740 00 88                      |    | Door Lock,Rear Left        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 900<br>W 906     |
| FCS-BS-1083 | 906 740 01 88                      |    | Door Lock,Rear Left        | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 900<br>W 906     |
| FCS-BS-1084 | 906 740 08 35                      |    | Door Lock,Rear             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 900<br>W 906     |
| FCS-BS-1085 | 906 740 09 35                      |    | Door Lock,Rear             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 900<br>W 906     |
| FCS-BS-1086 | 906 740 10 35                      |   | Door Lock,Rear             | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                 | W 900<br>W 906     |
| FCS-BS-1087 | 906 760 01 77                      |  | Locking Know Guide         | SPRINTER 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI                 | W 900<br>W 906     |
| FCS-BS-1088 | 901 766 00 62                      |  | Door Hinge                 | SPRINTER 208<br>210;212;308<br>312;412;413                        | W 638<br>W 901-906 |
| FCS-BS-1089 | 901 766 01 61                      |  | Door Hinge                 | SPRINTER 208<br>210;212;308<br>312;412;413                        | W 638<br>W 901-906 |
| FCS-BS-1090 | 638 760 08 47                      |  | Sliding Door Roller Guide  | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                  | W 638              |
| FCS-BS-1091 | 638 740 12 47                      |  | Sliding Door Roller Guide  | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                  | W 638              |
| FCS-BS-1092 | 638 760 18 47RH<br>638 760 19 47LH |  | Sliding Door Roller Guide  | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                  | W 638              |
| FCS-BS-1093 | 639 760 01 47<br>639 760 13 47     |  | Sliding Door Roller Guide  | VIANO 109<br>VITO 111<br>115                                      | W 639              |

|             |                                |                                                                                     |                                                         |                                                                                    |                                  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1094 | 639 760 15 47                  |     | Sliding Door Roller Guide                               | VIANO 109<br>VITO 111<br>115                                                       | W 639                            |
| FCS-BS-1095 | 639 760 17 47                  |    | Door Hinge                                              | VIANO 109<br>VITO 111<br>115                                                       | W 639                            |
| FCS-BS-1096 | 901 760 01 28                  |    | Side Door Slide Mechanism<br>Lower                      | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1097 | 901 760 01 28-1                |    | Side Door Slide Mechanism<br>Lower                      | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1098 | 901 760 10 47                  |    | Side Door Slide Mechanism<br>Upper                      | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1099 | 901 760 13 47                  |    | Side Door Slide<br>Mechanism Intermediate               | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI   | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1100 | 906 760 01 47<br>906 760 00 47 |   | Side Door Slide Mechanism<br>Upper                      | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1101 | 906 760 03 47                  |  | Side Door Slide<br>Mechanism Intermediate               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1102 | 906 760 05 47                  |  | Sliding Door Roller Guide                               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1103 | A 639 760 25 47                |  | Door Slide Roller - Middle                              |                                                                                    |                                  |
| FCS-BS-1104 | 2E1 843 398                    |  | Vw Cafter 30-35 Bus 2006<br>Lower Door Slide Mechanism  |                                                                                    |                                  |
| FCS-BS-1105 | 2E1 843 336                    |  | Vw Cafter 30-35 Bus 2006<br>Middle Door Slide Mechanism |                                                                                    |                                  |
| FCS-BS-1106 | 2E1 843 436                    |  | Vw Cafter 30-35 Bus 2006<br>Upper Door Roller Assy      |                                                                                    |                                  |
| FCS-BS-1107 | 901 720 00 66                  |  | Interior Door Handle,L                                  | SPRINTER 208<br>308<br>312<br>412                                                  | W 901<br>W 902<br>W 903<br>W 904 |

|             |                                                                                   |                                                                                     |                                    |                                                                                  |                                           |
|-------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BS-1108 | 901 720 01 66                                                                     |     | Interior Door Handle,R             | SPRINTER 208<br>308<br>312<br>412                                                | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-1109 | 901 743 01 72                                                                     |    | Handle Interior Rear Door          | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 904                   |
| FCS-BS-1110 | 901 760 03 02                                                                     |    | Window Handle Opener               | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 904                   |
| FCS-BS-1111 | 670 760 02 05<br>901 462 01 79<br>000 462 01 79<br>670 890 63 67<br>051 339 10 AA |    | Lock Cylinder                      | SPRINTER<br>VITO<br>609<br>1317                                                  | W 638<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1112 | 000 760 13 59                                                                     |    | Door Handle                        | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 638;W 901<br>W 902;W 903<br>W 904;W 905 |
| FCS-BS-1113 | 901 760 04 59                                                                     |    | Door Handle                        | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-1114 | 901 760 13 61                                                                     |   | Interior Handle Assembly Side Door | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904          |
| FCS-BS-1115 | 906 760 00 70                                                                     |  | Door Handle,Front                  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                     |
| FCS-BS-1116 | 906 760 01 70                                                                     |  | Door Handle,Rear                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 906                                     |
| FCS-BS-1117 |                                                                                   |  | Door Handle Chromed Cover          | VITO<br>VIANO                                                                    |                                           |
| FCS-BS-1118 |                                                                                   |  | Door Handle Chromed Cover          | VITO<br>VIANO                                                                    |                                           |
| FCS-BS-1119 |                                                                                   |  | Door Handle Chromed Cover          | VITO<br>VIANO                                                                    |                                           |
| FCS-BS-1120 |                                                                                   |  | Chromed Cover                      | VITO<br>VIANO                                                                    |                                           |
| FCS-BS-1121 |                                                                                   |  | Door Handle Chromed Cover          | VITO<br>VIANO                                                                    |                                           |



|             |                                    |                                                                                     |                                |               |  |
|-------------|------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|---------------|--|
| FCS-BS-1122 |                                    |     | Decoration Cover Rim           | VITO<br>VIANO |  |
| FCS-BS-1123 |                                    |    | Decoration Cover Rim           | VITO<br>VIANO |  |
| FCS-BS-1124 |                                    |    | Decoration Cover Rim           | VITO<br>VIANO |  |
| FCS-BS-1125 |                                    |    | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1126 |                                    |    | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1127 |                                    |    | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1128 |                                    |  | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1129 |                                    |  | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1130 |                                    |  | Door Handle Chromed Cover      | VITO<br>VIANO |  |
| FCS-BS-1131 |                                    |  | Door Handle Chromed Cover      | SPRINTER      |  |
| FCS-BS-1132 | A000 760 02 61                     |  | Interior Handle Assembly -Left |               |  |
| FCS-BS-1133 | A 673 720 00 75<br>A 673 723 00 09 |  | Door Handle                    |               |  |
| FCS-BS-1134 | 673 723 00 46<br>673 723 00 83     |  | Door Hanlde Components         |               |  |
| FCS-BS-1135 | A 601 760 18 47                    |  | Door Slide Mechanism           |               |  |

|             |                                           |                                                                                     |                      |                                                                                  |                                     |
|-------------|-------------------------------------------|-------------------------------------------------------------------------------------|----------------------|----------------------------------------------------------------------------------|-------------------------------------|
| FCS-BS-1136 |                                           |     | Door Handle          | SPRINTER                                                                         |                                     |
| FCS-BS-1137 |                                           |    | Door Track End       | SPRINTER                                                                         |                                     |
| FCS-BS-1138 | 639 747 01 87                             |    | Inside Door Handle   | SPRINTER                                                                         |                                     |
| FCS-BS-1139 | 638 760 04 04                             |    | Pull Cable,Side Door | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                               |
| FCS-BS-1140 | 901 760 01 04                             |    | Pull Cable,Side Door | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901;W 902<br>W 903;W 904<br>W 690 |
| FCS-BS-1141 | 901 760 05 04                             |    | Pull Cable,Side Door | SPRINTER 208<br>210;212<br>308;312<br>412;413<br>416                             | W 901-905                           |
| FCS-BS-1142 | 901 760 07 04                             |   | Pull Cable,Side Door | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                                     | W 904                               |
| FCS-BS-1143 | 639 750 01 59                             |  | Hood Opener Cable    | VITO 109<br>111<br>115 CDI                                                       | W 639                               |
| FCS-BS-1144 | 63667500004<br>63667540034<br>A6397500304 |  | Fuel Tank Cover      | VITO<br>VIANO                                                                    |                                     |
| FCS-BS-1145 | 639 760 07 59                             |  | Rear Trunk Handle    | VITO<br>VIANO                                                                    |                                     |
| FCS-BS-1146 | 901 750 03 59                             |  | Hood Opener Cable    | SPRINTER 208<br>308<br>312<br>412                                                | W 901<br>W 902<br>W 903<br>W 904    |
| FCS-BS-1147 | 906 880 00 59                             |  | Hood Opener Cable    | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI                | W 901<br>W 902<br>W 903<br>W 904    |
| FCS-BS-1148 | 901 833 00 31                             |  | Heating Wire Cable   | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                                     | W 901<br>W 902<br>W 903<br>W 904    |
| FCS-BS-1149 | 901 760 02 28                             |  | Bracket              | SPRINTER 208<br>311<br>312<br>313 CDI                                            | W 901<br>W 902<br>W 903<br>W 904    |

|             |                                     |                                                                                     |                                 |                                                                                  |                                  |
|-------------|-------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|----------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1150 | 906 750 03 50                       |     | Engine Hood Catch               |                                                                                  |                                  |
| FCS-BS-1151 | A 901 750 02 84                     |    | Hood Lock Latch                 |                                                                                  |                                  |
| FCS-BS-1152 | 906 750 04 50                       |    | Engine Hood Catch               |                                                                                  |                                  |
| FCS-BS-1153 | 901 760 04 28<br>901 760 05 28      |    | Door Catch                      | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1154 | 901 766 01 19                       |    | Rear Door Lower Plate           | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1155 | 901 766 02 19                       |    | Rear Door Upper Plate           | SPRINTER 208<br>210;212;312;412<br>208 CDI;313 CDI<br>316 CDI;413 CDI<br>416 CDI | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1156 | 638 810 00 16                       |   | Outside Mirror, manual, Left    | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                            |
| FCS-BS-1157 | 638 810 01 16                       |  | Outside Mirror, Manual, Right   | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                            |
| FCS-BS-1158 | 638 810 06 16                       |  | Outside Mirror, Electric, Left  | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                            |
| FCS-BS-1159 | 638 810 07 16                       |  | Outside Mirror, Electric, Right | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                 | W 638                            |
| FCS-BS-1160 | 639 810 07 19RH<br>639 810 06 19 LH |  | Rearview Mirror                 | VITO 2012                                                                        |                                  |
| FCS-BS-1161 |                                     |  | Mirror Cover Chromed            | VITO 2012                                                                        |                                  |
| FCS-BS-1162 | 639 810 07 16 LH<br>639 810 91 16RH |  | Rearview Mirror                 | VITO 2012                                                                        |                                  |
| FCS-BS-1163 | 639 810 05 16                       |  | Outside Mirror, Left            | VITO 2008<br>111<br>115 CDI                                                      | W 639                            |

|             |                                    |                                                                                     |                                    |                                                   |                                  |
|-------------|------------------------------------|-------------------------------------------------------------------------------------|------------------------------------|---------------------------------------------------|----------------------------------|
| FCS-BS-1164 | 639 810 06 16                      |     | Outside Mirror,Right               | VITO 2008<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-1165 | 639 810 45 16                      |    | Outside Mirror,electric,Left       | VITO 2008<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-1166 | 639 810 46 16                      |    | Outside Mirror,Electric,right      | VITO 2008<br>111<br>115 CDI                       | W 639                            |
| FCS-BS-1167 | 230 820 07 21                      |    | Mirror Indicator                   | VIANO 2008                                        |                                  |
| FCS-BS-1168 | 901 810 55 16<br>901 810 01 16 LH  |    | Outside Mirror,Left                | SPRINTER 208<br>308<br>312<br>412<br>413 CDI      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1169 | 901 810 64 16<br>901 810 02 16 RH  |    | Outside Mirror,Right               | SPRINTER 208<br>308<br>312<br>412<br>413 CDI      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1170 | 901 810 57 16<br>901 810 09 16 LH  |   | Outside Mirror,Electric,Left       | SPRINTER 209 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-904                        |
| FCS-BS-1171 | 901 810 66 16<br>901 810 10 16 RH  |  | Outside Mirror,Electric,Right      | SPRINTER 209 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-904                        |
| FCS-BS-1172 | 001 811 04 33                      |  | Outside Mirror Glass,Straight<br>R | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-905                        |
| FCS-BS-1173 | 001 811 05 33                      |  | Outside Mirror Glass,straight L    | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-905                        |
| FCS-BS-1174 | 001 811 51 33                      |  | Outside Mirror Glass,Curved L      | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-905                        |
| FCS-BS-1175 | 001 811 52 33                      |  | Outside Mirror Glass,curved L      | SPRINTER 208 CDI<br>213 CDI<br>313 CDI<br>416 CDI | W 901-905                        |
| FCS-BS-1176 |                                    |  | Mirror Chromed Cover               |                                                   |                                  |
| FCS-BS-1177 | 906 810 19 93RH<br>906 810 18 93LH |  | Rearview Mirror                    |                                                   |                                  |

|             |                                                                      |                                                                                     |                   |  |  |
|-------------|----------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------|--|--|
| FCS-BS-1178 | 906 810 61 16RH<br>906 810 60 16LH                                   |     | Rearview Mirror   |  |  |
| FCS-BS-1179 | 906 810 51 16<br>906 810 20 93RH<br>906 810 50 16<br>906 810 21 93LH |    | Rearview Mirror   |  |  |
| FCS-BS-1180 | 906 810 62 16RH<br>906 810 63 16LH                                   |    | Rearview Mirror   |  |  |
| FCS-BS-1181 | 906 810 23 93RH<br>906 810 22 93LH                                   |    | Rearview Mirror   |  |  |
| FCS-BS-1182 | 906 810 65 16RH<br>906 810 64 16LH                                   |    | Rearview Mirror   |  |  |
| FCS-BS-1183 | 906 810 24 93RH<br>906 810 25 93LH                                   |    | Rearview Mirror   |  |  |
| FCS-BS-1184 | 906 810 66 16RH<br>906 810 67 16LH                                   |   | Rearview Mirror   |  |  |
| FCS-BS-1185 | 906 810 33 93RH<br>906 810 32 93LH                                   |  | Rearview Mirror   |  |  |
| FCS-BS-1186 |                                                                      |  | Rearview Mirror   |  |  |
| FCS-BS-1187 |                                                                      |  | Rearview Mirror   |  |  |
| FCS-BS-1188 |                                                                      |  | Rearview Mirror   |  |  |
| FCS-BS-1189 | 901 008 000 17                                                       |  | Rearview Mirror   |  |  |
| FCS-BS-1190 |                                                                      |  | Mirror Cover      |  |  |
| FCS-BS-1191 | 901 811 01 07LH<br>901 811 02 07RH                                   |  | Mirror Cover Trim |  |  |


|             |                                                                      |                                                                                     |                       |                                                                    |       |
|-------------|----------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------|-------|
| FCS-BS-1192 | 906 811 01 07RH<br>906 810 01 07LH                                   |     | Mirror Trim           |                                                                    |       |
| FCS-BS-1193 | 002 811 53 33RH<br>002 811 52 33LH                                   |    | Big Glass Unit        |                                                                    |       |
| FCS-BS-1194 | 002 811 40 33RH<br>002 811 39 33LH                                   |    | Small Glass Unit      |                                                                    |       |
| FCS-BS-1195 | 002 811 16 33<br>002 811 18 33RH<br>002 811 15 33<br>002 811 17 33LH |    | Big Glass Unit        |                                                                    |       |
| FCS-BS-1196 | 002 811 20 33RH<br>002 811 19 33LH                                   |    | Small Glass Unit      |                                                                    |       |
| FCS-BS-1197 |                                                                      |    | Mirror Cover          |                                                                    |       |
| FCS-BS-1198 |                                                                      |   | Chromed Mirror Cover  |                                                                    |       |
| FCS-BS-1199 |                                                                      |  | Mirror Frame          |                                                                    |       |
| FCS-BS-1200 |                                                                      |  | Mirror Cover          |                                                                    |       |
| FCS-BS-1201 |                                                                      |  | Chromed Mirror Cover  |                                                                    |       |
| FCS-BS-1202 | 001 822 89 20 LH                                                     |  | Mirror Lamp,L         | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....) | W 906 |
| FCS-BS-1203 | 001 822 90 20                                                        |  | Mirror Lamp,R         | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....) | W 906 |
| FCS-BS-1204 | 000 820 12 77                                                        |  | Mirror Indicator Bulb | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....) | W 906 |
| FCS-BS-1205 | 661 810 56 16 LH                                                     |  | Mirror Assy           | MB100                                                              |       |



|             |                                                                    |                                                                                                                                                                        |                          |                                                                                                  |                                  |
|-------------|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1206 | 661 810 55 16 RH                                                   |                                                                                        | Mirror Assy              | MB100                                                                                            |                                  |
| FCS-BS-1207 | 901 820 01 01                                                      |                                                                                       | Interior Lamp            | SPRINTER 208<br>212;213;312<br>313;412;413                                                       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1208 | 639 820 02 56<br>2E0943021A                                        |                                                                                       | Licence Plate Lamp       | VITO 109<br>111<br>115 CDI                                                                       | W 636<br>W 639<br>W 906          |
| FCS-BS-1209 | 901 820 01 56                                                      | <br> | Licence Plate Lamp       | SPRINTER 208<br>311;312;313<br>412;413;416                                                       | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1210 | 639 545 13 13<br>A639 545 13 13                                    |                                                                                       | Switch window lift VIANO | VITO<br>VIANO                                                                                    | W 639                            |
| FCS-BS-1211 | 639 545 09 13<br>639 545 01 13<br>A639 545 09 13<br>A639 545 01 13 |                                                                                       | Switch, Window Lift      | VITO<br>VIANO                                                                                    | W 639                            |
| FCS-BS-1212 | 906 545 12 13<br>A906 545 12 13                                    |                                                                                      | Switch, Window Lift      | SPRINTER<br>VITO<br>609<br>1317                                                                  | W 906                            |
| FCS-BS-1213 | 906 545 19 13<br>906 545 15 16<br>906 545 09 13<br>680 423 84 AA   |                                                                                     | Window Adjuster Switch   | SPRINTER                                                                                         | W906                             |
| FCS-BS-1214 | 906 545 05 13<br>906 545 15 13<br>A906 545 05 13<br>A906 545 15 13 |                                                                                     | Window Adjuster Switch   | SPRINTER                                                                                         | W906                             |
| FCS-BS-1215 | 906 545 15 13<br>906 545 05 13<br>A906 545 15 13<br>A906 545 05 13 |                                                                                     | Window Adjuster Switch   | VW CRAFTER                                                                                       |                                  |
| FCS-BS-1216 | 906 545 02 13<br>A906 545 02 13                                    |                                                                                     | Window Adjuster Switch   | SPRINTER                                                                                         |                                  |
| FCS-BS-1217 | 901 671 02 20<br>901 671 00 20<br>5560G242<br>5427ASMV             |                                                                                     | Windscreen Seal          | SPRINTER 208<br>212;211 CDI<br>216 CDI;308 CDI;316 CDI<br>410;408 CDI;411 CDI<br>413 CDI;416 CDI | W 901-905                        |
| FCS-BS-1218 | 906 545 05 04                                                      |                                                                                     | Head Lamp Switch         | SPRINTER                                                                                         |                                  |
| FCS-BS-1219 | 901 820 00 44                                                      |                                                                                     | Wiper Arm, Left          | SPRINTER 208<br>210;212;308<br>312;408;410<br>412                                                | W 901<br>W 902<br>W 903<br>W 904 |

|             |                                                                                     |                                                                                     |                                |                                                                                    |                                               |
|-------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|------------------------------------------------------------------------------------|-----------------------------------------------|
| FCS-BS-1220 | 901 820 01 44                                                                       |     | Wiper Arm,Right                | SPRINTER 208<br>210;212;308<br>312;408;410<br>412                                  | W 901<br>W 902<br>W 903<br>W 904              |
| FCS-BS-1221 | 906 820 06 44<br>001 820 59 44                                                      |    | Wiper Arm,Windscreen<br>Washer |                                                                                    | W 906                                         |
| FCS-BS-1222 | 906 820 07 44<br>001 820 61 44                                                      |    | Wiper Arm,Windscreen<br>Washer |                                                                                    | W 906                                         |
| FCS-BS-1223 | 001 820 39 45                                                                       |    | Wiper Blade                    |                                                                                    |                                               |
| FCS-BS-1224 | A 901 820 00 81<br>339 702 03 83                                                    |    | Wiper Linkage                  |                                                                                    |                                               |
| FCS-BS-1225 | 039 024 13 45<br>039 024 13 04                                                      |    | Wiper Motor                    |                                                                                    |                                               |
| FCS-BS-1226 | 001 810 40 45                                                                       |   | Wiper Blade                    |                                                                                    |                                               |
| FCS-BS-1227 | 906 820 00 45                                                                       |  | Front Wiper Blade Set (pair)   |                                                                                    |                                               |
| FCS-BS-1228 | 000 860 33 26                                                                       |  | Water Pump,Window<br>Cleaning  | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI                                  | W 601<br>W 602<br>W 611<br>W 638<br>W 901-905 |
| FCS-BS-1229 | 000 860 58 26                                                                       |  | Water Pump,Window<br>Cleaning  | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>VIANO                                    | W 906                                         |
| FCS-BS-1230 | 210 869 08 21<br>210 869 09 21<br>221 869 01 21<br>671 283 621 54<br>671 283 776 12 |  | Water Pump>window Cleaning     | SPRINTER<br>VITO<br>VIANO                                                          | W 639                                         |
| FCS-BS-1231 | 001 830 56 08                                                                       |  | Blower Motor                   | SPRINTER 208<br>308<br>312<br>412<br>413 CDI                                       |                                               |
| FCS-BS-1232 | 002 830 15 08                                                                       |  | Blower Motor                   | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                                         |
| FCS-BS-1233 | 000 835 60 07                                                                       |  | Blower Motor                   | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                                         |

|             |                                                                  |                                                                                     |                                          |                                                                                    |                                            |
|-------------|------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------|
| FCS-BS-1234 | 000 835 61 07                                                    |     | Blower Motor                             |                                                                                    |                                            |
| FCS-BS-1235 | (638)00283016 08<br>003 830 03 08                                |    | Vito V-Class                             |                                                                                    |                                            |
| FCS-BS-1236 | (638)0028301508<br>698217<br>34596<br>0148990032<br>01489900328  |    | Vito V-Class                             |                                                                                    |                                            |
| FCS-BS-1237 | 901 832 01 23                                                    |    | Hose From Heater                         | SPRINTER 213 CDI<br>313 CDI<br>408 CDI<br>616 CDI                                  | W 901<br>W 902<br>W 903<br>W 904<br>W 905  |
| FCS-BS-1238 | 901 832 34 23<br>901 832 51 23<br>901 832 59 23<br>901 832 67 23 |    | Heating Hoses<br>Cab Heating,Ventilation | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI                       | W 901<br>W 902<br>W 903<br>W 904<br>W 905  |
| FCS-BS-1239 | 901 832 37 23                                                    |    | Heater Hose                              | SPRINTER 208<br>213<br>313<br>411<br>413 CDI                                       | W 901<br>W 902<br>W 903<br>W 904           |
| FCS-BS-1240 | 901 832 39 23<br>901 832 78 23                                   |   | Heating Hoses<br>Cab Heating,Ventilation | SPRINTER 208 CDI<br>213 CDI;313 CDI<br>408 CDI;411 CDI<br>413 CDI                  | W 901<br>W 902<br>W 903<br>W 904           |
| FCS-BS-1241 | 901 832 41 23<br>901 832 61 23                                   |  | Heating Hoses<br>Cab Heating,Ventilation | SPRINTER 308 CDI<br>311 CDI<br>313 CDI<br>316 CDI                                  | W 901<br>W 902<br>W 903<br>W 904<br>W 905  |
| FCS-BS-1242 | 001 821 13 60                                                    |  | Resistance                               | SPRINTER 208 CDI<br>211 CDI<br>308 CDI<br>313 CDI<br>413 CDI                       | OM 611<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1243 | 001 821 25 60                                                    |  | Pre-Resistor,Blower                      | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                                      |
| FCS-BS-1244 | 001 821 67 60                                                    |  | Resistance                               | SPRINTER 208<br>210;212;308<br>312;408;410<br>412                                  | OM 611<br>W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1245 | 000 821 29 92<br>2E0 820 521                                     |  | Pre-Resistor,Blower                      | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CD<br>,515 CDI<br>(01.06-.....) | W 906                                      |
| FCS-BS-1246 | 000 870 00 89                                                    |  | Pre-Resistor,Blower                      | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI                       | W 901-904                                  |
| FCS-BS-1247 | 002 830 84 84                                                    |  | Control Valve,Coolant                    | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI                       | W 901-905                                  |

|             |                                                                    |                                                                                     |                                       |                                                                                    |                         |
|-------------|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|------------------------------------------------------------------------------------|-------------------------|
| FCS-BS-1248 | 001 835 13 64                                                      |     | Water Pump<br>Independent Car Hearing | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI                       | W 638<br>W 901-904      |
| FCS-BS-1249 | 001 835 30 47                                                      |    | Interior Air Cabin Filter             | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-1250 | 639 835 02 47                                                      |    | Interior Air Cabin Filter             | VITO 109<br>111<br>115 CDI                                                         | W 639                   |
| FCS-BS-1251 | 9018300418<br>000-8303318<br>9018300018<br>2D0819638<br>2D0819638A |    | Air filter                            |                                                                                    |                         |
| FCS-BS-1252 | 906 830 03 18<br>906 830 02 18<br>008 012 876 AA<br>068 012 876 AA |    | Interior Air Cabin Filter             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                   |
| FCS-BS-1253 | 000 820 16 66                                                      |    | Headlight Lens,L                      | SPRINTER 208<br>212;308;312;<br>408;412                                            | W 901<br>W 902<br>W 903 |
| FCS-BS-1254 | 000 820 17 66                                                      |   | Headlight Lens,R                      | SPRINTER 208<br>212;308;312<br>408;412                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1255 | 003 826 93 90                                                      |  | Head Lamp Glass,L                     | VITO 110 D<br>108 CDI<br>112 CDI                                                   | W 638                   |
| FCS-BS-1256 | 003 826 94 90                                                      |  | Head Lamp Glass,R                     | VITO 110 D<br>108 CDI<br>112 CDI                                                   | W 638                   |
| FCS-BS-1257 | 638 820 00 21                                                      |  | Corner Lamp,L                         | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-1258 | 638 820 01 21                                                      |  | Corner Lamp,R                         | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-1259 | 638 820 08 21                                                      |  | Corner Lamp,L                         | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-1260 | 638 820 09 21                                                      |  | Corner Lamp,R                         | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                   |
| FCS-BS-1261 | 210 820 04 21                                                      |  | Side Lamp,L&R                         | SPRINTER 208<br>210;208 CDI<br>211 CDI;311<br>312                                  | W 901<br>W 902<br>W 903 |

|             |                                                                                   |                                                                                     |                    |                                                                             |                                  |
|-------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------|-----------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1262 | 001 820 49 21<br>001 820 50 21                                                    |     | Side Lamp,L&R      | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI               | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1263 | 002 820 60 56<br>002 820 60 56                                                    |    | Exterior Lamp,Red  | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI               | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1264 | 022 139 5R3                                                                       |    | Reflector          | SPRINTER                                                                    |                                  |
| FCS-BS-1265 | 002 820 44 56                                                                     |    | Side Marker Lamp   | SPRINTER 208<br>212;213;312<br>313;412;413                                  | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1266 | 901 820 01 21                                                                     |    | Corner Lamp,L      | SPRINTER 208<br>210;212;308<br>312;408;410<br>412                           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1267 | 901 820 02 21                                                                     |    | Corner Lamp,R      | SPRINTER 208<br>210;212;308<br>312;408;410<br>412                           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1268 | 9018200121 LH<br>9018200221 RH                                                    |   | Corner Lamp        |                                                                             |                                  |
| FCS-BS-1269 | 9018200121 LH<br>9018200221 RH                                                    |  | Corner Lamp        |                                                                             |                                  |
| FCS-BS-1270 |                                                                                   |  | Corner Lamp Socket |                                                                             |                                  |
| FCS-BS-1271 | 6618203321 LH<br>6618203421 RH                                                    |  | Corner Lamp        |                                                                             |                                  |
| FCS-BS-1272 | 004 237 20 11<br>004.237-291(7751)<br>004.237-321(4033)<br>RED<br>001 820 92 56   |  | Warning Lamp       | VARIO 212<br>609;214;709;208CDI<br>711;211CDI;814;213CDI<br>210;SPRINTER208 | W 668<br>W 670<br>W 920<br>W 904 |
| FCS-BS-1273 | 004.237-301(7582)<br>004.237-311(4032)<br>WHITE<br>001 820 82 56<br>001 820 83 56 |  | Warning Lamp       | VARIO 212<br>609;214;709;208CDI<br>711;211CDI;814;213CDI<br>210;SPRINTER208 | W 668<br>W 670<br>W 920<br>W 904 |
| FCS-BS-1274 | 001 820 49 21<br>001 820 50 21                                                    |  | Side Lamp          |                                                                             |                                  |
| FCS-BS-1275 | 001 820 39 21<br>001 820 40 21                                                    |  | Side Lamp          |                                                                             |                                  |

|             |                                  |                                                                                     |                           |                                                                                    |                                  |
|-------------|----------------------------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1276 | 906 820 02 01                    |     | Interior Lamp With Switch |                                                                                    |                                  |
| FCS-BS-1277 | 906 820 01 01                    |    | Interior Lamp             |                                                                                    |                                  |
| FCS-BS-1278 | 002 820 64 56                    |    | Side Marker Lamp          | SPRINTER 208<br>213;311;312<br>313;412;413                                         | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1279 | 003 820 29 56                    |    | Side Marker Lamp          | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1280 | 906 820 14 56                    |    | LED Side Marker Lamp      |                                                                                    |                                  |
| FCS-BS-1281 | 901 637 02 40                    |    | Headlight Cover           | SPRINTER 212<br>312<br>412                                                         | W 901- 904                       |
| FCS-BS-1282 | 901 637 03 40                    |   | Headlight Cover           | SPRINTER 212<br>312<br>412                                                         | W 901- 904                       |
| FCS-BS-1283 | 638 820 00 61                    |  | Headlight,Left            | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-1284 | 638 820 01 61                    |  | Headlight,Right           | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-1285 | 639 820 01 61                    |  | Headlight,Left            | VITO 109<br>111<br>115 CDI                                                         | W 639                            |
| FCS-BS-1286 | 639 820 02 61                    |  | Headlight,Right           | VITO 109<br>111<br>115 CDI                                                         | W 639                            |
| FCS-BS-1287 |                                  |  | Head Lamp                 | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1288 | 6398201961 RH<br>6398201861 LH   |  | Head Lamp                 | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1289 | A6398202861 LH<br>A6398202961 RH |  | Head Lamp                 | VITO<br>VIANO                                                                      |                                  |



|             |                                          |                                                                                     |                            |                                            |                         |
|-------------|------------------------------------------|-------------------------------------------------------------------------------------|----------------------------|--------------------------------------------|-------------------------|
| FCS-BS-1290 | 639 820 00 21                            |     | Side Lamp                  | VITO<br>VIANO                              |                         |
| FCS-BS-1291 | 639 820 00 56<br>A639 626 00 14          |    | Rear High Lever Brake Lamp | VITO<br>VIANO                              |                         |
| FCS-BS-1292 | 639 826 04 40 RH<br>639 826 05 40 LH     |    | Rear Bumper Reflector      | VITO<br>VIANO                              |                         |
| FCS-BS-1293 | 661 820 74 61 LH<br>661 820 75 61 RH     |    | Head Lamp                  | MB 100                                     |                         |
| FCS-BS-1294 | 901 820 01 61                            |    | Headlight,L                | SPRINTER 208<br>212;308;310<br>312;408;412 | W 901<br>W 902<br>W 903 |
| FCS-BS-1295 | 901 820 02 61                            |    | Headlight,R                | SPRINTER 208<br>212;308;310<br>312;408;412 | W 901<br>W 902<br>W 903 |
| FCS-BS-1296 | 1EH 006 900-051 RH<br>1EH 006 900-061 LH |   | Head Lamp                  |                                            |                         |
| FCS-BS-1297 | 901 820 25 61 RH<br>901 820 24 61 LH     |  | Head Lamp Left Hand Drive  |                                            |                         |
| FCS-BS-1298 | 901 820 27 61 RH<br>901 820 26 61 LH     |  | Head Lamp Left Hand Drive  |                                            |                         |
| FCS-BS-1299 |                                          |  | Head Lamp Left Hand Drive  |                                            |                         |
| FCS-BS-1300 |                                          |  | Head Lamp Left Hand Drive  |                                            |                         |
| FCS-BS-1301 | 901 820 31 61 RH<br>901 820 30 61 LH     |  | Head Lamp Right Hand Drive |                                            |                         |
| FCS-BS-1302 | 901 820 29 61 RH<br>901 820 28 61 LH     |  | Head Lamp Right Hand Drive |                                            |                         |
| FCS-BS-1303 |                                          |  | Head Lamp Right Hand Drive |                                            |                         |

|             |                                      |                                                                                     |                            |  |  |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|----------------------------|--|--|
| FCS-BS-1304 |                                      |     | Head Lamp Right Hand Drive |  |  |
| FCS-BS-1305 | 901 820 10 61 LH<br>901 820 11 61 RH |    | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1306 | 901 820 14 61 RH<br>901 820 15 61 LH |    | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1307 |                                      |    | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1308 |                                      |    | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1309 | 901 820 13 61 RH<br>901 820 12 61 LH |    | Head Lamp Right Hand Drive |  |  |
| FCS-BS-1310 | 901 820 17 61 RH<br>901 820 16 61 LH |   | Head Lamp Right Hand Drive |  |  |
| FCS-BS-1311 |                                      |  | Head Lamp Right Hand Drive |  |  |
| FCS-BS-1312 |                                      |  | Head Lamp Right Hand Drive |  |  |
| FCS-BS-1313 | 906 820 01 61 LH<br>906 820 02 61 RH |  | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1314 | 906 820 05 61 RH<br>906 820 06 61 LH |  | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1315 |                                      |  | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1316 |                                      |  | Head Lamp Left Hand Drive  |  |  |
| FCS-BS-1317 | 906 820 04 61 RH<br>906 820 03 61 LH |  | Head Lamp Right Hand Drive |  |  |

|             |                                                                          |                                                                                     |                            |                                                  |                |
|-------------|--------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------|----------------|
| FCS-BS-1318 | 906 820 08 61 RH<br>906 820 07 61 LH                                     |     | Head Lamp Right Hand Drive |                                                  |                |
| FCS-BS-1319 |                                                                          |    | Head Lamp Right Hand Drive |                                                  |                |
| FCS-BS-1320 |                                                                          |    | Head Lamp Right Hand Drive |                                                  |                |
| FCS-BS-1321 | 906 820 09 61 RH<br>906 820 10 61 LH                                     |    | Head Lamp                  |                                                  |                |
| FCS-BS-1322 | 906 820 28 61<br>906 820 24 61 RH<br>906 820 29 61<br>906 820 23 61 LH   |    | Head Lamp                  |                                                  |                |
| FCS-BS-1323 | 906 820 32 61 RH<br>906 820 31 61 LH                                     |    | Head Lamp                  |                                                  |                |
| FCS-BS-1324 | 211 820 06 56/<br>906 820 09 56 RH<br>211 820 05 56/<br>906 820 08 56 LH |   | Fog Lamp                   |                                                  |                |
| FCS-BS-1325 | 906 820 41 61<br>906 820 39 61 RH<br>906 820 40 61<br>906 820 38 61 LH   |  | Fog Lamp                   |                                                  |                |
| FCS-BS-1326 | 638 820 12 64                                                            |  | Tail Lamp,L                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI | W 638          |
| FCS-BS-1327 | 638 820 17 64                                                            |  | Tail Lamp,R                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI | W 638          |
| FCS-BS-1328 | 638 820 14 64                                                            |  | Tail Lamp,L                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI |                |
| FCS-BS-1329 | 638 820 19 64                                                            |  | Tail Lamp,R                | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI |                |
| FCS-BS-1330 | 661 820 36 64 LH<br>661 820 37 64 RH                                     |  | Tail Lamp                  | MB100                                            |                |
| FCS-BS-1331 | 639 820 01 64                                                            |  | Tail Lamp,L                | VITO 109<br>111<br>115 CDI                       | W 636<br>W 639 |



|             |               |                                                                                     |                                     |                                                                                    |                                  |
|-------------|---------------|-------------------------------------------------------------------------------------|-------------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1332 | 639 820 02 64 |     | Tail Lamp,R                         | VITO 109<br>111<br>115 CDI                                                         | W 636<br>W 639                   |
| FCS-BS-1333 | 901 820 17 64 |    | Tail Lamp,L                         | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1334 | 901 820 18 64 |    | Tail Lamp,R                         | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1335 | 000 826 07 56 |    | Tail Lamp,L                         | SPRINTER 208<br>212;213;312<br>313;412;413                                         | W 906                            |
| FCS-BS-1336 | 000 826 08 56 |    | Tail Lamp,R                         | SPRINTER 208<br>212;213;312<br>313;412;413                                         | W 906                            |
| FCS-BS-1337 | 000 820 05 77 |    | Light Socket,L&R                    | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1338 | 000 811 19 10 |   | Decorative Light                    | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1339 |               |  | Tail Lamp Decoration Strip          | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1340 |               |  | Tail Lamp                           | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1341 | 000 826 20 56 |  | Combination Rearlight<br>lens,Left  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1342 | 000 826 21 56 |  | Combination Rearlight<br>lens,Right | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1343 | 906 820 04 64 |  | Tail Lamp,Left                      | SPRINTER 315 CDI                                                                   | W 906                            |
| FCS-BS-1344 | 906 820 17 64 |  | Tail Lamp,Right                     | SPRINTER 315 CDI                                                                   | W 906                            |
| FCS-BS-1345 | 906 826 00 40 |  | Reflector,L                         | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....)                 | W 906                            |

|             |                                      |                                                                                     |                       |                                                                                    |                                  |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1346 | 906 826 01 40                        |     | Reflector,R           | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....)                 | W 906                            |
| FCS-BS-1347 | 906 820 01 64                        |    | Tail Lamp,Left        | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....)                 | W 906                            |
| FCS-BS-1348 | 906 820 02 64                        |    | Tail Lamp,Right       | SPRINTER 209 CDI<br>315 CDI<br>511 CDI<br>515 CDI<br>(01.06-.....)                 | W 906                            |
| FCS-BS-1349 | 000 820 13 77                        |    | Light Socket,L&R      | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1350 | 002 544 08 03 RH                     |    | Tail Lamp             |                                                                                    |                                  |
| FCS-BS-1351 | 002 544 07 90 RH                     |    | Tail Lamp Lens        |                                                                                    |                                  |
| FCS-BS-1352 | 002 544 07 03 LH                     |   | Tail Lamp             |                                                                                    |                                  |
| FCS-BS-1353 | 002 544 06 90 LH                     |  | Tail Lamp Lens        |                                                                                    |                                  |
| FCS-BS-1354 | 002 544 55 03                        |  | Head Lamp Glass,Right | SPRINTER 208 CDI<br>211 CDI<br>308 CDI<br>313 CDI<br>413 CDI                       | W 901<br>W 902<br>W 903          |
| FCS-BS-1355 | 002 544 54 03                        |  | Side Lamp,Left        | SPRINTER 208 CDI<br>211 CDI<br>308 CDI<br>313 CDI<br>413 CDI                       | W 901<br>W 902<br>W 903          |
| FCS-BS-1356 | 002 544 47 90                        |  | Lens Rear Light       | SPRINTER<br>ATEGO                                                                  | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1357 | 639 630 46 07 RH<br>639 630 43 07 LH |  | Fender Viano          |                                                                                    |                                  |
| FCS-BS-1358 | 638 880 14 06                        |  | Fender,L              | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |
| FCS-BS-1359 | 638 880 15 06                        |  | Fender,R              | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638                            |

|             |                                |  |                      |                                                                                    |           |
|-------------|--------------------------------|--|----------------------|------------------------------------------------------------------------------------|-----------|
| FCS-BS-1360 | 639 630 51 07                  |  | Fender,L             | VITO 109<br>111<br>115 CDI                                                         | W 639     |
| FCS-BS-1361 | 639 630 52 07                  |  | Fender,R             | VITO 109<br>111<br>115 CDI                                                         | W 639     |
| FCS-BS-1362 | 901 630 69 07                  |  | Fender,L (2000-2005) | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>313 CDI;408 CDI<br>413 CDI                  | W 901-905 |
| FCS-BS-1363 | 901 630 70 07                  |  | Fender,R (2000-2005) | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>313 CDI;408 CDI<br>413 CDI                  | W 901-905 |
| FCS-BS-1364 | 901 637 46 01<br>901 637 30 01 |  | Fender,L (1995-1999) | SPRINTER 208<br>212<br>312                                                         | W 901-905 |
| FCS-BS-1365 | 901 637 47 01<br>901 637 31 01 |  | Fender,R (1995-1999) | SPRINTER 208<br>212<br>312                                                         | W 901-905 |
| FCS-BS-1366 | 906 637 77 19                  |  | Fender,Left          | SPRINTER 209 CDI<br>215 CDI;309 CDI;315 CDI<br>511 CDI;515 CDI<br>(01.06-.....)    | W 906     |
| FCS-BS-1367 | 906 637 78 19                  |  | Fender,Right         | SPRINTER 209 CDI<br>215 CDI;309 CDI;315 CDI<br>511 CDI;515 CDI<br>(01.06-.....)    | W 906     |
| FCS-BS-1368 | 901 750 02 02                  |  | Engine Hood          |                                                                                    |           |
| FCS-BS-1369 | 638 750 00 02                  |  | Engine Hood          | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI                                   | W 638     |
| FCS-BS-1370 | 639 750 05 02                  |  | Engine Hood          | VITO 109<br>111<br>115 CDI                                                         | W 639     |
| FCS-BS-1371 | 901 750 00 02                  |  | Engine Hood          | SPRINTER 208<br>212<br>312<br>412                                                  | W 901-904 |
| FCS-BS-1372 | 906 750 00 02                  |  | Engine Hood          | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906     |
| FCS-BS-1373 | 906 880 02 57                  |  | Engine Hood          |                                                                                    |           |



|             |                                      |                                                                                     |                            |                                                  |                                  |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------|----------------------------------|
| FCS-BS-1374 | 901 880 03 51<br>901 880 01 51       |     | Front Cowling              | SPRINTER 208<br>212<br>312<br>412                | W 901-904                        |
| FCS-BS-1375 | 901 524 08 25                        |    | Oil Pan Protect Cover      | SPRINTER 208<br>212<br>312<br>412                | W 901-905                        |
| FCS-BS-1376 | 124 880 03 20                        |    | Engine Hood Opener Handle  | PKW<br>VIANO                                     | W 639                            |
| FCS-BS-1377 | 901 988 00 25                        |    | Treenail                   | SPRINTER 208<br>311;312;313<br>412;413           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1378 | 000 991 50 71                        |    | Mounting Clip              |                                                  |                                  |
| FCS-BS-1379 | 661 500 30 61 LH<br>661 500 31 61 RH |    | Vent Pipe                  | MB100                                            |                                  |
| FCS-BS-1380 |                                      |   | Ashtray                    | MB100                                            |                                  |
| FCS-BS-1381 |                                      |  | Window Button              | MB100                                            |                                  |
| FCS-BS-1382 | 901 880 01 14<br>901 885 00 14       |  | Front Bumper Bracket       | SPRINTER 208<br>311;312;313<br>412;413           | W 901<br>W 902<br>W 903          |
| FCS-BS-1383 | 901 880 03 14                        |  | Rear Bumper Bracket,L      | SPRINTER 208<br>311;312;313<br>412;413           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1384 | 901 880 04 14                        |  | Rear Bumper Bracket,R      | SPRINTER 208<br>311;312;313<br>412;413           | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1385 | 638 880 05 70                        |  | Front Bumper               | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI | W 638                            |
| FCS-BS-1386 | 901 310 07 22                        |  | Front Bumper Reinforcement |                                                  |                                  |
| FCS-BS-1387 | 901 880 02 70                        |  | Front Bumper               | SPRINTER 208<br>312<br>412                       | W 901<br>W 902<br>W 903<br>W 904 |

|             |                                      |                                                                                     |                            |                                                                                    |                                  |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1388 | 901 880 06 70                        |     | Front Bumper               | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1389 | 901 880 08 70                        |    | Front Bumper               | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>313 CDI;408 CDI<br>413 CDI                  | W 901-904                        |
| FCS-BS-1390 | 906 880 01 70                        |    | Front Bumper               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1391 | 906 880 05 70                        |    | Front Bumper               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1392 | 906 880 07 70                        |    | Front Bumper               | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1393 | 906 885 00 11                        |    | Bumper Ventilation Grille  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1394 | 906 885 00 53                        |  | Bumper Ventilation Grille  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1395 | 901 727 07 28                        |  | Tow Cover                  |                                                                                    |                                  |
| FCS-BS-1396 | 900 836 01 18 RH<br>900 836 00 18 LH |  | Hood Grille                | SPRINTER                                                                           |                                  |
| FCS-BS-1397 |                                      |  | Chromed Hood Grille Strip  | SPRINTER                                                                           |                                  |
| FCS-BS-1398 | 906 885 00 75                        |  | License Plate              | SPRINTER                                                                           |                                  |
| FCS-BS-1399 | 000 885 00 24                        |  | Front Bumper Tow Cover     | SPRINTER                                                                           |                                  |
| FCS-BS-1400 | 906 885 00 11                        |  | Lower Bumper Grille        |                                                                                    |                                  |
| FCS-BS-1401 | 906 620 02 34                        |  | Front Bumper Reinforcement |                                                                                    |                                  |

|             |                                      |                                                                                     |                           |                                                                                    |                                  |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1402 | A 906 620 25 00                      |     | Cross Member              |                                                                                    |                                  |
| FCS-BS-1403 | 639 880 17 01                        |    | Front Bumper              |                                                                                    |                                  |
| FCS-BS-1404 | 661 880 57 70                        |    | Front Bumper              | MB100                                                                              |                                  |
| FCS-BS-1405 |                                      |    | Trailer Cover             | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1406 | 901 885 02 02                        |    | Rear Bumper               |                                                                                    |                                  |
| FCS-BS-1407 | 901 880 03 71                        |    | Rear Bumper,L             | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1408 | 901 880 04 71                        |   | Rear Bumper,R             | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1409 | 901 885 00 16<br>901 885 01 16       |  | Side Bumper Reinforcement |                                                                                    |                                  |
| FCS-BS-1410 | 901 880 05 71<br>901 885 01 02       |  | Rear Bumper Middle        | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>313 CDI;408 CDI<br>413 CDI                  | W 901-905                        |
| FCS-BS-1411 | 901 885 02 16                        |  | Rear Bumper Inner         |                                                                                    |                                  |
| FCS-BS-1412 | 906 880 01 71                        |  | Bumper                    | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1413 | 906 880 10 71                        |  | Rear Bumper,L             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1414 | 906 880 11 71                        |  | Rear Bumper,R             | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1415 | 601 885 02 03 LH<br>601 885 03 03 RH |  | Mb 207 Side Bumper        |                                                                                    |                                  |


|             |                                                 |                                                                                     |                        |                                                                                    |                         |
|-------------|-------------------------------------------------|-------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------------|-------------------------|
| FCS-BS-1416 | 670 880 02 72 LH<br>670 880 03 72 RH            |     | Rear Bumper Cover      |                                                                                    |                         |
| FCS-BS-1417 | 906 880 05 71<br>906 880 31 71<br>906 880 32 71 |    | Rear Center Bumper     |                                                                                    |                         |
| FCS-BS-1418 | 661 885 34 03 RH<br>661 885 35 03 LH            |    | Side Bumper            | MB100                                                                              |                         |
| FCS-BS-1419 | 901 882 01 05                                   |    | Splash Guard,L         | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1420 | 901 882 04 05                                   |    | Splash Guard,R         | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1421 | 901 882 01 14                                   |    | Splash Guard Bracket   | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1422 | 901 882 03 14                                   |   | Splash Guard Bracket,L | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1423 | 901 882 04 14                                   |  | Splash Guard Bracket,R | SPRINTER 208<br>311;312;313<br>412;413                                             | W 901<br>W 902<br>W 903 |
| FCS-BS-1424 | 904 882 01 14                                   |  | Bracket,L&R            | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI                      | W 904                   |
| FCS-BS-1425 | 904 882 01 05                                   |  | Splash Guard ,L        | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                   |
| FCS-BS-1426 | 904 882 02 05                                   |  | Splash Guard ,R        | SPRINTER 408<br>410;412<br>408 CDI;411 CDI<br>413 CDI;416 CDI<br>(02.96-05.06)     | W 904                   |
| FCS-BS-1427 | 906 882 00 04                                   |  | Mudflap,Mudguard,Left  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                   |
| FCS-BS-1428 | 906 882 01 04                                   |  | Mudflap,Mudguard,Right | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                   |
| FCS-BS-1429 | 906 882 06 04                                   |  | Mudflap,Mudguard,Left  | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                   |

|               |                                      |                                                                                     |                                   |                                                                                    |                                  |
|---------------|--------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1430   | 906 882 07 04                        |     | Mudflap,Mudguard,Right            | SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI<br>(01.06-.....) | W 906                            |
| FCS-BS-1431   | 906 882 03 04 RH<br>906 882 02 04 LH |    | Mudguard                          |                                                                                    |                                  |
| FCS-BS-1432   |                                      |    | Mudflap                           |                                                                                    |                                  |
| FCS-BS-1433   | B665 800 00                          |    | Front Mudflap Kit                 | VITO<br>VIANO<br>109<br>111<br>115                                                 | W 639                            |
| FCS-BS-1434   | B665 800 00 R                        |    | Front Mudflap Kit                 | VITO<br>VIANO<br>109<br>111<br>115                                                 | W 639                            |
| FCS-BS-1435   | B665 800 01                          |    | Front Mudflap Kit                 | VITO<br>VIANO<br>109<br>111<br>115                                                 | W 639                            |
| FCS-BS-1436   | B665 800 01 R                        |   | Front Mudflap Kit                 | VITO<br>VIANO<br>109<br>111<br>115                                                 | W 639                            |
| FCS-BS-1437   | 639 684 33 77 RH<br>639 684 32 77 LH |  | Inner Mudguard                    | VITO<br>VIANO                                                                      |                                  |
| FCS-BS-1438   | 906 882 10 14                        |  | Radiator Support Bracket,L        | SPRINTER 315 CDI<br>318 CDI<br>515 CDI<br>518 CDI                                  |                                  |
| FCS-BS-1439   | 906 882 11 14                        |  | Radiator Support Bracket,R        | SPRINTER 315 CDI<br>318 CDI<br>515 CDI<br>518 CDI                                  | W 638                            |
| FCS-BS-1440-A | 901 820 00 21                        |  | Exterior Lamp Rear White<br>Color | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1440-B | 901 820 00 21                        |  | Exterior Lamp Rear Amber<br>Color | SPRINTER 208<br>210;312<br>213 CDI;311 CDI<br>313 CDI;413 CDI                      | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1441   | 901 880 03 85                        |  | Grille                            | SPRINTER 208 CDI<br>213 CDI;308 CDI<br>413 CDI;616 CDI                             | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1442   | 901 888 01 73                        |  | Grille Case                       |                                                                                    |                                  |


|             |                                                 |                                                                                     |                      |                                                              |                |
|-------------|-------------------------------------------------|-------------------------------------------------------------------------------------|----------------------|--------------------------------------------------------------|----------------|
| FCS-BS-1443 | 901 817 00 16                                   |     | Grille Badge         |                                                              |                |
| FCS-BS-1444 | 901 810 00 18                                   |    | Badge For Hood       |                                                              |                |
| FCS-BS-1445 |                                                 |    | Grille Without Case  |                                                              |                |
| FCS-BS-1446 | 901 880 01 83                                   |    | Grille               |                                                              |                |
| FCS-BS-1447 | 901 830 02 18                                   |    | Bumper Grille        |                                                              |                |
| FCS-BS-1448 | 661 750 33 18                                   |    | Grille               | MB100                                                        |                |
| FCS-BS-1449 | 901 830 07 18                                   |  | Bumper Grille        |                                                              |                |
| FCS-BS-1450 | 901 817 49 14                                   |  | Grille Sticker       |                                                              |                |
| FCS-BS-1451 | 638 888 03 15                                   |  | Grille               | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI             | W 638          |
| FCS-BS-1452 | 901 880 01 03                                   |  | Front Panel          |                                                              |                |
| FCS-BS-1453 | 906 880 03 85                                   |  | Grille               | SPRINTER 208 CDI<br>213 CDI<br>308 CDI<br>413 CDI<br>616 CDI | W 900<br>W 906 |
| FCS-BS-1454 |                                                 |  | Grille Chromed Strip |                                                              |                |
| FCS-BS-1455 | 906 888 05 23<br>906 880 07 85<br>906 880 08 85 |  | Front Grille         |                                                              |                |
| FCS-BS-1456 |                                                 |  | Grille Chromed Strip |                                                              |                |



|             |                                                 |                                                                                     |                         |                                                                              |                                  |
|-------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------|------------------------------------------------------------------------------|----------------------------------|
| FCS-BS-1457 | 906 888 00 51                                   |     | Front Grille Frame      |                                                                              |                                  |
| FCS-BS-1458 | 906 880 00 03<br>906 880 02 03<br>906 880 06 03 |    | Radiator Support        |                                                                              |                                  |
| FCS-BS-1459 | 906 620 00 24<br>906 620 01 24                  |    | Front Grille Frame      |                                                                              |                                  |
| FCS-BS-1460 | 639 880 01 85                                   |    | Front Grille            | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1461 | 639 888 01 85                                   |    | Front Grille            | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1462 | 636 880 21 71                                   |    | Radiator Frame          | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1463 | 639 884 06 74<br>639 884 07 74                  |   | Upper Strip Of Bumper   | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1464 |                                                 |  | Front Grille            | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1465 |                                                 |  | Front Grille            | VITO<br>VIANO                                                                |                                  |
| FCS-BS-1466 | 014 997 51 46                                   |  | Seal Ring               | SPRINTER 311<br>315<br>318<br>515<br>518                                     | OM 651                           |
| FCS-BS-1467 | 014 997 25 46                                   |  | Seal Ring               | SPRINTER 311<br>315<br>318<br>515<br>518                                     | OM 651                           |
| FCS-BS-1468 | 602 997 00 46                                   |  | Seal Ring               |                                                                              |                                  |
| FCS-BS-1469 | 017 997 55 47                                   |  | Seal Ring               | SPRINTER 208<br>212;308;310;312<br>412;311 CDI<br>313 CDI;413 CDI;416 CDI    | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BS-1470 | 019 997 09 47                                   |  | Seal Ring To Front Axle | SPRINTER 208<br>212;308;310<br>312;412<br>311 CDI;313 CDI<br>413 CDI;416 CDI | W 901<br>W 902<br>W 903<br>W 904 |

|             |                 |                                                                                     |                                          |                                                                   |                                                |
|-------------|-----------------|-------------------------------------------------------------------------------------|------------------------------------------|-------------------------------------------------------------------|------------------------------------------------|
| FCS-BS-1471 | 004 990 28 12   |     | Screw                                    | SPRINTER 208 CDI<br>213 CDI;313 CDI;413 CDI<br>315;518            | OM 611<br>OM 612<br>OM 646<br>OM 647<br>OM 648 |
| FCS-BS-1472 | 611 150 06 94   |    | Control Swirl Covers<br>(induction Pipe) | SPRINTER 208 CDI<br>214 CDI;313 CDI<br>413 CDI;416 CDI<br>616 CDI | OM 611<br>OM 612                               |
| FCS-BS-1473 | 906 423 04 20   |    | Protective Plate                         |                                                                   |                                                |
| FCS-BS-1474 | 642 091 01 50   |    | Control Swirl Covers<br>(induction Pipe) |                                                                   | OM 642                                         |
| FCS-BS-1475 | 903 992 00 03   |    | Bearing,Manual Transmissoin              | SPRINTER 901-905                                                  | W 901<br>W 902<br>W 903<br>W 904<br>W 905      |
| FCS-BS-1476 | 000 545 81 08   |    | Ignition Starter Switch                  |                                                                   |                                                |
| FCS-BS-1477 | A 901 460 01 04 |   | Steering Lock Ignition Lock              |                                                                   |                                                |
| FCS-BS-1478 | A 000 421 45 06 |  | Brake Anchor                             |                                                                   |                                                |
| FCS-BS-1479 | 906 670 05 01   |  | Front Window                             |                                                                   |                                                |
| FCS-BS-1480 | 901 680 06 14   |  | Paper Clip                               |                                                                   |                                                |
| FCS-BS-1481 | 901 689 28 08   |  | Dashboard Cover                          |                                                                   |                                                |
| FCS-BS-1482 | 901 680 16 07   |  | Dashboard Vent                           |                                                                   |                                                |
| FCS-BS-1483 | 901 689 02 91   |  | Dashboard Panel                          |                                                                   |                                                |
| FCS-BS-1484 | 901 680 14 39   |  | Auto Parts Ornamental Cover              |                                                                   |                                                |

|             |                                                                                      |                                                                                     |                                 |          |  |
|-------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|----------|--|
| FCS-BS-1485 | 901 689 05 91                                                                        |     | Glove Compartment               |          |  |
| FCS-BS-1486 | 901 680 18 07                                                                        |    | Dashboard Frame                 |          |  |
| FCS-BS-1487 | 901 688 16 06                                                                        |    | Dashboard Panelling             |          |  |
| FCS-BS-1488 | 901 688 23 06                                                                        |    | Dashboard Panelling             |          |  |
| FCS-BS-1489 | A 901 680 03 56                                                                      |    | Right Front Stay                |          |  |
| FCS-BS-1490 | 906 630 20 07 LH<br>906 630 21 07 RH                                                 |    | Fender Bracket                  |          |  |
| FCS-BS-1491 | 906 740 00 30                                                                        |  | Protective Trim Of License Lamp | SPRINTER |  |
| FCS-BS-1492 |                                                                                      |  | Protective Trim Of License Lamp | SPRINTER |  |
| FCS-BS-1493 | 906 880 27 71 LH<br>906 880 26 71 RH                                                 |  | Corner Bumper Cover             |          |  |
| FCS-BS-1494 | 906 686 03 07                                                                        |  | Protective Strip                |          |  |
| FCS-BS-1495 | 906 690 48 82<br>906 690 26 62 RH<br>906 690 25 62<br>906 690 47 82 LH               |  | Protective Strip                |          |  |
| FCS-BS-1496 | 906 690 11 82<br>906 690 30 62 LH<br>906 690 12 82<br>906 690 33 62 RH               |  | Protective Strip                |          |  |
| FCS-BS-1497 | 906 690 49 82<br>906 690 04 00<br>906 690 01 62 LH<br>906 690 05 00<br>906 690 02 62 |  | Protective Strip                |          |  |
| FCS-BS-1498 | 906 690 33 00<br>906 690 14 82 RH<br>906 690 13 82<br>906 690 32 00 LH               |  | Protective Strip                |          |  |

|             |                                                                                      |                                                                                     |                                            |  |  |
|-------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------|--|--|
| FCS-BS-1499 | 906 690 31 62<br>906 690 25 82 LH<br>906 690 34 62<br>906 690 26 82 RH               |     | Protective Strip                           |  |  |
| FCS-BS-1500 | 906 690 16 82<br>906 690 20 62<br>906 690 35 00 RH<br>906 690 15 82<br>906 690 19 62 |    | Protective Strip                           |  |  |
| FCS-BS-1501 | 906 690 32 62<br>906 690 27 82 LH<br>906 690 35 62<br>906 690 28 82 RH               |    | Protective Strip                           |  |  |
| FCS-BS-1502 | 906 690 53 82<br>906 690 08 00 LH<br>906 690 54 82<br>906 690 10 00 RH               |    | Protective Strip                           |  |  |
| FCS-BS-1503 |                                                                                      |    | Rear Licence Plate                         |  |  |
| FCS-BS-1504 | 906 686 07 10                                                                        |    | Entrance Sliding Door<br>Footstep Paneling |  |  |
| FCS-BS-1505 | 906 758 00 58                                                                        |   | Rear Door Badge With Base                  |  |  |
| FCS-BS-1506 |                                                                                      |  | Rear Door Badge Base                       |  |  |
| FCS-BS-1507 |                                                                                      |  | Rear Door Badge                            |  |  |
| FCS-BS-1508 |                                                                                      |  | Rear Door Badge With House                 |  |  |
| FCS-BS-1509 |                                                                                      |  | Rear Door Badge House                      |  |  |
| FCS-BS-1510 | 906 740 02 16                                                                        |  | Door Check                                 |  |  |
| FCS-BS-1511 | 906 760 12 28                                                                        |  | Door Check                                 |  |  |
| FCS-BS-1512 | 906 817 09 14                                                                        |  | Mark Sticker                               |  |  |

|             |                                                                                   |                                                                                     |                          |               |  |
|-------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------|---------------|--|
| FCS-BS-1513 | 906 817 25 14                                                                     |    | Mark Sticker             |               |  |
| FCS-BS-1514 | 906 817 23 14                                                                     |    | Mark Sticker             |               |  |
| FCS-BS-1515 | 000 989 03 98                                                                     |    | Rubber Sealing           |               |  |
| FCS-BS-1516 |                                                                                   |    | Clips                    | SPRINGER      |  |
| FCS-BS-1517 | 906 820 33 69                                                                     |    | Sliding Door Cable Track |               |  |
| FCS-BS-1518 |                                                                                   |    | Rear Bumper              | VITO<br>VIANO |  |
| FCS-BS-1519 | 6398801871<br>6398802371 LH<br>6398801971<br>6398802471 RH                        |   | Rear Side Bumper         | VITO<br>VIANO |  |
| FCS-BS-1520 | 636 694 04 25 LH<br>636 694 05 25 RH                                              |  | Tail Lamp Side Cover     | VITO<br>VIANO |  |
| FCS-BS-1521 | 636 690 10 62<br>636 690 00 62<br>636 690 06 62<br>636 690 08 62<br>636 690 13 62 |  | Side Door Moulding Kit   | VITO<br>VIANO |  |
| FCS-BS-1522 |                                                                                   |  | Side Door Moulding Kit   | VITO<br>VIANO |  |
| FCS-BS-1523 | 636 743 00 30                                                                     |  | Rear Trunk Strip         | VITO<br>VIANO |  |
| FCS-BS-1524 | 636 743 00 30                                                                     |  | Rear Trunk Chromed Strip | VITO<br>VIANO |  |
| FCS-BS-1525 |                                                                                   |  | Table Inside The Van     | VITO<br>VIANO |  |
| FCS-BS-1526 |                                                                                   |  | Central Armrest          | VITO<br>VIANO |  |

|             |                                                                                   |                                                                                     |                      |               |  |
|-------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------|---------------|--|
| FCS-BS-1527 |                                                                                   |    | Luggage Rack         | VITO<br>VIANO |  |
| FCS-BS-1528 |                                                                                   |    | Luxury Pedal         | VITO<br>VIANO |  |
| FCS-BS-1529 | 636 690 10 62<br>636 690 00 62<br>636 690 06 62<br>636 690 08 62<br>636 690 13 62 |    | Daytime Running Lamp | VITO<br>VIANO |  |
| FCS-BS-1530 |                                                                                   |    | Front Bumper         | VITO<br>VIANO |  |
| FCS-BS-1531 | 639 885 01 53                                                                     |    | Bumper Grille        | VITO<br>VIANO |  |
| FCS-BS-1532 | 639 880 66 71                                                                     |    | Rear Bumper          | VITO<br>VIANO |  |
| FCS-BS-1533 |                                                                                   |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1534 |                                                                                   |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1535 | 6398851919006                                                                     |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1536 | 639886981054                                                                      |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1537 | 639 880 71 71                                                                     |  | Daytime Running Lamp | VITO<br>VIANO |  |
| FCS-BS-1538 |                                                                                   |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1539 | 639 885 01 53                                                                     |  | Bumper Accessory     | VITO<br>VIANO |  |
| FCS-BS-1540 | 639 698 09 54                                                                     |  | Side Bumper Strip    | VITO<br>VIANO |  |

|             |               |                                                                                     |                                           |               |  |
|-------------|---------------|-------------------------------------------------------------------------------------|-------------------------------------------|---------------|--|
| FCS-BS-1541 | 639 698 09 27 |     | Front Bumper Inner Linner                 | VITO<br>VIANO |  |
| FCS-BS-1542 | 639 885 26 14 |    | Bumper Accessory                          | VITO<br>VIANO |  |
| FCS-BS-1543 |               |    | Side Bumper Strip                         | VITO<br>VIANO |  |
| FCS-BS-1544 | 639 698 07 27 |    | Front Bumper Inner Linner                 | VITO<br>VIANO |  |
| FCS-BS-1545 |               |    | Front Bumper                              | VITO<br>VIANO |  |
| FCS-BS-1546 | 639 885 00 25 |    | Beneath The Bumper Bar                    | VITO<br>VIANO |  |
| FCS-BS-1547 | 639 885 01 53 |  | Rear Bumper                               | VITO<br>VIANO |  |
| FCS-BS-1548 |               |  | Front Bumper                              | VITO<br>VIANO |  |
| FCS-BS-1549 |               |  | Rear Bumper                               | VITO<br>VIANO |  |
| FCS-BS-1550 |               |  | Front Bumper                              | VITO<br>VIANO |  |
| FCS-BS-1551 |               |  | Front Bumper                              | VITO<br>VIANO |  |
| FCS-BS-1552 |               |  | Daytime Running Lamp                      | VITO<br>VIANO |  |
| FCS-BS-1553 |               |  | Daytime Running Lamp                      | VITO<br>VIANO |  |
| FCS-BS-1554 |               |  | Front Bumper<br>With Daytime Running Lamp | VITO<br>VIANO |  |




|             |                                                                  |                                                                                     |                      |                      |  |
|-------------|------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------|----------------------|--|
| FCS-BS-1555 |                                                                  |     | Rear Bumper          | VITO<br>VIANO        |  |
| FCS-BS-1556 | 9066840377<br>9066841777                                         |    | Lining, R            | Mercedes Sprinter906 |  |
| FCS-BS-1557 | 9066840277                                                       |    | Lining,L             | Mercedes Sprinter906 |  |
| FCS-BS-1558 | 906 684 13 77<br>906 684 18 77                                   |    | Lining, R            | Mercedes Sprinter906 |  |
| FCS-BS-1559 | 906 684 12 77                                                    |    | Lining,L             | Mercedes Sprinter906 |  |
| FCS-BS-1560 | 906 880 01 71<br>906 880 02 71<br>906 880 03 71<br>906 880 04 71 |    | Rear,Bumper          | Mercedes Sprinter906 |  |
| FCS-BS-1561 | 906 668 600 74                                                   |  | Rear, Trim           | Mercedes Sprinter906 |  |
| FCS-BS-1562 | 906 620 04 24                                                    |  | Head lamp bracket RH | Mercedes Sprinter906 |  |
| FCS-BS-1563 | 906 620 02 24                                                    |  | Head lamp bracket LH | Mercedes Sprinter906 |  |
| FCS-BS-1564 | 906 889 01 31                                                    |  | Bracket              | Mercedes Sprinter906 |  |
| FCS-BS-1565 | 906 889 00 31                                                    |  | Bracket              | Mercedes Sprinter906 |  |
| FCS-BS-1566 | 906 505 10 88                                                    |  | Lower Cover          | Mercedes Sprinter906 |  |
| FCS-BS-1567 | 9066230525 L<br>9066230625 R                                     |  | Bracket              | Mercedes Sprinter906 |  |
| FCS-BS-1568 | 9066230725 L<br>9066230825 R                                     |  | Bracket              | Mercedes Sprinter906 |  |

|             |                  |                                                                                     |                                            |                      |  |
|-------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------|----------------------|--|
| FCS-BS-1569 | 906 505 00 88    |    | Upper Cover                                | Mercedes Sprinter906 |  |
| FCS-BS-1570 | 906 505 02 88    |    | Right Cover                                | Mercedes Sprinter906 |  |
| FCS-BS-1571 | 906 505 01 88    |    | Left Cover                                 | Mercedes Sprinter906 |  |
| FCS-BS-1572 | 906 505 04 88    |    | Cover RH                                   | Mercedes Sprinter906 |  |
| FCS-BS-1573 | 906 505 03 88    |    | Cover LH                                   | Mercedes Sprinter906 |  |
| FCS-BS-1574 | 906 490 07 21    |    | Escape-Pipe                                | Mercedes Sprinter906 |  |
| FCS-BS-1575 |                  |   | MAT                                        | Mercedes Sprinter906 |  |
| FCS-BS-1576 |                  |  | MAT                                        | Mercedes Sprinter906 |  |
| FCS-BS-1577 | 906 880 15 70    |  | Front Bumper                               | Mercedes Sprinter906 |  |
| FCS-BS-1578 | 906 637 51 09    |  | Metal Panelling LWB MWB<br>Drive Side 1 RH | Mercedes Sprinter906 |  |
| FCS-BS-1579 | 906 635 709 RH   |  | Metal Panelling LWB<br>Drive Side 2 RH     | Mercedes Sprinter906 |  |
| FCS-BS-1580 | 906 637 56 09 LH |  | Metal Panelling LWB MID LH                 | Mercedes Sprinter906 |  |
| FCS-BS-1581 | 906 637 61 09 RH |  | Metal Panelling Dvr Side 2<br>MWB          | Mercedes Sprinter906 |  |
| FCS-BS-1582 | 906 637 60 09 LH |  | Metal Panelling<br>Pass Side 2 MWB         | Mercedes Sprinter906 |  |

|             |                  |                                                                                     |                                        |                                                                 |  |
|-------------|------------------|-------------------------------------------------------------------------------------|----------------------------------------|-----------------------------------------------------------------|--|
| FCS-BS-1583 | 906 637 54 09    |     | Metal Panelling<br>Pass Side 1 MWB     | Mercedes Sprinter906                                            |  |
| FCS-BS-1584 | 906 637 55 09    |    | Metal Panelling Dvr Side 1<br>MWB      | Mercedes Sprinter906                                            |  |
| FCS-BS-1585 | 906 881 02 01 RH |    | Front Wing Fac Laft RH                 | Mercedes Sprinter906                                            |  |
| FCS-BS-1586 | 906 881 01 01 LH |    | Front Wing Fac Laft LH                 | Mercedes Sprinter906                                            |  |
| FCS-BS-1587 | 906 637 63 09 RH |    | Metal Panelling LWB<br>Drive Side 3 RH | Mercedes Sprinter906                                            |  |
| FCS-BS-1588 | 906 637 62 09 LH |    | Metal Panelling LWB<br>Pass Side 3 LH  | Mercedes Sprinter906                                            |  |
| FCS-BS-1589 |                  |   | Handle                                 | Mercedes Sprinter906                                            |  |
| FCS-BS-1590 | 906 760 01 61 LH |  | Door Handle, Interior - Front -<br>LH  | SPRT 209 CDI, 215 CDI,<br>309 CDI, 315 CDI, 511 CDI,<br>515 CDI |  |
| FCS-BS-1591 | 906 760 02 61RH  |  | Door Handle, Interior - Front -<br>RH  | SPRT 209 CDI, 215 CDI,<br>309 CDI, 315 CDI, 511 CDI,<br>515 CDI |  |
| FCS-BS-1592 | 000 727 0037 LH  |  | Door Handle, Interior - Front -<br>LH  | SPRT CDI                                                        |  |
| FCS-BS-1593 | 000 727 01 37RH  |  | Door Handle, Interior - Front -<br>RH  | SPRT CDI                                                        |  |
| FCS-BS-1594 | 0007430372       |  | Door Handle , Rear                     | VITO 108<br>220 CDI                                             |  |
| FCS-BS-1595 | 6387270580 RH    |  | Door Handle,<br>Interior-Front-Right   | VITO 108<br>110<br>112 CDI<br>200 CDI<br>220 CDI                |  |
| FCS-BS-1596 | 6387270480 LH    |  | Door Handle,<br>Interior-Front-Left    | VITO 108<br>110<br>112 CDI<br>200 CDI,<br>220 CDI               |  |

|             |                                                 |                                                                                     |                                      |                                                   |  |
|-------------|-------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------|---------------------------------------------------|--|
| FCS-BS-1597 | 901 760 08 04<br>901 760 09 04<br>690 760 70 04 |     | Side Door Pull Cable                 | SPRT CDI                                          |  |
| FCS-BS-1598 | 0006700373                                      |    | Window Regulator Crank               | SPR 208<br>413CDI                                 |  |
| FCS-BS-1599 | 6397600628                                      |    | Door Hinge, Top R + L                | VITO 639                                          |  |
| FCS-BS-1600 | 9067600061                                      |    | Door Handle, Interior - Rear         | SPRT 209 CDI<br>309 CDI<br>315 CDI<br>515 CDI     |  |
| FCS-BS-1601 | 6397600161                                      |    | Door Handle, Interior - Rear         | VITO 639                                          |  |
| FCS-BS-1602 | 6397600261                                      |    | Door Handle, Interior - Front -<br>L | VITO 639                                          |  |
| FCS-BS-1603 | 6397600361                                      |   | Door Handle, Interior - Front -<br>R | VITO 639                                          |  |
| FCS-BS-1604 | 9017500084                                      |  | Handle, Bonnet Release               | SPRT CDI                                          |  |
| FCS-BS-1605 | 9067600077                                      |  | Guide, Locking Knob                  | SPRT 315CDI                                       |  |
| FCS-BS-1606 | 9067500550                                      |  | Engine Hood Catch , Top              | SPRT 315CDI                                       |  |
| FCS-BS-1607 | 6018170116                                      |  | Logo                                 | 207<br>307<br>310<br>410                          |  |
| FCS-BS-1608 | 9018170816                                      |  | Logo                                 | 208CDI<br>211CDI<br>313CDI<br>316CDI              |  |
| FCS-BS-1609 | 9018800085                                      |  | Radiator Grille Shell                | SPRT 208<br>308,408,313<br>411,316,416<br>616 CDI |  |
| FCS-BS-1610 | 6120103220                                      |  | Cylinder Head                        | CDI<br>OM612<br>Om647                             |  |

|             |            |                                                                                     |                            |                                                   |  |
|-------------|------------|-------------------------------------------------------------------------------------|----------------------------|---------------------------------------------------|--|
| FCS-BS-1611 | 6510304005 |     | Flywheel                   | OM 651                                            |  |
| FCS-BS-1612 | 6010500816 |    | Sliding Rail Clamping Rail | OM 601<br>OM 602<br>603,604<br>605,606            |  |
| FCS-BS-1613 | 0000322405 |    | Fuel Filter                | 609,709,711<br>811,814<br>OM314<br>OM364<br>OM366 |  |
| FCS-BS-1614 | 6021800009 |    | Oil Filter                 | OM602                                             |  |
| FCS-BS-1615 | 3641800109 |    | Oil Filter                 | 609-709 D                                         |  |
| FCS-BS-1616 | 0008303318 |    | Interieur Air Cabin Filter | SPRT<br>208,308<br>312,412<br>413 CDI             |  |
| FCS-BS-1617 | 6110701487 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1618 | 6110700587 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1619 | 6110700687 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1620 | 6110700887 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1621 | 6110700987 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1622 | 6110701187 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1623 | 6110701387 |  | Injector                   | OM 611 DE LA<br>OM 612 DE LA                      |  |
| FCS-BS-1624 | 0000940948 |  | Air Mass Sensor            | SPRT VITO M111                                    |  |


|             |              |                                                                                     |                                      |                                                                                                                        |  |
|-------------|--------------|-------------------------------------------------------------------------------------|--------------------------------------|------------------------------------------------------------------------------------------------------------------------|--|
| FCS-BS-1625 | 1120940048   |     | Air Mass Sensor                      | SPRT VITO M112                                                                                                         |  |
| FCS-BS-1626 | 0000941048   |    | Air Mass Sensor                      | VITO<br>108 CDI<br>110 CDI<br>112 CDI                                                                                  |  |
| FCS-BS-1627 | 3641590301   |    | Heater Plug                          | 609<br>709<br>711<br>811<br>814                                                                                        |  |
| FCS-BS-1628 | 667 325 0053 |    | Spacer Tube, Spring                  |                                                                                                                        |  |
| FCS-BS-1629 | 0002020919   |    | Belt Tightener Pulley                | OM,611,612,613<br>OM,646,647,648                                                                                       |  |
| FCS-BS-1630 | 6041500060   |    | Pulley, Alternator                   | SPRT 208 412                                                                                                           |  |
| FCS-BS-1631 | 1032000114   |   | Vibration Absorber,<br>V-Ribbed Belt | M103<br>W124<br>W126<br>W129                                                                                           |  |
| FCS-BS-1632 | 172509503    |  | Clutch Disc                          | 207.208.209<br>210,307<br>310,410                                                                                      |  |
| FCS-BS-1633 | 0102508503   |  | Clutch Disc                          | 609<br>709<br>711                                                                                                      |  |
| FCS-BS-1634 | 0102508603   |  | Clutch Disc                          | 711<br>811<br>814<br>814 K                                                                                             |  |
| FCS-BS-1635 | 0005459809   |  | Brake Light Switch                   | SPRT 208<br>211<br>311<br>313<br>413 CDI                                                                               |  |
| FCS-BS-1636 | 9013200089   |  | Rod To Rear Torsion Bar              | SPRT 208, 210, 212<br>214, 208 CDI, 211 CDI<br>213 CDI ( 01.95 -05.06 )<br>SPRT 208, 210, 212<br>214, 208 CDI, 211 CDI |  |
| FCS-BS-1637 | 6023200302   |  | 207 Spring Front Leaf No:1           | 207,208,209<br>210,307,310                                                                                             |  |
| FCS-BS-1638 | 60132002     |  | 207 Spring Front Leaf No:2           | 207,208,209<br>210,307,310                                                                                             |  |

|             |                              |                                                                                     |                                          |                                                                            |  |
|-------------|------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|----------------------------------------------------------------------------|--|
| FCS-BS-1639 | 9043201706                   |    | Rear 3 Leaf                              | SPRT 408,410<br>412,408 CDI<br>411 CDI,413 CDI<br>416 CDI ( 02.96 -05.06 ) |  |
| FCS-BS-1640 | 9013221119                   |    | Rubber Buffer, Suspension                | MERCEDES                                                                   |  |
| FCS-BS-1641 | 6753301519                   |    | Repair Kit,<br>king Pin Set 33q (Single) | 117 K<br>1317 K<br>1320 K                                                  |  |
| FCS-BS-1642 | 9063251147                   |    | U-Bout                                   |                                                                            |  |
| FCS-BS-1643 | 0014014802                   |    | Wheel disc 17*7.5                        | 906                                                                        |  |
| FCS-BS-1644 | 9063304107<br>9063304707     |    | Track Control Arm - R                    | CRAFTER SPRT<br>315CDI<br>316CDI<br>318CDI<br>518CDI                       |  |
| FCS-BS-1645 | 9063304007<br>9063304607     |   | Track Control Arm - L                    | CRAFTER SPRT<br>315CDI<br>316CDI<br>318CDI<br>518CDI                       |  |
| FCS-BS-1646 | 9033500439                   |  | Ring Gear And Pinion - 7/34              | SPRINTER 208<br>212<br>308<br>312                                          |  |
| FCS-BS-1647 | 0019818905                   |  | Wheel Bearing Kit Rear                   | SPRT<br>208<br>312<br>412                                                  |  |
| FCS-BS-1648 | 9063503710/1<br>2E0501171E/1 |  | Rear Axle Shaft :L (Short, Thin)         | SPRTW 906<br>315<br>515CDI,<br>VW CRAFTER                                  |  |
| FCS-BS-1649 | 9063503810/1<br>2E0501172E/1 |  | Rear Axle Shaft : R (Long,Thin)          | SPRT<br>W 906<br>315<br>515CDI<br>VW CRAFTER                               |  |
| FCS-BS-1650 | 124175                       |  | Universal Joint                          | 207<br>208<br>209                                                          |  |
| FCS-BS-1651 | 9704100031                   |  | Universal Joint                          | ATEGO<br>VARIO<br>614<br>615<br>814                                        |  |
| FCS-BS-1652 |                              |  | Universal Joint                          | SPRT<br>W 901<br>902<br>903<br>904                                         |  |




|             |                                                      |                                                                                     |                                        |                                       |  |
|-------------|------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------|---------------------------------------|--|
| FCS-BS-1653 | 6314202185                                           |     | Park Brake Cable R / L                 | MB100<br>MB120                        |  |
| FCS-BS-1654 | 0004315901                                           |    | Brake Master Cylinder                  | VITO 638                              |  |
| FCS-BS-1655 | 1234200073<br>1164230050                             |    | Hand Brake Shoe Adjuster               | SPRT<br>W 901-904<br>OM 601-602       |  |
| FCS-BS-1656 | 9064202385                                           |    | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1657 | 9064203885                                           |    | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1658 | 9064202785<br>9064203985<br>9064205585               |    | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1659 | 9064202885<br>9064203785<br>9064205385<br>9064205685 |   | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1660 | 9064203885<br>9064205785                             |  | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1661 | 9064205885                                           |  | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1662 | 9064202985<br>9064206985                             |  | Cable, Parking Brake                   | SPRT 906                              |  |
| FCS-BS-1663 | 6204900365                                           |  | Flexible Metal Tube<br>To Exhaust Pipe | 609<br>709<br>711<br>814              |  |
| FCS-BS-1664 | 9063503710/1<br>2E0501171E/1                         |  | Hose Top To Radiator                   | SPRT<br>208,308<br>312,412<br>413 CDI |  |
| FCS-BS-1665 | 0045423207                                           |  | Flexible Shaft , 2,50                  | 609<br>709<br>711<br>814              |  |
| FCS-BS-1666 | 0055457424                                           |  | Steering Column<br>Mounted Switch      | 207,208,209<br>307,310,410            |  |

|             |                                           |                                                                                     |                                                     |                                                                      |  |
|-------------|-------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------|----------------------------------------------------------------------|--|
| FCS-BS-1667 | 9068200456                                |    | Rear Brake Lamp                                     | 906                                                                  |  |
| FCS-BS-1668 |                                           |    | Tail Lamp Chrome Cover RH                           | 906                                                                  |  |
| FCS-BS-1669 |                                           |    | Tail Lamp Chrome Cover LH                           | 906                                                                  |  |
| FCS-BS-1670 | A9017301235                               |    | Door Lock                                           |                                                                      |  |
| FCS-BS-1671 | A0005456204<br>0005456204                 |    | Head Light Switch                                   | 300E 86<br>300SDL 86<br>420SEL 86<br>560SEC 86<br>560SEL 86          |  |
| FCS-BS-1672 | 0005456504<br>A0005456504                 |    | Head Light Switch                                   | 300SD 92-93<br>300SE 92-93<br>400SE 92<br>400SEL 93<br>500SEC 93     |  |
| FCS-BS-1673 | 0008206010<br>0008206010KZ                |   | Defroster Switch                                    | 190D 84-89<br>190E 84-93<br>280S 75-76<br>280SE 77-80<br>300SD 78-80 |  |
| FCS-BS-1674 | A9065450213<br>9065450213                 |  | POWER WINDOW MAIN<br>SWITCH<br>Front Left Worldwide | MB SPRINTER<br>(W906) 06-                                            |  |
| FCS-BS-1675 | HVW9065451613<br>9065451613<br>2E0959877J |  | POWER WINDOW MAIN<br>SWITCH<br>Front Left Worldwide | VW CRAFTER ALL                                                       |  |
| FCS-BS-1676 |                                           |  | WINDOW SWITCH CAP Front<br>Left Worldwide           | MB VITO/VIANO<br>(W639) 04                                           |  |
| FCS-BS-1677 |                                           |  | WINDOW SWITCH CAP Front<br>Right Worldwide          | MB VITO/VIANO<br>(W639) 04                                           |  |
| FCS-BS-1678 | A6395451013<br>6395451013                 |  | POWER WINDOW MAIN<br>SWITCH<br>Front Left Worldwide | MB VITO/VIANO<br>(W639) 04                                           |  |
| FCS-BS-1679 |                                           |  | WINDOW SWITCH CAP Rear<br>Left Worldwide            | MB VITO/VIANO<br>(W639) 04                                           |  |
| FCS-BS-1680 |                                           |  | WINDOW SWITCH CAP Rear<br>Right Worldwide           | MB VITO/VIANO<br>(W639) 04                                           |  |

|             |                                      |                                                                                     |                                                                           |                                       |                                       |
|-------------|--------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------|---------------------------------------|---------------------------------------|
| FCS-BS-1681 | A6395451513<br>6395451513            |     | POWER WINDOW MAIN SWITCH<br>Without mirror switch Front<br>Left Worldwide | MB VITO/VIANO<br>(W639) 04-           | ILLUMINATED BY<br>YELLOW LED<br>7 PIN |
| FCS-BS-1682 | HVW9065450913<br>2E0959877Q          |    | Power Window<br>Passenger Switch                                          | VW CRAFTER ALL                        | ILLUMINATED BY RED<br>LED<br>3 PIN    |
| FCS-BS-1683 | A6395450613<br>6395450613            |    | POWER WINDOW PASSENGER<br>SWITCH<br>Front Right Worldwide                 | MB VITO/VIANO<br>(W639) 04-           | ILLUMINATED BY<br>YELLOW LED<br>4 PIN |
| FCS-BS-1684 | 6395451413<br>A6395451413            |    | POWER WINDOW PASSENGER<br>SWITCH<br>Front Right Worldwide                 | MB VITO/VIANO (W639)<br>(2004 - 2014) | ILLUMINATED BY<br>YELLOW LED<br>4 PIN |
| FCS-BS-1685 | A000 323 15 85                       |    | Bush Shock Absorber                                                       |                                       | D33mm                                 |
| FCS-BS-1686 | 115 992 01 10                        |    | Bush rocker                                                               |                                       |                                       |
| FCS-BS-1687 | MEYLE 0140010003<br>601 016 03 81    |   | Vacuum Branch pipe                                                        |                                       |                                       |
| FCS-BS-1688 | 9034210012                           |  | Front Brake Disc                                                          |                                       |                                       |
| FCS-BS-1689 | 9024230112                           |  | Rear brake Disc                                                           |                                       |                                       |
| FCS-BS-1690 | FE 07517<br>9014210312<br>9014210612 |  | Front Brake Disc                                                          |                                       |                                       |
| FCS-BS-1691 | MKD949<br>A0024204120                |  | Brake pad                                                                 |                                       |                                       |
| FCS-BS-1692 | MKD1006<br>A0024203820               |  | Brake pad                                                                 | OM 651                                |                                       |
| FCS-BS-1693 | ABE GDB317                           |  | Brake pad                                                                 |                                       |                                       |
| FCS-BS-1694 | LTC1W029ABE<br>GDB1220               |  | Brake pad                                                                 |                                       |                                       |

|             |                                |                                                                                     |                   |                                                  |       |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------|--------------------------------------------------|-------|
| FCS-BS-1695 | MEYLE 0340410003<br>6104101710 |     | Bearing           | OM602                                            |       |
| FCS-BS-1696 | 6383300010                     |    | Track Control Arm | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI | W 638 |
| FCS-BS-1697 | 6383100110                     |    | Track Control Arm | VITO 108<br>110<br>108 CDI<br>110 CDI<br>112 CDI | W 638 |
| FCS-BS-1698 | 6393300410                     |    | Track Control Arm | VITO<br>VIANO<br>108<br>111<br>113               | W639  |
| FCS-BS-1699 | 6393300510                     |    | Track Control Arm | VITO<br>VIANO<br>108<br>111<br>113               | W639  |
| FCS-BS-1700 | 6393301207                     |    | Track Control Arm | VITO<br>VIANO<br>108<br>111<br>113               | W639  |
| FCS-BS-1701 | 6393301307                     |   | Track Control Arm | VITO<br>VIANO<br>108<br>111<br>113               | W639  |
| FCS-BS-1702 |                                |  | Tube              | SPRINTER 906                                     |       |
| FCS-BS-1703 |                                |  | Hinge             | SPRINTER 906                                     |       |
| FCS-BS-1704 |                                |  | Hinge             | SPRINTER 906                                     |       |
| FCS-BS-1705 |                                |  |                   | SPRINTER 906                                     |       |
| FCS-BS-1706 | 9068179014                     |  | Mark              | SPRINTER 906                                     |       |
| FCS-BS-1707 | 9068176714                     |  | Mark              | SPRINTER 906                                     |       |
| FCS-BS-1708 | 906440775                      |  | Wiring Harness    | SPRINTER 906                                     |       |

|             |                                |                                                                                     |                                         |                  |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------|------------------|--|
| FCS-BS-1709 | 6392670234                     |     | Gear Badge                              | SPRINTER<br>VITO |  |
| FCS-BS-1710 | 9068850353 RH<br>9068850253 LH |    | Fog Lamp Housing                        | SPRINTER 906     |  |
| FCS-BS-1711 | 0009985205                     |    | Rubber For Grille Frame                 | SPRINTER 906     |  |
| FCS-BS-1712 |                                |    | Connector For Air-conditioner<br>Switch | SPRINTER 906     |  |
| FCS-BS-1713 |                                |    | Seat                                    | SPRINTER 906     |  |
| FCS-BS-1714 |                                |    | Seat Cover                              | SPRINTER 906     |  |
| FCS-BS-1715 |                                |   | Seat Cover                              | SPRINTER 906     |  |
| FCS-BS-1716 |                                |  | Seat Clips                              | SPRINTER 906     |  |
| FCS-BS-1717 | 9015850001                     |  | Tool                                    | SPRINTER 906     |  |
| FCS-BS-1718 |                                |  | Seat Bracket                            | SPRINTER 906     |  |
| FCS-BS-1719 | 0008320000<br>74552600         |  | Heater Control Bracket                  | SPRINTER 906     |  |
| FCS-BS-1720 | 9068200475                     |  | Antenna                                 | SPRINTER 906     |  |
| FCS-BS-1721 | 9066861574                     |  | Protective Strip Bracket                | SPRINTER 906     |  |
| FCS-BS-1722 | 9068809600<br>9068800071       |  | Foot Step                               | SPRINTER 906     |  |

|               |                                                                          |                                                                                     |                                |               |  |
|---------------|--------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|---------------|--|
| FCS-BS-1723   |                                                                          |     | Sprinter Back Door L/R         | SPRINTER 906  |  |
| FCS-BS-1724   |                                                                          |    | Sprinter Sliding Door LH RHD   | SPRINTER 906  |  |
| FCS-BS-1725   | A6365280106                                                              |    | Air Filter Housing             | VITO<br>VIANO |  |
| FCS-BS-1726   | A6365050355/001                                                          |    | Fan Shroud                     | VITO<br>VIANO |  |
| FCS-BS-1727   | 6369061300                                                               |    | Fan Collection Cover Old Model | VITO<br>VIANO |  |
| FCS-BS-1728   | 6365000093                                                               |    | Fan Collection Cover New Model | VITO<br>VIANO |  |
| FCS-BS-1729   | 3136613392<br>A6395001093<br>0130308106<br>65194031076304                |   | Fan Blade                      | VITO<br>VIANO |  |
| FCS-BS-1730   | A6395030001                                                              |  | Fan Guard                      | VITO<br>VIANO |  |
| FCS-BS-1731   |                                                                          |  | Mirror Cover Chromed           | VITO<br>VIANO |  |
| FCS-BS-1732   | A4479065900<br>A4478200161<br>4479065900<br>4478200161 RH<br>A4479065800 |  | Head Lamp                      |               |  |
| FCS-BS-1732-1 | A4479067700 LH<br>A4479067800 RH                                         |  | Head Lamp                      | VITO<br>VIANO |  |
| FCS-BS-1733   | A4478200164 RH<br>A4478200064 LH                                         |  | Tail Lamp Single Tailgate      | VITO<br>VIANO |  |
| FCS-BS-1734   | 4478201164 LH<br>4478201264 RH                                           |  | Tail Lamp Double Tailgate      | VITO<br>VIANO |  |
| FCS-BS-1735   |                                                                          |  | Front Grille                   | VITO<br>VIANO |  |

|             |                                                            |                                                                                     |                                  |               |  |
|-------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------|---------------|--|
| FCS-BS-1736 | 6369061300                                                 |     | Front Grille Moulding<br>Chromde | VITO<br>VIANO |  |
| FCS-BS-1737 |                                                            |    | Front Bumper                     | VITO<br>VIANO |  |
| FCS-BS-1738 | A4488850600                                                |    | Rear Bumper                      | VITO<br>VIANO |  |
| FCS-BS-1739 | 4478110400<br>Z8Q3601090 LH<br>4478110500<br>Z8Q3601120 RH |    | Door Mirror                      | VITO<br>VIANO |  |
| FCS-BS-1740 | A4487540000<br>A4486370500                                 |    | Fuel Tank Cap                    | VITO<br>VIANO |  |
| FCS-BS-1741 | A4478850063                                                |    | Air Channel                      | VITO<br>VIANO |  |
| FCS-BS-1742 | A4478850210 RH<br>A4478850110 LH                           |   | Pillar                           | VITO<br>VIANO |  |
| FCS-BS-1743 | A4478850814 LH<br>A4478850914 RH                           |  | Bracket                          | VITO<br>VIANO |  |
| FCS-BS-1744 | A4478850064                                                |  | Bracket                          | VITO<br>VIANO |  |
| FCS-BS-1745 | 4488852200/001 LH<br>4488852300/001 RH                     |  | Front Bumper Bracket             | VITO<br>VIANO |  |
| FCS-BS-1746 | 4478801114 LH<br>4478801214 RH                             |  | Bracket                          | VITO<br>VIANO |  |
| FCS-BS-1747 | A4478850214                                                |  | Bracket                          | VITO<br>VIANO |  |
| FCS-BS-1748 | A4479065200 LH<br>A4479065300 RH                           |  | Head Lamp                        | VITO<br>VIANO |  |
| FCS-BS-1749 | A4478200564 LH<br>A4478200664                              |  | Tail Lamp Led Model              | VITO<br>VIANO |  |



|             |                                                            |                                                                                     |                                       |               |  |
|-------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|---------------|--|
| FCS-BS-1750 | 9068800785                                                 |     | Front Grille                          | VITO<br>VIANO |  |
| FCS-BS-1751 |                                                            |    | Hood Moulding                         | VITO<br>VIANO |  |
| FCS-BS-1752 | A4488850200                                                |    | Front Bumper                          | VITO<br>VIANO |  |
| FCS-BS-1753 | A4488851600/002                                            |    | Front Bumper Grille Lower             | VITO<br>VIANO |  |
| FCS-BS-1754 | A4478260040 LH<br>A4478260140 RH                           |    | Rear Bumper Reflector                 | VITO<br>VIANO |  |
| FCS-BS-1755 | 4478111000<br>Z8Q3601670 LH<br>4478111100<br>Z8Q3601780 RH |    | Door Mirror                           | VITO<br>VIANO |  |
| FCS-BS-1756 | A4479060800<br>A4479060700<br>A4479060044                  |  | High Brake Light                      | VITO<br>VIANO |  |
| FCS-BS-1757 |                                                            |  | Day Running Light                     | VITO<br>VIANO |  |
| FCS-BS-1758 |                                                            |  | Liftgate Garnish Molding<br>Chromed   | VITO<br>VIANO |  |
| FCS-BS-1759 |                                                            |  | Luggage Rack                          | VITO<br>VIANO |  |
| FCS-BS-1760 |                                                            |  | Luxury Pedal                          | VITO<br>VIANO |  |
| FCS-BS-1761 |                                                            |  | Luxury Pedal                          | VITO<br>VIANO |  |
| FCS-BS-1762 | A4488840000/001 LH<br>A4488840100/001 RH                   |  | Fog Lamp Cover                        | VITO<br>VIANO |  |
| FCS-BS-1763 | A4488840000/001 LH<br>A4488840100/001RH                    |  | Fog Lamp Cover With<br>Chromed Stripe | VITO<br>VIANO |  |


|             |                                                          |                                                                                     |                                       |                       |  |
|-------------|----------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|-----------------------|--|
| FCS-BS-1764 |                                                          |     | Fog Lamp Cover With Day Running Light | VITO VIANO            |  |
| FCS-BS-1765 | A4478900000                                              |    | Front Mudguard                        | VITO VIANO            |  |
| FCS-BS-1766 | A4478900100                                              |    | Rear Mudguard                         | VITO VIANO            |  |
| FCS-BS-1767 | A4486843000<br>A4486840400<br>A4486843100<br>A4486840500 |    | Front And Rear Inner Mudguard         | VITO VIANO            |  |
| FCS-BS-1768 | A4486860000                                              |    | Inner Cushion Cover Plate             | VITO VIANO            |  |
| FCS-BS-1769 | A4486940400 LH<br>A4486940500 RH                         |    | Rear Door Shock Plate                 | VITO VIANO            |  |
| FCS-BS-1770 | A4474011600                                              |   | Wheel Cover                           | VITO VIANO            |  |
| FCS-BS-1771 | 6pk2264<br>0149970792<br>0149971792                      |  | V-Belt                                |                       |  |
| FCS-BS-1772 | 0009937596<br>6PK2255                                    |  | V-Belt                                |                       |  |
| FCS-BS-1773 | 0019933896                                               |  | Connecting Belt                       |                       |  |
| FCS-BS-1774 | 9013331227                                               |  | Tie Rod End                           | SPRINTER 901          |  |
| FCS-BS-1775 | 6461801601                                               |  | Oil Pump                              | SPRINTER VITO 2.2 CDI |  |
| FCS-BS-1776 | 9047600447                                               |  | Side Door Roller                      | SPRINTER 412 VWLT 46  |  |
| FCS-BS-1777 | 9092670000                                               |  | Cable Of The Stage                    | SPRINTER 909          |  |

|             |             |                                                                                     |                                      |               |  |
|-------------|-------------|-------------------------------------------------------------------------------------|--------------------------------------|---------------|--|
| FCS-BS-1778 | A6392600051 |     | Cable                                | VITO<br>VIANO |  |
| FCS-BS-1779 | a6392600151 |    | Cable                                | VITO<br>VIANO |  |
| FCS-BS-1780 | 0002600009  |    | Manual Gearshift Knob Boot Mechanism | SPRINTER 901  |  |
| FCS-BS-1781 | 9016890739  |    | Dash Board                           | SPRINTER 901  |  |
| FCS-BS-1782 | A9063000304 |    | Step Pedal                           | SPRINTER 906  |  |
| FCS-BS-1783 | A0044205383 |    | Brake Caliper                        |               |  |
| FCS-BS-1784 | A0044205483 |   | Brake Caliper                        |               |  |
| FCS-BS-1785 | A6394200883 |  | Brake Caliper                        |               |  |
| FCS-BS-1786 | A6394200983 |  | Brake Caliper                        |               |  |
| FCS-BS-1787 | 0014208683  |  | Brake Caliper                        |               |  |
| FCS-BS-1788 | 0014208783  |  | Brake Caliper                        |               |  |
| FCS-BS-1789 | A6393240684 |  | Rod To Front Torsion Bar             |               |  |
| FCS-BS-1790 | A6393200989 |  | Stabiliser                           |               |  |
| FCS-BS-1791 | A6393201089 |  | Stabiliser                           |               |  |

|             |               |                                                                                     |                           |              |  |
|-------------|---------------|-------------------------------------------------------------------------------------|---------------------------|--------------|--|
| FCS-BS-1792 | A6393242904   |     | Spring Rear               |              |  |
| FCS-BS-1793 | A6393240206   |    | Rubber Mounting           |              |  |
| FCS-BS-1794 | A6393240306   |    | Rubber Mounting           |              |  |
| FCS-BS-1795 | 9017400216    |    | Rear Door Check           | SPRINTER 901 |  |
| FCS-BS-1796 | A6394600648   |    | Track Rod End             |              |  |
| FCS-BS-1797 | A6394600748   |    | Track Rod End             |              |  |
| FCS-BS-1798 | A6394603300   |   | Steering Assy             |              |  |
| FCS-BS-1799 | A6395010503   |  | Water Reservoir           |              |  |
| FCS-BS-1800 | 0018358706    |  | Heater Blower Resistor    |              |  |
| FCS-BS-1801 | 000 980 19 02 |  | Differential Side Bearing |              |  |
| FCS-BS-1802 | 0019806902    |  | Pinion Head Bearing       |              |  |
| FCS-BS-1803 | A0038353501   |  | Heater Exchanger          |              |  |
| FCS-BS-1804 | A0009938276   |  | Oil Pump Chain            |              |  |
| FCS-BS-1805 | 0039977594    |  | Timing Chain              |              |  |

|             |                                                                    |                                                                                     |                                |                        |  |
|-------------|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|------------------------|--|
| FCS-BS-1806 | A6510500800                                                        |     | Chain Adjuster                 |                        |  |
| FCS-BS-1807 | 6511811101<br>6511802001<br>A/R6511811101                          |    | Oil Pump                       | OM651                  |  |
| FCS-BS-1808 | 6511802801                                                         |    | Oil Pump                       | 2.1L L4-DIESEL         |  |
| FCS-BS-1809 | 6112300115                                                         |    | Pulley For Power Steering Pump |                        |  |
| FCS-BS-1810 | 0015458709                                                         |    | Brake Light Switch             |                        |  |
| FCS-BS-1811 | 6112000015                                                         |    | Engine Coolant Thermostat      |                        |  |
| FCS-BS-1812 | 6110500101                                                         |   | Camshaft                       |                        |  |
| FCS-BS-1813 | 6111550415                                                         |  | Freewheel Clutch Alternator    |                        |  |
| FCS-BS-1814 | 2711550115                                                         |  | Alternator Pulley              |                        |  |
| FCS-BS-1815 | HU718-1K                                                           |  | Oil Filter                     |                        |  |
| FCS-BS-1816 | 0018305708                                                         |  | Interior Blower Motor          | SPRINTER<br>VWLT 96-06 |  |
| FCS-BS-1817 | 0008352285                                                         |  | Blower Motor                   |                        |  |
| FCS-BS-1818 | 0002308011<br>0002306511<br>0002308111<br>0012301411<br>0012302811 |  | AC Compressor                  |                        |  |
| FCS-BS-1819 | 2308300184                                                         |  | A/C Expansion Valve            |                        |  |

|             |                          |                                                                                     |                                                     |                            |  |
|-------------|--------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------|----------------------------|--|
| FCS-BS-1820 | 1863869012<br>0189812510 |     | Bearing                                             |                            |  |
| FCS-BS-1821 | 9068200040               |    | Wiper Linkage                                       | SPRINTER 906<br>VW CRAFTER |  |
| FCS-BS-1822 | 0018204945               |    | Wiper Blade                                         |                            |  |
| FCS-BS-1823 | 6398200408               |    | Rear Wiper Motor                                    |                            |  |
| FCS-BS-1824 | 6398201008               |    | Rear Wiper Motor                                    |                            |  |
| FCS-BS-1825 | 9064230420               |    | Protection Of Brake Pads                            | SPRINTER 906               |  |
| FCS-BS-1826 | 0064208420               |   | Front Brake Pad                                     | VITO                       |  |
| FCS-BS-1827 | A0064204420              |  | Rear Break Pad                                      | VITO                       |  |
| FCS-BS-1828 | 6677200096               |  | Mercedes Vario Interior<br>HandleAssembly Side Door | VARIO                      |  |
| FCS-BS-1829 | 9013200089               |  | Stabilizer Link                                     | SPRINTER 901               |  |
| FCS-BS-1830 | 6395010701               |  | Radiator                                            |                            |  |
| FCS-BS-1831 | A0000941048              |  | Mass Airflow Sensor                                 |                            |  |
| FCS-BS-1832 | A0008356207              |  | Blower Motor Assy                                   |                            |  |
| FCS-BS-1833 | 6393202213               |  | Shock Absorber                                      |                            |  |

|             |                                         |                                                                                     |                                     |  |  |
|-------------|-----------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|--|--|
| FCS-BS-1834 | A6393261000                             |     | Shock Absorber                      |  |  |
| FCS-BS-1835 | 0064667801                              |    | Power Steering Pump                 |  |  |
| FCS-BS-1836 | 0024662601                              |    | Power Steering Pump                 |  |  |
| FCS-BS-1837 | 0054662401<br>0054662501                |    | Power Steering Pump                 |  |  |
| FCS-BS-1838 | A6395000593                             |    | Fan Blade Assy                      |  |  |
| FCS-BS-1839 | A0015005293<br>3136613299<br>6395030001 |    | Fan Collection Assy                 |  |  |
| FCS-BS-1840 | 0012523305                              |   | Clutch Disc                         |  |  |
| FCS-BS-1841 | 0091533128                              |  | Pressure Converter Valve            |  |  |
| FCS-BS-1842 | 0051535528                              |  | Pressure Converter, Exhaust Control |  |  |
| FCS-BS-1843 | 0123335002                              |  | Alternator Generator                |  |  |
| FCS-BS-1844 | 6111550315/28619                        |  | Alternator Pulley                   |  |  |
| FCS-BS-1845 | 1197311239                              |  | Voltage                             |  |  |
| FCS-BS-1846 | 28903803                                |  | Voltage                             |  |  |
| FCS-BS-1847 | 9012680143                              |  | Selected Shift Cable Clap           |  |  |



|               |                   |                                                                                     |                                   |  |  |
|---------------|-------------------|-------------------------------------------------------------------------------------|-----------------------------------|--|--|
| FCS-BS-1848   | 9066301231        |     | BRACKET                           |  |  |
| FCS-BS-1849   | 9068204169 RH RHD |    | SLIDING DOOR SNAKE                |  |  |
| FCS-BS-1850   | 9068890014 L      |    | BUMPER COVER UPPER BRACKET<br>L   |  |  |
| FCS-BS-1851   | 9068890114 R      |    | BUMPER COVER UPPER BRACKET<br>R   |  |  |
| FCS-BS-1852   | 9108200200 LH     |    | TAIL LAMP LEFT<br>EURO BULB TYPE  |  |  |
| FCS-BS-1853   | 9108200300 RH     |    | TAIL LAMP RIGHT<br>EURO BULB TYPE |  |  |
| FCS-BS-1854   | 9108205200 LH     |    | TAIL LAMP LEFT<br>EURO LED TYPE   |  |  |
| FCS-BS-1855   | 9108205300 RH     |  | TAIL LAMP RIGHT<br>EURO LED TYPE  |  |  |
| FCS-BS-1855-1 |                   |  | CIRCUIT BOARD                     |  |  |
| FCS-BS-1855-2 |                   |  | TAIL LAMP LEFT<br>USA BULB TYPE   |  |  |
| FCS-BS-1855-3 |                   |  | TAIL LAMP RIGHT<br>USA BULB TYPE  |  |  |
| FCS-BS-1856   | 9108852600        |  | Grille                            |  |  |
| FCS-BS-1857   |                   |  | GRILLE CHROMED COVER              |  |  |
| FCS-BS-1858   | 9108880000        |  |                                   |  |  |
| FCS-BS-1859   | 9108852700        |  | GRILLE WITH STRIPE                |  |  |

|             |                                                                                            |                                                                                     |                  |  |  |
|-------------|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------|--|--|
| FCS-BS-1860 | 9108853800 (左上)<br>9108853700 (右上)<br>9108854000 (左中)<br>9108853900 (右中)<br>9108854100 (下) |     | STRIPE           |  |  |
| FCS-BS-1861 | 9109060200 LH                                                                              |    | Head Lamp LH     |  |  |
| FCS-BS-1862 | 9109060300 RH                                                                              |    | Head Lamp RH     |  |  |
| FCS-BS-1863 | 9108810000 LH                                                                              |    | Fender,L         |  |  |
| FCS-BS-1864 | 9108810100 RH                                                                              |    | Fender,R         |  |  |
| FCS-BS-1865 | 9108890000                                                                                 |    | Mudflap          |  |  |
| FCS-BS-1866 | 9108890100                                                                                 |   | Mudflap          |  |  |
| FCS-BS-1867 | 9078890200                                                                                 |  | Mudflap          |  |  |
| FCS-BS-1868 | 9078890300                                                                                 |  | Mudflap          |  |  |
| FCS-BS-1869 | 9068800257                                                                                 |  | Engine Hood      |  |  |
| FCS-BS-1870 | 9108204800 LH                                                                              |  | REFLECTOR LH     |  |  |
| FCS-BS-1871 | 9108204900 RH                                                                              |  | REFLECTOR RH     |  |  |
| FCS-BS-1872 | 9078853600 LH                                                                              |  | BUMPER CORNER LH |  |  |
| FCS-BS-1873 | 9078853500 RH                                                                              |  | BUMPER CORNER RH |  |  |
| FCS-BS-1874 | 9078801100                                                                                 |  | FOOT STEP        |  |  |

|             |                                |                                                                                     |                           |  |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------|--|--|
| FCS-BS-1875 |                                |     | SPRINTER 2019             |  |  |
| FCS-BS-1876 |                                |    | DOOR HANDLE CHROMED COVER |  |  |
| FCS-BS-1877 |                                |    | DOOR HANDLE CHROMED COVER |  |  |
| FCS-BS-1878 | 9106905700 LH<br>9106900902 LH |    | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1879 | 9106907200 RH<br>9106901002 RH |    | PROTECTIVE STRIP RH       |  |  |
| FCS-BS-1880 | 9106905800 LH<br>9106901102 LH |    | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1881 | 9106907300 RH<br>9106901202 RH |    | PROTECTIVE STRIP RH       |  |  |
| FCS-BS-1882 | 9106900600 LH                  |  | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1883 | 9106906800 RH                  |  | PROTECTIVE STRIP RH       |  |  |
| FCS-BS-1884 | 9106900000 LH                  |  | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1885 | 9106900100 RH                  |  | PROTECTIVE STRIP RH       |  |  |
| FCS-BS-1886 | 9106906100 LH                  |  | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1887 | 9106907600 RH                  |  | PROTECTIVE STRIP RH       |  |  |
| FCS-BS-1888 | 9106900200 LH                  |  | PROTECTIVE STRIP LH       |  |  |
| FCS-BS-1889 | 9106900300 RH                  |  | PROTECTIVE STRIP RH       |  |  |

|             |                                |                                                                                     |                     |  |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------|--|--|
| FCS-BS-1890 | 9108803700 LH                  |     | PROTECTIVE STRIP LH |  |  |
| FCS-BS-1891 | 9108803800 RH                  |    | PROTECTIVE STRIP RH |  |  |
| FCS-BS-1892 |                                |    | PROTECTIVE STRIP LH |  |  |
| FCS-BS-1893 | 9106907000 RH                  |    | PROTECTIVE STRIP RH |  |  |
| FCS-BS-1894 | 9106909900 LH                  |    | PROTECTIVE STRIP LH |  |  |
| FCS-BS-1895 |                                |    | PROTECTIVE STRIP RH |  |  |
| FCS-BS-1896 | 9106900301 LH                  |    | PROTECTIVE STRIP LH |  |  |
| FCS-BS-1897 |                                |  | PROTECTIVE STRIP RH |  |  |
| FCS-BS-1898 |                                |  | PROTECTIVE STRIP LH |  |  |
| FCS-BS-1899 | 9106900201 RH                  |  | PROTECTIVE STRIP RH |  |  |
| FCS-BS-1900 |                                |  | MIRROR MANUAL       |  |  |
| FCS-BS-1901 |                                |  | MIRROR ELECTRICAL   |  |  |
| FCS-BS-1902 | 9109064700 LH<br>9109064600 RH |  | MIRROR LAMP         |  |  |
| FCS-BS-1903 | 9108112900 LH<br>9108112800 RH |  | BIG GLASS UNIT      |  |  |
| FCS-BS-1904 | 9108113700 LH<br>9108113600 RH |  | SMALL GLASS UNIT    |  |  |
| FCS-BS-1905 | 9108114100 LH<br>9108114000 RH |  | BLACK COVER         |  |  |

|             |                                |                                                                                     |                                       |                       |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|-----------------------|--|
| FCS-BS-1906 | 9108113800 LH<br>9108113900 RH |     | COVER HOUSING                         |                       |  |
| FCS-BS-1907 | 9108111700 LH<br>9108111600 RH |    | MIRROR ARM                            |                       |  |
| FCS-BS-1908 | 4159062700 LH                  |    | TAIL LAMP LH                          | MB CITAN              |  |
| FCS-BS-1909 | 4159062800 RH                  |    | TAIL LAMP RH                          | MB CITAN              |  |
| FCS-BS-1910 | 963027201 LH                   |    | MIRROR LH                             | MB CITAN              |  |
| FCS-BS-1911 | 963010714 RH                   |    | MIRROR RH                             | MB CITAN              |  |
| FCS-BS-1912 | 220-17766                      |    | TAIL LAMP LH                          | MB CITAN              |  |
| FCS-BS-1913 |                                |  | TAIL LAMP RH                          | MB CITAN              |  |
| FCS-BS-1914 | 9068203661 LH                  |  | HEAD LAMP LH                          | FREIGHTLINR SPRINTER  |  |
| FCS-BS-1915 | 9068203761 RH                  |  | HEAD LAMP RH                          | FREIGHTLINR SPRINTER  |  |
| FCS-BS-1916 | 9068880623                     |  | FREIGHT LINER GRILLE                  | FREIGHTLINR SPRINTER  |  |
| FCS-BS-1917 | 9068206000<br>1EJ011.030-45    |  | HEAD LAMP LH                          | SPRINTER US 2014-2018 |  |
| FCS-BS-1918 | 9068206100<br>1EJ011.030-46    |  | HEAD LAMP RH                          | SPRINTER US 2014-2018 |  |
| FCS-BS-1919 | 9109060400<br>90162418AF       |  | Head Lamp Electric(USA TYPE)<br>LEFT  |                       |  |
| FCS-BS-1920 | 9109060500<br>90162419AF       |  | Head Lamp Electric(USA TYPE)<br>RIGHT |                       |  |

|             |                                |                                                                                     |                               |  |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|-------------------------------|--|--|
| FCS-BS-1921 |                                |     | HEAD LAMP LED EURO TYPE LEFT  |  |  |
| FCS-BS-1922 |                                |    | HEAD LAMP LED EURO TYPE RIGHT |  |  |
| FCS-BS-1923 | 9109065400                     |    | HEAD LAMP LED USA TYPE LEFT   |  |  |
| FCS-BS-1924 | 9109066200                     |    | HEAD LAMP LED USA TYPE RIGHT  |  |  |
| FCS-BS-1925 | 9109062900 LH<br>RH            |    | FOG LAMP                      |  |  |
| FCS-BS-1926 | 9106962600                     |    | GRILLE                        |  |  |
| FCS-BS-1927 | 9109606300                     |   | BRAKE LIGHT                   |  |  |
| FCS-BS-1928 | 9078800900                     |  | RADIATOR BRACKET              |  |  |
| FCS-BS-1929 | 9068800403                     |  | RADIATOR BRACKET              |  |  |
| FCS-BS-1930 | 9107408900 LH<br>9107409000 RH |  | HINGE (UP)                    |  |  |
| FCS-BS-1931 | 9107409500 LH<br>9107409600 RH |  | HINGE (LOWER)                 |  |  |
| FCS-BS-1932 | 9108859300                     |  | FRONT BUMPER WITHOUT HOLE     |  |  |
| FCS-BS-1933 | 9108858100                     |  | FRONT BUMPER WIT HOLE         |  |  |
| FCS-BS-1934 |                                |  | STEP                          |  |  |
| FCS-BS-1935 | 9108850600                     |  | TRAILER COVER                 |  |  |
| FCS-BS-1936 | 9108854300 LH<br>9108854400 RH |  | FOG LAMP CASE                 |  |  |

|             |                                |                                                                                     |                           |                         |  |
|-------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------|-------------------------|--|
| FCS-BS-1937 | 9108850400 LH<br>9108850500 RH |     | BRACKET                   |                         |  |
| FCS-BS-1938 | 9108801400<br>9108854500       |    | REAR BUMPER               |                         |  |
| FCS-BS-1939 | 9108360700 RH<br>9108360300 LH |    | GRILLE                    |                         |  |
| FCS-BS-1940 | 9076370800 LH<br>9076370900 RH |    | METAL PANELLING           |                         |  |
| FCS-BS-1941 | 9076371800 LH<br>9076371900 RH |    | METAL PANELLING           |                         |  |
| FCS-BS-1942 | 9106375701                     |    | METAL PANELLING           |                         |  |
| FCS-BS-1943 | 9106374700 LH<br>9106375000 RH |    | METAL PANELLING           |                         |  |
| FCS-BS-1944 |                                |   | MIRROR LONG ARM,(2019),RH | MERCEDES SPRINTER 2019- |  |
| FCS-BS-1945 |                                |  | MIRROR LONG ARM,(2019),LH | MERCEDES SPRINTER 2019- |  |





**FREECARS (CHINA) COMPANY LIMITED**

**GUANGZHOU SUN ASIA IMPORT AND EXPORT CO.,LTD**

RM801-803,Goctic Centre,No.450,Huanshi East Road,Yuexiu District Guangzhou City

Tel: +86-20-84201892 Fax: +86-20-84201893 Mob: +86-13002023915

Email: freecars@163.com sales@freecars.com.cn

Website: www.freecarsautoparts.com

## Mercedes Van Other Spare parts

| ITEM NO.   | OEM           | PHOTOS                                                                              | DESCRIPIFION               | MODEL                           | REMARK                                         |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|---------------------------------|------------------------------------------------|
| FCS-BP-001 | 364 010 11 80 |    | Gasket Set ,Wet Sump       | 309;508;608<br>609;709;711      | OM 314<br>OM 364                               |
| FCS-BP-002 | 352 032 11 05 |    | Ring Gear To Flywheel      | 508<br>608<br>609<br>709        | OM 314<br>OM 352<br>OM 353<br>OM 364<br>OM 366 |
| FCS-BP-003 | 352 032 13 05 |    | Ring Gear To Flywheel      |                                 | OM 352<br>OM 353<br>OM 357<br>OM 366<br>OM 904 |
| FCS-BP-004 | 366 052 01 05 |    | Ring Gear To Flywheel      |                                 | OM 352<br>OM 353<br>OM 357<br>OM 366<br>OM 904 |
| FCS-BP-005 | 615 050 09 16 |  | Timing Chain Guides        | MB 100<br>140<br>207 D<br>307   | OM 615<br>OM 616<br>OM 617                     |
| FCS-BP-006 | 000 070 24 53 |  | Vacuum Box                 |                                 | OM 615<br>OM 616<br>OM 617                     |
| FCS-BP-007 | 000 070 33 53 |  | Vacuum Box                 | SPRINTER 208<br>308<br>408      | OM 601<br>OM 602                               |
| FCS-BP-008 | 601 070 20 45 |  | Timing Gear Injection Pump |                                 | OM 602                                         |
| FCS-BP-009 | 000 090 01 51 |  | Rep.Kit.Fuel Pump          | MB 309;508;608<br>609;711;814 D | OM 314<br>OM 353<br>OM 364                     |
| FCS-BP-010 | 000 090 10 50 |  | Fuel Pump                  | MB 608<br>613<br>617<br>1120    | OM 352                                         |
| FCS-BP-011 | 000 091 21 90 |  | Fuel Pump                  | MB 608<br>613<br>617<br>1120    | OM 364                                         |

|            |               |                                                                                     |                        |                                   |                                                  |
|------------|---------------|-------------------------------------------------------------------------------------|------------------------|-----------------------------------|--------------------------------------------------|
| FCS-BP-012 | 000 090 22 50 |     | Fuel Pump              | MB 608<br>613<br>617<br>1120      | OM 364                                           |
| FCS-BP-013 | 244 701 00 33 |    | Rep.Kit.Hand Feed Pump | MB 608<br>613<br>617<br>1120      | OM 356<br>OM 366<br>OM 616                       |
| FCS-BP-014 | 000 090 00 50 |    | Rep.Kit.Hand Feed Pump | MB 608<br>613<br>617<br>1120      | OM 356<br>OM 366<br>OM 616                       |
| FCS-BP-015 | 000 090 02 10 |    | Rep.Kit.Hand Feed Pump | MB 608<br>613<br>617<br>1120      | OM 314<br>OM 352<br>OM 356<br>OM 364<br>OM 366   |
| FCS-BP-016 | 001 092 04 01 |    | Fuel Filter            | 207<br>307<br>407<br>507          | OM 615<br>OM 616<br>OM 617                       |
| FCS-BP-017 | 601 090 14 52 |    | Fuel Filter            | 210<br>307<br>308<br>312<br>412   | OM 601<br>OM 602.911<br>OM 602.961<br>OM 603.912 |
| FCS-BP-018 | 000 090 11 51 |  | Fuel Filter            | 609<br>709<br>711<br>811<br>814   | OM 314<br>OM 364<br>OM 366                       |
| FCS-BP-019 | 000 090 15 51 |  | Fuel Filter            | VARIO<br>ATEGO                    | OM 904<br>OM 906                                 |
| FCS-BP-020 | 000 477 31 15 |  | Fuel Filter            | TRUCK                             |                                                  |
| FCS-BP-021 | 000 092 15 05 |  | Fuel Filter            | TRUCK                             |                                                  |
| FCS-BP-022 | 366 180 08 09 |  | Oil Filter             | TRUCK                             | OM 366                                           |
| FCS-BP-023 | 615 184 00 25 |  | Oil Filter             | 207<br>208<br>209                 | OM 615<br>OM 616                                 |
| FCS-BP-024 | 000 180 16 09 |  | Oil Filter             | 614<br>812<br>814<br>815<br>VARIO | OM 904                                           |

|            |                                |                                                                                     |                            |                                             |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------|---------------------------------------------|----------------------------------|
| FCS-BP-025 | 000 180 23 38                  |     | Cover                      | 614<br>812<br>814<br>815<br>VARIO           | OM 904                           |
| FCS-BP-026 | 000 180 24 38                  |    | Cover                      | 614<br>812<br>814<br>815<br>VARIO           | OM 904                           |
| FCS-BP-027 | 001 094 47 04                  |    | Air Filter                 | BUS 303<br>TRUCK<br>1317K<br>1320K<br>1425K | W 600<br>W 673<br>W 674<br>W 676 |
| FCS-BP-028 | 001 094 94 04                  |    | Air Filter                 | 613;813<br>813K;1013<br>1017K;1113          | W 313                            |
| FCS-BP-029 | 001 094 96 04                  |    | Air Filter                 | 309<br>508<br>608<br>613                    | W 313<br>W 314                   |
| FCS-BP-030 | 002 094 60 04<br>002 094 70 04 |    | Air Filter                 | 207<br>208<br>209<br>210                    | OM 615<br>OM 616<br>OM 617       |
| FCS-BP-031 | 002 094 73 04                  |  | Air Filter                 | 811K<br>814K<br>817K<br>914K<br>1317K       | W 673<br>W 674<br>W 675          |
| FCS-BP-032 | 002 094 92 04                  |  | Air Filter                 | 609<br>709<br>VARIO<br>612<br>614           | W 667<br>W 668<br>W 669<br>W 670 |
| FCS-BP-033 | 002 094 93 04                  |  | Air Filter                 | 711;811;814<br>VARIO;612;614;815            | W 667<br>W 668<br>W 669<br>W 670 |
| FCS-BP-034 | 003 094 51 04                  |  | Air Filter                 | 209;210;307<br>310;409;410                  | W 601<br>W 602<br>W 611          |
| FCS-BP-035 | 631 094 01 04                  |  | Radiator Support Bracket,L | MB 100<br>MB 120                            | W 631                            |
| FCS-BP-036 | 364 096 19 99                  |  | Air Filter                 | 711<br>811<br>814                           | OM 364                           |
| FCS-BP-037 | 366 096 08 99                  |  | Turbocharger               | TRUCK                                       | OM 366                           |

|            |               |                                                                                     |                   |                                        |                                                 |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------|----------------------------------------|-------------------------------------------------|
| FCS-BP-038 | 004 151 36 01 |     | Starter           | 210;310;410<br>SPRINTER 212<br>312;412 | OM 602                                          |
| FCS-BP-039 | 004 151 59 01 |    | Starter           | 508;608;609<br>709;811;814             | OM 314<br>OM 352<br>OM 364<br>OM 366            |
| FCS-BP-040 | 364 159 00 01 |    | Heater Plug       | 609                                    | OM 364<br>OM 366                                |
| FCS-BP-041 | 102 200 02 22 |    | Fan Clutch(Visco) | T1;TN;407<br>408 D;410;T2;LN1          | OM 611;OM 612<br>W 901;W 902<br>W 903;W 904     |
| FCS-BP-042 | 602 200 01 22 |    | Fan Clutch(Visco) | 408<br>409<br>410                      | OM 602.940<br>OM 602.990<br>OM 602.993<br>W 611 |
| FCS-BP-043 | 603 200 05 22 |    | Fan Clutch(Visco) | MB 210<br>310<br>410<br>507            | OM 603                                          |
| FCS-BP-044 | 616 200 03 22 |  | Fan Clutch(Visco) | 207<br>307<br>407                      | OM 615<br>OM 616<br>W 601<br>W 602              |
| FCS-BP-045 | 617 200 03 22 |  | Fan Clutch(Visco) | 207<br>307<br>507                      | OM 617                                          |
| FCS-BP-046 | 904 200 11 22 |  | Fan Clutch(Visco) | VARIO<br>ATEGO                         | OM 904<br>OM 906                                |
| FCS-BP-047 | 617 200 03 23 |  | Fan Blade         | 210<br>408<br>409<br>410               | OM 364.959<br>OM 602.930<br>OM 617<br>W 611     |
| FCS-BP-048 | 314 200 12 23 |  | Fan Blade         | 209<br>309<br>409                      | OM 314<br>OM 364                                |
| FCS-BP-049 | 102 200 43 01 |  | Water Pump        | MB 210<br>310<br>410                   | M 102<br>W 601                                  |
| FCS-BP-050 | 314 200 42 01 |  | Water Pump        | 309<br>508<br>608                      | OM 314                                          |

|            |                                |                                                                                     |                                   |                                     |                                             |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|-------------------------------------|---------------------------------------------|
| FCS-BP-051 | 353 200 56 01                  |     | Water Pump                        | 309<br>508<br>608                   | OM 314<br>OM 352                            |
| FCS-BP-052 | 364 200 20 01                  |    | Water Pump                        | 609<br>709<br>711<br>811<br>814     | OM 364                                      |
| FCS-BP-053 | 616 200 07 20                  |    | Water Pump                        | MB 100                              | OM 616<br>OM 617                            |
| FCS-BP-054 | 617 200 07 20                  |    | Water Pump                        | 209<br>309<br>409                   | OM 617                                      |
| FCS-BP-055 | 904 200 26 01                  |    | Water Pump                        | VARIO<br>ATEGO                      | OM 904<br>OM 906                            |
| FCS-BP-056 | 364 200 18 01                  |    | Rep.Kit.Water Pump                | 609<br>709<br>811<br>814            | OM 364<br>OM 366                            |
| FCS-BP-057 | 366 200 08 04                  |  | Rep.Kit.Water Pump                | 1017<br>1317                        | OM 366                                      |
| FCS-BP-058 | 115 200 00 58                  |  | Coolant Pipe                      | MB 207<br>309<br>409                | M 102                                       |
| FCS-BP-059 | 005 203 28 75                  |  | Thermostat                        | 609<br>709<br>711<br>811<br>814     | OM 314<br>OM 352<br>OM 364<br>OM 366        |
| FCS-BP-060 | 906 200 20 70                  |  | Tensioner Pulley Ribbed V Belt    | VARIO<br>614<br>814<br>815          | OM 904<br>OM 906                            |
| FCS-BP-061 | 604 200 01 14<br>601 200 03 14 |  | Vibration Absorber, V-Ribbed Belt | MB 208<br>210;310<br>408;410<br>507 | OM 601<br>OM 602                            |
| FCS-BP-062 | 314 223 01 12                  |  | Engine Mounting                   | 309<br>508<br>608                   | OM 314<br>OM 352<br>W 309<br>W 310          |
| FCS-BP-063 | 601 240 06 17                  |  | Engine Mounting                   | 207;208;209<br>210;307;310;410      | OM 601<br>OM 602<br>W 601<br>W 602<br>W 611 |

|            |               |                                                                                     |                  |                                                       |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|------------------|-------------------------------------------------------|-------------------------------------------|
| FCS-BP-064 | 601 240 09 17 |     | Engine Mounting  | 207;208;210<br>310;406;407<br>408;409;410             | W 601<br>W 602<br>W 611                   |
| FCS-BP-065 | 601 242 00 13 |    | Engine Mounting  | 207<br>208                                            | W 309<br>W 310                            |
| FCS-BP-066 | 000 241 36 13 |    | Engine Mounting  | ATEGO                                                 | W 668<br>W 670<br>W 673<br>W 674<br>W 688 |
| FCS-BP-067 | 309 241 02 13 |    | Engine Mounting  | 406<br>407<br>408<br>409<br>410                       | OM 364<br>OM 366<br>W 309                 |
| FCS-BP-068 | 310 241 03 13 |    | Engine Mounting  | 309<br>508<br>608<br>709                              | W 309<br>W 310<br>W 314                   |
| FCS-BP-069 | 310 242 01 13 |    | Engine Mounting  | 309;406;407<br>408;409;410<br>508;608                 | W 309<br>W 310                            |
| FCS-BP-070 | 631 241 00 65 |  | Engine Mounting  | MB 100<br>MB 120                                      | W 631                                     |
| FCS-BP-071 | 668 240 02 17 |  | Engine Mounting  | 609<br>709<br>711<br>811<br>814                       | W 601<br>W 602<br>W 611                   |
| FCS-BP-072 | 668 242 01 43 |  | Gearbox Mounting | 609<br>709<br>711                                     | W 668<br>W 670<br>W 673<br>W 674<br>W 688 |
| FCS-BP-073 | 673 240 04 17 |  | Engine Mounting  | 709K;809K<br>811K;814K<br>914K;1117<br>1317           | W 673<br>W 674                            |
| FCS-BP-074 | 601 240 03 18 |  | Gearbox Mounting | 207;208;209;<br>210;307;308<br>310;407;408<br>409;410 | W 601<br>W 602<br>W 611                   |
| FCS-BP-075 | 601 240 07 18 |  | Gearbox Mounting | 207;208;209;<br>210;307;308<br>310;407;408<br>409;410 | W 601<br>W 602<br>W 611                   |
| FCS-BP-076 | 631 242 01 13 |  | Engine Mounting  | MB 100<br>MB 120                                      | W 631                                     |

|            |                                |                                                                                     |                        |                                                                              |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-077 | 000 250 40 15                  |     | Clutch Release Bearing | 309<br>508<br>608                                                            | W 309;W 310;W 314<br>W 316;W 380;W 385    |
| FCS-BP-078 | 000 250 51 15                  |    | Clutch Release Bearing | 207;208;209<br>210;307;310<br>410                                            | W 601<br>W 602<br>W 667                   |
| FCS-BP-079 | 001 250 08 15                  |    | Clutch Release Bearing | 609<br>709<br>711<br>811<br>814                                              | W 668<br>W 669<br>W 670<br>W 688          |
| FCS-BP-080 | 001 250 93 15                  |    | Clutch Release Bearing | 814K<br>817K<br>914K<br>1317K                                                | W 616;W 617;W 673<br>W 674;W 675;W 676    |
| FCS-BP-081 | 631 250 01 15                  |    | Clutch Release Bearing | MB 100<br>MB 120                                                             | W 631                                     |
| FCS-BP-082 | 002 250 51 15                  |    | Clutch Release Bearing | 1016; 1924;1023; ATEGO<br>1215; 715;1224; 814<br>1517; 815;1529; 817<br>1923 | W 970                                     |
| FCS-BP-083 | 002 250 52 15<br>002 250 72 15 |  | Releaser               | ATEGO<br>AXOR<br>UNIMOG                                                      |                                           |
| FCS-BP-084 | 002 250 55 15                  |  | Clutch Release Bearing | ATEGO<br>ACTROS                                                              |                                           |
| FCS-BP-085 | 002 250 58 15<br>002 250 74 15 |  | Releaser               | ATEGO<br>AXOR<br>UNIMOG                                                      |                                           |
| FCS-BP-086 | 000 254 02 20                  |  | Clutch Release Bearing | 612;614<br>812;814<br>815;VARIO                                              | W 668<br>W 669<br>W 670                   |
| FCS-BP-087 | 002 250 97 03                  |  | Clutch Disc            | TRUCK                                                                        | W 383<br>W 385<br>W 387<br>W 389          |
| FCS-BP-088 | 003 250 84 03                  |  | Clutch Disc            | 1013; 1613K;1017; 1617K<br>817K; 2219K;917K; 2224K<br>1117K;1413K;1419K      | W 380<br>W 381<br>W 385<br>W 676<br>W 684 |
| FCS-BP-089 | 005 250 01 03                  |  | Clutch Disc            | TRUCK<br>BUS                                                                 | W 371;W 385<br>W 391;W 393<br>W 620;W 623 |







|            |                                                 |                                                                                     |                       |                                                                        |                                           |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-090 | 007 250 95 03<br>007 250 96 03<br>007 250 97 03 |     | Clutch Disc           | 207;208;209<br>210;307;310<br>410                                      | W 601<br>W 602<br>W 611                   |
| FCS-BP-091 | 009 250 40 03                                   |    | Clutch Disc           | 0302; 1813;0303; 1817<br>0304; 1819;1313;1513<br>1617;1621             | W 352<br>W 355<br>W 360<br>W 373          |
| FCS-BP-092 | 009 250 91 03                                   |    | Clutch Disc           | 207<br>208<br>209<br>210<br>(04.77-02.96)                              | W 601                                     |
| FCS-BP-093 | 010 250 85 03                                   |    | Clutch Disc           | 609;709<br>711;809<br>811;814                                          | W 318<br>W 668<br>W 669<br>W 670<br>W 684 |
| FCS-BP-094 | 010 250 86 03                                   |    | Clutch Disc           | 711<br>811<br>814<br>814K                                              | W 318<br>W 669<br>W 670<br>W 684          |
| FCS-BP-095 | 013 250 21 03<br>019 250 68 03                  |    | Clutch Disc           | 1729;1735;1834<br>1838;1922;1927<br>2024;2027;2435                     | W 396<br>W 613<br>W 655<br>W 657<br>W 659 |
| FCS-BP-096 | 014 250 94 03                                   |  | Clutch Disc           | 309;406;407<br>408;409;410<br>508;608                                  | W 309<br>W 310<br>W 316                   |
| FCS-BP-097 | 019 250 42 03                                   |  | Clutch Disc           | VARIO 812<br>814<br>815                                                |                                           |
| FCS-BP-098 | 631 250 03 03                                   |  | Clutch Disc           | MB 100<br>MB 120                                                       | W 631                                     |
| FCS-BP-099 | 003 250 10 04                                   |  | Clutch Pressure Plate | 309;406<br>407;408<br>409;410<br>508;608                               | W 309<br>W 310<br>W 314<br>W 316          |
| FCS-BP-100 | 003 250 93 04                                   |  | Clutch Pressure Plate | 609;709;711<br>809;811;814                                             | W 668<br>W 669<br>W 670                   |
| FCS-BP-101 | 003 250 98 04                                   |  | Clutch Pressure Plate | 814K<br>914K<br>1017K<br>1217K                                         | W 673<br>W 674<br>W 684                   |
| FCS-BP-102 | 003 250 99 04                                   |  | Clutch Pressure Plate | 814; 1317K;814K; 1317AK<br>817K; 1514K;914K; 1517K<br>917K;1114K;1117K | W 674<br>W 675<br>W 676<br>W 676<br>W 684 |

|            |                                                                                                |                                                                                     |                        |                                                               |                                           |
|------------|------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------|---------------------------------------------------------------|-------------------------------------------|
| FCS-BP-103 | 004 250 24 04                                                                                  |     | Clutch Pressure Plate  | 817K; 2521;917K; 2622<br>1117K; 2635;1317K;1517K<br>1935;2417 | W 371;W 652<br>W 653;W 654<br>W 676;W 677 |
| FCS-BP-104 | 004 250 51 04                                                                                  |    | Clutch Pressure Plate  | 609;709;711<br>VARIO;612;614;812<br>(04.86-02.94)             | W 668<br>W 669<br>W 670<br>W 688          |
| FCS-BP-105 | 005 250 18 04                                                                                  |    | Clutch Pressure Plate  | 207<br>208<br>310<br>409<br>410                               | W 601<br>W 602<br>W 611                   |
| FCS-BP-106 | 006 250 34 04                                                                                  |    | Clutch Pressure Plate  | ATEGO<br>AXOR<br>UNIMOG                                       | OM 906                                    |
| FCS-BP-107 | 006 250 67 04                                                                                  |    | Engine Mounting        | ATEGO<br>VARIO                                                |                                           |
| FCS-BP-108 | 115 290 00 29                                                                                  |    | Release Yoke           | 111; 408;123; 409<br>207; 509;208;210<br>307;310;407          | W 109;W 309;W 601<br>W 602;W 611;W 667    |
| FCS-BP-109 | 001 295 70 06                                                                                  |   | Clutch Master Cylinder | TRUCK                                                         | W 651<br>W 652<br>W 653<br>W 654<br>W 655 |
| FCS-BP-110 | 001 295 86 06<br>001 295 11 06<br>F9M003ABE<br>001 295 76 06<br>001 295 17 06<br>001 295 79 06 |  | Clutch Master Cylinder | 207;208;209;210<br>307;310;410                                | W 601<br>W 602<br>W 611                   |
| FCS-BP-111 | 001 295 87 06                                                                                  |  | Clutch Master Cylinder | 309;406;407<br>408;409;410<br>508;608;709                     | W 309<br>W 310<br>W 314                   |
| FCS-BP-112 | 001 295 91 06                                                                                  |  | Clutch Master Cylinder | ATEGO                                                         | W 375<br>W 950<br>W 970<br>W 972          |
| FCS-BP-113 | 001 295 97 06                                                                                  |  | Clutch Master Cylinder | 814K<br>817K<br>1317K<br>1320K                                | W 637;W 674;W 675<br>W 676;W 677;W 678    |
| FCS-BP-114 | 002 295 10 06                                                                                  |  | Clutch Master Cylinder | ATEGO                                                         |                                           |
| FCS-BP-115 | 000 285 83 07<br>308 295 70 07                                                                 |  | Clutch Slave Cylinder  | 406; 811;407; 913<br>408; 1013;409; 1113<br>410;508;608;709   | W 309<br>W 310<br>W 314<br>W 318<br>W 378 |

|            |                                                                                                    |                                                                                     |                                |                                                                              |                                                    |
|------------|----------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|------------------------------------------------------------------------------|----------------------------------------------------|
| FCS-BP-116 | 000 295 89 07                                                                                      |     | Clutch Slave Cylinder          | MB 100<br>MB 120                                                             | W 631                                              |
| FCS-BP-117 | 001 295 96 07                                                                                      |    | Clutch Master Cylinder         | 609;613;709;614;<br>809;811;812;814<br>817K;917K<br>1117K;1517K<br>VARIO 612 | W 371;W 619;W 668<br>W 669;W 670;W 676<br>W 677    |
| FCS-BP-118 | 002 295 07 07<br>001 295 40 07<br>001 295 58 07<br>001 295 74 07<br>001 295 07 07<br>673 295 00 07 |    | Clutch Slave Cylinder          | 814K<br>817K<br>1317K<br>1320K                                               | W 371;W 384;W 392<br>W 660;W 685;W 688<br>W 696    |
| FCS-BP-119 | 002 295 13 07                                                                                      |    | Clutch Slave Cylinder          | 207;208;209<br>210;307;310<br>410                                            | W 601<br>W 602<br>W 611<br>W 667                   |
| FCS-BP-120 | 631 290 00 12                                                                                      |    | Clutch Master Cylinder         | MB 100<br>MB 120                                                             | W 631                                              |
| FCS-BP-121 | 667 290 02 12                                                                                      |   | Clutch Master Cylinder         | 507;508;509;510<br>609;613;709;711<br>811;814                                | W 667<br>W 668<br>W 669<br>W 670                   |
| FCS-BP-122 | 620 268 00 42                                                                                      |  | Gear Lever Knob                | TRUCK                                                                        |                                                    |
| FCS-BP-123 | 309 300 09 07                                                                                      |  | Wire Cable Knob                | 309<br>508<br>608                                                            | W 309<br>W 310                                     |
| FCS-BP-124 | 970 317 03 18                                                                                      |  | Cable, Cab Tilt Device         | ATEGO                                                                        | W 375<br>W 950<br>W 970<br>W 972                   |
| FCS-BP-125 | 004 542 42 07                                                                                      |  | Km(Kilometer)Cable             |                                                                              | W 314;W 318<br>W 346;W 381<br>W 385;W 617<br>W 620 |
| FCS-BP-126 | 670 750 00 59                                                                                      |  | Hood Opener Cable              | 609<br>709<br>711<br>811<br>814                                              | W 669<br>W 670                                     |
| FCS-BP-127 | 958 891 00 00                                                                                      |  | Cable, stowage Box Flap Opener | ATEGO                                                                        |                                                    |
| FCS-BP-128 | 631 293 07 38                                                                                      |  | Clutch Cable                   | MB 100<br>MB 120                                                             | W 631                                              |

|            |                 |                                                                                     |                        |                                           |                         |
|------------|-----------------|-------------------------------------------------------------------------------------|------------------------|-------------------------------------------|-------------------------|
| FCS-BP-129 | 631 300 05 30   |     | Wire Cable             | MB 100<br>MB 120                          | W 631                   |
| FCS-BP-130 | 673 301 00 23   |    | Clutch Release Bearing | 814K<br>817K<br>914K<br>1317K             | W 673<br>W 674<br>W 676 |
| FCS-BP-131 | 309 320 12 02   |    | Spring,Front           | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-132 | 309 320 33 06   |    | Spring,Front           | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-133 | 309 320 00 93   |    | Spring,Rear,Leaf No:1  | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-134 | 309 320 02 94   |    | Spring,Rear,Leaf No:1  | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-135 | 309 321 11 12   |  | Spring,Front,Leaf No:2 | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-136 | 309 324 30 12   |  | Spring,Front,Leaf No:2 | 309;406;407;408<br>409;410;508<br>608;613 | W 309                   |
| FCS-BP-137 | 601 320 06 02   |  | Spring,Front           | 207;208;209;210<br>307;310;410            | W 601<br>W 602          |
| FCS-BP-138 | 601 320 06 02-1 |  | Spring,Rear,Leaf No:1  | 207;208;209;210<br>307;310;410            | W 601<br>W 602          |
| FCS-BP-139 | 601 320 06 02-2 |  | Spring,Front,Leaf No:2 | 207;208;209;210<br>307;310;410            | W 601<br>W 602          |
| FCS-BP-140 | 601 320 20 06   |  | Spring,Rear            | 207;208;209<br>307;308;309                | W 601                   |
| FCS-BP-141 | 601 320 22 06   |  | Spring,Rear            | 210<br>310                                | W 601                   |

|            |                           |                                                                                     |                        |                                                    |                         |
|------------|---------------------------|-------------------------------------------------------------------------------------|------------------------|----------------------------------------------------|-------------------------|
| FCS-BP-142 | 601 320 05 93             |     | Spring,Rear,Leaf No:2  | 207;208;209<br>307;308;309                         | W 601                   |
| FCS-BP-143 | 601 320 06 93             |    | Spring,Rear,Leaf No:1  | 207;208;209<br>307;308;309                         | W 601                   |
| FCS-BP-144 | 601 320 10 93             |    | Spring,Rear,Leaf No:1  | 210<br>310                                         | W 601                   |
| FCS-BP-145 | 601 320 11 93             |    | Spring,Rear,Leaf No:2  | 209<br>210<br>307<br>310                           | W 601                   |
| FCS-BP-146 | 611 320 37 06             |    | Spring,Rear            | 407<br>409<br>410                                  | W 611                   |
| FCS-BP-147 | 611 320 02 93             |   | Spring,Rear,Leaf No:1  | 408<br>409<br>410<br>507                           | W 611                   |
| FCS-BP-148 | 611 324 03 12             |  | Spring,Rear,Leaf No:2  | 408<br>409<br>410<br>507                           | W 611                   |
| FCS-BP-149 | 667 320 40 02             |  | Spring,Front           | 507;508;509;510<br>609;709;711;811<br>814          | W 667<br>W 668<br>W 669 |
| FCS-BP-150 | 667 320 40 02-1           |  | Spring,Front,Leaf No:1 | 507;508;509;510<br>609;709;711;811<br>814          | W 667<br>W 668<br>W 669 |
| FCS-BP-151 | 66732002<br>667 320 32 02 |  | Spring,Front,Leaf No:2 | 507;508;509;510<br>609;709;711;811<br>814;VARIO    | W 667<br>W 668<br>W 669 |
| FCS-BP-152 | 667 320 34 02             |  | Spring,Rear            | 507;508;509;510<br>609;709;711;811<br>814;VARIO    | W 667<br>W 668<br>W 669 |
| FCS-BP-153 | 667 320 34 02-1           |  | Spring,Rear,Leaf No:1  | 507;508;509;510<br>609;709;711;811<br>814<br>VARIO | W 667<br>W 668<br>W 669 |
| FCS-BP-154 | 667 320 34 02-2           |  | Spring,Rear,Leaf No:2  | 507;508;509;510<br>609;709;711;811<br>814<br>VARIO | W 667<br>W 668<br>W 669 |


|            |                 |                                                                                     |                                |                                                                                  |                                                 |
|------------|-----------------|-------------------------------------------------------------------------------------|--------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------|
| FCS-BP-155 | 674 320 40 02   |     | Spring,Front                   | 814K<br>817K<br>914K<br>1317K                                                    | W 674<br>W 676                                  |
| FCS-BP-156 | 674 320 40 02-1 |    | Spring,Front,Leaf No:1         | 814K<br>817K<br>914K<br>1317K                                                    | W 674<br>W 676                                  |
| FCS-BP-157 | 674 320 40 02-2 |    | Spring,Front,Leaf No:2         | 814K;817K;914K;917K<br>1117K;1317K;1517K                                         | W 674<br>W 677                                  |
| FCS-BP-158 | 674 320 50 06   |    | Spring,Rear                    | 814K;817K;914K;917K<br>1117K;1317K;1517K                                         | W 674<br>W 678                                  |
| FCS-BP-159 | 674 320 50 06-1 |    | Spring,Front,Leaf No:1         | 814K;817K;914K;917K<br>1117K;1317K;1517K                                         | W 674<br>W 678                                  |
| FCS-BP-160 | 674 320 50 06-2 |    | Spring,Front,Leaf No:2         | 814K;817K;914K;917K<br>1117K;1317K;1517K                                         | W 674<br>W 679                                  |
| FCS-BP-161 | 310 320 00 50   |  | Rubber Bushing To Rear Spring  | 309<br>508<br>608<br>613 D<br>Q 309                                              | W 310<br>W 313                                  |
| FCS-BP-162 | 667 320 00 44   |  | Rubber Bushing To Rear Spring  | 609;709;711<br>809;811;814                                                       | W 667<br>W 668<br>W 669<br>W 670                |
| FCS-BP-163 | 970 320 00 44   |  | Bush,Leaf Spring               | ATEGO                                                                            | W 375<br>W 958<br>W 970<br>W 972<br>W 974       |
| FCS-BP-164 | 970 320 01 44   |  | Bush,Leaf Spring               | ATEGO                                                                            | W 375<br>W 958<br>W 970<br>W 972<br>W 974       |
| FCS-BP-165 | 970 320 03 44   |  | Bush,Leaf Spring               | ATEGO<br>815<br>817<br>1317                                                      | W 375;W 675;W 676<br>W 679;W 958;W 970<br>W 972 |
| FCS-BP-166 | 319 324 07 50   |  | Rubber Bushing To Front Spring | MB 100<br>MB 120                                                                 | W 375;W 675;W 676<br>W 679;W 958;W 970<br>W 972 |
| FCS-BP-167 | 667 325 00 84   |  | Spring Buffer                  | 507 D;508 D/DK<br>510;609 D;709 D<br>711 D;809 D/DT<br>811D/DA/DK<br>814 D.VARIO | W 667;W 668;W 669<br>W 670;W 690;W 903<br>W 904 |

|            |                                |                                                                                     |                                  |                                                                                    |                                                 |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------|
| FCS-BP-168 | 675 325 02 84                  |     | Rubber Busher,Suspension         | 814K;817K;914K<br>917K;1117K;1317K<br>1517K                                        |                                                 |
| FCS-BP-169 | 309 310 02 77                  |    | Buffer To Body Mounting,Rear     | 309;406;407;408<br>409;410;508;608<br>613 D;O309                                   | W 309<br>W 310<br>W 313                         |
| FCS-BP-170 | 309 310 07 77                  |    | Buffer To Body<br>Mounting,Front | 309<br>508<br>608<br>613 D<br>O 309                                                | W 309<br>W 310<br>W 313                         |
| FCS-BP-171 | 667 320 00 77                  |    | Rubber Busher,Suspension         | 814K;817K;914K<br>917K;1117K;1317K<br>1517K                                        |                                                 |
| FCS-BP-172 | 667 317 05 55                  |    | Cover To Frame Cab<br>Suspension | 507;508;509;510<br>609;709;711;809<br>811;814                                      | W 667<br>W 668<br>W 669<br>W 670                |
| FCS-BP-173 | 667 317 00 12                  |    | Cover To Frame Cab<br>Suspension | 609<br>709<br>711<br>814                                                           | W 371;W 384;W 392<br>W 660;W 685;W 688<br>W 696 |
| FCS-BP-174 | 631 330 00 75                  |  | Control Arm Bushing              | MB 100<br>140<br>160                                                               | W 631                                           |
| FCS-BP-175 | 309 320 00 73<br>314 326 01 53 |  | Bushing To Torsion Bar           | 508;608;609;709<br>811;814;814K;817K                                               | W 308;W 378;W 408<br>W 460;W 673;W 976          |
| FCS-BP-176 | 667 320 00 73                  |  | Bushing To Torsion Bar           | 811;814;VARIO<br>SPRINTER 209 CDI<br>215 CDI;309 CDI<br>315 CDI;511 CDI<br>515 CDI | W 398;W 667;W 668<br>W 670;W 905;W 979          |
| FCS-BP-177 | 318 320 00 73                  |  | Bushing To Torsion Bar           | 814K<br>817K<br>914K<br>1317K<br>1320K                                             | W 310;W 405;W 427<br>W 444;W 676;W 958<br>W 976 |
| FCS-BP-178 | 670 320 03 44                  |  | Rubber Bushing To Rear<br>Spring | 709<br>711<br>811<br>814                                                           | W 669<br>W 670<br>W 673<br>W 674                |
| FCS-BP-179 | 670 320 04 44                  |  | Rubber Bushing To Rear<br>Spring | 609;709;711;811<br>814;VARIO;812;814;815                                           | W 668<br>W 669<br>W 670<br>W 673<br>W 674       |
| FCS-BP-180 | 673 320 01 50                  |  | Rubber Bushing To Rear<br>Spring | 709K;814K;917K<br>1114K;1117K;1120L                                                | W 673<br>W 674<br>W 675<br>W 676<br>W 677       |




|            |                                                 |                                                                                     |                                   |                                                                                                    |                                                 |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------------------------|-------------------------------------------------|
| FCS-BP-181 | 675 320 01 50                                   |     | Bush,Leaf Spring                  | 817K;914K;917K;1114K;<br>1117K;1120K;1314K<br>1317K;1317AK;1320K<br>1514K;1517K;1520K              | W 675<br>W 676<br>W 677<br>W 678<br>W 679       |
| FCS-BP-182 | 673 320 00 50                                   |    | Rubber Bushing To Front Spring    | 709; 1320K;809; 1517K<br>814; 1520K;817K;914<br>917K;1117K;1120K<br>1317K                          | W 673<br>W 674<br>W 675<br>W 676<br>W 677       |
| FCS-BP-183 | 675 320 00 50                                   |    | Bush,Leaf Spring                  | 817K; 1320K;914K; 1514K<br>917K; 1517K;1114K;<br>1520K;1117K;1120K;<br>1314K;1317K;1317AK          | W 675<br>W 676<br>W 677<br>W 678<br>W 679       |
| FCS-BP-184 | 673 320 02 50                                   |    | Rubber Bushing To Rear Spring     | 709;709K;809K;811<br>811K;814;1114;1317<br>1320                                                    | W 673<br>W 674<br>W 675                         |
| FCS-BP-185 | 309 320 01 77                                   |    | Rubber Spring,Front               | 309<br>508<br>608                                                                                  | W 309;W 310;W 667<br>W 668;W 669;W 670          |
| FCS-BP-186 | 309 320 02 77                                   |    | Rubber Spring,Front               | 309;406;407;408;<br>409;410;508;608<br>609;613 D;709<br>711;O 309                                  | W 309<br>W 310<br>W 313<br>W 669                |
| FCS-BP-187 | 000 321 00 50<br>000 321 01 50<br>000 321 03 50 |  | Rubber Buffer To Front Spring     | 207;208;209;210<br>307;308;409;410                                                                 | W 601<br>W 602                                  |
| FCS-BP-188 | 601 321 00 62                                   |  | Rubber Buffer To Spring           | 207;208;209;210;<br>307;308;310;407 D<br>408 D;409 D;410;410 D                                     | W 601<br>W 602<br>W 611                         |
| FCS-BP-189 | 601 321 03 50                                   |  | Bushing To Torsion Bar            | 207;208;209;210;<br>307;308;310;407<br>408;408;409;410                                             | W 405;W 408;W 418<br>W 437;W 601;W 602<br>W 718 |
| FCS-BP-190 | 602 321 00 50<br>602 321 02 50                  |  | Spring,Rear,Leaf No:2             | 207;208;209<br>210;307;308<br>310                                                                  | W 601<br>W 602<br>W 611                         |
| FCS-BP-191 | 667 322 06 50                                   |  | Rubber Buffer To Front Spring     | MB 100;MB 120<br>609;709;711<br>811;814                                                            | W 631<br>W 667<br>W 668<br>W 669<br>W 670       |
| FCS-BP-192 | 000 323 43 85                                   |  | Rubber Mounting To Shock Absorber | 208<br>210<br>307<br>310                                                                           | W 601<br>W 602                                  |
| FCS-BP-193 | 000 323 78 85                                   |  | Spring,Rear,Leaf No:2             | 207;208;210;310;<br>210;212;308; 310<br>208 CDI;211 CDI;308 CDI<br>311 CDI;316 CDI<br>SPRINTER 208 | W 601<br>W 602<br>W 901<br>W 902<br>W 903       |

|            |               |                                                                                     |                                         |                                                                                                        |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|-----------------------------------------|--------------------------------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-194 | 309 323 03 85 |     | Rubber Mounting To<br>Front Spring Bar  | 309;508;L 406DG<br>L 407D;L 408DG<br>L 608D;LK 608 D<br>O 309D                                         | W 308<br>W 309<br>W 310<br>W 313<br>W 378 |
| FCS-BP-195 | 631 323 00 44 |    | Rubber Mounting To<br>Front Spring Bar  | MB 100 D<br>MB 120<br>O 100 CITY                                                                       | W 631                                     |
| FCS-BP-196 | 667 323 03 85 |    | Stabilizer Mounting                     | 507 D<br>508 D/DK<br>510                                                                               | W 667                                     |
| FCS-BP-197 | 667 323 04 85 |    | Rubber Mounting To<br>Front Torsion Bar | 609<br>709<br>711<br>814<br>VARIO                                                                      | W 668<br>W 669<br>W 688<br>W 692          |
| FCS-BP-198 | 667 323 05 85 |    | Rubber Mounting To<br>Front Torsion Bar | 609;709;711;811<br>814;VARIO 812<br>814;815                                                            | W 670                                     |
| FCS-BP-199 | 667 323 06 85 |    | Stabilizer Mounting                     | O 814 R/S;LO 814<br>VARIO;712 E<br>LO 809;LO 813D<br>814;815                                           | W 371;W 398<br>W 669;W 685<br>W 688;W 692 |
| FCS-BP-200 | 670 323 03 85 |  | Rubber Mounting To<br>Rear Torsion Bar  | 814;1114<br>1114K;1314K<br>1317;1317AK<br>1320;1514K                                                   | W 673<br>W 674<br>W 675                   |
| FCS-BP-201 | 673 323 03 85 |  | Stabilizer Mounting                     | 809K;811K;814K<br>814L;817F/K/L/LS/S<br>914AK;917K                                                     | W 673<br>W 674<br>W 676                   |
| FCS-BP-202 | 673 323 04 85 |  | Rubber Mounting To<br>Front Torsion Bar | 709<br>809<br>814<br>817<br>914                                                                        | W 673                                     |
| FCS-BP-203 | 675 323 04 85 |  | Stabilizer Mounting                     | 814;814K;914K;917K;<br>1114;1114K/S;O 1114;<br>1120L/LS;1120 S;1317<br>1117;1117L;1117L/LS<br>O 1117/L | W 674<br>W 675<br>W 676<br>W 677          |
| FCS-BP-204 | 675 323 07 85 |  | Spring,Front,Leaf No:1                  | 1124 F;1314 K;1314 L<br>1317;1317K;1317L/LS<br>1317S;1320S/F                                           | W 675<br>W 676<br>W 677                   |
| FCS-BP-205 | 675 323 12 85 |  | Stabilizer Mounting                     | 914;1114;1117;<br>1314K;1317K;1320L<br>1320L/LS;1324L<br>1324L/S;1824L;2020L                           | W 675<br>W 676<br>W 677<br>W 678<br>W 679 |
| FCS-BP-206 | 675 323 16 85 |  | Stabilizer Mounting                     | 917AF/LAF<br>1114A<br>1120AF<br>1124AF                                                                 | W 676<br>W 677<br>W 678                   |

|            |               |                                                                                     |                            |                                                                               |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-207 | 675 323 17 85 |     | Stabilizer Mounting        | 914AK<br>917AK<br>1114A/AK<br>1117A<br>1314AK                                 | W 674<br>W 675<br>W 676<br>W 678          |
| FCS-BP-208 | 675 323 18 85 |    | Stabilizer Mounting        | 814L/K/S<br>817L/LS/KO/S<br>914K;1120F;1124F<br>1314L/KO/LKO<br>1317L/LS/KO/S | W 674<br>W 675<br>W 676<br>W 677<br>W 679 |
| FCS-BP-209 | 675 323 19 85 |    | Stabilizer Mounting        | 914;1114;1117<br>1314;1317;1320                                               | W 675<br>W 676<br>W 678                   |
| FCS-BP-210 | 970 323 12 85 |    | Stabilizer Mounting        | ATEGO                                                                         | W 970<br>W 972<br>W 976                   |
| FCS-BP-211 | 970 323 15 85 |    | Bearing Bush,Stabilizer    | ATEGO                                                                         | W 375<br>W 970<br>W 972<br>W 975          |
| FCS-BP-212 | 970 323 17 85 |    | Stabilizer Mounting        | ATEGO<br>TOURINO                                                              | W 375;W 444;W 958<br>W 970;W 975;W 976    |
| FCS-BP-213 | 974 323 02 85 |  | Bearing Bush,Stabilizer    | ATEGO                                                                         | W 970<br>W 972<br>W 974<br>W 975<br>W 976 |
| FCS-BP-214 | 974 323 03 85 |  | Stabilizer Mounting        | ATEGO                                                                         | W 970<br>W 972<br>W 974<br>W 975<br>W 976 |
| FCS-BP-215 | 000 325 04 85 |  | Stabilizer Mounting        | ATEGO<br>ACTROS                                                               | W 374<br>W 972<br>W 942<br>W 950<br>W 952 |
| FCS-BP-216 | 667 323 02 26 |  | Clamp To Front Torsion Bar | 207;208;209;210;<br>507;508;510;609<br>709;711;814;VARIO                      | W 601<br>W 602<br>W 611<br>W 667<br>W 669 |
| FCS-BP-217 | 667 323 05 40 |  | Clamp To Front Torsion Bar | 609<br>709<br>711<br>811<br>814                                               | W 668<br>W 669<br>W 670<br>W 688<br>W 692 |
| FCS-BP-218 | 667 323 06 40 |  | Clamp To Front Torsion Bar | 609<br>709<br>711<br>811<br>814                                               | W 667<br>W 668<br>W 669                   |
| FCS-BP-219 | 668 323 0140  |  | Clamp To Front Torsion Bar | 609<br>709<br>711<br>811<br>814                                               | W 668<br>W 669<br>W 670<br>W 688<br>W 692 |

|            |                 |                                                                                     |                                    |                                                                                                   |                                                    |
|------------|-----------------|-------------------------------------------------------------------------------------|------------------------------------|---------------------------------------------------------------------------------------------------|----------------------------------------------------|
| FCS-BP-220 | 611 324 03 50   |     | Rubber Bushing To Rear Spring      | 407<br>408<br>409<br>410                                                                          | W 611                                              |
| FCS-BP-221 | 602 324 00 50   |    | Rubber Bushing To Rear Spring      | 207;208;209;210<br>307;308;310                                                                    | W 601<br>W 602                                     |
| FCS-BP-222 | 319 324 07 50-1 |    | Rubber Bushing To Rear Spring      | 309;406;407;408;<br>409;410;508;608<br>609;613 D;O 309                                            | W 309<br>W 310<br>W 313                            |
| FCS-BP-223 | 673 324 01 50   |    | Bushing For Spring Plastic         | TRUCK 709<br>809<br>814                                                                           | W 673<br>W 674<br>W 675<br>W 676<br>W 677          |
| FCS-BP-224 | 673 325 01 44   |    | Rubber Buffer To Rear Spring       | 507;508;509;510;<br>609;613;709;709K<br>811;814K;914;914K                                         | W 667;W 668<br>W 669;W 674<br>W 675;W 676<br>W 677 |
| FCS-BP-225 | 674 325 02 44   |    | Rubber Buffer,Suspension           | 709;711;809;814L;<br>O 814;914K;1120AF/LS<br>1117A/AK/K/L/LO/LS<br>1124AF;1314L/K<br>1317AK;1320L | W 673;W 674<br>W 675;W 676<br>W 677;W 679          |
| FCS-BP-226 | 675 325 01 44   |  | Rubber Buffer,Suspension           | 1114;1314L;OHL1316<br>1317K;1420;OH 1421L<br>1621L;1623 LG;OH 1636L                               | W 382;W 673;W 674<br>W 675;W 390;W 397<br>W 398    |
| FCS-BP-227 | 673 325 02 84   |  | Rubber Buffer To Spring            | 609<br>709<br>711<br>811<br>814                                                                   | W 673;W 674<br>W 675;W 676<br>W 677;W 679          |
| FCS-BP-228 | 309 326 02 81   |  | Rubber Mountig To Rear Torsion Bar | 309;406;407;408<br>409;410;508;608                                                                | W 309<br>W 310                                     |
| FCS-BP-229 | 601 326 04 82   |  | Rubber Mountig To Rear Torsion Bar | 207<br>208<br>210                                                                                 | W 601                                              |
| FCS-BP-230 | 602 326 02 82   |  | Rubber Mountig To Rear Torsion Bar | 207;208;210<br>308;310;410                                                                        | W 601<br>W 602                                     |
| FCS-BP-231 | 602 326 04 82   |  | Rubber Mountig To Rear Torsion Bar | 207;207 D;208<br>208 D;209 D;210<br>210 D;307;310                                                 | W 601                                              |
| FCS-BP-232 | 602 326 08 82   |  | Stabilizer Mounting                |                                                                                                   | W 601<br>W 602                                     |

|            |                                |                                                                                     |                                        |                                                                                                           |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------------------|-----------------------------------------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-233 | 611 326 00 81                  |     | Rubber Mounting To<br>Rear Torsion Bar | 407<br>408<br>409<br>410                                                                                  | W 611                                     |
| FCS-BP-234 | 667 326 00 81                  |    | Rubber Spring,Front                    | 507;508;509<br>510;609;VARIO<br>609;709;711                                                               | W 667<br>W 668<br>W 669                   |
| FCS-BP-235 | 667 326 01 81                  |    | Rubber Buffer To Front Spring          | 507;508;509;510;<br>711;811;VARIO 512<br>809;811;814;815                                                  | W 667<br>W 668<br>W 669<br>W 670<br>W 673 |
| FCS-BP-236 | 667 326 14 81                  |    | Stabilizer Mounting                    | VARIO                                                                                                     | W 669                                     |
| FCS-BP-237 | 668 326 01 81                  |    | Rubber Mounting To<br>Rear Torsion Bar | 809; VARIO 709<br>811;814;811;812<br>814;815;709K<br>809K;811K                                            | W 669<br>W 670<br>W 673<br>W 685<br>W 688 |
| FCS-BP-238 | 669 326 00 81                  |    | Rubber Mounting To<br>Rear Torsion Bar | 609;709;711<br>809;811;814                                                                                | W 668<br>W 669<br>W 670                   |
| FCS-BP-239 | 673 326 02 81<br>673 326 05 81 |  | Rubber Mounting To<br>Rear Torsion Bar | 814K<br>1317<br>1320K                                                                                     | W 673<br>W 674<br>W 676                   |
| FCS-BP-240 | 673 326 01 81<br>673 326 06 81 |  | Rubber Mounting To<br>Rear Torsion Bar | 814K<br>1317K<br>1320K                                                                                    | W 674<br>W 676<br>W 697                   |
| FCS-BP-241 | 673 326 03 81<br>673 326 07 81 |  | Rubber Mounting To<br>Rear Torsion Bar | 814K<br>817K<br>917AF/LAF<br>1317K<br>1320K                                                               | W 674<br>W 676<br>W 697                   |
| FCS-BP-242 | 674 326 00 81                  |  | Stabilizer Mounting                    | 814L<br>817L/LS                                                                                           | W674<br>W 676                             |
| FCS-BP-243 | 675 326 04 81                  |  | Stabilizer Mounting                    | 814L;817L/LS;1114S/K<br>1117S;1120S;1314K<br>1317K;1317S;1320S                                            | W 674<br>W 675<br>W 676<br>W 677          |
| FCS-BP-244 | 675 326 05 81                  |  | Stabilizer Mounting                    | 1114K<br>O 1114<br>1314K<br>1317AK<br>1514K                                                               |                                           |
| FCS-BP-245 | 675 326 06 81                  |  | Stabilizer Mounting                    | 814 LO;O 814L;817;<br>O 817L;1114L;1117L;<br>1117L/LS;1120L/LS<br>1317LS;1317L/LS<br>1320L;1324L/LS;1824L | W 674<br>W 675<br>W 676<br>W 677<br>W 679 |

|            |                                |                                                                                     |                                        |                                                                             |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------------------|-----------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-246 | 675 326 07 81                  |     | Stabilizer Mounting                    | O 1114L/42<br>O 1114L/49<br>O 1117L<br>O 1117LO<br>O 1120L                  | W 675<br>W 676<br>W 677                   |
| FCS-BP-247 | 675 326 09 81                  |    | Stabilizer Mounting                    | 914AK;917AK;1114K<br>1114A/AK;1117A<br>1120S;1314K;1317K<br>1320S;1324S     | W 674;W 675;W 676<br>W 677;W 678;W 679    |
| FCS-BP-248 | 675 326 12 81                  |    | Stabilizer Mounting                    | 917AF/LAF;1114A<br>1117A;1120F;1124F<br>1514K;1517K;O 1114<br>O 1117;O 1120 | W 675<br>W 676<br>W 677<br>W 678          |
| FCS-BP-249 | 667 326 06 81                  |    | Rubber Mounting To<br>Rear Torsion Bar | 811<br>814                                                                  | W 669<br>W 670                            |
| FCS-BP-250 | 318 351 01 25                  |    | Clamp To Rear Spring                   | 709K;814K;817K<br>914K;1114K<br>1314K;1317AK<br>1514K                       | W 673<br>W 674<br>W 675                   |
| FCS-BP-251 | 601 325 05 47                  |    | Clamp To Rear Spring                   | 207<br>210<br>307<br>308<br>310                                             | W 601<br>W 602                            |
| FCS-BP-252 | 601 326 02 40                  |  | Clamp To Rear Torsion Bar              | 207;208;209;210<br>307;308;310                                              | W 601<br>W 602                            |
| FCS-BP-253 | 601 326 03 40                  |  | Bracket To Front Torsion Bar           | 207<br>208<br>210<br>307<br>310                                             | W 309<br>W 310<br>W 601<br>W 667<br>W 669 |
| FCS-BP-254 | 602 326 01 40                  |  | Bracket To Front Torsion Bar           | 207;208;210<br>307;310;407<br>408;409;410                                   | W 601<br>W 602<br>W 611                   |
| FCS-BP-255 | 601 326 03 26                  |  | Clamp To Front Torsion Bar             | 207<br>208<br>210<br>307<br>310                                             | W 601<br>W 602                            |
| FCS-BP-256 | 667 351 48 25                  |  | Clamp To Rear Spring                   | 609<br>709<br>814                                                           | W 668<br>W 669                            |
| FCS-BP-257 | 309 320 00 28<br>309 586 02 32 |  | Rep.Kit.Stabilizer                     | L 406 DG<br>LK 406 DG<br>407 D;408 D<br>409;410                             | W 309                                     |
| FCS-BP-258 | 309 320 02 28<br>309 586 01 32 |  | Rep.Kit.Stabilizer                     | 309 D;L 406 DG<br>407 D;508 DG;508 D/O<br>L 608 D/LF;613 D<br>O 309 DL      | W 309<br>W 310<br>W 313                   |



|            |                                                 |                                                                                     |                     |                                                  |                                  |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|---------------------|--------------------------------------------------|----------------------------------|
| FCS-BP-259 | 601 320 04 11                                   |     | Rep.Kit.Stabilizer  | 207;208;209;210<br>307;310;410                   | W 601<br>W 602<br>W 611          |
| FCS-BP-260 | 601 320 03 28                                   |    | Rep.Kit.Stabilizer  | 207;208;209<br>210;307;310                       |                                  |
| FCS-BP-261 | 601 320 00 83<br>601 320 07 11<br>601 586 00 32 |    | Rep.Kit.Stabilizer  | 207;208;209;210<br>307;310;410                   | W 601<br>W 602                   |
| FCS-BP-262 | 601 320 01 83<br>601 586 01 32                  |    | Rep.Kit.Stabilizer  | 207;208;209;210<br>307;310;410                   | W 601                            |
| FCS-BP-263 | 611 320 03 11                                   |    | Rep.Kit.Stabilizer  | 410<br>407 D<br>408 D<br>409 D<br>410 D          | W 611                            |
| FCS-BP-264 | 668 320 04 11                                   |    | Rep.Kit.Stabilizer  | 609 D;709 D;711 D<br>L 710 D;L 913 D<br>LO 813 D | W 668<br>W 669<br>W 692          |
| FCS-BP-265 | 668 320 05 11                                   |  | Rep.Kit.Stabilizer  | 609;709;711<br>809;811;814                       |                                  |
| FCS-BP-266 | 670 320 12 11                                   |  | Rep.Kit.Stabilizer  | 609;709;711<br>809;811;814<br>(04.86-02.94)      | W 669<br>W 670                   |
| FCS-BP-267 | 670 320 14 11                                   |  | Rep.Kit.Stabilizer  | 609<br>709<br>711<br>811<br>814                  | W 670                            |
| FCS-BP-268 | 670 320 18 11                                   |  | Rep.Kit.Stabilizer  | 507;508;509<br>510;609;613                       | W 667<br>W 668                   |
| FCS-BP-269 | 673 320 47 11                                   |  | Rep.Kit.Stabilizer  | 507 D<br>508 D/DK<br>510                         | W 667                            |
| FCS-BP-270 | N5151105                                        |  | Shock Absorber,Rear | 609;613;709;711<br>809;811;814                   | W 668<br>W 669<br>W 670          |
| FCS-BP-271 | 004 326 13 00                                   |  | Shock Absorber      |                                                  | W 667<br>W 668<br>W 669<br>W 670 |





|            |                                                                  |                                                                                     |                            |                                                                                        |                                                 |
|------------|------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------|
| FCS-BP-272 | 005 326 29 00<br>673 326 00 00<br>673 326 11 00<br>673 326 13 00 |     | Shock Absorber,Front       | 814K;817K;914K;917K<br>1117K;1317K;1517K                                               | W 673<br>W 674<br>W 676                         |
| FCS-BP-273 | 005 326 36 00                                                    |    | Shock Absorber,Rear        | 814K;817K;914K;917K<br>1117K;1317K;1517K                                               | W 673<br>W 674<br>W 676                         |
| FCS-BP-274 | 375 890 00 19                                                    |    | Shock Absorber,Front       | 609;613;709;711<br>809;811;814                                                         | W 668<br>W 669<br>W 670                         |
| FCS-BP-275 | 601 320 07 30                                                    |    | Shock Absorber,Front       | 207;208;209<br>307;310;410                                                             | W 601<br>W 602                                  |
| FCS-BP-276 | 601 320 12 31                                                    |    | Shock Absorber,Rear        | 207;208;209<br>307;310;410                                                             | W 601<br>W 602                                  |
| FCS-BP-277 | 005 323 09 00                                                    |    |                            |                                                                                        |                                                 |
| FCS-BP-278 | 631 320 16 30                                                    |  | Shock Absorber             | MB 100<br>MB 120                                                                       | W 631                                           |
| FCS-BP-279 | 631 320 09 31                                                    |  | Shock Absorber,Rear        | MB 100<br>MB 120                                                                       | W 631                                           |
| FCS-BP-280 | 673 324 04 08                                                    |  | Rubber Buffer,Suspension   | 709;711;914;<br>914 KO;1114;<br>1114 A; 1524;1724<br>1117 L;1314 K;1324/S<br>1514;1520 | W 673;W 674;W 675<br>W 676;W 677;W 678<br>W 679 |
| FCS-BP-281 | 631 330 14 49                                                    |  | Rep.Kit.Intermediate Lever | MB 100<br>MB 120                                                                       | W 631                                           |
| FCS-BP-282 | 631 330 64 07                                                    |  | Rep.Kit.Torsion            | MB 100<br>MB 120                                                                       | W 631                                           |
| FCS-BP-283 | 310 330 00 19                                                    |  | Rep.Kit.King Pin Set       | 609<br>709<br>711                                                                      | W 668<br>W 669                                  |
| FCS-BP-284 | 310 330 03 19                                                    |  | Rep.Kit.King Pin Set       | 309;406;407;408<br>409;410;508;608                                                     | W 309<br>W 310                                  |

|            |                 |                                                                                     |                      |                                                                    |                                        |
|------------|-----------------|-------------------------------------------------------------------------------------|----------------------|--------------------------------------------------------------------|----------------------------------------|
| FCS-BP-285 | 310 330 03 19   |     | Rep.Kit.King Pin Set | 309;406;407;408<br>409;410;508;608                                 | W 309<br>W 310                         |
| FCS-BP-286 | 316 330 01 19-2 |    | Rep.Kit.King Pin Set | 608;708;709;808<br>811;814K;913<br>1013;1113;1317K                 | W 309<br>W 310                         |
| FCS-BP-287 | 601 330 00 19   |    | Rep.Kit.King Pin Set | 207;208;209<br>210;307;310                                         | W 601<br>W 602                         |
| FCS-BP-288 | 601 330 01 19   |    | Rep.Kit.King Pin Set | 207;208;209<br>210;307;310                                         | W 601<br>W 602                         |
| FCS-BP-289 | 601 330 03 19   |    | Rep.Kit.King Pin Set | 207<br>208<br>307<br>310<br>410                                    | W 601<br>W 602                         |
| FCS-BP-290 | 601 330 03 19-2 |    | Rep.Kit.King Pin Set | 207<br>208<br>307<br>310<br>410                                    | W 601<br>W 602                         |
| FCS-BP-291 | 611 330 00 19   |  | Rep.Kit.King Pin Set | 407<br>408<br>409<br>410                                           | W 611                                  |
| FCS-BP-292 | 611 330 04 19   |  | Rep.Kit.King Pin Set | 407<br>408<br>409<br>410                                           | W 611                                  |
| FCS-BP-293 | 668 330 00 19   |  | Rep.Kit.King Pin Set | 609<br>613<br>709<br>711                                           | W 668<br>W 669                         |
| FCS-BP-294 | 670 330 01 19   |  | Rep.Kit.King Pin Set | 609;709;711<br>811;814;814K                                        | W 669<br>W 670                         |
| FCS-BP-295 | 667 326 06 81   |  |                      |                                                                    |                                        |
| FCS-BP-296 | 003 981 95 05   |  | Bearing              | 309;406;407;408;<br>409;410;508;608,<br>609;709;711;811<br>814     | W 309;W 310;W 667<br>W 668;W 669;W 670 |
| FCS-BP-297 | 003 981 96 05   |  | Bearing              | 309; 609;406; 709<br>407; 711;408; 811<br>409; 814;410;508<br>608, | W 309;W 310;W 667<br>W 668;W 669;W 670 |

|            |               |                                                                                     |                         |                                                                        |                                        |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------------|------------------------------------------------------------------------|----------------------------------------|
| FCS-BP-298 | 611 330 07 25 |     | Wheel Bearing Kit,Front | 207;208;209;210<br>307;310;409;410                                     | W 601<br>W 602                         |
| FCS-BP-299 | 601 350 04 68 |    | Wheel Bearing Kit,Raer  | 207<br>208<br>210<br>307<br>310                                        | W 601<br>W 602                         |
| FCS-BP-300 | 631 330 02 51 |    | Wheel Bearing Kit,Front | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-301 | 631 402 143 A |    | Wheel Bearing Kit,Raer  | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-302 | 631 402 143 B |    | Wheel Bearing Kit,Raer  | MB 100<br>MB 120<br>MB 140                                             | W 631                                  |
| FCS-BP-303 | 670 330 04 25 |    | Wheel Bearing Kit,Front | 609;709;711;809<br>811;814;VARIO                                       | W 669<br>W 670                         |
| FCS-BP-304 | 631 330 13 01 |   | Drive Shaft             | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-305 | 631 330 00 85 |  | Front Axle Boot,Inner   | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-306 | 631 330 01 85 |  | Front Axle Boot,Outer   | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-307 | 631 997 21 46 |  | Axle Seal Ring,Inner    | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-308 | 631 997 22 46 |  | Axle Seal Ring,Outer    | MB 100<br>MB 120                                                       | W 631                                  |
| FCS-BP-309 | 017 997 55 47 |  | Seal Ring               | SPRINTER 208<br>207;208;210;310;<br>410;609;709;711<br>814;308;312;412 | W 601;W 611;W 669<br>W 670;W 673;W 904 |
| FCS-BP-310 | 019 997 08 47 |  | Axle Seal Ring          | 207;208;209;210<br>307;310;410                                         | W 601<br>W 602<br>W 611                |

|            |                                                 |                                                                                     |                       |                                                       |                                  |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------|----------------------------------|
| FCS-BP-311 | 003 997 64 48                                   |     | Seal Ring,Rear Axle   | 207<br>208<br>209<br>307<br>310                       | W 601<br>W 602                   |
| FCS-BP-312 | 631 334 0253                                    |    | Wheel Hub Spacer Tube | MB 100<br>140<br>160                                  | W 631                            |
| FCS-BP-313 | 601 357 51 19                                   |    | Rep.Kit.Stabilizer    | 207<br>208<br>209<br>307<br>310                       | W 601<br>W 602                   |
| FCS-BP-314 | 611 350 50 10                                   |    | Rear Axle Shaft       | 408<br>409<br>410                                     | W 611                            |
| FCS-BP-315 | 667 356 00 73                                   |    | Lock To Drive Shaft   | 609<br>709<br>711<br>814                              | W 901<br>W 902<br>W 903<br>W 904 |
| FCS-BP-316 | 000 330 06 35<br>000 330 85 35<br>000 330 87 35 |    | Steering Tie Rod End  | 609;709;711<br>809;811;814                            | W 669<br>W 670                   |
| FCS-BP-317 | 000 330 07 35<br>000 330 86 35<br>000 330 88 35 |  | Steering Tie Rod End  | 609;709;711<br>809;811;814                            | W 669<br>W 670                   |
| FCS-BP-318 | 000 330 0 835                                   |  | Steering Tie Rod End  | 309,406,407,<br>408,409;410<br>508;608;708<br>709;808 | W 309<br>W 310<br>W 314          |
| FCS-BP-319 | 000 330 09 35                                   |  | Steering Tie Rod End  | 309,406,407,408,<br>409;410;508;608<br>708;709;808    | W 309<br>W 310<br>W 314          |
| FCS-BP-320 | 000 330 93 35                                   |  | Steering Tie Rod End  | 609;709;711<br>809;811;814                            | W 669<br>W 670                   |
| FCS-BP-321 | 000 330 94 35                                   |  | Shock Absorber,Rear   | 609;709;711<br>809;811;814                            | W 669<br>W 670                   |
| FCS-BP-322 | 000 330 97 35                                   |  | Shock Absorber,Front  | 609;709;711<br>809;811;814                            | W 669<br>W 670                   |
| FCS-BP-323 | 001 330 11 35                                   |  | Steering Tie Rod End  | 507;508;509<br>510;609;613<br>709;711                 | W 667<br>W 668<br>W 669          |

|            |                                |                                                                                     |                          |                                                                        |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|--------------------------|------------------------------------------------------------------------|----------------------------------|
| FCS-BP-324 | 001 330 12 35<br>001 330 14 35 |     | Steering Tie Rod End     | 507;508;509;510<br>609;613;709;711                                     | W 667<br>W 668<br>W 669          |
| FCS-BP-325 | 310 330 02 35<br>310 330 22 35 |    | Steering Tie Rod End     | 309;406;407;408<br>409;410;508;608<br>708;709;808                      | W 309<br>W 310<br>W 314          |
| FCS-BP-326 | 310 330 03 35<br>310 330 23 35 |    | Steering Tie Rod End     | 309;406;407;408<br>409;410;508;608<br>708;709;808                      | W 309<br>W 310<br>W 314          |
| FCS-BP-327 | 601 330 04 35                  |    | Steering Tie Rod End     | 207<br>208<br>307<br>310                                               | W 601<br>W 602                   |
| FCS-BP-328 | 601 330 05 35                  |    | Steering Tie Rod End     | 207<br>208<br>307<br>310                                               | W 601<br>W 602                   |
| FCS-BP-329 | 602 330 57 35                  |   | Steering Tie Rod End     | 207;208;209<br>210;307;308<br>310                                      | W 601<br>W 602                   |
| FCS-BP-330 | 602 330 58 35                  |  | Steering Tie Rod End     | 207;208;209<br>210;307;308<br>310                                      | W 601<br>W 602                   |
| FCS-BP-331 | 631 330 05 35                  |  | Steering Tie Rod End     | MB 100<br>140<br>160                                                   | W 631                            |
| FCS-BP-332 | 631 320 00 28                  |  | Steering Link Ball Joint | MB 100<br>140<br>160                                                   | W 631                            |
| FCS-BP-333 | 631 463 00 29                  |  | Steering Tie Rod End     | MB 100<br>MB 120                                                       | W 631                            |
| FCS-BP-334 | 631 338 04 10                  |  | Steering Tie Rod End     | MB 100<br>MB 120                                                       | W 631                            |
| FCS-BP-335 | 631 338 05 10                  |  | Steering Tie Rod End     | MB 100<br>MB 120                                                       | W 631                            |
| FCS-BP-336 | 000 460 45 48                  |  | Steering Tie Rod End     | 207; 406;208; 407<br>209; 408;210; 409<br>307; 410;308; 508<br>310,608 | W 309<br>W 310<br>W 601<br>W 602 |

|            |               |                                                                                     |                                          |                                    |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|------------------------------------------|------------------------------------|----------------------------------|
| FCS-BP-337 | 000 996 66 45 |     | Ball Socket, Gearshift Linkage           | MB.TRUCK                           | W 673<br>W 674                   |
| FCS-BP-338 | 000 996 67 45 |    | Ball Socket, Gearshift Linkage           | MB.TRUCK                           | W 673<br>W 674                   |
| FCS-BP-339 | 000 996 70 45 |    | Ball Socket, Gearshift Linkage           | MB.TRUCK                           | W 673<br>W 674                   |
| FCS-BP-340 | 601 430 05 35 |    | Connecting Rod For Brake Power Regulator | 209;309;310<br>409;410;VARIO       |                                  |
| FCS-BP-341 | 631 323 10 65 |    | Torsion Bar                              | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-342 | 631 323 11 65 |    | Torsion Bar                              | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-343 | 631 330 07 03 |   | Tie Rod                                  | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-344 | 631 330 06 03 |  | Tie Rod                                  | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-345 | 631 334 04 01 |  | Wheel Hub                                | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-346 | 602 330 09 03 |  | Drag Link                                | 207;208;210<br>307;310;410         | W 601<br>W 602                   |
| FCS-BP-347 | 631 460 07 05 |  | Drag Link                                | MB 100<br>MB 120                   | W 631                            |
| FCS-BP-348 | 309 460 31 05 |  | Tie Rod                                  | 207;208;210;307<br>309;310;410;508 | W 309<br>W 310<br>W 601<br>W 602 |
| FCS-BP-349 | 668 460 22 05 |  | Drag Link                                | 609<br>709<br>711<br>811<br>814    | W 668<br>W 669<br>W 670          |

|            |                                |                                                                                     |                           |                                                                                   |                                                    |
|------------|--------------------------------|-------------------------------------------------------------------------------------|---------------------------|-----------------------------------------------------------------------------------|----------------------------------------------------|
| FCS-BP-350 | 673 460 08 05                  |     | Drag Link                 | 817K<br>914K<br>1317K                                                             | W 673<br>W 674<br>W 676                            |
| FCS-BP-351 | 667 460 17 05                  |    | Drag Link                 | VARIO 612<br>614<br>812                                                           | W 669                                              |
| FCS-BP-352 | 670 460 16 05                  |    | Drag Link                 | 711<br>714<br>811                                                                 | W 670                                              |
| FCS-BP-353 | 309 350 08 39<br>309 350 14 39 |    | Ring Gear & Pinion        | 309;406;407<br>408;409;410<br>508;608                                             | W 309<br>W 310                                     |
| FCS-BP-354 | 668 350 07 39                  |    | Ring Gear & Pinion        | 609<br>709<br>711<br>814                                                          | W 668<br>W 669<br>W 670                            |
| FCS-BP-355 | 668 350 00 26                  |    | Rep.Kit.Differential Gear | 609<br>709<br>711<br>811<br>814                                                   | W 668<br>W 669<br>W 670<br>W 673                   |
| FCS-BP-356 | 668 350 03 23                  |  | Differential Gear         | 507;508;509;510<br>609;613;711<br>(01.70-12.94)<br>(04.77-12.94)<br>(04.86-12.94) |                                                    |
| FCS-BP-357 | 6.75-19.5                      |  | Wheel Disc                | TRUCK;814;817<br>917;1120;1320                                                    | W 668<br>W 669                                     |
| FCS-BP-358 | 669 400 00 02                  |  | Wheel Disc                | 609<br>709<br>711<br>VARIO<br>616 CDI                                             | W 669<br>W 905                                     |
| FCS-BP-359 | 318 402 00 71                  |  | Wheel Nut                 | 609;709;711;VARIO;<br>814;817;817K914K<br>917K;1117K;1317K<br>1517K               | W 314;W 318<br>W 669;W 673<br>W 674;W 676          |
| FCS-BP-360 | 309 402 02 71                  |  | Wheel Nut                 | 309;406;407;408;<br>409;410;508; VARIO<br>609;709;711;809<br>811;814              | W 309;W 310<br>W 313;W 611<br>W 667;W 669<br>W 670 |
| FCS-BP-361 | 601 401 02 70                  |  | Wheel Nut                 | SPRINTER 208<br>207;307;310;210;<br>212;214;208 CDI<br>211 CDI;213 CDI<br>216 CDI | W 601<br>W 602<br>W 901<br>W 902                   |
| FCS-BP-362 | 601 410 17 10                  |  | Intermediate Bearing      | 207;208;209;210<br>308;310;410                                                    | W 601<br>W 602<br>W 611                            |



|            |                                                                                   |                                                                                     |                                  |                                       |                                           |
|------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------|---------------------------------------|-------------------------------------------|
| FCS-BP-363 | 601 410 21 10<br>601 410 17 10                                                    |     | Intermediate Bearing             | 207;208;210<br>307;310;410            | W 601<br>W 602<br>W 611                   |
| FCS-BP-364 | 310 410 08 22                                                                     |    | Intermediate Bearing             | 309<br>407<br>508<br>608              | W 309<br>W 310<br>W 313                   |
| FCS-BP-365 | 460 410 00 22<br>460 410 02 22                                                    |    | Intermediate Bearing             | 609<br>709<br>711<br>814<br>VARIO     | W 668<br>W 669<br>W 670<br>W 673          |
| FCS-BP-366 | 381 410 00 10<br>381 410 02 22<br>381 410 12 22<br>381 410 15 22<br>385 410 00 10 |    | Intermediate Bearing             | 814<br>1317<br>TRUCK                  | W 318;W 380<br>W 381;W 678<br>W 684;W 970 |
| FCS-BP-367 | 3814100922<br>3814101522                                                          |    | Intermediate Bearing             | 711<br>814<br>TRUCK                   | W 381;W 383<br>W 385;W 616<br>W 678;W 970 |
| FCS-BP-368 | 385 410 01 10<br>385 410 01 22<br>385 410 09 22<br>385 410 17 22<br>385 586 01 41 |    | Intermediate Bearing             | 814<br>1317<br>TRUCK                  | W 355;W 380<br>W 389;W 397<br>W 437;W 976 |
| FCS-BP-369 | 670 411 01 12                                                                     |  | Intermediate Bearing             | VARIO;612;614<br>812;814;815<br>ATEGO | W 669<br>W 970                            |
| FCS-BP-370 | 656 411 00 12                                                                     |  |                                  |                                       |                                           |
| FCS-BP-371 | 970 411 00 12                                                                     |  | Intermediate Bearing             | VARIO;612;614<br>812;814;815<br>ATEGO | W 669<br>W 970                            |
| FCS-BP-372 | 611 411 00 47                                                                     |  | Propeller Shaft Vibration Damper | 207;208;209<br>210;308;310<br>410     | W 601<br>W 602<br>W 611                   |
| FCS-BP-373 | 631 330 05 35                                                                     |  | Boot                             | 207;307;309;410<br>SPRINTER           | OM 601<br>OM 602                          |
| FCS-BP-374 | 24-75                                                                             |  | Universal Joint                  | 207<br>208<br>209                     | W 601<br>W 602                            |
| FCS-BP-375 | 26-69                                                                             |  | Universal Joint                  | 210<br>307<br>310<br>409<br>410       |                                           |

|            |                         |                                                                                     |                                    |                                                       |                         |
|------------|-------------------------|-------------------------------------------------------------------------------------|------------------------------------|-------------------------------------------------------|-------------------------|
| FCS-BP-376 | 31-88                   |     |                                    |                                                       |                         |
| FCS-BP-377 | 31-110<br>971 410 00 31 |    | Universal Joint                    | VARIO<br>614<br>615<br>814                            | W 668<br>W 669<br>W 670 |
| FCS-BP-378 | 38-100<br>385 410 02 31 |    | Universal Joint                    | 309<br>508<br>608<br>613                              | W 309<br>W 310          |
| FCS-BP-379 | 42-106<br>000 410 40 31 |    | Universal Joint                    | 609<br>709<br>711<br>811<br>814                       | W 668<br>W 669<br>W 670 |
| FCS-BP-380 | 005 420 81 18           |    | Wheel Brake Cylinder               | 207;208;209;307;310<br>(04.77-02.96)                  | W 601<br>W 602          |
| FCS-BP-381 | 008 420 44 18           |    | Wheel Brake Cylinder               | 407<br>408<br>409<br>410<br>(04.82-06.95)             | W 611                   |
| FCS-BP-382 | 631 420 00 18           |  | Wheel Brake Cylinder               | MB 100<br>MB 120                                      | W 631                   |
| FCS-BP-383 | 009 420 82 18           |  | Wheel Brake Cylinder               | 309;406;407;508;608<br>(01.68-12.94)<br>(09.63-12.88) | W 309<br>W 310          |
| FCS-BP-384 | 673 420 08 24           |  | Multi Function Brake Cylinder      | 709;709K;809K;811<br>811K;814;814K;914<br>914K        | W 631<br>W 674          |
| FCS-BP-385 | 668 420 02 18           |  | Wheel Brake Cylinder               | 609<br>711<br>811<br>814                              | W 668<br>W 669<br>W 670 |
| FCS-BP-386 | 000 431 33 28           |  | Brake Cylinder Diaphragm           | 814<br>817<br>914                                     | W 669<br>W 670          |
| FCS-BP-387 | 000 423 12 86           |  | Membrane<br>Spring-Loaded Cylinder | 814K<br>1317K                                         |                         |
| FCS-BP-388 | 309 420 13 85           |  | Park Brake Cable                   | 406;407;408;409<br>410;508;608;613                    | W 309<br>W 310<br>W 313 |

|            |               |                                                                                     |                          |                                                                    |                |
|------------|---------------|-------------------------------------------------------------------------------------|--------------------------|--------------------------------------------------------------------|----------------|
| FCS-BP-389 | 309 420 14 85 |     | Park Brake Cable         | 309<br>508<br>608<br>609                                           |                |
| FCS-BP-390 | 310 420 09 85 |    | Park Brake Cable         | 309;407;508;608<br>(01.68-12.94)<br>(09.63-12.88)<br>(09.63-12.88) | W 309<br>W 310 |
| FCS-BP-391 | 601 420 11 85 |    | Park Brake Cable, L&R    | 207<br>208<br>209<br>210<br>(04.77-02.96)                          | W 601<br>W 602 |
| FCS-BP-392 | 601 420 16 85 |    | Park Brake Cable         | 210<br>307<br>310                                                  |                |
| FCS-BP-393 | 601 420 17 85 |    | Park Brake Cable         | 210<br>307<br>310                                                  |                |
| FCS-BP-394 | 601 420 18 85 |    | Park Brake Cable         | 210<br>307<br>310                                                  |                |
| FCS-BP-395 | 601 420 46 85 |  | Park Brake Cable, Rear-L | 210<br>307<br>310<br>(04.77-02.96)                                 | W 601<br>W 602 |
| FCS-BP-396 | 601 420 47 85 |  | Park Brake Cable, Rear-R | 210<br>307<br>310<br>(04.77-02.96)                                 | W 601<br>W 602 |
| FCS-BP-397 | 611 420 11 85 |  | Park Brake Cable         | 409<br>410                                                         | W 601<br>W 602 |
| FCS-BP-398 | 611 420 16 85 |  | Park Brake Cable, Rear-L | 407<br>408<br>409<br>410<br>(04.82-06.95)                          | W 611          |
| FCS-BP-399 | 611 620 17 85 |                                                                                     | Park Brake Cable, Rear-R | 407<br>408<br>409<br>410<br>(04.82-06.95)                          | W 611          |
| FCS-BP-400 | 631 420 20 85 |  | Park Brake Cable, L&R    | MB 100<br>MB 120                                                   | W 309<br>W 310 |
| FCS-BP-401 | 667 420 29 85 |  | Park Brake Cable, Rear-R | 609;709;711<br>811;814<br>VARIO                                    |                |


|            |               |                                                                                     |                         |                                                                                              |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|-------------------------|----------------------------------------------------------------------------------------------|----------------------------------|
| FCS-BP-402 | 667 420 30 85 |     | Park Brake Cable,Rear-L | 609<br>709<br>711<br>811<br>814                                                              | W 667<br>W 668<br>W 669<br>W 670 |
| FCS-BP-403 | 667 420 31 85 |    | Park Brake Cable,Rear-L | 609;709;711;811<br>814;VARIO;612<br>614;812                                                  | W 667<br>W 668<br>W 669<br>W 670 |
| FCS-BP-404 | 667 420 32 85 |    | Park Brake Cable,Rear-R | 609;709;711;811<br>814;VARIO;612<br>614;812                                                  | W 667<br>W 668<br>W 669<br>W 670 |
| FCS-BP-405 | 667 420 39 85 |    | Park Brake Cable        | 609<br>709<br>711<br>811<br>814                                                              |                                  |
| FCS-BP-406 | 667 420 40 85 |    | Park Brake Cable        | 609<br>709<br>711<br>811<br>814                                                              |                                  |
| FCS-BP-407 | 668 420 28 85 |    | Park Brake Cable,Rear-L | 609;613;709;711<br>809;814<br>(04.77-12.94)<br>(04.86-12.94)                                 | W 668<br>W 669<br>W 670          |
| FCS-BP-408 | 668 420 29 85 |  | Park Brake Cable,Rear-R | 609;709;711<br>(04.77-12.94)<br>(04.86-12.94)                                                | W 668<br>W 669<br>W 670          |
| FCS-BP-409 | 668 420 31 85 |  | Park Brake Cable,Rear-R | 814                                                                                          |                                  |
| FCS-BP-410 | 668 420 49 85 |  | Park Brake Cable,Rear-R | 811<br>814<br>(04.86-12.94)                                                                  | W 670                            |
| FCS-BP-411 | 668 420 50 85 |  | Park Brake Cable,Rear-L | 811<br>814<br>(04.86-12.94)                                                                  | W 670                            |
| FCS-BP-412 | 002 420 78 20 |  | Intermediate Bearing    | 1016;1023;1215;<br>1224;1517;1529;<br>1923;1924;814<br>815;817<br>ATEGO 715                  | W 970                            |
| FCS-BP-413 | 002 420 49 20 |  | Brake Pad Set,Front     | ATEGO;ACTROS Mp2<br>ATEGO;AXOR<br>(04.96-10.02);(04.03-.....)<br>(05.98-09.04);(01.02-.....) |                                  |
| FCS-BP-414 | 002 420 62 20 |  | Brake Pad Set,Front     | 609;709;711<br>811;814;VARIO<br>615;715;815                                                  | W 668<br>W 669<br>W 670          |


|            |               |                                                                                     |                                  |                                                                          |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------------|--------------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-415 | 601 420 87 20 |     | Intermediate Bearing             | 207;208;209;210<br>307;310;409;410                                       | W 601<br>W 602<br>W 611                   |
| FCS-BP-416 | 003 420 72 20 |    | Propeller Shaft Vibration Damper | VARIO;612;614<br>812;814;815<br>ATEGO                                    | W 667<br>W 668<br>W 669<br>W 670<br>W 684 |
| FCS-BP-417 | 601 423 78 10 |    | Brake Pad Set,Rear               | 210<br>307<br>308<br>310<br>(04.77-02.96)                                | W 601<br>W 602                            |
| FCS-BP-418 | 602 423 65 10 |    | Brake Pad Set,Rear               | 210<br>307<br>308<br>310<br>(04.77-02.96)                                | W 602                                     |
| FCS-BP-419 | 611 423 25 10 |    | Brake Pad Set,Rear               | 407<br>408<br>409<br>410<br>(04.82-06.95)                                | W 611                                     |
| FCS-BP-420 | 309 421 50 10 |    | Brake Pad Set,Rear               | 406;407;408;409<br>410;508;608<br>(01.68-12.94)<br>(09.63-12.88)         | W 309<br>W 310                            |
| FCS-BP-421 | 310 421 44 10 |  | Brake Pad Set,Rear               | 406;407;408;409<br>410;508;608<br>(01.68-12.94)<br>(09.63-12.88)         | W 309                                     |
| FCS-BP-422 | 670 423 55 11 |  | Brake Pad Set,Rear               | 507;508;509;510<br>609;709<br>(01.70-12.94)<br>(04.77-12.94)             | W 667<br>W 668                            |
| FCS-BP-423 | 318 421 18 10 |  | Brake Pad Set,Rear               | 309; 608;406; 613<br>407; 808;408; 809<br>409; 811;410; 913<br>508; 1013 | W 309<br>W 310<br>W 314<br>W 316<br>W 318 |
| FCS-BP-424 | 670 423 64 11 |  | Brake Pad Set,Rear               | 711<br>809<br>811<br>814<br>(04.86-12.94)                                | W 669<br>W 670                            |
| FCS-BP-425 | 673 421 28 31 |  | Brake Pad Set,Rear               | 709;709K;811K<br>814K;817K;914K                                          | W 670<br>W 673<br>W 674                   |
| FCS-BP-426 | 675 421 42 30 |  | Brake Pad Set,Rear               | 814;814K;817K<br>914;917K;1314K<br>1317K;1317AK                          | W 675<br>W 676<br>W 974                   |
| FCS-BP-427 | 631 420 03 20 |  | Brake Pad Set,Front              | MB 100<br>MB 120                                                         | W 631                                     |


|            |               |                                                                                     |                      |                                                                      |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------|----------------------------------------------------------------------|-------------------------------------------|
| FCS-BP-428 | 631 423 00 10 |     | Hand Brake Pad Set   | MB 100                                                               | W 631                                     |
| FCS-BP-429 | 601 540 06 17 |    | Brake Warning Sensor |                                                                      | W 601<br>W 602                            |
| FCS-BP-430 | 601 540 13 17 |    | Brake Warning Sensor |                                                                      | W 601<br>W 602<br>W 611<br>W 667          |
| FCS-BP-431 | 677 540 07 17 |    | Brake Warning Sensor |                                                                      | W 669                                     |
| FCS-BP-432 | 669 540 04 17 |    | Brake Warning Sensor | 609<br>711<br>811<br>814                                             | W 667<br>W 678<br>W 679<br>W 670<br>W 672 |
| FCS-BP-433 | 601 420 02 72 |    | Brake Disc,Front     | 207;208;209<br>210;307;310<br>(04.77-02.96)                          | W 601<br>W 602                            |
| FCS-BP-434 | 601 423 50 01 |  | Brake Drum,Rear      | 307<br>308<br>310                                                    | W 601<br>W 602                            |
| FCS-BP-435 | 601 423 51 01 |  | Brake Drum,Rear      | 207<br>208<br>209<br>210<br>(04.77-02.96)                            | W 601                                     |
| FCS-BP-436 | 631 420 03 72 |  | Brake Disc,Front     | MB 100<br>MB 120                                                     | W 631                                     |
| FCS-BP-437 | 631 423 00 01 |  | Brake Drum,Rear      | MB 100<br>MB 120                                                     | W 631                                     |
| FCS-BP-438 | 668 421 02 12 |  | Brake Disc,Front     | VARIO                                                                | W 668<br>W 670                            |
| FCS-BP-439 | 669 421 06 12 |  | Brake Disc,Front     | 609;709;VARIO<br>512 D;612;814;815<br>(04.77-12.94)<br>(04.86-12.94) | W 668<br>W 669<br>W 670                   |
| FCS-BP-440 | 670 421 03 12 |  | Brake Disc,Front     | 711<br>811<br>814<br>(04.86-12.94)                                   | W 669<br>W 670                            |

|            |               |                                                                                     |                  |                                                                                   |                          |
|------------|---------------|-------------------------------------------------------------------------------------|------------------|-----------------------------------------------------------------------------------|--------------------------|
| FCS-BP-441 | 975 421 02 12 |     | Brake Disc,Front | ATEGO 815;1217<br>1218;1317;1326<br>(01.98-10.04)<br>(10.04-.....)                |                          |
| FCS-BP-442 | 668 423 00 12 |    | Brake Disc,Rear  | VARIO 612<br>614<br>812<br>814<br>815                                             | W 668<br>W 670           |
| FCS-BP-443 | 668 423 01 12 |    | Brake Disc,Rear  | VARIO 612<br>614;812<br>814;815<br>(09.96-....)                                   | OM 904<br>W 668<br>W 670 |
| FCS-BP-444 | 668 423 04 12 |    | Brake Disc,Rear  | VARIO 612<br>614;812<br>814;815                                                   | OM 904<br>W 668<br>W 670 |
| FCS-BP-445 | 668 423 05 12 |    | Brake Disc,Rear  | VARIO 612<br>614;812<br>814;815<br>(09.96-....)                                   | OM 904<br>W 668<br>W 670 |
| FCS-BP-446 | 310 356 00 02 |    | Brake Drum,Rear  | 309;406;407;408<br>409;410;508<br>(01.68-12.94)<br>(09.63-12.88)                  | W 309<br>W 310           |
| FCS-BP-447 | 668 421 01 12 |  | Brake Drum,Rear  | 814<br>815                                                                        | OM 612<br>OM 614         |
| FCS-BP-448 | 309 334 02 04 |  | Brake Drum,Front | 309<br>508<br>608                                                                 | W 309                    |
| FCS-BP-449 | 309 334 05 04 |  | Brake Drum,Front | 309<br>508<br>608<br>613                                                          | W 309<br>W 310           |
| FCS-BP-450 | 309 356 04 02 |  | Brake Drum,Rear  | 309;406;407<br>408;409;410<br>508<br>(01.68-12.94)<br>(09.63-12.88)               | W 309                    |
| FCS-BP-451 | 310 334 14 04 |  | Brake Drum,Front | 309<br>508<br>608<br>613                                                          | W 309<br>W 310<br>W 313  |
| FCS-BP-452 | 310 356 07 02 |  | Brake Drum,Rear  | 309;406;407;408<br>409;410;508<br>(01.68-12.94)<br>(09.63-12.88)<br>(09.63-12.88) | W 309<br>W 310<br>W 313  |
| FCS-BP-453 | 611 356 09 02 |  | Brake Drum,Rear  | 407;408;409;410<br>507;509;510<br>(04.82-06.95)<br>(01.70-12.94)                  | W 611<br>W 667           |



|            |               |                                                                                     |                            |                                                                          |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------|----------------------------------|
| FCS-BP-454 | 673 356 12 02 |     | Brake Drum,Rear            | 811K<br>814K<br>817K<br>914K                                             | W 673<br>W 674<br>W 676          |
| FCS-BP-455 | 675 334 55 04 |    | Brake Drum,Front           | 814K<br>817K<br>914K<br>1317K                                            | W 668<br>W 669<br>W 670          |
| FCS-BP-456 | 674 356 12 02 |    | Brake Drum,Rear            | 709;709K;809K;811;<br>811K;814;914K817K<br>917K;1117K;1317K<br>1517K;914 | W 673                            |
| FCS-BP-457 | 000 420 14 44 |    | Rep.Kit.Brake Caliper      | 609;709;711;811<br>814;VARIO;612<br>615;815                              | W 668<br>W 669<br>W 670          |
| FCS-BP-458 | 631 420 00 44 |    | Rep.Kit.Brake Caliper      | MB 100<br>MB 120                                                         |                                  |
| FCS-BP-459 | 631 420 00 51 |    | Rep.Kit.Brake Caliper      | MB 100<br>MB 120                                                         | W 631                            |
| FCS-BP-460 | 000 421 14 63 |  | Rep.Kit.Brake Caliper      | VARIO 520<br>814/96                                                      |                                  |
| FCS-BP-461 | 000 420 68 83 |  | Rep.Kit.Brake Caliper      | 207;208;209<br>210;308;310                                               | W 601<br>W 602                   |
| FCS-BP-462 | 001 430 03 60 |  | Rep.Kit.Brake Caliper      | 207<br>307<br>309<br>508<br>608                                          | W 601<br>W 602<br>W 460<br>W 463 |
| FCS-BP-463 | 001 586 80 42 |  | Rep.Kit.Brake Caliper      | 207<br>210<br>307<br>310                                                 | W 601<br>W 602                   |
| FCS-BP-464 | 002 586 53 42 |  | Rep.Kit.Brake Caliper      | 207;208;209<br>210;308;310                                               | W 601<br>W 602<br>W 611          |
| FCS-BP-465 | 002 586 37 43 |  | Rep.Kit.Brake Caliper      | 207<br>307<br>309<br>508<br>608                                          | W 601<br>W 602<br>W 460<br>W 463 |
| FCS-BP-466 | 000 420 04 76 |  | Rep.Kit.Brake Caliper Rear | VARIO<br>612<br>812<br>815                                               | W 667<br>W 668<br>W 670          |

|            |                                |                                                                                     |                            |                                 |                         |
|------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------|---------------------------------|-------------------------|
| FCS-BP-467 | 000 421 83 86                  |     | Rep.Kit.Brake Caliper Rear | VARIO<br>612<br>812<br>815      | W 667<br>W 668<br>W 670 |
| FCS-BP-468 | 340 420 16 28                  |    | Brake Line                 | 309<br>508<br>608<br>613        | W 309<br>W 310          |
| FCS-BP-469 | 601 420 39 28                  |    | Brake Line                 | 207<br>208<br>210<br>310        |                         |
| FCS-BP-470 | 601 420 51 28                  |    | Brake Line                 | 207<br>208<br>210<br>310        | W 601<br>W 602<br>W 611 |
| FCS-BP-471 | 631 420 60 28                  |    | Brake Line,Front           | MB 100<br>140<br>160            | W 631                   |
| FCS-BP-472 | 631 420 43 28                  |    | Brake Line,Rear            | MB 100<br>140<br>160            | W 631                   |
| FCS-BP-473 | 601 423 01 47                  |  | Brake Shoe Rod             | 207<br>307<br>308<br>310        | W 601<br>W 602          |
| FCS-BP-474 | 631 430 07 01                  |  | Brake Master Cylinder      | MB 100<br>MB 120                | W 631                   |
| FCS-BP-475 | 002 430 64 01                  |  | Brake Master Cylinder      | 309<br>406<br>407<br>508 L      | W 309<br>W 310          |
| FCS-BP-476 | 004 430 28 01                  |  | Brake Master Cylinder      | 207<br>307<br>309<br>310<br>508 | W 601<br>W 602          |
| FCS-BP-477 | 003 430 82 01                  |  | Brake Master Cylinder      | 207<br>307<br>309<br>310<br>508 | W 601<br>W 602          |
| FCS-BP-478 | 004 430 53 01                  |  | Brake Master Cylinder      | 609<br>709                      | W 668                   |
| FCS-BP-479 | 004 430 48 01<br>005 430 75 01 |  | Brake Master Cylinder      | 709;709 DK;711<br>809;811;814   |                         |

|            |                                |                                                                                     |                       |                                     |                                           |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-----------------------|-------------------------------------|-------------------------------------------|
| FCS-BP-480 | 006 430 02 01                  |     | Brake Master Cylinder | VARIO                               | W 667<br>W 668<br>W 670                   |
| FCS-BP-481 | 000 144 07 18                  |    | Power Cylinder        | 609<br>709<br>711<br>811<br>814     | W 667<br>W 668<br>W 669<br>W 670          |
| FCS-BP-482 | 000 742 14 12                  |    | Cylinder              | 609<br>709<br>814<br>814K           | OM 354<br>OM 364<br>OM 384                |
| FCS-BP-483 | 601 420 24 38                  |    | Wedge Drum Brake      | 207<br>210<br>307<br>308<br>410     | W 601<br>W 602<br>W 611                   |
| FCS-BP-484 | 000 421 34 91                  |    | Brake Pad Caliper     | VARIO<br>ALL MODELS                 | W 667<br>W 668<br>W 670                   |
| FCS-BP-485 | 000 421 35 91                  |    | Brake Pad Caliper     | 609;709;711<br>811;814;VARIO        | W 669<br>W 670                            |
| FCS-BP-486 | 970 460 07 05                  |  | Drag Link             | ATEGO;712;714<br>715;815<br>817;823 |                                           |
| FCS-BP-487 | 601 471 03 30                  |  | Fuel Cap              | 207;208;307;308<br>309;310;409;410  | W 601<br>W 602                            |
| FCS-BP-488 | 670 492 04 01<br>673 490 00 65 |  | Exhaust Pipe          | 609<br>709<br>711<br>814            | W 669;W 670<br>W 673;W 676<br>W 677;W 679 |
| FCS-BP-489 | 4900207                        |  | Exhaust Pipe          | 207<br>208<br>210<br>307            |                                           |
| FCS-BP-490 | 309 500 17 02                  |  | Radiator              | 309<br>508<br>608                   | W 309<br>W 310                            |
| FCS-BP-491 | 601 500 67 03                  |  | Radiator              | 207<br>208<br>209<br>210            | W 601<br>W 602<br>W 611                   |
| FCS-BP-492 | 631 500 05 02                  |  | Radiator              | MB 100<br>MB 120                    | W 631                                     |

|            |                                                 |                                                                                     |                        |                                            |                                                 |
|------------|-------------------------------------------------|-------------------------------------------------------------------------------------|------------------------|--------------------------------------------|-------------------------------------------------|
| FCS-BP-493 | 668 500 06 01                                   |     | Radiator               | 609<br>709<br>711<br>811<br>814            | W 667<br>W 668<br>W 669<br>W 670                |
| FCS-BP-494 | 673 500 28 03                                   |    | Radiator               | 814k<br>814k<br>914k                       | W 674                                           |
| FCS-BP-495 | 000 501 02 15<br>000 501 29 15                  |    | Radiator Cap           | 310<br>407<br>410                          |                                                 |
| FCS-BP-496 | 000 501 62 15                                   |    | Radiator Cap           | 207<br>208<br>210<br>307<br>310            | W 601;W 602;W 611<br>W 901;W 902;W 903<br>W 904 |
| FCS-BP-497 | 601 505 16 55                                   |    | Radiator Fan Shroud    | 408<br>409<br>410                          | OM 601<br>OM 602                                |
| FCS-BP-498 | 001 987 26 40<br>001 987 52 40<br>322 504 02 12 |    | Radiator Rubber Buffer | 309;508;608;709<br>814;1117;1317<br>TRUCKS | W 300;W 418<br>W 600;W 669<br>W 698;W 976       |
| FCS-BP-499 | 001 987 53 40                                   |  | Radiator Rubber Buffer | 309<br>508<br>608                          | W 300<br>W 352<br>W 669<br>W 678<br>W 958       |
| FCS-BP-500 | 608 988 00 11                                   |  | Radiator Mounting      | 207<br>210<br>310<br>508                   | W 668<br>W 669<br>W 670                         |
| FCS-BP-501 | 601 094 07 82                                   |  | Hose To Air Filter     | 207<br>210<br>307<br>310<br>410            |                                                 |
| FCS-BP-502 | 601 501 26 82                                   |  | Radiator Hose          | 601<br>602<br>611                          | W 601<br>W 602<br>W 611                         |
| FCS-BP-503 | 601 501 29 82                                   |  | Radiator Hose          | 601<br>602<br>611                          | W 601<br>W 602<br>W 611                         |
| FCS-BP-504 | 601 501 37 82                                   |  | Radiator Hose          | 601<br>602<br>611                          | W 601<br>W 602<br>W 611                         |
| FCS-BP-505 | 601 501 45 82                                   |  | Radiator Hose          | 601<br>602<br>611                          | W 601<br>W 602<br>W 611                         |

|            |               |                                                                                     |                            |                                    |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|------------------------------------|-------------------------------------------|
| FCS-BP-506 | 006 542 13 07 |     | Km(Kilometer)Cable         | 207;208;209<br>210;307;310<br>410  | W 601<br>W 602<br>W 611                   |
| FCS-BP-507 | 004 542 12 07 |    | Km(Kilometer)Cable         | 309<br>508<br>608<br>609           | W 309<br>W310                             |
| FCS-BP-508 | 004 542 57 07 |    | Km(Kilometer)Cable         | 609<br>709<br>711<br>814           | W 668<br>W 669<br>W 670                   |
| FCS-BP-509 | 631 540 01 68 |    | Km(Kilometer)Cable         | MB 100<br>MB 120                   | W 631                                     |
| FCS-BP-510 | 601 542 01 07 |    | Km(Kilometer)Cable         | 207<br>208<br>210                  | W 602                                     |
| FCS-BP-511 | 005 542 73 07 |    | Km(Kilometer)Cable         | 207<br>208<br>210<br>(04.77-02.96) | W 601                                     |
| FCS-BP-512 | 001 542 59 07 |  | Rep.Kit.Brake Caliper Rear | 608<br>709<br>1114K                | W 314<br>W 341                            |
| FCS-BP-513 | 004 542 66 07 |  | Brake Line                 | TRUCK                              |                                           |
| FCS-BP-514 | 004 542 92 07 |  | Brake Line                 |                                    | W 387<br>W 389<br>W 391<br>W 393<br>W 395 |
| FCS-BP-515 | 001 542 21 17 |  | Oil Pressure Switch        | 309;508;608<br>609;709<br>711;814  | OM 314<br>OM 352                          |
| FCS-BP-516 | 004 542 89 17 |  | Oil Pressure Switch        | TRUCK<br>BUS                       | OM 366<br>OM 402<br>OM 407<br>OM 422      |
| FCS-BP-517 | 005 542 90 17 |  | Oil Pressure Switch        | 208;210;308<br>310;408;410         |                                           |
| FCS-BP-518 | 013 542 05 17 |  | Oil Pressure Switch        |                                    | OM 104                                    |

|            |               |                                                                                     |                            |                                                          |                                                    |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------------|----------------------------------------------------------|----------------------------------------------------|
| FCS-BP-519 | 001 542 23 17 |     | Coolant Temperature Switch | 309;508;608<br>609;709;711                               | OM 314<br>OM 352                                   |
| FCS-BP-520 | 008 542 56 17 |    | Brake Master Cylinder      | 207<br>208<br>210<br>310                                 | OM 601<br>OM 602                                   |
| FCS-BP-521 | 001 545 12 09 |    | Reverse Light Switch       | MB.TRUCK<br>BUS                                          | W 601<br>W 602                                     |
| FCS-BP-522 | 002 545 68 14 |    | Reverse Light Switch       | PKW<br>MB 210<br>310<br>410                              | W 601<br>W 602<br>W 611                            |
| FCS-BP-523 | 000 545 69 09 |    | Stoplight Switch           | 207<br>210<br>307<br>609<br>709                          | W 309<br>W 310<br>W 631<br>W 670<br>W 674          |
| FCS-BP-524 | 000 545 54 14 |    | Pressure Switch            | TRUCK<br>BUS                                             | W 310<br>W 313<br>W 684                            |
| FCS-BP-525 | 001 545 47 14 |  | Pressure Switch            | TRUCK<br>BUS                                             | W 903<br>W 904                                     |
| FCS-BP-526 | 000 542 06 30 |  | Angle Drive                | 207<br>210<br>310<br>508                                 | W 343<br>W 352<br>W 650<br>W 671<br>W 675          |
| FCS-BP-527 | 620 540 00 45 |  | Steering Column Switch     | 1222;1417;1422;1614;<br>1617;1625;1628;1635<br>1935;2622 | W 371;W 613<br>W 615;W 617<br>W 621;W 624<br>W 645 |
| FCS-BP-528 | 631 540 01 44 |  | Steering Column Switch     | MB 100<br>MB 120                                         | W 631                                              |
| FCS-BP-529 | 631 545 02 22 |  | Windshield Wiper Switch    | MB 100<br>MB 120                                         | W 631                                              |
| FCS-BP-530 | 631 545 02 10 |  | Steering Column Switch     | MB 100<br>MB 120                                         | W 631                                              |
| FCS-BP-531 | 673 540 04 45 |  | Steering Column Switch     | 609<br>709<br>VARIO                                      | W 668<br>W 669<br>W 673<br>W 675                   |



|            |               |                                                                                     |                                       |                                 |                                           |
|------------|---------------|-------------------------------------------------------------------------------------|---------------------------------------|---------------------------------|-------------------------------------------|
| FCS-BP-532 | 684 540 00 44 |     | Steering Column Switch                | MB 100<br>MB 120<br>MB 800      | W 631<br>W 684                            |
| FCS-BP-533 | 008 545 01 24 |    | Steering Column Switch                | ATEGO<br>ACTROS                 | W 613<br>W 675                            |
| FCS-BP-534 | 006 545 78 24 |    | Steering Column Switch                | 207;208<br>209;307<br>310;410   | W 601<br>W 602<br>W 611                   |
| FCS-BP-535 | 005 545 51 24 |    | Steering Column Switch                | 1213<br>1419<br>1619            |                                           |
| FCS-BP-536 | 673 695 00 30 |    | Radio Set Cover                       | 609<br>709<br>711<br>814        |                                           |
| FCS-BP-537 | 673 720 00 75 |    | Interior Door Handle                  | 609;709<br>711;811<br>814;1317K | W 669<br>W 670<br>W 673<br>W 675          |
| FCS-BP-538 | 000 720 12 35 |  | Lock, Outside Right                   | 609<br>709<br>711<br>814        | W 371<br>W 669<br>W 670<br>W 673          |
| FCS-BP-539 | 000 720 13 35 |  | Lock, Outside Left                    | 609<br>709<br>711<br>814        | W 371<br>W 669<br>W 670<br>W 673<br>W 684 |
| FCS-BP-540 | 000 723 05 03 |  | Latch To Lock                         | 609;709<br>711;811<br>814;VARIO | W 332<br>W 669<br>W 670<br>W 673          |
| FCS-BP-541 | 000 720 29 35 |  | Lock, Inside R                        | 609<br>709<br>711<br>814        |                                           |
| FCS-BP-542 | 601 720 03 35 |  | Side Door Slide Mechanism<br>Front, L | 207<br>307<br>410               | W 601<br>W 602<br>W 616<br>W 617          |
| FCS-BP-543 | 601 720 04 35 |  | Side Door Slide Mechanism<br>Front, R | 207<br>307<br>410               | W 601<br>W 616<br>W 617                   |
| FCS-BP-544 | 601 740 01 35 |  | Side Door Slide Mechanism<br>Rear     | 207<br>208<br>210<br>307<br>310 | W 601<br>W 602<br>W 616<br>W 617          |



|            |                 |                                                                                     |                             |                                            |                                           |
|------------|-----------------|-------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------|-------------------------------------------|
| FCS-BP-545 | 673 760 00 02   |     | Window Handle Opener        | 609;709<br>711;811<br>814;1317K            | W 601<br>W 611<br>W 670<br>W 673<br>W 675 |
| FCS-BP-546 | 670 760 02 05   |    | Tumbler, Lock               | SPRINTER<br>VITO<br>609<br>1317            | W 601<br>W 602<br>W 615<br>W 616<br>W 617 |
| FCS-BP-547 | 601 760 18 47   |    | Side Door Slide Mechanism   | 207;307<br>308;310<br>410;MB 100<br>MB 120 | W 601<br>W 631                            |
| FCS-BP-548 | 601 760 18 47-1 |    | Side Door Slide Mechanism   | 207;307<br>308;310<br>410;MB 100<br>MB 120 | W 601<br>W 631                            |
| FCS-BP-549 | 611 760 05 47   |    | Lock To Side Door           | SPRINTER<br>408<br>409<br>410              |                                           |
| FCS-BP-550 | 670 760 01 59   |    | Door Handle                 | 207;208<br>210;609<br>709;711              | W 371;W 601<br>W 669;W 670<br>W 675;W 684 |
| FCS-BP-551 | 670 760 03 59   |  | Door Handle                 | 609<br>709<br>711<br>814                   |                                           |
| FCS-BP-552 | 631 760 04 61   |  | Interior Handle Assembly, L | MB 100<br>MB 140<br>MB 160                 | W 332<br>W 371<br>W 631<br>W 684          |
| FCS-BP-553 | 631 760 05 61   |  | Interior Handle Assembly, R | MB 100<br>MB 140<br>MB 160                 | W 332<br>W 371<br>W 631<br>W 684          |
| FCS-BP-554 | 601 743 12 11   |  | Plate                       | 207<br>208<br>210<br>307<br>310            | W 601<br>W 611                            |
| FCS-BP-555 | 611 810 01 16   |  | Outside Mirror              | 207<br>208<br>210<br>307<br>410            | W 601<br>W 602<br>W 615<br>W 616          |
| FCS-BP-556 | 631 810 18 16   |  | Outside Mirror, Left        | MB 100<br>MB 140<br>MB 160                 |                                           |
| FCS-BP-557 | 631 810 19 16   |  | Outside Mirror, Right       | MB 100<br>MB 140<br>MB 160                 |                                           |

|            |               |                                                                                     |                      |                                            |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|----------------------|--------------------------------------------|----------------------------------|
| FCS-BP-558 | 631 810 30 16 |     | Outside Mirror,Left  | MB 100<br>MB 140<br>MB 160                 |                                  |
| FCS-BP-559 | 631 810 31 16 |    | Outside Mirror,Right | MB 100<br>MB 140<br>MB 160                 |                                  |
| FCS-BP-560 | 000 826 71 90 |    | Headlight Lens,L     | 309<br>508<br>608<br>613                   | W 309<br>W 310<br>W 314          |
| FCS-BP-561 | 000 826 72 90 |    | Headlight Lens,R     | 309<br>508<br>608<br>613                   | W 309<br>W 310<br>W 314          |
| FCS-BP-562 | 002 826 41 90 |    | Headlight Lens,L     | 207;208;209;210;307<br>310;408;409;410     | W 309<br>W 601<br>W 602<br>W 611 |
| FCS-BP-563 | 002 826 42 90 |    | Headlight Lens,R     | 207;208;209;210;307<br>310;408;409;410     | W 309<br>W 601<br>W 602<br>W 611 |
| FCS-BP-564 | 002 826 96 90 |  | Headlight Lens,L     | 609;709;711;811<br>814;1017;1317K<br>1320K | W 670<br>W 673<br>W 674          |
| FCS-BP-565 | 002 826 97 90 |  | Headlight Lens,R     | 609;709;711;811<br>814;1017;1317K<br>1320K | W 670<br>W 673<br>W 674          |
| FCS-BP-566 | 004 826 02 90 |  | Headlight Lens,L     | VARIO<br>614<br>812<br>814<br>815          | W 668<br>W 669                   |
| FCS-BP-567 | 004 826 03 90 |  | Headlight Lens,R     | VARIO<br>614<br>812<br>814<br>815          | W 668<br>W 669                   |
| FCS-BP-568 | 631 826 00 90 |  | Headlight Lens,L     | MB 100<br>MB 140                           | W 631                            |
| FCS-BP-569 | 631 826 01 90 |  | Headlight Lens,R     | MB 100<br>MB 140                           | W 631                            |
| FCS-BP-570 | 001 540 62 70 |  | Tail Lamp            |                                            |                                  |

|            |               |                                                                                     |                 |                                                                              |                                  |
|------------|---------------|-------------------------------------------------------------------------------------|-----------------|------------------------------------------------------------------------------|----------------------------------|
| FCS-BP-571 | 001 540 63 70 |     | Tail Lamp       |                                                                              |                                  |
| FCS-BP-572 | 002 544 12 90 |    | Rear Light Lens |                                                                              |                                  |
| FCS-BP-573 | 002 544 16 90 |    | Rear Light Lens |                                                                              |                                  |
| FCS-BP-574 | 001 544 80 03 |    | Tail Lamp       | 814;817K;914;917K;<br>1114K;1117K;1120K<br>1317K;1317AK;1514K<br>1517K;1520K | W 674<br>W 675<br>W 676<br>W 677 |
| FCS-BP-575 | 001 544 81 03 |    | Tail Lamp       |                                                                              |                                  |
| FCS-BP-576 | 002 826 36 90 |    | Rear Light Lens | 309<br>508<br>608<br>613                                                     | W 309<br>W 310                   |
| FCS-BP-577 | 000 820 91 61 |  | Headlight,Left  | 207<br>208<br>307<br>310<br>410                                              | W 601<br>W 602<br>W 611          |
| FCS-BP-578 | 000 820 92 61 |  | Headlight,Right | 207<br>208<br>307<br>310<br>410                                              | W 601<br>W 602<br>W 611          |
| FCS-BP-579 | 001 820 37 61 |  | Headlight,Left  | 609;709<br>711;811<br>814;VARIO                                              | W 668<br>W 669<br>W 670          |
| FCS-BP-580 | 001 820 38 61 |  | Headlight,Right | 609;709<br>711;811<br>814;VARIO                                              | W 668<br>W 669<br>W 670          |
| FCS-BP-581 | 314 820 03 61 |  | Headlight,Left  | 309<br>508<br>608<br>613                                                     | W 309<br>W 310                   |
| FCS-BP-582 | 314 820 04 61 |  | Headlight,Right | 309<br>508<br>608<br>613                                                     | W 309<br>W 310                   |
| FCS-BP-583 | 631 820 53 61 |  | Headlight,Left  | MB 100<br>MB 140<br>MB 160                                                   |                                  |

|            |               |                                                                                     |                       |                                   |                         |
|------------|---------------|-------------------------------------------------------------------------------------|-----------------------|-----------------------------------|-------------------------|
| FCS-BP-584 | 631 820 54 61 |     | Headlight,Right       | MB 100<br>MB 140<br>MB 160        |                         |
| FCS-BP-585 | 670 820 13 61 |    | Headlight,Left        | VARIO<br>812<br>814<br>815        | W 669<br>W 670          |
| FCS-BP-586 | 670 820 14 61 |    | Headlight,Right       | VARIO<br>812<br>814<br>815        | W 669<br>W 670          |
| FCS-BP-587 | 000 820 63 21 |    | Side Lamp,L           |                                   |                         |
| FCS-BP-588 | 000 820 62 21 |    | Side Lamp,R           |                                   |                         |
| FCS-BP-589 | 000 820 75 21 |    | Side Lamp,L           | 609<br>709<br>711<br>814          | W 668<br>W 669<br>W 670 |
| FCS-BP-590 | 000 820 76 21 |  | Side Lamp,R           | 609<br>709<br>711<br>814          | W 668<br>W 669<br>W 670 |
| FCS-BP-591 | 000 820 79 21 |  | Side Lamp,L           | 609<br>709<br>711<br>814          | W 670                   |
| FCS-BP-592 | 000 820 80 21 |  | Side Lamp,R           | 609<br>709<br>711<br>814          | W 670                   |
| FCS-BP-593 | 670 820 05 21 |  | Side Lamp,L           | VARIO<br>614<br>615<br>814<br>815 | W 669                   |
| FCS-BP-594 | 670 820 06 21 |  | Side Lamp,R           | VARIO<br>614<br>615<br>814<br>815 | W 669                   |
| FCS-BP-595 | 000 822 50 10 |  | Lens,Indicator        |                                   |                         |
| FCS-BP-596 | 001 822 60 10 |  | Blinker Lamp Lens,L&R | 609<br>709<br>711<br>811<br>814   | W 669                   |

|            |                                |                                                                                     |                 |                                                            |                                  |
|------------|--------------------------------|-------------------------------------------------------------------------------------|-----------------|------------------------------------------------------------|----------------------------------|
| FCS-BP-597 | 001 822 67 20                  |     | Side Lamp,L     | 207<br>307<br>310<br>410                                   | W 601<br>W 602<br>W 611          |
| FCS-BP-598 | 001 822 68 20                  |    | Side Lamp,R     | 207<br>307<br>310<br>410                                   | W 601<br>W 602<br>W 611          |
| FCS-BP-599 | 601 743 12 11                  |    | Side Lamp,L     | MB 100<br>MB 140<br>MB 160                                 |                                  |
| FCS-BP-600 | 631 822 03 20                  |    | Side Lamp,R     | MB 100<br>MB 140<br>MB 160                                 |                                  |
| FCS-BP-601 | 670 826 00 40                  |    | Side Lamp,L     | VARIO<br>614<br>615<br>814<br>815                          | W 669<br>W 670                   |
| FCS-BP-602 | 670 826 01 40                  |    | Side Lamp,R     | VARIO<br>614<br>615<br>814<br>815                          | W 669<br>W 670                   |
| FCS-BP-603 | 001 544 83 90                  |  | Rear Light Lens | O 405;817K;914K;917K;<br>1114K;1117K;1317K<br>1517K;MB 800 | W 357<br>W 676<br>W 678<br>W 684 |
| FCS-BP-604 | 000 826 20 10                  |  | Tail Lamp,Lens  | 207<br>208<br>307<br>310<br>410                            | W 601<br>W 602                   |
| FCS-BP-605 | 0018265390 LH<br>0018265490 RH |  | Rear Light Lens | 406;407;408<br>409;410;508<br>608                          | W 309<br>W 310                   |
| FCS-BP-606 | 000 826 30 24                  |  | Lens            |                                                            |                                  |
| FCS-BP-607 | 000 826 31 24                  |  | Lens            |                                                            |                                  |
| FCS-BP-608 | 631 751 00 18                  |  | Grille          | MB 100<br>MB 140<br>MB 160                                 |                                  |
| FCS-BP-609 | 631 751 02 18                  |  | Grille          | MB 100<br>MB 140<br>MB 160                                 |                                  |

|            |               |                                                                                     |                                 |                                                                           |                                                    |
|------------|---------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------|----------------------------------------------------|
| FCS-BP-610 | 601 888 00 23 |    | Grille                          | 207;208;209;210<br>307;310;409<br>(04.77-02.96)<br>(04.82-06.95)          | W 601<br>W 602<br>W 611                            |
| FCS-BP-611 | 601 880 00 40 |    | Blinker Lamp Cover,L            | 207;208;209;210<br>307;310;409<br>(04.77-02.96)<br>(04.82-06.95)          | W 601<br>W 602<br>W 611                            |
| FCS-BP-612 | 601 880 01 40 |    | Blinker Lamp Cover,R            | 207;208;209;210<br>307;310;409<br>(04.77-02.96)<br>(04.82-06.95)          | W 601<br>W 602<br>W 611                            |
| FCS-BP-613 | 601 520 15 70 |    | Front Bumper                    | 207;208;209;210<br>307;310;409<br>(04.77-02.96)                           | W 601<br>W 602<br>W 615<br>W 616<br>W 617          |
| FCS-BP-614 | 631 880 02 70 |    | Front Bumper                    | MB 100<br>MB 120                                                          | W 631                                              |
| FCS-BP-615 | 673 880 01 70 |    | Front Bumper                    | 811K;814K;817K<br>914K;1017K;1317K                                        | W 673                                              |
| FCS-BP-616 | 670 880 02 70 |  | Front Bumper                    | 609;613;709;711<br>814;VARIO 612<br>614<br>(04.77-12.94)<br>(04.86-12.94) | W 668                                              |
| FCS-BP-617 | 631 885 06 03 |  | Rear Bumper,L                   | MB 100<br>MB 120                                                          | W 631                                              |
| FCS-BP-618 | 631 885 07 03 |  | Rear Bumper,R                   | MB 100<br>MB 120                                                          | W 631                                              |
| FCS-BP-619 | 001 997 12 41 |  | Seal Ring                       | 207<br>208<br>210<br>310                                                  |                                                    |
| FCS-BP-620 | 314 890 00 01 |  | Mounting Cab To<br>Cross,Member | 309;508;608;811<br>913;1013;1113<br>MB 800                                | W 314<br>W 316<br>W 318<br>W 684                   |
| FCS-BP-621 | 322 264 00 96 |  | Boot To Gearshift Lever         | 309<br>508<br>608                                                         | W 314<br>W 316<br>W 318<br>W 684                   |
| FCS-BP-622 | 673 325 01 44 |  | Rubber Buffer,Suspension        | ATEGO;1120AF;1124AF<br>1314AK;1317AK;1320AK<br>1514K;1517K;1520           | W 375;W 675<br>W 676;W 970<br>W 972;W 975<br>W 976 |