




**FREECARS (CHINA) COMPANY LIMITED**  
**GUANGZHOU SUN ASIA IMPORT AND EXPORT CO.,LTD**  
RM801-803,Goctic Centre,No.450,Huanshi East Road,Yuexiu District Guangzhou City  
Tel: +86-20-84201892 Fax: +86-20-84201893 Mob: +86-13002023915  
Email: freecars@163.com sales@freecars.com.cn  
Website: www.freecarsautoparts.com

### American Truck Switch Series


| OTK NO.     | FCS NO.   | Description                    | Photo | Model                                                                                                | OE NO.                                                                      | Pin |
|-------------|-----------|--------------------------------|-------|------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|-----|
| OTK01-06047 | FCS-SW001 | Turn Signal Switch             |       | Freightliner                                                                                         | A06-52311-000,<br>A0652311000                                               |     |
| OTK01-06058 | FCS-SW002 | Turn Signal Switch             |       | Kenworths, Peterbilts Trucks                                                                         | 577.75010<br>Peterbilt P271067                                              | 8   |
| OTK01-06060 | FCS-SW003 | Turn Signal Switch             |       |                                                                                                      | 577.59015                                                                   |     |
| OTK01-06064 | FCS-SW004 | Turn Signal Switch             |       | Freightliner Cascadia 08-                                                                            | 204.048,<br>A06-52311-000,<br>A0652311000                                   | 14  |
| OTK01-06123 | FCS-SW005 | Gear Shift Transmission Switch |       | Mercedes Benz Actros<br>Freightliner Cascadia                                                        | A0095452124                                                                 | 4   |
| OTK01-07051 | FCS-SW006 | Turn Signal Switch             |       | PALANCR DIREC<br>UNIVERSAL<br>SIARWES                                                                | 48272,<br>Paccar TL10300<br>90251G<br>Grote 03606251                        | 8   |
| OTK01-07052 | FCS-SW007 | Turn Signal Switch             |       | Kenworth                                                                                             | 48282,Paccar TL1095<br>844013203<br>Grote 03606051<br>SIGNALSTAT 915Y105    | 8   |
| OTK01-07056 | FCS-SW008 | Turn Signal Switch             |       | Kenworth, Freightliner                                                                               | Kenworth K3012953<br>Paccar TL3020<br>K301-295-3<br>Grote 01481187<br>48532 |     |
| OTK01-07073 | FCS-SW009 | Turn Signal Switch             |       | Freightliner M2 (11-02)                                                                              | Freightliner A0636946000<br>A0636956002<br>A0636956003,9785201              | 6   |
| OTK01-07079 | FCS-SW010 | Turn Signal Switch             |       | IC 2004-89, International 2010-01                                                                    | NAVISTAR 1669742C91<br>1685611C91<br>1699742C91<br>2502912C91,9785101       |     |
| OTK01-07080 | FCS-SW011 | TURN SIGNAL SWITCH             |       | Freightliner Century Class 2003-98<br>Freightliner Columbia 2003-00<br>Freightliner Coronado 2003-00 | Freightliner A1413495000<br>A1413495003,9785204                             | 8   |
| OTK01-07081 | FCS-SW012 | Turn Signal Switch             |       | Freightliner                                                                                         | Freightliner A0644025000<br>VSM 999496,9785211                              | 8   |

| OTK NO.     | FCS NO.   | Description        | Photo                                                                               | Model                                                 | OE NO.                                                                                   | Pin   |
|-------------|-----------|--------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------|------------------------------------------------------------------------------------------|-------|
| OTK01-07082 | FCS-SW013 | Turn Signal Switch |    | Freightliner FL60, FL80                               | 01483071, 6805450124                                                                     | 8     |
| OTK01-07083 | FCS-SW014 | Turn Signal Switch |    | Freightliner                                          | Mack 1MR4279<br>1MR574<br>25155885<br>9785504<br>Paccar TL3510, 577.62004                |       |
| OTK01-07084 | FCS-SW015 | Turn Signal Switch |    | Freightliner                                          | Mack 1MR2178P11<br>1MR57<br>1MR575A<br>25101664<br>9785503<br>Paccar TL3520              |       |
| OTK01-07085 | FCS-SW016 | Turn Signal Switch |    | International Truck                                   | 1685613C1, 2502238C1                                                                     | -     |
| OTK01-07086 | FCS-SW017 | Turn Signal Switch |    | Freightliner, Mack CV Model                           | Mack 1MR578<br>1MR578M<br>1MR578AM<br>20795152                                           |       |
| OTK01-07088 | FCS-SW018 | Turn Signal Switch |    | UNIVERSAL<br>Volvo/White                              | Paccar TL105<br>Volvo/White 844010005<br>Signal Stat 900Y129                             |       |
| OTK01-07093 | FCS-SW019 | Turn Signal Switch |  | Freightliner                                          | Freightliner 01481177<br>01481176<br>Paccar TL3005,<br>Grote 48522                       | 8     |
| OTK01-07094 | FCS-SW020 | Turn Signal Switch |  | Freightliner                                          | Freightliner A1413495002<br>A1413495005, 577.46004,                                      | 8     |
| OTK01-07103 | FCS-SW021 | TURN SIGNAL SWITCH |  | Kenworth C500 T300 T400<br>Peterbilt 579 384 389      | Paccar TL3025<br>TRW 480836<br>48083601<br>480836E<br>01481376, 57759006<br>VSM 01481377 |       |
| OTK01-07104 | FCS-SW022 | TURN SIGNAL SWITCH |  | Peterbilt                                             | Peterbilt TL1090<br>1603827<br>57775001<br>Signal Stat 915Y104S1G                        |       |
| OTK01-07105 | FCS-SW023 | TURN SIGNAL SWITCH |  | Kenworth T600 T200 W900                               | Grote 01481383                                                                           |       |
| OTK01-07110 | FCS-SW024 | TURN SIGNAL SWITCH |  | Mack DM 2005-86, Mack MR<br>2007-86, Mack MRU 2015-08 | Mack 1MR571<br>21475716<br>577.62001<br>Paccar TL3525<br>VSM 915Y703                     | 7+2+1 |
| OTK01-07112 | FCS-SW025 | TURN SIGNAL SWITCH |  | Peterbilt 3**<br>Kenworth T600                        | Peterbilt TL30350<br>577.75011                                                           | 8     |

| OTK NO.     | FCS NO.   | Description            | Photo                                                                               | Model                                                                                                        | OE NO.                                                                              | Pin    |
|-------------|-----------|------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------|
| OTK01-07122 | FCS-SW026 | TURN SIGNAL SWITCH     |    | Peterbilt 3** / 5***<br>Kenworth T600<br>International 4400<br>Volvo VNL                                     | Peterbilt 480827<br>577.75009<br>Paccar TL3030<br>TRW 480827                        |        |
| OTK01-07125 | FCS-SW027 | TURN SIGNAL SWITCH     |    | Freightliner FS65 2006-02<br>Thomas Saf-T-Liner 2007-02                                                      | Freightliner A0622743002<br>978-5210<br>577.46008                                   |        |
| OTK01-07135 | FCS-SW028 | TURN SIGNAL SWITCH     |    | Mack                                                                                                         | Mack 1MR572<br>25025234<br>577.62002<br>Paccar TL3530<br>VSM 910Y601                |        |
| OTK01-07139 | FCS-SW029 | TURN SIGNAL SWITCH     |    | Mack RD 1995-87<br>Ford C-Series<br>Ford L-Series                                                            | Mack 1MR3412P1<br>1MR3412P2<br>1MR3412<br>1MR3440<br>577.62010<br>Ford E5HT13B302AA |        |
| OTK01-07153 | FCS-SW030 | TURN SIGNAL SWITCH     |    | Freightliner                                                                                                 | Freightliner A0657916000<br>577.46013                                               |        |
| OTK01-07157 | FCS-SW031 | TURN SIGNAL SWITCH     |    | Mack CX VISION CHU CXN CXU GU                                                                                | Mack 21750459<br>577.62014                                                          |        |
| OTK01-07233 | FCS-SW032 | Turn Signal Switch     |  | International 9200i 2009<br>Kenworth T270 2016-2010<br>T300 2008<br>T370 2014-2008<br>T600 2013<br>W900 2012 | VSM 01483095<br>577.59005<br>Kenworth TL30450                                       | 8      |
| OTK02-08022 | FCS-SW033 | Ignition Lock Cylinder |  | Buick, Cadillac, Jeep, Oldsmobile,<br>Pontiac                                                                | 4489225, 7025216, 8120081,<br>J8120081                                              | -      |
| OTK02-08024 | FCS-SW034 | Ignition Lock Cylinder |  | Buick, Cadillac, Chevrolet, GMC,<br>International, Pontiac, Oldsmobile                                       | 1155883, 12300443, 12534399,<br>12534401                                            | -      |
| OTK02-08124 | FCS-SW035 | Ignition Switch        |  | International                                                                                                | 577.59548                                                                           | 7 PIN  |
| OTK02-08125 | FCS-SW036 | Ignition Switch        |  | International                                                                                                | 577.55533                                                                           | 11 PIN |
| OTK02-08126 | FCS-SW037 | Ignition Switch        |  | International                                                                                                | 577.55534                                                                           | 11PIN  |

| OTK NO.     | FCS NO.   | Description                        | Photo                                                                               | Model                                                                                                                                                                                                                                                                               | OE NO.                                                                                                                                  | Pin |
|-------------|-----------|------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----|
| OTK02-08182 | FCS-SW038 | Ignition Starter Switch            |    | AMERICAN MOTORS 1970-1984<br>BUICK 1969-1996<br>CADILLAC 1973-1995<br>CHEVROLET 1969-1998<br>GMC 1971-1994<br>INTERNATIONAL 1974-1980<br>JEEP 1975-1994<br>OLDSMOBILE 1970-1996<br>PONTIAC 1970-2001                                                                                | 1990096, 1990099, 1990106,<br>1990110, 1990116, 3197598,<br>3250575, 8128890, J3197598,<br>J3250575, J8128890, LS309                    | 9   |
| OTK02-08186 | FCS-SW039 | Ignition Lock                      |    | International 1000D 1970<br>International 1010 1971-1972<br>International 1110 1972<br>International 1210 1972<br>International M SERIES VAN 1961<br>International SCOUT 1961-1969<br>International SCOUT II 1971<br>Jeep CHEROKEE 1974<br>Jeep CJ3 1962-1966<br>Jeep CJ5 1963-1974 | 1116513, 1116539, 1116613,<br>1116616, 12339179, 167609R91,<br>344688C91, 347002C1, 929960,<br>931067, 931697, 946435,<br>947399, LS473 | 11  |
| OTK03-05029 | FCS-SW040 | Ignition Starter Switch            |    | Mercedes-Benz SprinterDodge<br>Sprinter (06-03) Freightliner<br>Sprinter (06-02)                                                                                                                                                                                                    | 0005458108, 5103664AA                                                                                                                   | 5   |
| OTK04-01353 | FCS-SW041 | Mirror Switch                      |    | Freightliner Century 2009-03                                                                                                                                                                                                                                                        | Freightliner 34103PF<br>9015201<br>577.46501                                                                                            | 8   |
| OTK04-01362 | FCS-SW042 | Power Window Switch                |   | Freightliner Columbia 2010-03                                                                                                                                                                                                                                                       | A0630769027,<br>577.46503,<br>9015205                                                                                                   | 10  |
| OTK04-01363 | FCS-SW043 | Power Window Switch                |  | Freightliner Columbia 2010-03                                                                                                                                                                                                                                                       | A0630769008,<br>9015204,<br>577.46502                                                                                                   | 10  |
| OTK04-01364 | FCS-SW044 | Power Window Switch                |  | Freightliner Columbia 2017-03                                                                                                                                                                                                                                                       | A0630769010,<br>9015206,<br>577.46504                                                                                                   | 10  |
| OTK04-01367 | FCS-SW045 | Brake Light Switch                 |  | Mercedes-Benz E550, E320,<br>CLS550, CLS63 AMG, E350, E63<br>AMG, SprinterFreightliner<br>SprinterVolkswagen Crafter                                                                                                                                                                | 0015454409, 0015456709,<br>2E0945515A, 68013462AA,<br>68013462AB, 68022569AA                                                            | 4   |
| OTK04-01389 | FCS-SW046 | MIRROR SWITCH (Dual Heated Mirror) |  | Kenworth T660 2010-06                                                                                                                                                                                                                                                               | PACCAR P271098001<br>9015401,577.59521                                                                                                  | 10  |
| OTK04-01400 | FCS-SW047 | Toggle Switch                      |  | Kenworth                                                                                                                                                                                                                                                                            | Kenworth K301198,<br>Dynacraft D66053210,<br>Eaton 8946K929                                                                             | 1   |
| OTK04-01401 | FCS-SW048 | Toggle Switch                      |  | Kenworth                                                                                                                                                                                                                                                                            | Kenworth K301201,<br>Dynacraft D66053213,<br>Eaton 8946K932                                                                             | 2   |
| OTK04-01402 | FCS-SW049 | Toggle Switch                      |  | Kenworth                                                                                                                                                                                                                                                                            | Kenworth K301424,<br>Dynacraft D66053237,<br>Eaton 8946K1197                                                                            | 3   |

| OTK NO.     | FCS NO.   | Description                | Photo                                                                               | Model        | OE NO.                                                      | Pin |
|-------------|-----------|----------------------------|-------------------------------------------------------------------------------------|--------------|-------------------------------------------------------------|-----|
| OTK04-01403 | FCS-SW050 | Toggle Switch              |    | Peterbilt    | Peterbilt 1603399,<br>Eaton 8946K833                        | 2   |
| OTK04-01404 | FCS-SW051 | Toggle Switch              |    | Freightliner | Freightliner A6815450722,<br>Eaton 8956K897                 | 2   |
| OTK04-01405 | FCS-SW052 | Toggle Switch              |    | Peterbilt    | Peterbilt 1604830,<br>Eaton 8956K648                        | 4   |
| OTK04-01406 | FCS-SW053 | Toggle Switch              |    | Freightliner | Freightliner A6815450622,<br>Eaton 8956K895                 | 6   |
| OTK04-01407 | FCS-SW054 | Toggle Switch              |    | Freightliner | Freightliner A6815451522,<br>Eaton 8956K913                 | 6   |
| OTK04-01408 | FCS-SW055 | Toggle Switch              |    | Kenworth     | Kenworth K301196,<br>Eaton 8946K927,<br>Dynacraft D66053204 | 2   |
| OTK04-01409 | FCS-SW056 | Toggle Switch              |  | Peterbilt    | Peterbilt 1603398,<br>Eaton 8946K832                        | 3   |
| OTK04-01410 | FCS-SW057 | Toggle Switch              |  | Peterbilt    | Peterbilt 1603401,<br>Eaton 8946K835                        | 4   |
| OTK04-01438 | FCS-SW058 | SWITCH (Momentary Contact) |  | Kenworth     | Kenworth P271123007,<br>577.59307                           | 5   |
| OTK04-01452 | FCS-SW059 | Toggle Switch              |  | Peterbilt    | 16-06657, 1606657                                           | 4   |
| OTK04-01453 | FCS-SW060 | Toggle Switch              |  | Kenworth     | K301-270, K301270                                           | 4   |
| OTK04-01454 | FCS-SW061 | Toggle Switch              |  | Kenworth     | K301-300, K301300                                           | 2   |
| OTK04-01455 | FCS-SW062 | Toggle Switch              |  | Kenworth     | K301-301, K301301                                           | 3   |

| OTK NO.     | FCS NO.   | Description         | Photo                                                                               | Model                                                      | OE NO.                                                           | Pin |
|-------------|-----------|---------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------|------------------------------------------------------------------|-----|
| OTK04-01456 | FCS-SW063 | Head Light Switch   |    | International                                              | IHC 1661234C1<br>1661234C2<br>1661234C3<br>8941K535<br>577.55520 | 5   |
| OTK04-01461 | FCS-SW064 | Toggle Switch       |    | Kenworth                                                   | K301317                                                          | 6   |
| OTK04-01463 | FCS-SW065 | Toggle Switch       |    | Kenworth                                                   | K301-387, K301387                                                | 6   |
| OTK04-01473 | FCS-SW066 | Head Light Switch   |    | Mack Models CH, CV, CX                                     | Mack 1MR4323M<br>25633258,577.62513                              |     |
| OTK04-01474 | FCS-SW067 | Head Light Switch   |    | Mack Model CX                                              | Mack 1MR4323M42<br>25169835,577.62514                            | 7   |
| OTK04-01475 | FCS-SW068 | Toggle Switch       |   | Peterbilt                                                  | 1604831                                                          | 3   |
| OTK04-01476 | FCS-SW069 | Rocker Switch       |  | Peterbilt                                                  | Peterbilt 16091215G8EEF2A11<br>577.75606<br>Eaton 8961K1955      | 8   |
| OTK04-01477 | FCS-SW070 | Power Window Switch |  | Peterbilt                                                  | 1609209, 16-09209PKG,<br>1609209PKG,577.75607                    | 5   |
| OTK04-01478 | FCS-SW071 | A/C Control Switch  |  | Peterbilt                                                  | Peterbilt 8320001000<br>889626258411,577.75608                   | 5   |
| OTK04-01479 | FCS-SW072 | Rocker Switch       |  | Peterbilt                                                  | Peterbilt 8320002000,577.75609                                   | 5   |
| OTK04-01480 | FCS-SW073 | Rocker Switch       |  | Peterbilt                                                  | Peterbilt 8320003000,577.75610                                   | 5   |
| OTK04-01482 | FCS-SW074 | Brake Light Switch  |  | International<br>4300, 4400, 3200, RXT, TerraStar,<br>4100 | NAVISTAR 2505677C91<br>5005836                                   | 2   |
| OTK04-01483 | FCS-SW075 | Dimmer Switch       |  | International<br>9100, 9200, 9300, 9400, 9900,<br>5000     | 452187C2,9010012                                                 | 3   |

| OTK NO.     | FCS NO.   | Description           | Photo                                                                               | Model                                                                        | OE NO.                                                             | Pin |
|-------------|-----------|-----------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------|--------------------------------------------------------------------|-----|
| OTK04-01487 | FCS-SW076 | Head Light Switch     |    | Freightliner Century, Columbia                                               | A0630769000, A06-30769-000,577.46507                               | 8   |
| OTK04-01494 | FCS-SW077 | Wiper Control Switch  |    | Freightliner Columbia, Coronado                                              | 06-23096-003, 0646159001, 646159001, A0623096002,577.46660,9015210 | 8   |
| OTK04-01495 | FCS-SW078 | Wiper Control Switch  |    | International 5500, 5600, 5900, 9100, 9200, 9400, 9800, 9900                 | 3534329C1,577.3038                                                 | 8   |
| OTK04-01501 | FCS-SW079 | Clutch Switch         |    | International 4300, 4400, 7300, 7400, 7500, ProStar, 8600 TranStar           | 2505658C91                                                         | 4   |
| OTK04-01511 | FCS-SW080 | Mirror Switch         |    | International 7300, 7400, 4300, 4400, 3200, 7500, 7700, 8500, 8600, CXT, RXT | 2209205C1, 2505204C1, 4084847C1, 901-5126                          | 8   |
| OTK04-01516 | FCS-SW081 | Power Window Switch   |    | Freightliner Cascadia(17-07) Cascadia 113(14-10) Cascadia 125(14-08)         | 12862662, DTL12862662, 901-5203                                    | 8   |
| OTK04-01518 | FCS-SW082 | Toggle Switch         |  | Kenworth                                                                     | 577.59197 1PIN                                                     | 1   |
| OTK04-01519 | FCS-SW083 | Cruise Control Switch |  | International 4300, 4400, 7300, 7400, 7500, ProStar, 8600 TranStar           | 2506326C1, 2598851C1, 3877814C1,577.55920,9015129                  | 4   |
| OTK04-01521 | FCS-SW084 | Toggle Switch         |  | Kenworth                                                                     | 577.59362 4PIN ON-OFF-ON                                           | 4   |
| OTK04-01535 | FCS-SW085 | Toggle Switch         |  | Kenworth                                                                     | 577.59334 4PIN                                                     | 4   |
| OTK04-01547 | FCS-SW086 | Cruise Control Switch |  | Freightliner Columbia (15-01)                                                | A0630769012,9015215                                                | 7   |
| OTK04-01548 | FCS-SW087 | Head Light Switch     |  | International 4300, 4400, ProStar                                            | 3563061C1, 3563061C2,9015410,170.1243                              | 2   |
| OTK04-01552 | FCS-SW088 | Mirror Switch         |  | Freightliner Cascadia, Cascadia 113, Cascadia 125, Dodge Sprinter            | 15829700SR, DTL15829700, 0045459207, 5103845AA                     | 10  |

| OTK NO.     | FCS NO.   | Description            | Photo                                                                               | Model                                                                                             | OE NO.                                           | Pin |
|-------------|-----------|------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|--------------------------------------------------|-----|
| OTK04-01557 | FCS-SW089 | POT Switch             |    | Kenworth W900(15-13)                                                                              | G90106609,170.1243,9015410                       | 4   |
| OTK04-01559 | FCS-SW090 | Door Jamb Switch       |    | International 2574, 2674, 8100,<br>2554, 2654, 4700, 4800, 4900                                   | 485588C1,9015131                                 | 1   |
| OTK04-01564 | FCS-SW091 | Mirror Switch          |    | Kenworth                                                                                          | P271181004,577.59631                             | 10  |
| OTK04-01565 | FCS-SW092 | CLEARANCE LIGHT SWITCH |    | Kenworth                                                                                          | Paccar P27104003<br>8961K1896,577.59623          | 5   |
| OTK04-01566 | FCS-SW093 | LOWBEAM SWITCH         |    | Kenworth                                                                                          | Paccar P27104001<br>Eaton 8964K1894              | 6   |
| OTK04-01567 | FCS-SW094 | FRONT FOGLAMP SWITCH   |    | Kenworth                                                                                          | Paccar P27104008,577.59624                       | 6   |
| OTK04-01568 | FCS-SW095 | CRUISE SWITCH          |  | Kenworth                                                                                          | Paccar P27104014<br>577.59636<br>Eaton 8961K1905 | 8   |
| OTK04-01569 | FCS-SW096 | LIGHT SWITCH           |  | Kenworth                                                                                          | Paccar P27104011<br>577.59635<br>Eaton 8961K1902 | 7   |
| OTK04-01570 | FCS-SW097 | READING LIGHT SWITCH   |  | Kenworth W900                                                                                     | Paccar P27104010<br>577.56925<br>Eaton 8961K1901 | 8   |
| OTK04-01571 | FCS-SW098 | CRUISE SWITCH          |  | Kenworth W900                                                                                     | Paccar P27104015,577.59626                       | 7   |
| OTK04-01572 | FCS-SW099 | ENGINE CHECK SWITCH    |  | Kenworth T600 2015-08<br>Kenworth T600A 2007-06<br>Kenworth T660 2017-06<br>Kenworth T800 2017-06 | P27104016,577.59627,9015412                      | 8   |
| OTK04-01573 | FCS-SW100 | ENGINE CHECK SWITCH    |  | Kenworth T600 2015-08<br>Kenworth T600A 2007-06<br>Kenworth T660 2017-06<br>Kenworth T800 2017-06 | PACCAR<br>P27104017,577.59628,9015413            | 10  |
| OTK04-01574 | FCS-SW101 | AUXILIARY LIGHT SWITCH |  | Kenworth                                                                                          | Paccar P27104023<br>577.59629<br>Eaton 8961K1914 | 5   |

| OTK NO.     | FCS NO.   | Description                       | Photo                                                                               | Model                                                                                    | OE NO.                                                       | Pin |
|-------------|-----------|-----------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----|
| OTK04-01575 | FCS-SW102 | SPARE SWITCH                      |    | Kenworth                                                                                 | Paccar P27104049<br>577.59630<br>Eaton 8961K2126             | 10  |
| OTK04-01579 | FCS-SW103 | MIRROR SWITCH                     |    | Freightliner Cascadia 2017-07                                                            | Freightliner 15829700SR<br>DTL15829700,577.46700,901520<br>2 |     |
| OTK04-01590 | FCS-SW104 | ENGINE CHECK SWITCH               |    | Mack                                                                                     | Mack 25161198<br>1MR4323M6<br>Volvo 26550690                 | 5   |
| OTK04-01591 | FCS-SW105 | WIPER SWITCH                      |    | Mack                                                                                     | Mack 1MR4336<br>25173793<br>577.62511                        | 8   |
| OTK04-01613 | FCS-SW106 | Head Light Switch                 |    | Kenworth T2000 (10-97)                                                                   | P27100211PKG                                                 | 7   |
| OTK04-01656 | FCS-SW107 | Cruise Control Switch             |    | International 4100, 4200, 4300<br>7300, 7400, 7500, 7600, 7700<br>8500, 8600<br>CXT, RXT | 2590922C1                                                    | 5   |
| OTK04-01733 | FCS-SW108 | Power Window Switch               |  | Kenworth                                                                                 | 577.59519                                                    |     |
| OTK04-01772 | FCS-SW109 | Power Window Switch               |  | Freightliner Cascadia                                                                    | 577.46661                                                    | 8   |
| OTK04-01785 | FCS-SW110 | Speed Control Switch              |  | Freightliner Columbia                                                                    | A0630769011                                                  | 10  |
| OTK04-01991 | FCS-SW111 | PTO Control Switch                |  | Peterbilt                                                                                | G906022004BN<br>4 PIN                                        |     |
| OTK04-02065 | FCS-SW112 | Air Valve Suspension Dump Switch  |  | Kenworth T660                                                                            | G90-1066-02                                                  |     |
| OTK04-02066 | FCS-SW113 | Air Valve 5th Wheel Slider Switch |  | Kenworth T660                                                                            | G90-1066-03                                                  |     |
| OTK04-02067 | FCS-SW114 | Air Valve Pusher Axle Switch      |  | Kenworth T660                                                                            | G90-1066-10                                                  |     |

| OTK NO.     | FCS NO.   | Description                                    | Photo                                                                               | Model                 | OE NO.                   | Pin |
|-------------|-----------|------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|--------------------------|-----|
| OTK04-02165 | FCS-SW115 | Parking Light Switch                           |    | Mack CXN612 CXN613    | 1MR4323M61               | 8   |
| OTK04-02168 | FCS-SW116 | SUSPENSION HEIGHT<br>AIR ROCKER SWITCH         |    | Freightliner Cascadia | A12-26539-007            | 4   |
| OTK04-02181 | FCS-SW117 | HEAD LIGHT / PARKING<br>LAMPS ROCKER SWITCH    |    | Kenworth              | P27-1173-073             | 10  |
| OTK04-02182 | FCS-SW118 | AIR SUSPENSION DUMP<br>VALVE CONTROL<br>SWITCH |    | Kenworth              |                          | 4   |
| OTK04-02230 | FCS-SW119 | Park Lamp Switch                               |    | Kenworth T660         | P27104002                | 4   |
| OTK04-02231 | FCS-SW120 | Hazard Waring Switch                           |    | Kenworth T660, T800   | P27104025                | 8   |
| OTK04-02232 | FCS-SW121 | Mirror Switch                                  |  | Peterbilt 387         | P27-1037-2               | 7   |
| OTK04-02250 | FCS-SW122 | Door Lock Switch                               |  | Peterbilt             | 16-09211PKG              | 6   |
| OTK04-02252 | FCS-SW123 | Mirror Heat Switch                             |  | Freightliner          | A0637217002              | 9   |
| OTK04-02256 | FCS-SW124 | Air Suspension Switch                          |  | Peterbilt             | G90-6022-009BN, 3276-009 | 4   |
| OTK04-02257 | FCS-SW125 | Fifth Wheel Air Slide<br>Dash Switch           |  | Peterbilt             | 08-03333-003, 3246-002   | 4   |
| OTK04-02258 | FCS-SW126 | Toggle Switch                                  |  | Freightliner          | 59024-12                 | 2   |
| OTK04-02259 | FCS-SW127 | Toggle Switch                                  |  | Freightliner          | 59024-15                 | 4   |

| OTK NO.      | FCS NO.   | Description                | Photo                                                                             | Model               | OE NO.                                            | Pin   |
|--------------|-----------|----------------------------|-----------------------------------------------------------------------------------|---------------------|---------------------------------------------------|-------|
| OTK04-02269M | FCS-SW128 | Toggle Switch              |  | Freightliner        | 59024-110                                         | 4     |
| OTK04-02300  | FCS-SW129 | Speed Control Switch       |  | Freightliner M2 112 | A0637217054                                       | 8 Pin |
| OTK04-02301  | FCS-SW130 | Ignition Toggle Switch     |  | Mack CH, CV         | 1MR4323M12                                        | 4 Pin |
| OTK04-02302  | FCS-SW131 | Air Suspension Dump Switch |  | Kenworth T680, T880 | P271173053                                        | 8 Pin |
| OTK04-02307  | FCS-SW132 | Power Window Switch        |  | Mack Truck          | 82278971, 1MR4341BM15,<br>1MR4341M15, 1MR4341AM15 | 9     |